



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLJ 6711 Y

Parts	(a) Cost / List Price Items	\$	21,023.49
	Plus/Less 25%	\$	5,255.87
	Total of Cost / List	\$	15,767.62
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	15,812.62
Labour		\$	3,010.00
Total		\$	18,822.62

The above total will be subjected to 7% G.S.T.

Not Authorized
Repair B4 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor

Company

Survey conducted on

Kenneth

LKK

19/3/19

at 14:00

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Se

Date: 19/3/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLJ 6711 Y
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU403539041

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>BY</i>	1	\$45.00	S.N	✓
2	Front number plate garnish <i>CM</i>	1	\$129.00		✓
3	Bonnet <i>BY</i>	1	\$812.40		✓
4	Bonnet lock <i>D.Y</i>	1	\$130.00		✓
5	Bonnet hinge LH	1	\$57.80		?
6	Bonnet hinge RH	1	\$57.80		?
7	Bonnet heat insulator	1	\$440.12		?
8	Bonnet heat insulator clip	10	\$35.00		?
9	Front support panel centre	1	\$338.50		?
10	Front support panel LH	1	\$213.50		?
11	Front support panel RH	1	\$213.50		?
12	Headlamp panel LH <i>R</i>	1	\$89.20		X
13	Headlamp panel RH	1	\$89.20		?
14	Support panel lower <i>R</i>	1	\$387.95		X
15	Front support panel top garnish <i>CM</i>	1	\$285.40		✓
16	Front support panel top garnish clip <i>AC</i>	10	\$35.00		✓
17	Air duct	1	\$195.40		?
18	Air duct - inlet	1	\$109.75		?
19	Brace panel	1	\$105.20		?
20	Condenser	1	\$1,544.70		?
21	Radiator	1	\$1,841.80		?
22	Radiator fan motor RH	1	\$455.70		?
23	Radiator fan motor LH	1	\$491.79		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLJ 6711 Y

Make & Model : TOYOTA PRIUS

Chassis No : JTDKB3FU403539041

Submit By : Carmen Lim

Year Manufacture : 2016

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80		?
25	Radiator fan blade RH	1	\$219.80		?
26	Radiator top hose <i>PL</i>	1	\$49.80		X
27	Radiator bottom hose <i>SL</i>	1	\$46.95		X
28	Radiator spare tank	1	\$186.70		?
29	Headlamp LH	1	\$2,531.60		?
30	Headlamp RH <i>MSL</i>	1	\$2,531.60		✓
31	Front bumper <i>MS</i>	1	\$450.80		✓
32	Front bumper clip <i>MS</i>	10	\$40.00		✓
33	Front bumper reinforcement - upper	1	\$711.50		?
34	Front bumper reinforcement - lower	1	\$245.30		?
35	Front bumper side retainer RH <i>DR</i>	1	\$107.20		✓
36	Front bumper side retainer LH <i>DR</i>	1	\$107.20		✓
37	Front bumper upper grille <i>CM</i>	1	\$321.90		✓
38	Front bumper lower grille <i>CM</i>	1	\$148.60		✓
39	Front bumper emblem <i>CM</i>	1	\$87.10		✓
40	Front bumper tow cover RH <i>SL</i>	1	\$25.70		X
41	Front bumper tow cover LH <i>SL</i>	1	\$25.70		X
42	Front bumper sponge - upper	1	\$89.81		?
43	Front bumper sponge - lower	1	\$135.70		?
44	Fog lamp LH	1	\$910.70		?
45	Fog lamp RH	1	\$910.70		?
46	Engine under cover	1	\$198.30		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts


Vehicle No. : SLJ 6711 Y
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU403539041

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Engine under cover clip	10	\$35.00		7
48	Washer tank <i>Sh</i>	1	\$195.60		X
49	Washer tank motor <i>Sh</i>	1	\$196.74		X
50	RH front fender <i>R</i>	1	\$868.70		X
51	RH front fender undershield <i>Sh</i>	1	\$185.64		✓
52	RH front fender undershield clip <i>nn</i>	10	\$25.00		✓
53	RHF fender wording "HYBRID" <i>nn</i>	1	\$44.17		✓
54	LH front fender <i>R</i>	1	\$868.70		X
55	LH front fender undershield <i>Sh</i>	1	\$195.60		X
56	LH front fender undershield clip <i>nn</i>	10	\$25.00		X
57	LHF fender wording "HYBRID" <i>nn</i>	1	\$44.17		X
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. : SLJ 6711 Y Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.