



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLJ 6711 Y

Parts	(a) Cost / List Price Items	\$	21,023.49
	Plus/Less 25%	\$	5,255.87
	Total of Cost / List	\$	15,767.62
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	15,812.62
Labour		\$	3,010.00
Total		\$	18,822.62

The above total will be subjected to 7% G.S.T.

Finalised

19078.28

4769.57

14308.71

45

14353.71

1520 1620

15873.71

15923.71

Not Authorized

Phanny Bepain

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Sc

Date: 19/3/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemparf.com.sg

Spare Parts

Vehicle No. : SLJ 6711 Y
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU403539041

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	✓ S.N	✓
2	Front number plate garnish	1	\$129.00	✓	✓
3	Bonnet	1	\$812.40	✓	✓
4	Bonnet lock	1	\$130.00	✓	✓
5	Bonnet hinge LH ✓	1	\$57.80	✓	✓
6	Bonnet hinge RH ✓	1	\$57.80	✓	✓
7	Bonnet heat insulator ✓	1	\$440.12	✓	✓
8	Bonnet heat insulator clip	10	\$35.00		✓
9	Front support panel centre	1	\$338.50	✓	✓
10	Front support panel LH	1	\$213.50	✓	✓
11	Front support panel RH	1	\$213.50	✓	✓
12	Headlamp panel LH	1	\$89.20	✓	✓
13	Headlamp panel RH	1	\$89.20	✓	✓
14	Support panel lower	1	\$387.95		X
15	Front support panel top garnish	1	\$285.40	✓	✓
16	Front support panel top garnish clip	10	\$35.00	✓	✓
17	Air duct No. 1	1	\$195.40	✓	✓
18	Air duct - inlet No. 2	1	\$109.75	✓	✓
19	Brace panel	1	\$105.20		✓
20	Condenser	1	\$1,544.70	✓	✓
21	Radiator FLU	1	\$1,841.80	✓	✓
22	Radiator fan motor RH	1	\$455.70	✓	✓
23	Radiator fan motor LH	1	\$491.79	✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

7530.56
~~7828.56~~
SN: 4X

Spare Parts

Vehicle No. : **SLJ 6711 Y**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU403539041**

Submit By : **Carmen Lim**
 Year Manufacture : **2016**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80	/	(2)
25	Radiator fan blade RH	1	\$219.80	/	(2)
26	Radiator top hose	1	\$49.80		X
27	Radiator bottom hose	1	\$46.95		X
28	Radiator spare tank	1	\$186.70		3
29	Headlamp LH	1	\$2,531.60	/	(2)
30	Headlamp RH	1	\$2,531.60	/	1
31	Front bumper	1	\$450.80	/	1
32	Front bumper clip	10	\$40.00	/	1
33	Front bumper reinforcement - upper	1	\$711.50	/	(2)
34	Front bumper reinforcement - lower	1	\$245.30	/	(2)
35	Front bumper side retainer RH	1	\$107.20	/	1
36	Front bumper side retainer LH	1	\$107.20	/	1
37	Front bumper upper grille	1	\$321.90	/	1
38	Front bumper lower grille	1	\$148.60	/	1
39	Front bumper emblem	1	\$87.10	/	1
40	Front bumper tow cover RH	1	\$25.70		X
41	Front bumper tow cover LH	1	\$25.70		X
42	Front bumper sponge - upper	1	\$89.81	/	(2)
43	Front bumper sponge - lower	1	\$135.70	/	(2)
44	Fog lamp LH	1	\$910.70	/	(2)
45	Fog lamp RH	1	\$910.70	/	(2)
46	Engine under cover	1	\$198.30	/	(2)

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

9945-61

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLJ 6711 Y

TOYOTA PRIUS
 JTDKB3FU403539041

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim

2016

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Engine under cover clip	10	\$35.00		X
48	Washer tank	1	\$195.60		X
49	Washer tank motor	1	\$196.74		X
50	RH front fender	1	\$868.70		X
51	RH front fender undershield	1	\$185.64		✓
52	RH front fender undershield clip	10	\$25.00		X
53	RHF fender wording "HYBRID"	1	\$44.17		✓
54	LH front fender	1	\$868.70		X
55	LH front fender undershield	1	\$195.60		X
56	LH front fender undershield clip	10	\$25.00		X
57	LHF fender wording "HYBRID"	1	\$44.17		X
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

44.17

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SLJ 6711 Y

TOYOTA PRIUS

JTDKB3FU403539041

Submit By :

Year Manufacture :

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price
1	Air Cleaner Box <i>CRA</i>	1	\$957.80	✓
2	Front bumper reinforcement lower bracket LH <i>Ry</i>	1	\$137.30	✓
3	Front bumper reinforcement lower bracket RH <i>Ry</i>	1	\$137.30	✓
4	Front bumper top rubber <i>CR</i>	1	\$34.40	✓
5	Air Duct No.3 <i>nd</i>	1	\$49.74	✓
6	Radiator fan cowling <i>CRA</i>	1	\$241.40	✓
7		1		
8		1		
9		1		
10		1		
11		1		
12		1		
13		1		
14		1		
15		1		
16		1		
17		1		
18		1		
19		1		
20		4		
21		1		
22		1		
23		1		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

1557.94



