

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA INSURANCE SINGAPORE PTE LTD	DATE	: 18/03/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJT5503J		
MODEL	: TOYOTA COROLLA ALTIS 1.6 A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 15-Mar-19
		TIME	: 07:00HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 812.00	\$ 812.00
2	BOOTLID LOGO	1	\$ 50.00	\$ 50.00
3	BOOTLID EMBLEM '1.6'	1	\$ 60.00	\$ 60.00
4	BOOTLID EMBLEM 'COROLLA'	1	\$ 60.00	\$ 60.00
5	BOOTLID EMBLEM 'ALTIS'	1	\$ 45.00	\$ 45.00
6	BOOTLID EMBLEM 'WT-I'	1	\$ 60.00	\$ 60.00
7	BOOTLID TOP LOCK <i>Dented</i>	1	\$ 133.00	\$ 133.00
8	BOOTLID LOWER LOCK <i>New</i>	1	\$ 63.00	\$ 63.00
9	BOOTLID WEATHERSTRIP <i>Gr</i>	1	\$ 178.00	\$ 178.00
10	REAR BUMPER <i>Dented</i>	1	\$ 613.00	\$ 613.00
11	REAR BUMPER SIDE RETAINER(REAR) <i>New</i>	2	\$ 89.40	\$ 178.80
12	REAR BUMPER SIDE RETAINER(FRONT) <i>New</i>	2	\$ 134.50	\$ 269.00
13	REAR BUMPER REINFORCEMENT <i>New</i>	1	\$ 530.50	\$ 530.50
14	REAR BUMPER REINFORCEMENT SPONGE <i>cracked</i>	1	\$ 163.00	\$ 163.00
15	TAILLAMP <i>cracked</i>	2	\$ 366.70	\$ 733.40
16	TAILLAMP PANEL <i>Repair</i>	2	\$ 233.50	\$ 467.00
17	TAILLAMP BRACKET <i>New</i>	2	\$ 60.00	\$ 120.00
18	REAR END PANEL <i>Dented.</i>	1	\$ 868.70	\$ 868.70

758

492

586.60

19	REAR END PANEL TOP GARNISH <i>del</i>	1	\$ 233.00	\$ 233.00
----	---------------------------------------	---	-----------	-----------

Rear Bumper stay
not needed

2
85.20

TOTAL PRICE	\$ 5,637.40
LESS 25%	\$ 1,409.35
SUB TOTAL PRICE	\$ 4,228.05

3820
2865

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 45.00	\$ 45.00
2	BOOTLID SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	TAILLAMP CLIPS(SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	TAILLAMP PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 35.00	\$ 35.00
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00
8	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00

300

TOTAL \$ 600.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	800	
3	TUFF COAT	\$ 120.00	60	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO	\$ 100.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 130.00	50	
7	TRANSFER BOOTLID MECHANISM	\$ 160.00	X	
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	

1800

TOTAL

\$3,310.00

TOTAL PARTS COST : \$ 4,828.05
TOTAL LABOUR COST : \$ 3,310.00
TOTAL REPAIR COST : \$ 8,138.05

Adrian King
H/S 19/03/19
tel: 4965
4/5: 3914

APPROVED DETAILS

EXCESS :

NO. OF WORKING DAYS:

RE-SURVEY :

PART BY PART OR LUMP SUM :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

06 Days.

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :