

14.17 TON

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Claim Reference:

Assessment number: ck133496

Version: 1810

Date calculated: 03/18/2019 05:47 PM

Full Report

Registration: SDB8006Z

Printed: 18/03/2019 5:47 PM

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER COVER NEW PART PAINT K1R	14.0
	BOOTLID/TAILGATE REPAIR PAINTING <50%	19.0
	L/OUT U-SONIC SENDER SURFACE PAINT PLAST.	3.0
	R/OUT U-SONIC SENDER SURFACE PAINT PLAST.	3.0
	R/INN U-SONIC SENDER SURFACE PAINT PLAST.	3.0
	L/R SIDE PANEL SURFACE PAINT	7.0
	R/R SIDE PANEL SURFACE PAINT	7.0

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER COVER NEW PART PAINT K1R	73.31
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	35.21
2671	L/OUT U-SONIC SENDER SURFACE PAINT PLAST.	0.37
2672	R/OUT U-SONIC SENDER SURFACE PAINT PLAST.	0.37
2674	R/INN U-SONIC SENDER SURFACE PAINT PLAST.	0.37
3481	L/R SIDE PANEL SURFACE PAINT	18.18
3482	R/R SIDE PANEL SURFACE PAINT	18.18

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			56.0	
Preparation Main Work Metal		2.10	21.0	94.50
Preparation Comp. Work Plastic		0.50	5.0	22.50
Total	10 WU/h	8.20	82.0	369.00
Total	12 WU/h	8.20	98.4	369.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	73.31
Repair Painting	35.21
Surface-/Blend Paint	36.36
Surface Painting Plastic	1.11
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	173.09

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Claim Reference:

Assessment number: ck133496

Version: 1810

Date calculated: 03/18/2019 05:47 PM

Full Report

Registration: SDB8006Z

Printed: 18/03/2019 5:47 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 12 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		1.0	3.75
51 12 656	R + R REAR BUMPER		6.0	22.50
51 12 657	RENEW REAR BUMPER TRIM (BUMPER REMOVED)		3.0	11.25
NO NUMBER	R + R REAR LOWER BUMPER GUIDE		3.0	11.25
66 20 602	ADD/WORK PARK DISTANCE CONTROL		2.0	7.50
2931	BOOTLID/TAILGATE REPAIR		10.0*	37.50
2611	L/R REFLECTOR CHECK			
2643	REAR BUMPER CARRIER CHECK		10.0*	37.50
2644	RR BUMPER CTR GUIDE CHECK			
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.90	35.0	131.25
Total of Labour				131.25

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Claim Reference:

Assessment number: ck133496

Version: 1810

Date calculated: 03/18/2019 05:47 PM

Full Report

Registration: SDB8006Z

Printed: 18/03/2019 5:47 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	GOH CHAI HOCK	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-26
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	5 SERIES F10
Sub Model:	528 I
Model Sheet Number:	01 4A 02
Registration:	SDB8006Z
VIN number:	WBA5A52040G390313
Odometer:	

Model Specs

FROM 11/2015	EDITION SPORT	THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES
COMFORT ACCESS SYST	DIP REAR VIEW MIRROR	WHEEL 8.5/9J X19 ALU	NAVIG SYSTEM PROFESS
HI-FI SPEAKER SYSTEM	LED HEADLAMP	LED FOG LAMPS	HIGH BEAM ASSISTANT
INTER LIGHT AMBIENCE	HEADLAMP WASHERS	DAKOTA LEATHER TRIM	FRT SPORT SEATS
MULTIFUNCT DISPLAY	ELEC/SEAT ADJ MEMORY	AUTO TAILGATE CONTR	HEAD-UP DISPLAY
DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	REARVIEW CAMERA	2.0 LTR 180KW
M LEATHER STRG WHEEL	8-GEAR AUTOMATIC	245/40-/275/35 YR 19	WINDOW FRAME BLACK
INT MOULDING BLACK	TWO COAT METALLIC	TYRE W/FLAT RUNNING	

明義汽車私人有限公司

MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
 Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
 Email: info@minghee.com (Main), account@minghee.com (Accounts)
 Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 8143999

DATE	15/04/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SDB8006Z	OUR REF.	58922

GST REG.NO.: M2-0D90482-6 CO REG.NO.: 198905613E

ACCOUNT NUMBER: MOVAAUT3 TIME:14:22

MOVA AUTOMOTIVE PTE. LTD

BLK 1008, BUKIT MERAH

LANE 3, #01-08,

SINGAPORE 159722

159722

Telephone No : 62723892

ROUTE
BRBM1

DELIVER TO :

MOVA AUTOMOTIVE PTE. LTD

BLK 1008, BUKIT MERAH

LANE 3, #01-51

SINGAPORE 159722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 BW51 12 7 332 764	REAR BUMPER PDC	6H-2C	1 PC	1,400.00	1,400.00
2 BW66 20 9 270 495	PDC SENSOR	1C-04G	1 PC	185.00	185.00
3 BW51 12 7 184 765	GUIDE RR BUMPER BOTTOM	6D-1B	1 PC	75.00	75.00
4 BW51 16 1 881 149	RIVET	1D-04F	10 PCS	2.50	25.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor

HDK

Stockists

Payment via telegraphic transfer to
 Name of Bank: United Overseas Bank
 Account Name: Min Ghee Auto Pte Ltd

Branch Code: 046

Account No.: 503-309-511-3

*Please send a screen shot of your payment/

transfer confirmation to

account@minghee.com



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
 MIN GHEE AUTO PTE. LTD.

SIGN & COMPANY'S STAMP

For MIN GHEE AUTO PTE. LTD.

MOV Automotive Pte Ltd
Blk 1 08, Bukit Merah Lane
3, #0 -04/06/08. Singapore
159722

Claim Reference:

Assessment number: ck133496

Version: 1810

Date calculated: 03/18/2019 05:47 PM

Full Report

Registration: SDB8006Z

Printed: 18/03/2019 5:47 PM

Spare Parts

				prices as at 2018-09-10/02	
Code	Description	Part Number	Supplier		Price SGD
2583	REAR BUMPER COVER	51 12 7 332 764	CPA		1,400.00 ✓
2624	CTR LWR BUMPER	51 12 7 184 765	CPA		75.00 ✓
	GUIDE				
2650	REAR BUMPER MNTG KIT	51 12 2 482 063	CPA		25.00 ✓
2673	L/INN U-SONIC SENDER	66 20 9 233 044	CPA		185.00 ✓
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				1,685.00
u: Used parts	Addition(+15.00%)				252.75
	Total				1,937.75

Final Calculation

	SGD	SGD
Parts	1,685.00	
Addition(+15.00%)	252.75	
Total Parts		1,937.75
Labour Time Base 12 WU/h		
Total 35.0 WU X 45.00 SGD/h		
Total of Labour	131.25	131.25
Paint Work Time Base 10 WU/h		
Labour Cost 82.0 WU X 45.00 SGD/h	369.00	
Material Cost	173.09	
Total Paint Including Material		542.09
Repair Cost Excludes GST		2,611.09
GST (+7.00%)		182.78
Repair Cost Included GST		2,793.87

Signature
 16/04/19
 COR \$2611.09

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Claim Reference:

Assessment number: ck133496

Version: 1810

Date calculated: 03/18/2019 05:47 PM

Full Report

Registration: SDB8006Z

Printed: 18/03/2019 5:47 PM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repairer
4p 90000068
P/P or lump sum?
15/04/19 @ 1220
Resy after or by paint?
2 days
COR \$2611.09