

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8451L

DATE: 16. Mar. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 15. Mar. 2019

QBE

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Side Mirror – LH ✓			\$518.00
1	Front Door – LH <i>X repair</i>			\$2,256.40
1	Front Door Glass – LH ✓			\$228.20
SUB TOTAL				\$3,002.60
LESS 25%				\$750.65
DISCOUNTED TOTAL				\$2,251.95
1	Front Door Comfort Sticker ✓			\$75.00
				Nett
				\$75.00
Labour Charge				
1	Panel Beating			\$300.00 ²⁰⁰
1	Spray Painting Charge			\$250.00 ²⁰⁰
1	Tuff Kote			\$80.00 ^X
1	Wiring Charge			\$80.00 ²⁰
TOTAL LABOUR				\$710.00
ESTIMATE TOTAL				\$3,036.95
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Larry Ng

Kahinley

18/3/19 1146h

2 by

4/5

After Repair p/b

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey by a motor Surveyor
- To discontinue

Acknowledged by Repairer
Signature:
Date: