## COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE\*** 

VEHICLE NO: SHD 6837Y

MODEL · HVIINDAL i40

OM NOT FILE

DATE 18/3/2019 11:15

LIMM

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 553.0	0
	Rear Bumper Clip 10 pcs			\$ 22.0	0
	SUB TOTAL			\$ 575.0	0
	LESS 20%			\$ 115.0	00
	DISCOUNTED TOTAL			\$ 460.0	0
	Rear Bumper Rubber Mat			\$ 50.0	00
	Rear Bumper Advertisement Logo			\$ 50.0	00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.0	00
				\$ 300.0	0
	Labour Charge			260	
	Panel Beating			\$ 400.0	
	Spray Painting Charge			\$ 300.0	-
	Wiring Charge			\$ 39.0	_
	Remove/Refix Reverse Sensor			\$ 80.0	
	TOTAL LABOUR			\$ 810.0	0
	ESTIMATE TOTAL		*	\$ 1,570.0	0
	Kaluz (Class				
	Ko /mh 16/6/6/	LKF AU	Consul		
		the Repa	Consultants hence notify reper the following:		
	11 0/10 /	ISU.	y bet element y painting		
	18/3/19 1200h.	27	in 60 mills, man resurvey		
		I ng	Term 100		
	2 /7,	legin	Tan Br	tinsis	
	11.				
	43	Acres design		and the second	
	Aller Regar ple	Simulate:		1	
	After 190 Par	4101		1	
	//				

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.