

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1169 A

1 pc	Bonnet	✓	\$	979.00
1 pc	Bonnet lock	X	\$	36.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00	X	\$	46.00
1 pc	Bonnet grille	✓	\$	385.00
1 pc	Support panel	X	\$	645.00
1 pc	Front bumper	✓	\$	531.00
1 pc	Front bumper emblem	✓	\$	44.00
1 pc	Front bumper centre grille	X	\$	174.00
1 pc	Front bumper lower stiffer	X	\$	134.00
1 pc	Front bumper tow hook cover	X	\$	14.00
1 pc	Front bumper lip	X	\$	52.00
1 pc	Front bumper inner sponge	X	\$	110.00
1 pc	Front bumper reinforcement	?	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	X	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00	o/s - n/s X	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00	X	\$	132.00
			\$	5,762.00
			Less 10%	\$ 576.20
			\$	5,185.80

S/NETT

1 pc	Front no. plate with casing	✓	\$	50.00 35
1 pc	Front bumper clips	✓	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	o/s n/s X	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	o/s n/s X	\$	6.00
Sundry			\$	50.00 20
To check for wiring and to focus head lamps			\$	80.00 20
To top up aircon gas			\$	120.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs			\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.			\$	900.00 600
To putty and spray painting on front bumper, bonnet, bonnet grille.			\$	800.00 500
To apply rustproofing on the repaired and replaced panels.			\$	180.00 50
			\$	7,611.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify
the Repairer of the following:
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.
To putty and spray painting on front bumper, bonnet, bonnet grille.
To apply rustproofing on the repaired and replaced panels.