



Vic

Section A - Accident Details

Registration Number	SHC4098G
Case Reference Number	TAX/02/19/2126
Registration Date	30/10/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA KANG NGEE
Type of Accident	Head to Rear
Accident Date and Time	25/2/2019 5:15 PM
Accident Reported Date and Time	26/2/2019 11:59 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100613
Special Instruction to ARC, if any	TOS/AIG - LKK
Prepared Date and Time	16/3/2019 11:37 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Signature

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$936.00	\$200.00
Total Spare Part Cost	\$1,341.96	\$451.69
Total Other Cost	\$360.00	\$40.00
TOTAL COST	\$3,482.96	\$891.69
Lump Sum Total	\$3,500.00	\$900.00 (L/S)
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	18/03/2019 3:08 PM	18/03/2019 2:55 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER PAINT.

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685552
Estimator Telephone Number: 68662023
Accident Reporting Number: 68662672

Date Generated: 17/04/2019

User ID: PehBuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0104	Invoice Number	
Quotation Date	08.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$845.00	\$200.00
Total Labour	\$845.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check
		61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given
		65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given
Total					\$2,112.31		\$564.61		

564.61

- 202

451.69

+ 200.00

+ 240.00

891.69

458900/-