



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT19001261	Page	1
	100 BEACH ROAD	Date	: 18. Mar 2019		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: JACK NG		
Registration No	: SLS1223A	Engine No	: K24W72041211		
Chassis No	: JHMRC1880HC203554	Date Time	: 18. Mar 2019 8:37:57 PM		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Surveyor Name	:		
Owner's Name	: TEO GEOK KIANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 18/3/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TEO GEOK KIANG OWNER INSURER:AVIVA LTD ACC DATE:18/03/2019 SURVEYED BY: DATE: REF NO: TP INSURER:LONPAC INSURANCE TP VEH:YK 2645 Y						
04715-T6A-000ZZ	FACERR.BUMPER <i>DE</i>	1	537.50	25	403.12	28.22	431.34
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>X</i>	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>X</i>	1	45.40	25	34.05	2.38	36.43
71502-T6A-003ZH	FACE,R.RR.BUMPER <i>X</i>	1	76.80	25	57.60	4.03	61.63
71507-T6A-003ZH	FACE,L.RR.BUMPER <i>X</i>	1	76.80	25	57.60	4.03	61.63
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>ne</i>	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>ne</i>	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER <i>ne</i>	9	2.30	25	15.52	1.09	16.61
68100-T6A-Q10ZZ	TAILGATE COMP <i>Blue</i>	1	1070.80	25	803.10	56.22	859.32
75701-T6A-000	EMBLEMH <i>ne</i>	1	26.30	25	19.72	1.38	21.10
74440-T6A-003	WEATHERSTRIPTAILGATE <i>at</i>	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE <i>?</i>	1	185.40	25	139.05	9.73	148.78
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>?</i>	1	105.30	25	78.97	5.53	84.50
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD <i>Bro</i>	1	1011.00	25	758.25	53.08	811.33
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>ne</i>	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER <i>ne</i>	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER <i>ne</i>	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD <i>ne</i>	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM <i>ne</i>	1	3.70	25	2.77	0.19	2.96

Printed on 18/3/2019 9:03:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

Registration No : SLS1223A

Chassis No : JHMRC1880HC203554

Model : ODYSSEY 2.4 EX-S 17YM (EURO 6)

Owner's Name : TEO GEOK KIANG

Ins Policy No. :

Date of Accident : 18/3/2019

Document No. : SQT19001261

Date : 18. Mar 2019

Customer No. : WZL009

Svc Advisor : JACK NG

Engine No : K24W72041211

Date | Time : 18. Mar 2019 8:37:57 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5 <i>ALL</i>	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT <i>ne</i>	1	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>ne</i>	2	60.00		120.00	8.40	128.40
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER <i>?</i>	1	206.30	25	154.72	10.83	165.55
76720-T4N-H01	ARM,RR.WIPER <i>BRO</i>	1	42.60	25	31.95	2.24	34.19
76730-S3N-003	BLADEWINDSHIELD WIPER <i>ne</i>	1	42.80	25	32.10	2.25	34.35
33500-T6A-003	TAILLIGHT ASSYR. <i>?</i>	1	838.10	25	628.57	44.00	672.57
33550-T6A-003	TAILLIGHT ASSYL. <i>?</i>	1	838.10	25	628.57	44.00	672.57
34150-T6A-003	LIGHT ASSYR.LID <i>BRO</i>	1	386.20	25	289.65	20.28	309.93
34155-T6A-003	LIGHT ASSYL.LID <i>BRO</i>	1	386.20	25	289.65	20.28	309.93
66100-T6A-Q00ZZ	PANEL COMP,REAR <i>st (phub)?</i>	1	460.80	25	345.60	24.19	369.79
04656-T6A-310ZZ	PAN SET,3RD SEAT <i>?</i>	1	337.90	25	253.42	17.74	271.16
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>ne</i>	1	320.00		320.00	22.40	342.40
74940-SZW-003	BUZZER ASSYSMART <i>?</i>	1	61.30	25	45.97	3.22	49.19
NMDVR-IROADX9-2C	DVR, IROAD 2 CHANNEL <i>MIS</i>	1	429.90		429.90	30.09	459.99
Sum Item					6170.98	431.97	6,602.95

BO-V-KOOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00 <i>ne</i>		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00

BOSUN	SUNDRIES	1	100.00 <i>50</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	150.00 <i>120</i>		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	150.00 <i>120</i>		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	150.00 <i>? 120</i>		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00 <i>280</i>		380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00 <i>/</i>		380.00	26.60	406.60
BOMISC1	REMOVE & INSTALL REAR VIEW REVERSE CAMERA(N)	1	450.00 <i>/</i>		450.00	31.50	481.50
BOMISC1	REMOVE & INSTALL DVR, I ROAD 2 CHANNEL	1	560.00 <i>/</i>		560.00	39.20	599.20

Printed on 18/3/2019 9:03:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT19001261	Page	3
	100 BEACH ROAD	Date	: 18. Mar 2019		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: JACK NG		
Registration No	: SLS1223A	Engine No	: K24W72041211		
Chassis No	: JHMRC1880HC203554	Date Time	: 18. Mar 2019 8:37:57 PM		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Surveyor Name	:		
Owner's Name	: TEO GEOK KIANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 18/3/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	450.00		450.00	31.50	481.50
BODAMKIT	WINDSCREEN DAM KIT.	1	200.00		200.00	14.00	214.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BOMISC1	REMOVE & CLEAR ALL BROKEN GLASS	1	350.00		350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00		800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	6000.00		6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	5000.00		5000.00	350.00	5350.00
Sum Labor					16240.00	1,136.80	17,376.80

Survey By	RABUL - Hp 90010068	Total Amount	22,710.98	1,589.77	24,300.75
Date & Time	19/03/19 @ 1350	Total (Inclusive of GST)			24,300.75
Excess					
Status	8 days				
Signature					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Printed on 18/3/2019 9:03:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.