

(INSURER)

INS. CASE OWNER:

CC 4/LPC1900 4968, Ehb3n2

LKC:

IDAC:

Surveyor:

SCOVE

DOI:

ASSIGNMENT

19/7/19

Date / Time:

19/3/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YP 6174L

Name of Insured:

ELOSYS INFRASTRUCTURE PU

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

18/7/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

JATINDER SINGH

Driver Tel No.:

(VL: YES / NO)

Claim No.:

18/10/19/000/07528

Policy No.:

18/1001/0610-

Make / Model:

MTSUSHI

Place of Accident:

GTB

OLGIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SKK518TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

VIN's



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/07/19

12/08/19

15/08/19

05/09/19

YP 6174L 20/08/19 4968/4 - 18/7/19
SKK518TP

- PINKETED

- TP LOD IN

- PLS REVIEWED. OLD INVOLVED IN
A 3 VEH. C.C.; OLD CASE CATE

- TP & REPORT FOR WANDATE APPROVAL

- REPORT DONE

- SEEK WANDATE APPROVAL TO LPC

- LPC APPROVED WANDATE

- SEND 1st OFFER TO TP

- TP ACCEPTED OFFER

- RECURVED PV.

- ALL DOCS IN ORDER

- TO CLOSE.

STAGE

DATE / PIC

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup)

Call OE

After call hr to OE

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OE

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others:

PRELIMINARY ADVICE Date/Time: 20/08/19

Sent By: 63

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

H6

\$5 10,400.00

(7 days) Reduction:

30

%

Email

Call

FINAL SETTLEMENT

Date/Time: 20/08/19

Confirm with:

RAYMOND

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost:

(w/extra)

\$5 11,720.00

Loss of Rental (LOR):

\$5 1,300.00

(9 days)

X \$150

Loss of Use (LOU):

\$5

(5

x

days)

Loss of Income (LOI):

\$5

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

2.00

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/Independent)

Legal Cost

\$5

Total:

\$5 12,480.00

Global Sum \$5:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 12,480.00

Name 1:

VIN'S MOTOR PLS LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

-

Payee 3: (Strike if N.A.)

\$5

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

4450.00

3) Survey fee:

Steve

ASSIGNMENT

MV - 51,900
PV - 32,700
NV - 18,300

The U/C / Chassis frame / Body Structure affected due to collision.

1699-9

☐ Weekend IS

--	--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19004968/Ejb3

Date: 20.03.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKK5181P

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.03.2019 at the premises of M/s Vin's Automotive Group and have the following to report:-

Workshop Estimate Amount	: S\$	11,203.60
Revised Estimate Amount	: S\$	7,507.80
"Check" Items Amount	: S\$	2,103.56
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

STEVE
Licensed Appraiser

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resour

- Michelin Pilot Sport 4
- Opel Astra 2016
- 2018 / 2019 Kia Cerato K3 / Forte (BD Series)

Toyota Harrier Price Range Depreciation 2011 Vehicle Type

Advanced Search

Home » Used Cars » ABWIN (1994) Pte Ltd » Toyota Harrier 2.4A GL

Toyota Harrier 2.4A GL

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

ABWIN 論輝

YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price \$51,800

Depreciation ⓘ \$15,580 /yr
View models with similar depre

Reg Date 10-Jun-2011
(2yrs 2mths 21days COE left)

Mileage N.A.

Manufactured ⓘ 2010

Road Tax ⓘ \$1,638 /yr

Transmission Auto

Dereg Value ⓘ \$34,341 as of today (change)

OMV ⓘ \$34,215

COE ⓘ \$62,010

ARF ⓘ \$34,215

Engine Cap 2,362 cc

Power 118.0 kW (158 bhp)

Curb Weight ⓘ 1,600 kg

No. of Owners ⓘ 3

Type of Vehicle SUV

Features

Good Condition, Well Maintain, Wear And Tear Done, Servicing Done. Ready For A Road Trip With A Luxury Look.
View specs of the Toyota Harrier (2004-2012)

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

ABWIN (1994) Pte Ltd

• dealer's pricelist

• 158 vehs sold | 182 vehs availa

Address

20 Kaki Bukit Road 2

Search cars nearby this location

Contact Person(s)

Marcus

933931

Kevin

866881

Raymond Ho

93224-

Postex Compare | Last Updated on: 16-Mar-2019

https://www.sgcarMart.com/used_cars/info.php?ID=795750&DL=1394



ANNOUNCING AA Trust Automotive as sgCarMart Premium Dealer 2019



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



2.8MPV-A Low Interest PCV
Finance 2 Years Warranty
\$2500 Down Monthly From \$638
GV Credit Pte Ltd [Contact](#)



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

3 vehicles

Toyota Harrier

[Advanced Search](#)

Name	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Harrier	Any	Any	2010	Any	Any	Any	Available
	Toyota Harrier 2.4A G	\$37,500	\$14,510 /yr	30-Sep-2010	2,362 cc	155,093 km	SUV	Available
Guaranteed Best Condition Harrier 2.4A, See To Certify! Low Mileage Clocked Of 18000km Annually, No Other Repairs Needed. Bidded Car Number, 100% Accident Free. Ideal For Future COE Renewal. Call Now!								
Lake View Credit Pte Ltd								
Posted: 16-Mar-2019 Tags: 2010 Toyota Harrier, 2010 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota								
	Toyota Harrier 2.4A GL	\$30,333	\$16,210 /yr	21-Jan-2010	2,362 cc	118,000 km	SUV	Available
Only 1 Owner! Must View Must Try Must Buy, Reluctant Sale By Ex-Owner Changing To Mpv Due To Family Requirement. Seriously Well Maintained By This Army Officer. His Loss Is Your Gain. Option To Purchase...								
Posted: 15-Mar-2019 Tags: 2010 Toyota Harrier, 2010 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota								
	Toyota Harrier 2.4A	\$39,000	\$12,070 /yr	24-Dec-2010	2,362 cc	39,800 km	SUV	Available
Elegant White SUV, One Owner Only, Low Mileage Done, Comes With Electric Seat, Low Maintenance Cost, Very Well Maintained, Flexible In-house Loan Packages Available.								
Prime Motor & Leasing								
Posted: 14-Mar-2019 Tags: 2010 Toyota Harrier, 2010 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Name Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate insurance. Find buy used Toyota Harrier, Toyota Harrier Singapore, used Toyota Harrier, used vehicles Singapore or even buy used Toyota Harrier Singapore have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[Compare](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	9912Z

Vehicle Details

Vehicle No.:	SKK5181P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.4GL A
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	2AZB455506
Chassis No.:	ACU300113778
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$33,898.00
Original Registration Date:	03 Jun 2011
First Registration Date:	03 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$33,898.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jun 2021
PARF Rebate Amount:	\$20,338.00

Intended COE Rebate Details

COE Expiry Date:	02 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,490.00
COE Rebate Amount:	\$12,362.00
Total Rebate Amount:	\$32,700.00

The information contained herein is correct as at 18 Mar 2019

OK



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575726
6453 2121 (4 lines) / 6458 1111 (24 hrs)
6459 9795 / 6459 0433
admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

Our Ref : TP/032019/3815 Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date: 18/03/2019

Motor Claim Department

Lonpac Insurance Bhd.

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Sten CLKK)
8327 8813

WTL April 19/3/19
7 days 2.30 pm
L/S
Ry AL spy

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKK5181P

Make/Model : Toyota Harrier 2.4GL

1	pc	Front bumper / DD	\$	599.20 /
1	pc	Front bumper sponge ? BR	\$	145.30 /
2	pcs	Front bumper side retainer @ \$68.75 LH - RH	\$	137.50 /
1	pc	Front bumper reinforcement ? BT	\$	908.65 858.65 /
8	pcs	Front bumper clips @ \$4.00 / NEC	\$	32.00 30 /
1	pc	Rear windscreen moulding / NEC	\$	183.20 /
1	pc	Rear boot lid / DD	\$	1,190.00 /
1	pc	Rear boot lid rubber / CRU	\$	387.00 /
2	pcs	Rear boot lid shocker bracket @ \$137.60 X AN	\$	275.20 X
1	pc	Rear boot lid lock with motor * AN - BR	\$	438.00 /
1	pc	Rear boot lid handle X NN	\$	243.50 X
1	pc	Rear boot lid inner trim / CRU	\$	425.50 /
1	pc	Rear boot lid wiper motor & AN ? BR	\$	612.00 568 /
2	pcs	Rear boot lid reflector lamp @ \$392.10 LH - RH	\$	784.20 CR 562 /
1	pc	Rear boot lid emblem / NEC 281	\$	78.26 /
1	pc	Rear boot lid "240G" name plate / NEC	\$	46.55 /
1	pc	Rear boot lid "Harrier" name plate / NEC	\$	66.78 /
1 / 2	pcs	Rear lamp @ \$471.20 LH ✓ CR / RH AN	\$	942.40 471.20 /
1	pc	Rear bumper / DD	\$	752.28 /
8	pcs	Rear bumper clips @ \$4.00 / NEC	\$	32.00 30 /
1	pc	Rear bumper sponge ? / CRU	\$	135.20 /
1	pc	Rear bumper reinforcement ? / DD	\$	711.30 589.70 /
2	pcs	Rear bumper reflector @ \$126.80 X AN	\$	253.60 X
2	pcs	Rear bumper retainer @ \$85.60 LH - BR	\$	171.20 CR /
		Balance C/F	\$	9,550.82

Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/032019/3815

Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date: 18/03/2019

Balance B/F

\$ 9,550.82

1	pc	Rear end panel	✓ / CR	\$ 630.13	580.80 /	9320.24
1	pc	Rear end panel inner trim	✓ CR	\$ 262.92	/	- 25.16
1	pc	Rear spare tyre top cover	✓ BT	\$ 562.40	505.80 /	6990.18
2	pcs	Rear no. plate lamp @ 52.60	✓ LR / RH / BR	\$ 105.20	/	
				\$ 11,111.47		
Less 25%				\$ (2,777.87)		
				\$ 8,333.60		

1	pc	Front windscreen gum	✓ AEC	\$ 60.00	N	
1	pc	Front no. plate	✓ BR	\$ 40.00	N 35	
1	pc	Rear no. plate	✓ BR	\$ 40.00	N 35	
1	set	Rear bumper sensor	✓ BR	\$ 280.00	N 300	330
To remove and refix rear glass				\$ 150.00	100	
To repair front & rear damage				\$ 1,200.00	1000	
To spray painting				\$ 1,100.00	1000	
				\$ 11,203.60		2100

15054.03

VIN'S MOTOR PTE LTD

Total - 9420.18

P- 9420.18
Supp- 3611.91
13,032.09
L/S - 10,425.67
= 10,420.90 /

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/032019/3815
Accident date: 18/03/2019
Your Ref : YP6174L

Tax Invoice :

Date : 21/03/2019

Motor Claim Department

Lonpac Insurance Bhd.
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

SUPPLEMENTARY COST OF REPAIRS TO

Vehicle No. : SKK5181P
Make/Model : Toyota Harrier 2.4GL

✓ 2	pcs	Front headlamp @ \$1921.30 ^{845.10} RH / LH / BR	\$ 3,842.60 / 3690.20
✓ 1	pc	Rear RH spare tire top cover / BR	\$ 599.20 / 530.28
✓ 1	pc	Rear tool box / BR	\$ 481.50 / 384.80
✓ 2	pcs	Rear lamp garnish @ \$105.30 RH / LH / BR	\$ 210.60 /
Less: 25%			\$ 5,133.90 4815.88
			\$ (1,283.48) 356
			<u>\$ 8,984.33</u> 3611.91

VIN'S MOTOR PTE LTD

resurvey (supplementary items)

Naz LKK

21/3/19 1730

NH

Vin's

AUTOMOTIVE GROUP

limit 16K

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/032019/3815

Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date: 18/03/2019

Motor Claim Department

Lonpac Insurance Bhd.

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Store CLKK)
8322 8813

will report 19/3/19
7 days
L/S
By AL spy
2.30 pm

ESTIMATE COST OF REPAIRS TO

Repairing

Vehicle No. : SKK5181P

Make/Model : Toyota Harrier 2.4GL

1	pc	Front bumper / DD	\$	599.20
1	pc	Front bumper sponge ? BR /	\$	145.30
2	pcs	Front bumper side retainer @ \$68.75 LH / RH /	\$	137.50
1	pc	Front bumper reinforcement ? BT /	\$	908.65
8	pcs	Front bumper clips @ \$4.00 / NEC	\$	32.00
1	pc	Rear windscreen moulding / NEC	\$	183.20
1	pc	Rear boot lid / DD	\$	1,190.00
1	pc	Rear boot lid rubber / CR	\$	387.00
2	pcs	Rear boot lid shocker bracket @ \$137.60 X NN	\$	275.20
1	pc	Rear boot lid lock with motor X NN	\$	438.00
1	pc	Rear boot lid handle X NN	\$	243.50
1	pc	Rear boot lid inner trim / CR	\$	425.50
BR / 1	pc	Rear boot lid wiper motor X NN ?	\$	612.00
2	pcs	Rear boot lid reflector lamp @ \$392.10 LH / RH	\$	784.20
1	pc	Rear boot lid emblem / NEC	\$	78.26
1	pc	Rear boot lid "240G" name plate / NEC	\$	46.55
1	pc	Rear boot lid "Harrier" name plate / NEC	\$	66.78
2	pcs	Rear lamp @ \$471.20 LH ? RH X	\$	942.40
1	pc	Rear bumper / DD	\$	752.28
8	pcs	Rear bumper clips @ \$4.00 / NEC	\$	32.00
1	pc	Rear bumper sponge ? / CR	\$	135.20
1	pc	Rear bumper reinforcement ? / DD	\$	711.30
2	pcs	Rear bumper reflector @ \$126.80 X NN	\$	253.60
2	pcs	Rear bumper retainer @ \$85.60 LH / RH	\$	171.20
Balance C/F			\$	9,550.82

visually (checked items)

NA2 CLK

21/3/19 1730

Vin's

AUTOMOTIVE GROUP

△ Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/032019/3815

Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date:

18/03/2019

Balance B/F

\$ 9,550.82

1	pc	Rear end panel	✓ CR4	\$ 630.13
1	pc	Rear end panel inner trim	✓ CR4	\$ 262.92
✓ 1	pc	Rear spare tyre top cover	✓ BT	\$ 562.40
✓ 2	pcs	Rear no. plate lamp @ 52.60	✓ LH / RR	\$ 105.20
				<u>\$ 11,111.47</u>
Less 25%				<u>\$ (2,777.87)</u>
				\$ 8,333.60

1	pc	^{Rear} Front windscreen gum	✓ AEC	\$ 60.00	N
1	pc	Front no. plate	✓ RR	\$ 40.00	N
1	pc	Rear no. plate	✓ RR	\$ 40.00	N
1	set	Rear bumper sensor	✓ RR	\$ 280.00	N 300

To remove and refix rear glass
To repair front & rear damage
To spray painting

\$ 150.00 /00
\$ 1,200.00 /000
\$ 1,100.00 /000
\$ 11,203.60

VIN'S MOTOR PTE LTD





AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/032019/3815

Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date: 18/03/2019

Motor Claim Department

Lonpac Insurance Bhd.

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Stem CLKK)
8322 8813

WIL April 19/3/19
7 kg
L/S
Ry AL spy

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKK5181P

Make/Model : Toyota Harrier 2.4GL

1	pc	Front bumper / DD	\$	599.20	
1	pc	Front bumper sponge ?	\$	145.30	
2	pcs	Front bumper side retainer @ \$68.75 LH - RH	\$	137.50	DR
1	pc	Front bumper reinforcement ?	\$	908.65	
8	pcs	Front bumper clips @ \$4.00 / NEC	\$	32.00	JO
1	pc	Rear windscreen moulding / NEC	\$	183.20	
1	pc	Rear boot lid / DD	\$	1,190.00	
1	pc	Rear boot lid rubber / CRU	\$	387.00	275.20
2	pcs	Rear boot lid shocker bracket @ \$137.60 X AN	\$	275.20	
1	pc	Rear boot lid lock with motor * RH	\$	438.00	
1	pc	Rear boot lid handle X NN	\$	243.50	
1	pc	Rear boot lid inner trim / CRU	\$	425.50	
1	pc	Rear boot lid wiper motor X AN ?	\$	612.00	
2	pcs	Rear boot lid reflector lamp @ \$392.10 LH - RH	\$	784.20	DR
1	pc	Rear boot lid emblem / NEC	\$	78.26	
1	pc	Rear boot lid "240G" name plate / NEC	\$	46.55	
1	pc	Rear boot lid "Harrier" name plate / NEC	\$	66.78	
2	pcs	Rear lamp @ \$471.20 LH ? RH X	\$	942.40	
1	pc	Rear bumper / DD	\$	752.28	
8	pcs	Rear bumper clips @ \$4.00 / NEC	\$	32.00	JO
1	pc	Rear bumper sponge ? / CRU	\$	135.20	
1	pc	Rear bumper reinforcement ? / DD	\$	711.30	589.70
2	pcs	Rear bumper reflector @ \$126.80 X AN	\$	253.60	
2	pcs	Rear bumper retainer @ \$85.60 LH - RH	\$	171.20	DR
		Balance C/F	\$	9,550.82	



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

Our Ref : TP/032019/3815

Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date: 18/03/2019

Balance B/F \$ 9,550.82

1	pc	Rear end panel	✓	OD	\$ 630.13
1	pc	Rear end panel inner trim	✓	CRV	\$ 262.92
1	pc	Rear spare tyre top cover	✓	?	\$ 562.40
2	pcs	Rear no. plate lamp @ 52.60	✓	?	\$ 105.20
					<u>\$ 11,111.47</u>
Less 25%					<u>\$ (2,777.87)</u>
					<u>\$ 8,333.60</u>

1	pc	Front windscreen gum	✓	MEC	\$ 60.00	N
1	pc	Front no. plate	✓	BR	\$ 40.00	N
1	pc	Rear no. plate	✓	BR	\$ 40.00	N
1	set	Rear bumper sensor	✓	DR	\$ 280.00	N 300

To remove and refix rear glass	\$ 150.00	100
To repair front & rear damage	\$ 1,200.00	1000
To spray painting	\$ 1,100.00	1000
	<u>\$ 11,203.60</u>	

VIN'S MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 19 March 2019 9:16 AM
To: Admin @ VAuG; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/19/19/VC00/021538 Request For TP Survey For SKK5181P ; Your Insured: YP6174L [External Confidential]

Lonpac External - Confidential

Without Prejudice

Dear Raymond,

Thank you for your confirmation on the appointment of surveyor, Steve Chen.

Dear Nivitha

FYA -pls assign Steve Chen for the TP survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Admin @ VAuG [mailto:admin@vinsautogroup.com.sg]

Sent: Tuesday, 19 March, 2019 9:08 AM

To: GERALD POH WEE BIN

Cc: MT_Claim_SG

Subject: Re: Request For TP Survey For SKK5181P ; Your Insured: YP6174L [External Confidential]

Good morning,

Please assign to Steve Chen.

Thanks!

Best Regards

Raymond Teo

On Mon, Mar 18, 2019 at 5:47 PM GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Lonpac External - Confidential

WITHOUT PREJUDICE

Dear Raymond,

11.27pm @ 19/3/19
Raymond
vehicle In.
Steve

Please see attached and revert.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Admin @ VAuG [mailto:admin@vinsautogroup.com.sg]

Sent: Monday, 18 March, 2019 5:36 PM

To: ONG LI LI

Cc: NT_Claim_SG

Subject: Request For TP Survey For SKK5181P ; Your Insured: YP6174L

Good afternoon,

Please help us to arrange for survey

DOA: 18/03/2019

Location:

Sin Ming Autocity

166 Sin Ming Drive #08-09

Singapore 575722

Please send us a list of surveyor which should include independent surveyor.

Thanks!

Best Regards

Raymond Teo

Sin Ming AutoCity

160 Sin Ming Drive

Singapore 575722

Showroom/Office: #03-03

Workshops: #08-08/09

Tel: 64532121 (4 lines)

Fax: 64599795

Website: www.vinsautogroup.com.sg

Email: admin@vinsautogroup.com.sg

Follow us on :

** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **



Sin Ming AutoCity

160 Sin Ming Drive

Singapore 575722

Showroom/Office: #03-03

Workshops: #08-08/09

Tel: 64532121 (4 lines)

Fax: 64599795

Website: www.vinsautogroup.com.sg

Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19004968/Ehb3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 04-09-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 6174L	Veh. Inspected	SKK 5181P	
Policy No.	Z/18/VC00/101610	Coverage (\$)	0.00	
Claim No.	18/19/19/VC00/021538	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	19/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	2400	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	ACU300113778	Colour	BLACK	
Odometer	124970	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	225/55 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/55 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/55 R18	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/03/2019	Inspection Date	19/03/2019	
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 5181P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED	599.20	599.20
1	FRONT BUMPER SPONGE	BROKEN	145.30	145.30
2	FRONT BUMPER SIDE RETAINER @\$68.75	BROKEN	137.50	137.50
1	FRONT BUMPER REINFORCEMENT	BENT	908.65	858.65
8	FRONT BUMPER CLIPS @\$4.00	NECESSARY	32.00	30.00
1	REAR WINDSCREEN MOULDING	NECESSARY	183.20	183.20
1	REAR BOOT LID	DENTED	1,190.00	1,190.00
1	REAR BOOT LID RUBBER	CRUSHED	387.00	387.00
2	REAR BOOT LID SHOCKER BRACKET @\$137.60	NOT NECESSARY	275.20	-
1	REAR BOOT LID LOCK WITH MOTOR	BROKEN	438.00	438.00
1	REAR BOOT LID HANDLE	NOT NECESSARY	243.50	-
1	REAR BOOT LID INNER TRIM	CRUSHED	425.50	425.50
1	REAR BOOT LID WIPER MOTOR	BROKEN	612.00	568.00
2	REAR BOOT LID REFLECTOR LAMP @\$392.10	BROKEN	784.20	562.00
1	REAR BOOT LID EMBLEM	NECESSARY	78.26	78.26
1	REAR BOOT LID "240G" NAME PLATE	NECESSARY	46.55	46.55
1	REAR BOOT LID "HARRIER" NAME PLATE	NECESSARY	66.78	66.78
2	REAR LAMP @\$471.20	N/S BROKEN / O/S NOT NECESSARY	942.40	471.20
1	REAR BUMPER	DENTED	752.28	752.28
8	REAR BUMPER CLIPS @\$4.00	NECESSARY	32.00	30.00
1	REAR BUMPER SPONGE	CRUSHED	135.20	135.20
1	REAR BUMPER REINFORCEMENT	DENTED	711.30	589.70
2	REAR BUMPER REFLECTOR @\$126.80	NOT NECESSARY	253.60	-
2	REAR BUMPER RETAINER @\$85.60	BROKEN	171.20	171.20
2	FRONT HEADLAMP @\$1921.30 (ADDITIONAL)	BROKEN	3,842.60	3,690.20
1	REAR RH SPARE TIRE TOP COVER (ADDITIONAL)	BROKEN	599.20	530.28
1	REAR TOOL BOX (ADDITIONAL)	BROKEN	481.50	384.60
2	REAR LAMP GARNISH @\$105.30 (ADDITIONAL)	BROKEN	210.60	210.60
1	REAR END PANEL	DENTED	630.13	580.80
1	REAR END PANEL INNER TRIM	CRUSHED	262.92	262.92

Report Ref No. CC4/LPC19004968/Ehb3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE TOP COVER	BENT	562.40	505.80
2	REAR NO PLATE LAMP @\$52.60	BROKEN	105.20	105.20
	LESS 25% DISCOUNT		-4,061.34	-3,533.98
			12,184.03	10,601.94
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN GUM (SN)	NECESSARY	60.00	60.00
1	FRONT NO PLATE (SN)	BROKEN	40.00	35.00
1	REAR NO PLATE (SN)	BROKEN	40.00	35.00
1	SET REAR BUMPER SENSOR (SN)	BROKEN	280.00	200.00
			420.00	330.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIX REAR GLASS.		150.00	100.00
	TO REPAIR FRONT & REAR DAMAGE.		1,200.00	1,000.00
	TO SPRAY PAINTING.		1,100.00	1,000.00
			2,450.00	2,100.00
	GRAND TOTAL		15,054.03	13,031.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,400.00

Report Ref No. CC4/LPC19004968/Ehb3n2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.