



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/032019/3815

Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date: 18/03/2019

Motor Claim Department

Lonpac Insurance Bhd.

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Stem CLKK)
8322 8813

WIL APV-L 9/3/19
7 ckg
L/S
Ry AL Spy

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKK5181P

Make/Model : Toyota Harrier 2.4GL

1	pc	Front bumper / DD	\$	599.20
1	pc	Front bumper sponge ?	\$	145.30
2	pcs	Front bumper side retainer @ \$68.75 LH - RH	\$ DR	137.50
1	pc	Front bumper reinforcement ?	\$	908.65
8	pcs	Front bumper clips @ \$4.00 / NEC	\$	32.00 Jo
1	pc	Rear windscreen moulding / NEC	\$	183.20
1	pc	Rear boot lid / DD	\$	1,190.00
1	pc	Rear boot lid rubber / CRU	\$	387.00 275.20
2	pcs	Rear boot lid shocker bracket @ \$137.60 X MN	\$	275.20
1	pc	Rear boot lid lock with motor X MAH - BR	\$	438.00
1	pc	Rear boot lid handle X NN	\$	243.50
1	pc	Rear boot lid inner trim / CRU	\$	425.50
1	pc	Rear boot lid wiper motor X MAH ?	\$	612.00
2	pcs	Rear boot lid reflector lamp @ \$392.10 LH - RH	\$	784.20 DR
1	pc	Rear boot lid emblem / NEC	\$	78.26
1	pc	Rear boot lid "240G" name plate / NEC	\$	46.55
1	pc	Rear boot lid "Harrier" name plate / NEC	\$	66.78
2	pcs	Rear lamp @ \$471.20 LH ? RH X	\$	942.40
1	pc	Rear bumper / DD	\$	752.28
8	pcs	Rear bumper clips @ \$4.00 / NEC	\$	32.00 Jo
1	pc	Rear bumper sponge ? / CRU	\$	135.20
1	pc	Rear bumper reinforcement ? / DD	\$	711.30 589.70
2	pcs	Rear bumper reflector @ \$126.80 X NN	\$	253.60
2	pcs	Rear bumper retainer @ \$85.60 LH - RH	\$	171.20 BR
		Balance C/F	\$	9,550.82

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/032019/3815

Invoice No:

Accident date: 18/03/2019

Your Ref : YP6174L

Date: 18/03/2019

Balance B/F

\$ 9,550.82

1	pc	Rear end panel	✓	CRV	\$ 630.13
1	pc	Rear end panel inner trim	✓	CRV	\$ 262.92
1	pc	Rear spare tyre top cover	?		\$ 562.40
2	pcs	Rear no. plate lamp @ 52.60	?		\$ 105.20
					<u>\$ 11,111.47</u>
Less 25%					<u>\$ (2,777.87)</u>
					<u>\$ 8,333.60</u>

1	pc	Rear Front windscreen gum	✓	AIEC	\$ 60.00	N
1	pc	Front no. plate	✓	BR	\$ 40.00	N
1	pc	Rear no. plate	✓	BR	\$ 40.00	N
1	set	Rear bumper sensor	✓	BR	\$ 280.00	N 200

To remove and refix rear glass
To repair front & rear damage
To spray painting

\$ 150.00 100
\$ 1,200.00 1000
\$ 1,100.00 1000
\$ 11,203.60

VIN'S MOTOR PTE LTD



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: