

10/2/2001

ASSIGNMENT (Office)

SA View/

CWS

From Person

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

at Workshop n/s

of

Policy No.

Sum Insured

Make of Veh

(Client's Record)

CA / REV / REP / REV 24 HRS

Date/Time

Person Contacted

Vehicle

Date/Time

Action/Instruction

2/10/3/19

9/14/19

SHD 2289E - CS/RSI 1090130192 / Yfg1

SH 7986S - CS/FCI 19003484 / Ccl/3n2

@ 10:30 a.m. received PA to Karen via email.

Final fig \$ 23,990.36 (Red 2379.80, 999 confirmed by email

RASUL

KAREN TAN

es/FCI 19004970 / Rvd3

ASSIGNMENT (Office)

FCI

n2

per of location

Date/Time

2:38pm 19/3/19

Bill to

Insured

SH 7986S

Tel.

68610908

Claim No.

D19001896PSTH

Excess

D.O.A.

15/03/2019

20/3/19

H.O.D. Endorsement

chmsy

IN/OUT

DUA: 23/6/2019

DUA: 20/3/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001896MFSH

Date: 21 March 2019

Our Ref: CS/FCI19004970/R1vd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 2289E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/03/2019 at the premises of M/s Prime Auto Claims Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>20,771.57</u> .
Revised Estimate Amount	: S\$ <u>15,848.81</u> .
"Check" Items Amount	: S\$ <u>2,394.16</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 14 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-03-2019	Our Ref No. D19001896MFSH
Accident Date	15-03-2019	Claim Type. Third Party
Insured Vehicle	SH7986S	Third Party Vehicle. SHD2289E
Survey Location	6 BENOI PLACE	
Contact Person.	CHRISSY TEO	
Contact No.	68610908/ 0	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Alice Leong <aliceleong@primeautoclaims.com>
Sent: Tuesday, 9 April 2019 4:04 PM
To: Veron Chen (LKKAUTO); Rasul (LKKAUTO); SUR
Subject: RE: FINALIZE TO SHD2289E-DOA: 15/3/2019

Hi Veron,

Amount confirmed

Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: 09 April, 2019 4:00 PM
To: Alice Leong <aliceleong@primeautoclaims.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZE TO SHD2289E-DOA: 15/3/2019

Dear Alice,

WITHOUT PREJUDICE

Finalize at part by part \$23,990.36 and 14 days

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong <aliceleong@primeautoclaims.com>
Sent: Friday, 5 April 2019 11:12 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: FINALIZE TO SHD2289E
Importance: High

Hi Rasul,

Enclosed our after repair photos, our calculation sheet & supplementary for your retention. Shall we finalize at part by part \$23,990.36 and 14 days

Please let us have your confirmation within three days from our e-mail.

Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 9 April 2019 4:00 PM
To: Alice Leong; Rasul (LKKAuto); SUR
Subject: RE: FINALIZE TO SHD2289E-DOA: 15/3/2019

Dear Alice,

WITHOUT PREJUDICE

Finalize at part by part \$23,990.36 and 14 days

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong <aliceleong@primeautoclaims.com>
Sent: Friday, 5 April 2019 11:12 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: FINALIZE TO SHD2289E
Importance: High

Hi Rasul,

Enclosed our after repair photos, our calculation sheet & supplementary for your retention. Shall we finalize at part by part \$23,990.36 and 14 days

Please let us have your confirmation within three days from our e-mail.

Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 March 2019 10:30 AM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001896MFSH/1
Attachments: SHD 2289E - Preli Advise.pdf

Dear Karen,

Enclosed preliminary revised of vehicle SHD 2289E.

Thank you.

Best Regards,

Shirley Hiew | Case Handler (On Behalf Veron)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 19 March 2019 3:32 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001896MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 19 March 2019 2:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001896MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6293Z
Vehicle Details	
Vehicle No.:	SHD2289E
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	LEB6321016
Chassis No.:	GP71117031
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$24,640.00
Original Registration Date:	31 Oct 2017
First Registration Date:	31 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$28,124.00
Total Rebate Amount:	\$31,874.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Mar 2019

OK



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 18.03.2019

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2289E HONDA SHUTTLE (2017)

To Supply

1)	1pc	front bumper <i>DB</i>	\$	1,350.00
2)	1set	front bumper clip <i>neu</i>	\$	30.00
3)	1set	front bumper reinforcement <i>blo</i>	\$	420.90
4)	1pc	front bumper right side retainer <i>neu</i>	\$	35.00
5)	1pc	front bumper left side retainer <i>neu</i>	\$	35.00
6)	1pc	front bumper right spacer <i>neu</i>	\$	15.40
7)	1pc	front bumper left spacer <i>neu</i>	\$	15.40
8)	1pc	front bumper right side bracket <i>neu</i>	\$	38.00
9)	1pc	front bumper left side bracket <i>neu</i>	\$	38.00
10)	1pc	front bumper under cover ? <i>X sur</i>	\$	300.00
11)	1pc	front bumper right air duct ? <i>X sur</i>	\$	38.00
12)	1pc	front bumper grille <i>neu</i>	\$	140.00
13)	1pc	radiator grille base <i>neu</i>	\$	395.00
14)	1pc	radiator grille chrome garnish <i>neu</i>	\$	302.25
15)	1pc	"H" emblem <i>neu</i>	\$	18.32
16)	1pc	radiator grille lower chrome <i>neu</i>	\$	220.70
17)	1set	radiator grille clip <i>neu</i>	\$	16.00
18)	1pc	front grille stay ? <i>blo</i>	\$	65.00
19)	1pc	right head lamp lower bracket ? <i>blo</i>	\$	38.00
20)	1pc	left head lamp lower bracket ? <i>blo</i>	\$	38.00
21)	1pc	left head lamp assy <i>CA</i>	\$	2,250.00
22)	1pc	front bonnet <i>BA</i>	\$	1,050.00
23)	1set	front bonnet front seal <i>neu</i>	\$	27.40
24)	1pc	front bonnet insulator <i>X neu</i>	\$	140.00
25)	1pc	front bonnet lock <i>X sur</i>	\$	135.00

26) 1pc	front bonnet right hinge	HA	\$	40.00
27) 1pc	front bonnet left hinge	HA	\$	40.00
28) 1pc	A/con condensor	HA	\$	985.00
29) 1pc	a/con fan motor	cut	\$	330.00
30) 1pc	a/con fan blade	CR	\$	78.00
31) 1pc	a/con fan cowling	CR	\$	121.90
32) 1pc	radiator	HA	\$	1,540.40
33) 1pc	radiator fan motor	DE	\$	329.80
34) 1pc	radiator fan blade	DE	\$	78.00
35) 1pc	radiator fan cowling	CR	\$	115.00
36) 1pc	support panel	repair	\$	785.00
37) 1pc	rear bumper	DE	\$	1,350.00
38) 1pc	rear bumper left side retainer	DE	\$	42.50
39) 1pc	rear bumper right side retainer	DE	\$	42.50
40) 1set	rear bumper clip	DE	\$	20.00
41) 1pc	tailgate	DE	\$	1,380.00
42) 1pc	tailgate weatherstrip	DE	\$	168.50
43) 1pc	tailgate right absorber	X SU	\$	189.00
44) 1pc	tailgate left absorber	X SU	\$	185.00
45) 1pc	tailgate left lamp	CR	\$	435.00
46) 1pc	tailgate "H" emblem	DE	\$	38.00
47) 1pc	tailgate "Shuttle" emblem	DE	\$	58.00
48) 1pc	tailgate "Hybrid" emblem	DE	\$	75.00
49) 1pc	tailgate lock	HA	\$	180.00
50) 1pc	tailgate chrome garnish	CR	\$	685.00
51) 1pc	rear no plate lamp	X SU	\$	48.00
52) 1pc	tailgate trim board	cut	\$	320.00
53) 1pc	rear glass inlet seal	DE	\$	180.00
54) 1pc	rear end panel	HA	\$	685.00
55) 1pc	rear end panel top garnish	CR	\$	165.00
56) 1pc	rear tool box	DE	\$	285.00
57) 1pc	rear floor panel	DE	\$	1,250.00
58) 1pc	spooage tool lid	DE	\$	155.00
59) 1pc	key sensor	X SU	\$	175.50
60) 1set	keyless Smart enter Buzzer	X SU	\$	85.50

Sub total	\$	19,791.97
Less: 20% discount	\$	(3,958.40)
	\$	15,833.57

To supply S.Nett Parts

1) 1pc	"Prime Taxi" sticker	DE	\$	55.00
2) 1pc	"Dial-A-Cab" sticker	DE	\$	45.00
3) 1set	floor panel sealant	DE	\$	120.00
4) 1tube	rear glass sealant	DE	\$	40.00

5) 1pc front no plate

\$ 35 ~~38.00~~ *OK*

Sub total S.Nett Parts \$ 298.00

L/charges

1) Towing charges (use king trolley)

\$ *receipt* 100.00 *✓*

2) To tuff kote front portion

\$ 50.00 *✓*

3) To remove radiator, fan cowling, motor, blade , replace the above parts, check engine cooling system

\$ ~~80~~ 100.00 *50*

4) To remove a/con condensor, hose, pipe, fan cowling, blade & motor, refill a/con gas, check a/con cooling system,

\$ *50* 120.00

5) To focus right head lamp

\$ 30.00 *✓*

6) To remove front bumper, front grille, cut/welding support panel, right & left head lamp, knock right & left chassis frame, replace the above parts ajust & align bonnet, grille & bumper

\$ *500* 600.00

7) To putty, respray painting front bonnet inlet & outer, front bumper, support panel

\$ *500* 600.00

8) To tuff kote rear portion

\$ 100 200.00

9) To remove & replace rear glass

\$ 120.00 *✓*

10) To transfer rear boot lid trim board, handle, mechanism parts

\$ 60 120.00

11) To remove rear bumper, tailgate, right & left tailgate, knock & welding left & right chassis frame, cut & replace rear end panel & floor panel, replace the above parts

\$ *900* 1,200.00

12) To putty, respray painting rear boot lid inlet & outer, rear end panel, floor panel, rear bumper & etc. To polish

\$ *900* 1,400.00

Sub total L/charges \$ 4,640.00

Estimate Grand Total \$ 20,771.57

26,370.16

LKK Auto Cons. Inc.
the Repairer of the following:
• To resurvey before and after spray painting
• To display damaged part(s) during survey.
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
21/3/19

14 days
P/P

20/03/19 @ 0900hrs

Resurvey after repair

Note: Require market value



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 18.03.2019

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

store
Star 21/3/19 Resy day parts

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2289E HONDA SHUTTLE (2017)

To Supply

1) 1pc	front bumper <i>DB</i>	\$	1,350.00
2) 1set	front bumper clip <i>ne</i>	\$	30.00
3) 1set	front bumper reinforcement <i>blo</i>	\$	420.90
4) 1pc	front bumper right side retainer <i>ne</i>	\$	35.00
5) 1pc	front bumper left side retainer <i>ne</i>	\$	35.00
6) 1pc	front bumper right spacer <i>ne</i>	\$	15.40
7) 1pc	front bumper left spacer <i>ne</i>	\$	15.40
8) 1pc	front bumper right side bracket <i>ne</i>	\$	38.00
9) 1pc	front bumper left side bracket <i>ne</i>	\$	38.00
10) 1pc	front bumper under cover ?	\$	300.00X
11) 1pc	front bumper right air duct ?	\$	38.00X
12) 1pc	front bumper grille <i>ne</i>	\$	140.00
13) 1pc	radiator grille base <i>ne</i>	\$	395.00
14) 1pc	radiator grille chrome garnish <i>ne</i>	\$	302.25
15) 1pc	"H" emblem <i>ne</i>	\$	18.32
16) 1pc	radiator grille lower chrome <i>ne</i>	\$	220.70
17) 1set	radiator grille clip <i>ne</i>	\$	16.00
18) 1pc	front grille stay ? <i>BR</i>	\$	65.00
19) 1pc	right head lamp lower bracket ? <i>BR</i>	\$	38.00
20) 1pc	left head lamp lower bracket ? <i>BR</i>	\$	38.00
21) 1pc	left head lamp assy <i>CA</i>	\$	2,250.00
22) 1pc	front bonnet <i>BA</i>	\$	1,050.00
23) 1set	front bonnet front seal <i>ne</i>	\$	27.40
24) 1pc	front bonnet insulator X	\$	140.00X
25) 1pc	front bonnet lock X	\$	135.00X

26) 1pc	front bonnet right hinge	BT	\$	40.00
27) 1pc	front bonnet left hinge	BT	\$	40.00
28) 1pc	A/con condensor	BT	\$	985.00
29) 1pc	a/con fan motor	DO	\$	330.00
30) 1pc	a/con fan blade	CUT	\$	78.00
31) 1pc	a/con fan cowling	BR	\$	121.90
32) 1pc	radiator	DO	\$	1,540.40
33) 1pc	radiator fan motor	CUT	\$	329.80
34) 1pc	radiator fan blade	CUT	\$	78.00
35) 1pc	radiator fan cowling	DO	\$	115.00
36) 1pc	support panel repair	DO	\$	785.00
37) 1pc	rear bumper	DE	\$	1,350.00
38) 1pc	rear bumper left side retainer	RE	\$	42.50
39) 1pc	rear bumper right side retainer	RE	\$	42.50
40) 1set	rear bumper clip	RE	\$	20.00
41) 1pc	tailgate	RE	\$	1,380.00
42) 1pc	tailgate weatherstrip	RE	\$	168.50
43) 1pc	tailgate right absorber	X	\$	189.00X
44) 1pc	tailgate left absorber	X	\$	185.00X
45) 1pc	tailgate left lamp	LH - BR	\$	435.00
46) 1pc	tailgate "H" emblem	RE	\$	38.00
47) 1pc	tailgate "Shuttle" emblem	RE	\$	58.00
48) 1pc	tailgate "Hybrid" emblem	RE	\$	75.00
49) 1pc	tailgate lock	TA	\$	180.00
50) 1pc	tailgate chrome garnish	BR	\$	685.00
51) 1pc	rear no plate lamp	X	\$	48.00X
52) 1pc	tailgate trim board	CUT	\$	320.00
53) 1pc	rear glass inlet seal	RE	\$	180.00
54) 1pc	rear end panel	TA	\$	685.00
55) 1pc	rear end panel top garnish	CRA	\$	165.00
56) 1pc	rear tool box	DE	\$	285.00
57) 1pc	rear floor panel	RE	\$	1,250.00
58) 1pc	spoooge tool lid	DE	\$	155.00
59) 1pc	key sensor	X	\$	175.50X
60) 1set	keyless Smart enter Buzzer	X	\$	85.50X

Sub total	\$	19,791.97	18,495.97
Less: 20% discount	\$	(3,958.40)	- 3,699.20
	\$	15,833.57	14,796.77

To supply S.Nett Parts

1) 1pc	"Prime Taxi" sticker	RE	\$	55.00
2) 1pc	"Dial-A-Cab" sticker	RE	\$	45.00
3) 1set	floor panel sealant	RE	\$	60 120.00
4) 1tube	rear glass sealant	RE	\$	40.00

5) 1pc front no plate

\$ 35 ~~38.00~~
Sub total S.Nett Parts \$ 298.00 ~~235.00~~

L/charges

1) Towing charges (use king trolley)

\$ receipt 100.00 ~~2~~

2) To tuff kote front portion

\$ 50.00

3) To remove radiator, fan cowling, motor, blade, replace the above parts, check engine cooling system

\$ ~~100.00~~
50

4) To remove a/con condensor, hose, pipe, fan cowling, blade & motor, refill a/con gas, check a/con cooling system,

\$ 50 ~~120.00~~

5) To focus right head lamp

\$ 30.00

6) To remove front bumper, front grille, cut/welding support panel, right & left head lamp, knock right & left chassis frame, replace the above parts adjust & align bonnet, grille & bumper

\$ 500 ~~600.00~~

7) To putty, respray painting front bonnet inlet & outer, front bumper, support panel

\$ 500 ~~600.00~~

8) To tuff kote rear portion

\$ 100 ~~200.00~~

9) To remove & replace rear glass

\$ 120.00

10) To transfer rear boot lid trim board, handle, mechanism parts

\$ 60 ~~120.00~~

11) To remove rear bumper, tailgate, right & left tailgate, knock & welding left & right chassis frame, cut & replace rear end panel & floor panel, replace the above parts

\$ 900 ~~1,200.00~~

12) To putty, respray painting rear boot lid inlet & outer, rear end panel, floor panel, rear bumper & etc. To polish

\$ 900 ~~1,400.00~~

Sub total L/charges \$ 4,640.00 ~~3360.00~~
Estimate Grand Total \$ 20,771.57

LKK Auto Company
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068

14 days

P/P

20/03/19 @ 0900hrs

Resurvey after repair

Note: Require market value



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 05.04.2019

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: SUPPLEMENTARY COST OF REPAIR TO SHD2289E HONDA SHUTTLE (2017)

To Supply

1) 1pc	right tail lamp <i>crs</i>	\$	585.00
2) 1pc	tow hook cover <i>crs</i>	\$	23.00
3) 1pc	right rear lower plate 63323-TD4-300ZZ <i>crs</i>	\$	105.80
4) 1pc	left rear lower plate 63723-TD4-300ZZ <i>crs</i>	\$	105.80

Sub total parts	\$	819.60
Less: 20% discount	\$	(163.92)
	\$	<u>655.68</u>

Parts - 14,796.77
S. diff - 235.00
L/charges - 3360.00
Supplementary (1) - 4942.91
Supplementary (2) - 655.68

23,990.36



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 20.03.2019

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: SUPPLEMENTARY COST OF REPAIR TO SHD2289E HONDA SHUTTLE (2017)

To Supply

1) 1pc	right tail lamp <i>BR</i>		
2) 1pc	pocket, tailgate	<i>BR</i>	\$ 27.50
3) 1set	rear glass top & lower moulding	<i>NEC</i>	\$ 180.00
4) 1pc	right rear fender lamp	<i>BR</i>	\$ 585.00
5) 1pc	left front fender	<i>OO</i>	\$ 490.00
6) 1pc	right front fender	<i>OO</i>	\$ 490.00
7) 1pc	right head lamp	<i>BR</i>	\$ 2,250.00
8) 1pc	air duct	<i>DEF</i>	\$ 80.60
9) 1pc	electric water pump	<i>NEC</i>	\$ 623.70
10) 1pc	o-ring water pump	<i>NEC</i>	\$ 23.54
11) 1pc	thermostat	<i>BR NEC</i>	\$ 79.20
12) 1pc	thermostat housing	<i>BR</i>	\$ 254.10
13) 1pc	starter motor with socket	<i>BR</i>	\$ 1,095.00

Sub total parts	\$ 6,178.64
Less: 20% discount	\$ (1,235.73)
	<u>\$ 4,942.91</u>



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@gmail.com

Facsimile: 6844 7238

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 58120065L

Cash Sales/ Work Order

NO. 1209717

Date: 15/3



HOTLINE: 9182 8211

M/S: prime

Vehicle No: STD 2289 Model : 4/5 shuttle

From: 1 Nicom Way Time Start: 20.02

To: 6 Benoi Place Time End: 21.02

Remarks: _____

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☐ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ \$100/-

GST S\$ \$7/-

TOTAL S\$ \$107/-

bizSAFE₃

Important Note:

Received By _____

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

Quality



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19004970/R1vd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-04-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7986S	Veh. Inspected	SHD 2289E
Policy No.		Coverage (\$)	0.00
Claim No.	D19001896MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	19/03/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID 1.5 A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71117031	Colour	BROWN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	NEXEN	6 mm
L/H Front Tyre	185/60 R15	NEXEN	6 mm
R/H Rear Tyre	185/60 R15	NEXEN	6 mm
L/H Rear Tyre	185/60 R15	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/03/2019	Inspection Date	20/03/2019
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2289E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,350.00	1,350.00
1	SET FRONT BUMPER CLIP	NECESSARY	30.00	30.00
1	SET FRONT BUMPER REINFORCEMENT	BROKEN	420.90	420.90
1	FRONT BUMPER RIGHT SIDE RETAINER	NECESSARY	35.00	35.00
1	FRONT BUMPER LEFT SIDE RETAINER	NECESSARY	35.00	35.00
1	FRONT BUMPER RIGHT SPACER	NECESSARY	15.40	15.40
1	FRONT BUMPER LEFT SPACER	NECESSARY	15.40	15.40
1	FRONT BUMPER RIGHT SIDE BRACKET	NECESSARY	38.00	38.00
1	FRONT BUMPER LEFT SIDE BRACKET	NECESSARY	38.00	38.00
1	FRONT BUMPER UNDER COVER	SERVICEABLE	300.00	-
1	FRONT BUMPER RIGHT AIR DUCT	SERVICEABLE	38.00	-
1	FRONT BUMPER GRILLE	BROKEN	140.00	140.00
1	RADIATOR GRILLE BASE	BROKEN	395.00	395.00
1	RADIATOR GRILLE CHROME GARNISH	BROKEN	302.25	302.25
1	"H" EMBLEM	NECESSARY	18.32	18.32
1	RADIATOR GRILLE LOWER CHROME	BROKEN	220.70	220.70
1	SET RADIATOR GRILLE CLIP	NECESSARY	16.00	16.00
1	FRONT GRILLE STAY	BROKEN	65.00	65.00
1	RIGHT HEAD LAMP LOWER BRACKET	BROKEN	38.00	38.00
1	LEFT HEAD LAMP LOWER BRACKET	BROKEN	38.00	38.00
1	LEFT HEAD LAMP ASSY	CRACKED	2,250.00	2,250.00
1	FRONT BONNET	BENT	1,050.00	1,050.00
1	SET FRONT BONNET FRONT SEAL	NECESSARY	27.40	27.40
1	FRONT BONNET INSULATOR	NOT NECESSARY	140.00	-
1	FRONT BONNET LOCK	SERVICEABLE	135.00	-
1	FRONT BONNET RIGHT HINGE	BENT	40.00	40.00
1	FRONT BONNET LEFT HINGE	BENT	40.00	40.00
1	A/CON CONDENSOR	BENT	985.00	985.00
1	A/CON FAN MOTOR	CUT	330.00	330.00
1	A/CON FAN BLADE	CRACKED	78.00	78.00
1	A/CON FAN COWLING	CRACKED	121.90	121.90

Report Ref No. CS/FCI19004970/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR	BENT	1,540.40	1,540.40
1	RADIATOR FAN MOTOR	NECESSARY	329.80	329.80
1	RADIATOR FAN BLADE	DEFORMED	78.00	78.00
1	RADIATOR FAN COWLING	CRACKED	115.00	115.00
1	SUPPORT PANEL	BENT	785.00	785.00
1	REAR BUMPER	DEFORMED	1,350.00	1,350.00
1	REAR BUMPER LEFT SIDE RETAINER	NECESSARY	42.50	42.50
1	REAR BUMPER RIGHT SIDE RETAINER	NECESSARY	42.50	42.50
1	SET REAR BUMPER CLIP	NECESSARY	20.00	20.00
1	TAILGATE	BUCKLED	1,380.00	1,380.00
1	TAILGATE WEATHERSTRIP	NECESSARY	168.50	168.50
1	TAILGATE RIGHT ABSORBER	SERVICEABLE	189.00	-
1	TAILGATE LEFT ABSORBER	SERVICEABLE	185.00	-
1	TAILGATE LEFT LAMP	CRACKED	435.00	435.00
1	TAILGATE "H" EMBLEM	NECESSARY	38.00	38.00
1	TAILGATE "SHUTTLE" EMBLEM	NECESSARY	58.00	58.00
1	TAILGATE "HYBRID" EMBLEM	NECESSARY	75.00	75.00
1	TAILGATE LOCK	BENT	180.00	180.00
1	TAILGATE CHROME GARNISH	CRACKED	685.00	685.00
1	REAR NO PLATE LAMP	SERVICEABLE	48.00	-
1	TAILGATE TRIM BOARD	CUT	320.00	320.00
1	REAR GLASS INLET SEAL	NECESSARY	180.00	180.00
1	REAR END PANEL	BENT	685.00	685.00
1	REAR END PANEL TOP GARNISH	CRACKED	165.00	165.00
1	REAR TOOL BOX	DEFORMED	285.00	285.00
1	REAR FLOOR PANEL	BUCKLED	1,250.00	1,250.00
1	SPOOGE TOOL LID	DEFORMED	155.00	155.00
1	KEY SENSOR	NOT NECESSARY	175.50	-
1	SET KEYLESS SMART ENTER BUZZER	NOT NECESSARY	85.50	-
1	RIGHT TAIL LAMP (ADDITIONAL)	CRACKED	585.00	585.00
1	TOW HOOK COVER (ADDITIONAL)	CUT	23.00	23.00
1	RIGHT REAR LOWER PLATE 63323-TD4-300ZZ (ADDITIONAL)	CRACKED	105.80	105.80

Report Ref No. CS/FCI19004970/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LEFT REAR LOWER PLATE 63723-TD4-300ZZ (ADDITIONAL)	CRACKED	105.80	105.80
1	POCKET, TAILGATE (ADDITIONAL)	BROKEN	27.50	27.50
1	SET REAR GLASS TOP & LOWER MOULDING (ADDITIONAL)	NECESSARY	180.00	180.00
1	RIGHT REAR FENDER LAMP (ADDITIONAL)	BROKEN	585.00	585.00
1	LEFT FRONT FENDER (ADDITIONAL)	DENTED	490.00	490.00
1	RIGHT FRONT FENDER (ADDITIONAL)	DENTED	490.00	490.00
1	RIGHT HEAD LAMP (ADDITIONAL)	BROKEN	2,250.00	2,250.00
1	AIR DUCT (ADDITIONAL)	DEFORMED	80.60	80.60
1	ELECTRIC WATER PUMP (ADDITIONAL)	NECESSARY	623.70	623.70
1	O-RING WATER PUMP (ADDITIONAL)	NECESSARY	23.54	23.54
1	THERMOSTAT (ADDITIONAL)	NECESSARY	79.20	79.20
1	THERMOSTAT HOUSING (ADDITIONAL)	BROKEN	254.10	254.10
1	STARTER MOTOR WITH SOCKET (ADDITIONAL)	BROKEN	1,095.00	1,095.00
	LESS 20% DISCOUNT		-5,358.05	-5,098.85
			21,432.16	20,395.36
SPECIAL NETT ITEMS				
1	"PRIME TAXI" STICKER (SN)	NECESSARY	55.00	55.00
1	"DIAL-A-CAB STICKER (SN)	NECESSARY	45.00	45.00
1	SET FLOOR PANEL SEALANT (SN)	NECESSARY	120.00	60.00
1	TUBE REAR GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	FRONT NO PLATE (SN)	CRACKED	38.00	35.00
			298.00	235.00
LABOUR				
	TOWING CHARGES (USE KING TROLLEY).		100.00	100.00
	TO TUFF KOTE FRONT PORTION.		50.00	50.00
	TO REMOVE RADIATOR, FAN COWLING, MOTOR, BLADE, REPLACE THE ABOVE PARTS, CHECK ENGINE COOLING SYSTEM.		100.00	50.00
	TO REMOVE A/CON CONDENSOR, HOSE, PIPE, FAN COWLING, BLADE & MOTOR, REFILL A/CON GAS, CHECK A/CON COOLING SYSTEM.		120.00	50.00
	TO FOCUS RIGHT HEAD LAMP.		30.00	30.00

Report Ref No. CS/FCI19004970/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE FRONT BUMPER, FRONT GRILLE, CUT/WELDING SUPPORT PANEL, RIGHT & LEFT HEAD LAMP, KNOCK RIGHT & LEFT CHASSIS FRAME, REPLACE THE ABOVE PARTS ADJUST & ALIGN BONNET, GRILLE & BUMPER.		600.00	500.00
	TO PUTTY, RESPRAY PAINTING FRONT BONNET INLET & OUTER, FRONT BUMPER, SUPPORT PANEL.		600.00	500.00
	TO TUFF KOTE REAR PORTION.		200.00	100.00
	TO REMOVE & REPLACE REAR GLASS.		120.00	120.00
	TO TRANSFER REAR BOOT LID TRIM BOARD, HANDLE, MECHANISM PARTS.		120.00	60.00
	TO REMOVE REAR BUMPER, TAILGATE, RIGHT & LEFT TAILGATE, KNOCK & WELDING LEFT & RIGHT CHASSIS FRAME, CUT & REPLACE REAR END PANEL & FLOOR PANEL, REPLACE THE ABOVE PARTS.		1,200.00	900.00
	TO PUTTY, RESPRAY PAINTING REAR BOOT LID INLET & OUTER, REAR END PANEL, FLOOR PANEL, REAR BUMPER & ETC, TO POLISH.		1,400.00	900.00
			4,640.00	3,360.00
GRAND TOTAL			26,370.16	23,990.36
RECOMMENDED COST OF REPAIRS				23,990.36

Report Ref No. CS/FCI19004970/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.