



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 05.04.2019

MS First Capital Insurance Ltd

36 Robinson Road #16-01

City House

Singapore 068877

Attn: Motor Claims Dept

RE: SUPPLEMENTARY COST OF REPAIR TO SHD2289E HONDA SHUTTLE (2017)

To Supply

1) 1pc	right tail lamp <i>CR</i>	\$	585.00
2) 1pc	tow hook cover <i>CR</i>	\$	23.00
3) 1pc	right rear lower plate 63323-TD4-300ZZ <i>CR</i>	\$	105.80
4) 1pc	left rear lower plate 63723-TD4-300ZZ <i>CR</i>	\$	105.80

Sub total parts	\$	819.60
Less: 20% discount	\$	(163.92)
	\$	655.68

Parts - 14,796.77
S. diff - 235.00
L/charges - 3360.00
Supplementary (1) - 4942.91
Supplementary (2) - 655.68

23,990.36



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 20.03.2019

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: SUPPLEMENTARY COST OF REPAIR TO SHD2289E HONDA SHUTTLE (2017)

To Supply

1) 1pc	right tail lamp <i>BR</i>		
2) 1pc	pocket, tailgate <i>BR</i>	\$	27.50
3) 1set	rear glass top & lower moulding <i>NEC</i>	\$	180.00
4) 1pc	right rear fender lamp <i>BR</i>	\$	585.00
5) 1pc	left front fender <i>OO</i>	\$	490.00
6) 1pc	right front fender <i>OO</i>	\$	490.00
7) 1pc	right head lamp <i>BR</i>	\$	2,250.00
8) 1pc	air duct <i>DEF</i>	\$	80.60
9) 1pc	electric water pump <i>NEC</i>	\$	623.70
10) 1pc	o-ring water pump <i>NEC</i>	\$	23.54
11) 1pc	thermostat <i>BR NEC</i>	\$	79.20
12) 1pc	thermostat housing <i>BR</i>	\$	254.10
13) 1pc	starter motor with socket <i>BR</i>	\$	1,095.00

Sub total parts	\$	6,178.64
Less: 20% discount	\$	(1,235.73)
	\$	4,942.91