

<b>FINALIZATION</b>		Date/Time:	Confirm with:	Confirm by: <u>Bryan</u>
Repair Cost:	<u>45</u>	<u>\$5 800.00</u> ( <u>8</u> days) Reduction: <u>\$7596.00</u> @ <u>46</u>		Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>		Date/Time: <u>21/11/17 1:15 PM</u>	Confirm with: <u>Syed Yasin</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>22</u>			If NO or B 28, Ass. Lia
Repair Cost: <u>(W/AST)</u>	<u>\$5 946.00</u>			
Loss of Rental (LOR):	<u>\$5 1106.70</u> ( <u>10</u> days) x <u>\$110.67</u>			
Loss of Use (LOU):	<u>\$5 -</u> ( <u>5</u> x days)			
Loss of Income (LOI):	<u>\$5 400.00</u> ( <u>5</u> <u>40</u> x <u>10</u> days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]				
GLA/LTA Search	<u>\$5 -</u>			
Medical:	<u>\$5 -</u>			1) Claim status: Normal/Reject/Private Settle
Disbursement:	<u>\$5 -</u> (e.g. Tow/ Independent)			2) Report Format: <u>TP</u>
Legal Cost	<u>\$5 -</u>			3) Survey fee: <u>\$600/-</u>
<b>Total:</b>	<u>\$5 10922.70</u>	<b>Global Sum \$5:</b> <u>-</u>		
<b>FINAL PAYMENT</b>		Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	<u>\$5 10,922.70</u>	Name 1:	<u>Chunni motor work Pte Ltd</u>	
Payee 2: (Strike if N.A.)	<u>\$5</u>	Name 2:		
Payee 3: (Strike if N.A.)	<u>\$5</u>	Name 3:		



**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHB 6639M

DATE : 18.03.2019

MAKE :

TEL : 6542 5119



MODEL : HYUNDAI i40

FAX : 6542 6039

INDIA (CAR)

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>distorted / cut</i>			\$ 553.00	✓
	Rear Bumper Clip 10 pcs <i>Nec</i>			\$ 22.00	✓
	Rear Fender With Housing (RH) <i>Distorted</i>		2020.20	\$ 4236.80	✓
	Rear Fender Inner Lining (RH) <i>Nec</i>			\$ 169.30	X
	Rear Windscreen Moulding <i>Nec</i>			\$ 28.30	✓
	Rear Door (RH) <i>eye bt</i>			\$ 2,201.10	X ✓
	Front Door (RH) <i>eye bt</i>			\$ 2,256.40	X ✓
	Rear Tyre Rim (RH) <i>Nec</i>			\$ 325.30	X
	Rear Wheel Hub-Cap (RH) <i>distorted</i>			\$ 107.10	2 ✓
	Rear Wheelbearing ING & Hub <i>2 down</i>			\$ 362.00	2 ✓
	Rear Trailing Arm (RH) <i>2 distorted</i>			\$ 192.00	2 ✓
	Rear Assist (RH) <i>2 distorted</i>			\$ 145.70	2 ✓
	Rear Shock Absorber (RH) <i>2 distorted</i>			\$ 276.30	2 ✓
	Rear Shock Absorber Mounting (RH) <i>Nec</i>			\$ 81.30	X
	Rear Crossmember <i>2 distorted</i>			\$ 1,021.50	2 ✓
	Stabilizer Bar <i>2 distorted</i>			\$ 199.60	2 ✓
	Stabilizer Link <i>2 distorted</i>			\$ 85.90	2 ✓
	Rear Upper Arm (RH) <i>2 distorted</i>			\$ 335.75	2 ✓
	Rear Lower Arm (RH) <i>2 distorted</i>			\$ 353.80	2 ✓
	Rear Knuckle Arm (RH) <i>2 distorted</i>		10706.25	\$ 545.60	2 ✓
			8565.00	\$ 13,998.75	
				\$ 2,799.75	
	SUB TOTAL			\$ 11,199.00	
	LESS 20%				
	DISCOUNTED TOTAL				
	Rear Bumper Rubber Mat <i>Nec</i>			\$ 50.00	Nett ✓
	Rear Windscreen Sealant <i>Nec</i>			\$ 46.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>Nec</i>			\$ 80.00	Nett ✓
	Front Door Coloured Comfort Logo (RH) <i>Nec</i>			\$ 75.00	Nett ✓
	Rear Tyre (RH) <i>Nec</i>		251.00	\$ 216.00	Nett X
				\$ 467.00	

SHB 6639M

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,500.00 800/-
	Spray Painting Charge			\$ 1,000.00 700/-
	Wiring Charge			\$ 50.00 40/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 20/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00 150/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	<b>TOTAL LABOUR</b>		2220.00	\$ 4,730.00
	<b>ESTIMATE TOTAL</b>			\$ 16,396.00
	19/03/2019 C 0930ms		11636.00	
	HLA Antenna			
	1/5mm 8 dgs.			
				
	LKK Auto			
				
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

NAME  
ADDRESS

Home Tel.:

VIN:

Registration: SHB 6639 M

Technician:

Mileage: 823951

Time Printed 19.3.19 10:00 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
0°10'		-3°00' 3°00'
4°01'		-0°19' 5°41'
0°45'		-1°30' 1°30'
24°57'		
25°07'		

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°29'		-3°00' 3°00'
4°54'		-0°19' 5°41'
-0°52'		-1°30' 1°30'
8°22'		
7°53'		

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°38'		-3°00' 3°00'
-0°53'		-3°00' 3°00'
16°35'		-3°00' 3°00'
-0°07'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°48'		-3°30' 2°30'
0°06'		-1°30' 1°30'

Camber  
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°21'		-3°30' 2°30'
1°39'		-1°30' 1°30'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	BEFORE	Specified Range
-0°26'		-3°00' 3°00'
1°45'		-3°00' 3°00'
-0°46'		-3°00' 3°00'

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 19 March 2019 10:40 AM  
**To:** Chunni Motor; 'sur@lkkauto.com'; admin-d@lkkauto.com  
**Cc:** Manivel Priyadarshini  
**Subject:** RE: Accident involving veh no: SHB 6639M & SHC 2595B on 16.03.19  
**Attachments:** 18032019170652.pdf

12-07pm @11/3/19  
vehicle in  
lynx  
surv Byen

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHB6639M and let us have your report urgently.

This claim will be handled by Ms Priya.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Chunni Motor [mailto:chunnimotor@gmail.com]  
**Sent:** 19 March, 2019 9:45 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** Re: Accident involving veh no: SHB 6639M & SHC 2595B on 16.03.19

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,  
Chunni Motor work P/L

On Tue, Mar 19, 2019 at 9:42 AM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

**From:** Chunni Motor [<mailto:chunnimotor@gmail.com>]

**Sent:** 18 March, 2019 5:17 PM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Subject:** Accident involving veh no: SHB 6639M & SHC 2595B on 16.03.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

**Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.**

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHB6639M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	D4FDEU416409
Chassis No.:	KMHLB41UMDU043106
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$18,468.00
Original Registration Date:	05 Dec 2013
First Registration Date:	05 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$10,968.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Dec 2021
PARF Rebate Amount:	\$7,677.00
Intended COE Rebate Details	
COE Expiry Date:	04 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$21,171.00
<b>Total Rebate Amount:</b>	<b>\$28,848.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Mar 2019

OK

## Print Received Message

This mail is associated with :

**\*SHB6639M (MCT19030832)**

**[SHC2595B]**

TP

COMFORT TRANSPORTATION PTE LTD

Mar 18 2019 1:00AM

[COMFORT TRANSPORTATION PTE LTD]

Chunni Motor Work Pte Ltd - Amk

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 25/09/2019 17:27 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10922.70) - SHB6639M - Claim Handler: Priya

Approved:10922.70:Request TP WS to Issue Tax Invoice for Repairs in III's favour .

Your Ref : SHC 2595B

Our Ref : SHB 6639M

Syed Yasin Bin Syed Gaffar c/o  
**CHUNNI MOTOR WORK PTE LTD**  
Blk 10 Ang Mo Kio Industrial Park 2A  
#03-19 AMK AutoPoint  
Singapore 568047

Date : 1/05/19

The Motor Claims Department  
**India c/o LKK Auto Consultants P/L**  
51 Ubi Ave 1 # 01-25  
Paya Ubi Ind Park  
Singapore 408933

**WITHOUT PREJUDICE**

Dear Sir / Madam,

**RE: ACCIDENT INVOLVING SHB 6639M / SHC 2595B On 18.03.2019**

**ALONG Marina Bay Sand Tower 1 Taxi Stand**

I am the owner/hirer of motor vehicle/taxi, SHB 6639M, which was involved in the above-mentioned accident.

The motor vehicle/taxi was surveyed by your appointed appraiser at the premises of M/S CHUNNI MOTOR WORK PTE LTD. The accident was caused by your insured's negligent driving and or management of his vehicle. Therefore, I am claiming damages and losses sustained by me against you in connection with the accident based on the appraiser's recommendation.

Our claim is as follows:

1) Cost of Repair	SS	9,416.00
2) Loss of Rental	SS	1,106.70 (8110.67 x 10 days)
3) Loss of Income	SS	400.00 (400 x 10 days)
4) GIA Report Fee	SS	
5) LTA Search Fee	SS	
6) Survey Report Fee	SS	
	SS	<u>10,922.70</u>

We enclose herewith the following relevant supporting documents :

- a) Authorisation Letter
- b) Final repair bill(s)
- c) LTA Search
- d) GIA report(s)
- e) Insurance Certificate

Kindly look into the matter and revert as soon as possible. Thank you.

Yours faithfully



## LETTER OF AUTHORITY

To Whom It May Concern :

ACCIDENT INVOLVING **SHB 6639M/SHC 2595B**


ALONG Marina Bay Sand Tower 1 Taxi Stand ON 18.03.2019

I, Syed Yasin Bin Syed Gaffar, NRIC NO. S 0067414A of  
Blk 669 Jalan Damai # 05-55 Singapore 410669

Owner/hirer of motor vehicle Registration No **SHB 6639M**, insured by  
Ms First Capital Insurance Ltd under Policy No. D-18088936 MFSH

do hereby authorize M/s **Chunni Motor Work Pte Ltd** as my authorized representative to write,  
negotiate and settle claim on my behalf in my claim against the owner and/or Motor Vehicle  
Registration No, **SHC 2595B** in respect of the above mentioned accident. I also  
hereby authorize that the agreed settlement sum ( cost of repair, loss of use, earnings and rental,  
Survey report fee, LTA fee & GIA report fee ) be made in favour of my representative, M/s  
**Chunni Motor Work Pte Ltd** and that the said payment be forwarded to them as full and final  
discharge of my claim.

Dated : 18.03.2019

Signature :   
( Company's chop if necessary )

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT19030832  
Claimant Ref: SHB 6639M

We/I, CHUNNI MOTOR WORK PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 9,416.00 (repair cost), S\$ 1,506.70 (loss of ~~accident~~ <sup>income</sup>), S\$ - (search fee), vehicle no. SHB 6639M that was damaged pursuant to the accident which occurred on 18/03/2019 (date) at MARINA SAND TOWER 1/2 TAXI STAND (location) involving vehicle no. SHB 6639M (insured vehicle). This is pursuant to the inspection conducted on 19/03/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SHB 6639M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHB 6639M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 10,922.70 to CHUNNI MOTOR WORK PTE LTD

Dated this 28 SEP 2019 day of 20

#### CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

**Chunni Motor Work Pte Ltd**  
B1-10 Ang Mo Kio Industrial Park 2A  
AMK Autopoint #03-19  
Singapore 568047  
Tel: 6542-7162 Fax: 6542-8039  
Co. Reg. No: 200823110Q

#### WITNESS:

Signature:

ABT

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1 #02-25

PAYA UBI INDUSTRIAL PARK S(408933)

Nationality:

Occupation:

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

AMENDED

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PTE LTD 64 CECIL STREET #04/05 IOB BUILDING SINGAPORE 049711	VEHICLE NO SHB 6639 M	DATE 08.05.2019
	MAKE HYUNDAI	INVOICE NO 9749
	MODEL I40	ACC DATE/TIME 18.03.2019 @ 00:05 HRS

Cost of Repair \$ 8,800.00

Sub-total \$ 8,800.00

Add : 7 % - GST \$ 616.00

Total \$ 9,416.00

(SINGAPORE DOLLARS: NINE THOUSAND FOUR HUNDRED AND SIXTEEN ONLY)



Our Ref: CT19030466

Date: 21 March 2019



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 18/03/2019 @ 00:05 hrs  
ALONG MARINA BAY SAND TOWER 1 TAXI STAND  
INVOLVING SHC2595B

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHB6639M** (the "Taxi"). The Taxi was hired to **SYED YASIN B SYED G IC NO S0067414A** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$110.67** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

TIME	DATE	NAME OF DRIVER	MILEAGE READING		MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
						FROM	TO
28	18/31/2019	Ryed Yasin Bin Ryed Caffar	Accident	In	05:00	7:00	
45	27/31/2019	Ryed Yasin Bin Ryed Caffar	Repair	Out	7:00	11:00	
07							
00							
10							
30							
45							
34							
30							
25							
00							






**SINGAPORE  
POLICE FORCE**

Traffic Police  
10 Ubi Avenue 3  
Singapore 408865  
Tel +65 6547 0000  
Fax +65 6547 4883  
www.police.gov.sg

Our Ref : TP/IP/16907/2019  
Date : 28 May 2019

Donald Chew Chwee Leng  
Blk 55 Chai Chee Drive  
#02-168  
Singapore 460055



Dear Sir / Madam,

**TRAFFIC ACCIDENT INVOLVING SHB6639M AND SHC2595B ALONG BAYFRONT AVENUE ON 18/03/2019 AT ABOUT 0005 HRS**

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver of SHC2595B had committed the offence of Careless Driving under Rule 29 of the Road Traffic Rules. Action has been initiated against the driver for the said offence.
3. If you have any clarification, you may contact the Investigation Officer, SSS Leslie Tan at office number: 6547 6144.
4. Thank you.

Yours faithfully,

**HEAD INVESTIGATION  
TRAFFIC POLICE  
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Direct Settlement










































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019 <a href="#">Edit Reg</a>		19 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$58,800.00</b> <a href="#">Edit Estimates</a>	<b>\$58,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
























































<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHB6639M	Date of Loss:	18/03/2019 01:00 - :59 [63 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19030832	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC25958	Policy No. (Claimant):	D-18088936MFSH						
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 28/03/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>III_SG (25/09/2019): Alert - Adj Mandate Approved (\$10922.70) - SHB6639M - Claim Handler: Priya</li> <li>III_SG (24/09/2019): Alert - Adj Mandate Maintained - SHB6639M - Claim Handler: Priya</li> <li>III_SG (09/04/2019): Alert - Adj Mandate Maintained - SHB6639M - Claim Handler: Priya</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHB6639M (MCT19030832)  
[SHC2595B]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Mar 18 2019 1:00AM  
[COMFORT TRANSPORTATION PTE LTD]  
Chunni Motor Work Pte Ltd - Amk

Upload Documents			Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Video							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print			
1	25/09/19 17:22	Video - Accident		 Load MP4				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	27/04/19 13:05	Rear View Right		 Load JPG	<input checked="" type="checkbox"/>			
2	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
3	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
4	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
5	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
6	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
7	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
8	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
9	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
10	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
11	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
12	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
13	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
14	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
15	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
16	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
17	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
18	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
19	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
20	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
21	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
22	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
23	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
24	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
25	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
26	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
27	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
28	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
29	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
30	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
31	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
32	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
33	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
34	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
35	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
36	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
37	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
38	27/04/19 13:06	General View		 Load JPG	<input checked="" type="checkbox"/>			
39	27/04/19 13:06	Odometer Reading		 Load JPG	<input checked="" type="checkbox"/>			
40	27/04/19 13:06	Chassis Number		 Load JPG				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	27/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	27/04/19 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	27/04/19 13:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	27/04/19 13:07	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
92	27/04/19 13:07	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
93	27/04/19 13:07	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
94	27/04/19 13:07	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
95	27/04/19 13:07	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
96	27/04/19 13:07	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
97	27/04/19 13:07	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
98	27/04/19 13:07	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
99	27/04/19 13:07	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
100	27/04/19 13:07	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/03/19 16:36	EMAIL FROM III DD 19032019		Load PDF	
2	19/03/19 16:36	TP EST & GIA REPORT		Load PDF	
3	25/03/19 09:59	TP ESTIMATE- MARKED		Load PDF	
4	25/06/19 15:10	police investigation result		Load PDF	
5	23/09/19 12:51	RENTAL RECEIPT		Load PDF	
6	23/09/19 12:51	RENTAL MILEAGE		Load PDF	
7	23/09/19 12:51	LOD		Load PDF	
8	10/10/19 13:15	WORKSHOP INVOICE		Load PDF	
9	10/10/19 13:15	AUTHORISATION TO ACT FORM		Load PDF	
10	10/10/19 13:15	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	04/04/19 10:13	Singapore Accident Statement		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19004974/DGB3Q2

Date: 10/10/2019

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
**Claimant** SHB6639M **Insured Vehicle No :** SHC2595B  
**Vehicle No :** SHB6639M **Nature of Claim:** TP **Claim No:** MCT19030832  
**Date of Loss:** 18/03/2019

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB6639M**  
 Make & Model: HYUNDAI I40, 1.7 D (A) Engine No: D4FDEU416409  
 Reg. Date: 05/12/2013 (Man. Year: 2013) Chassis No: KMHLB41UMDU043106  
 Colour: Blue Odometer: 823951 km  
 Engine Capacity: 1685 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm  
 Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,666.00	8,816.00	2,850.00	24.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	2,220.00	2,510.00	53.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,396.00</b>	<b>11,036.00</b>	<b>5,360.00</b>	<b>32.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,800.00</b>		
(S\$)	16,396.00	8,800.00	7,596.00	46.33
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,147.72</b>	<b>616.00</b>	<b>531.72</b>	<b>46.33</b>
<b>Nett Amount (S\$)</b>	<b>17,543.72</b>	<b>9,416.00</b>	<b>8,127.72</b>	<b>46.33</b>
<b>+ Loss of Use (10.0 x S\$40.00/day) (S\$)</b>		<b>400.00</b>		
<b>+ Car Rental (10.0 x S\$110.67/day) (S\$)</b>		<b>1,106.70</b>		
<b>Nett Liability (S\$)</b>		<b>10,922.70</b>		

### INSPECTION

Date of Assignment: 19/03/2019  
 Date Inspected: 19/03/2019 Inspected At: Chunni Motor Work Pte Ltd - Amk (HQ)  
 Blk 10 #01-05/06, AMK Autopoint  
 Singapore 568047  
 Estimated Period of Repair: 8.0 days

---

**Adjuster:** BRYAN TANI**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB6639M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted / Cut	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*REAR FENDER (RH)	Dented	4,736.80 FL	*2,020.20 FL
4	1		*REAR FENDER INNER LINING (RH)	Not Necessary	169.30 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
6	1		*REAR DOOR (RH)	Bent	2,201.10 FL	*2,201.10 FL
7	1		*FRONT DOOR (RH)	Bent	2,256.40 FL	*2,256.40 FL
8	1		*REAR TYRE RIM (RH)	Not Necessary	325.30 FL	*- FL
9	1		*REAR WHEEL HUP-CAP (RH)	Distorted	107.10 FL	*107.10 FL
10	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
11	1		*REAR TRAILING ARM (RH)	Distorted	192.00 FL	*192.00 FL
12	1		*REAR ASSIST (RH)	Distorted	145.70 FL	*145.70 FL
13	1		*REAR SHOCK ABSORBER (RH)	Distorted	276.30 FL	*276.30 FL
14	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	81.30 FL	*- FL
15	1		*REAR CROSSMEMBER	Distorted	1,021.50 FL	*1,021.50 FL
16	1		*STABILIZER BAR	Distorted	199.60 FL	*199.60 FL
17	1		*STABILIZER LINK	Distorted	85.90 FL	*85.90 FL
18	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
19	1		*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
20	1		*REAR KNUCKLE ARM (RH)	Distorted	545.60 FL	*545.60 FL
21	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
23	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
24	1		*FRONT DOOR COLOURED COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
25	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,465.75</b>	<b>10,957.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,799.75</b>	<b>2,141.25</b>
<b>Total Parts (\$\$)</b>	<b>11,666.00</b>	<b>8,816.00</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,500.00	800.00
2	SPRAY PAINTING CHARGE	New	1,000.00	700.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	TRANSFER OF DOOR	New	240.00	120.00
10	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
11	REAR WHEEL ALIGNMENT	New	120.00	60.00
12	RE-SET REAR ABS SYSTEM }	New	200.00	150.00
13	RE-SET FRT & REAR POWER WINDOW SYSTEM }	New	400.00	0.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
Gross Labour Cost (S\$)			4,730.00	2,220.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;