


(LKK)

INDIA (CPL)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>distorted / cut</i>			\$ 553.00 ✓
	Rear Bumper Clip 10 pcs <i>Nuc</i>			\$ 22.00 ✓
	Rear Fender With Housing (RH) <i>Distorted</i>		2020-20	\$ 4,736.80 ✓
	Rear Fender Inner Lining (RH) <i>NH</i>			\$ 169.30 X
	Rear Windscreen Moulding <i>Nuc</i>			\$ 28.30 ✓
	Rear Door (RH) <i>reg</i>			\$ 2,201.10 X
	Front Door (RH) <i>reg</i>			\$ 2,256.40 X
	Rear Tyre Rim (RH) <i>NH</i>			\$ 325.30 X
	Rear Wheel Hup-Cap (RH) <i>2 distorted</i>			\$ 107.10 2 ✓
	Rear Wheelbearing ING & Hub <i>2 Down</i>			\$ 362.00 2 ✓
	Rear Trailing Arm (RH) <i>2 distorted</i>			\$ 192.00 2 ✓
	Rear Assist (RH) <i>2 distorted</i>			\$ 145.70 2 ✓
	Rear Shock Absorber (RH) <i>2 distorted</i>			\$ 276.30 2 ✓
	Rear Shock Absorber Mounting (RH) <i>NH</i>			\$ 81.30 X
	Rear Crossmember <i>2 distorted</i>			\$ 1,021.50 2 ✓
	Stabilizer Bar <i>2 distorted</i>			\$ 199.60 2 ✓
	Stabilizer Link <i>2 distorted</i>			\$ 85.90 2 ✓
	Rear Upper Arm (RH) <i>2 distorted</i>			\$ 335.75 2 ✓
	Rear Lower Arm (RH) <i>2 distorted</i>			\$ 353.80 2 ✓
	Rear Knuckle Arm (RH) <i>2 distorted</i>			\$ 545.60 2 ✓
	SUB TOTAL			\$ 13,998.75
	LESS 20%			\$ 2,799.75
	DISCOUNTED TOTAL			\$ 11,199.00
	Rear Bumper Rubber Mat <i>Nuc</i>			\$ 50.00 Nett ✓
	Rear Windscreen Scalant <i>Nuc</i>			\$ 46.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>Nuc</i>			\$ 80.00 Nett ✓
	Front Door Coloured Comfort Logo (RH) <i>Nuc</i>			\$ 75.00 Nett ✓
	Rear Tyre (RH) <i>NH</i>			\$ 216.00 Nett X
				\$ 467.00

SHB 6639M

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 800/-
	Spray Painting Charge			\$ 1,000.00 700/-
	Wiring Charge			\$ 50.00 24
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 24
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 } 150/-
	TOTAL LABOUR			\$ 4,730.00
	ESTIMATE TOTAL			\$ 16,396.00
	19/03/2019 c 0930ms W/LA Author 1/Sm 6 dgs.  Yau LKK Auto 			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				