

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 19 May 2020

Preliminary Advice

Insured Vehicle No	: SLH339P		
TP Vehicle No	: SJF8865T	Accident Date	: 08/03/2019
Make	: TOYOTA VIOS	Assignment Date	: 19/03/2019
Date of Inspection	: 19/03/2019	Est. Duration of Repair	: 4 days
Inspection At	: Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,568.70
Revised Amount	:S\$	2,249.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,249.10
Lump Sum Repair	:S\$	1,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.