

ASS. REC. BY:

REF: CS/CTI/19004984/AVd3nz

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Chong Bron Snof CTIDate/Time: 19.3.19 4.14p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 8098UInsured: SJC 9161 Aat Workshop m/s: Tick Hai Motor & Welding Services

Tel:

of Block 1 Kaki Bukit Avenue 6, #01-54Policy No: DMPCSN30940918011Claim No: SNM19D>01115C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11.3.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 19.3.19 5.21p.mPerson Contacted: ConnieVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGL 8098U - N/A / CTI 19004399/4	D.O.A - 11/3/2019
	SJC 9161A - N/A / CTI 19004399/4	D.O.A - 11/3/2019
18/6/19	Adrian confirmed LS \$2100 (Recd 5070.47, 7019)	

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGL8098U Yr Regn: 2014, JulyType: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Volvo S60 C.C. 1969Colour: Beige A/C: ☐ Insured / ☐ Std / ☐ Nil / ☐ NASp. Reading: 1009.9 T/Radio: ☐ Insured / ☐ Std / ☐ Nil / ☐ NA

Eng/No: _____

C/No: YVIFS40CDE2316092Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ STD A/Rim orTyre Size: F: 235/45R17R: 235/45R17BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 20/03/19Survey held at Tick HaiDes. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 18 JUN 2019

MV: 70K.

PV: 50.9K

Nett: 19.1K.

Date/Time, File Pass to?

Date/Time, File Return to?

1) 18/6 - typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2019		25 Mar 2019 09:27 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	BHAKTI ASHOK PATEL, ID: S2631191H		
Vehicle Reg. No.:	SGL8098U	Date of Loss:	11/03/2019 10:00 - :59
Claim Type:	TP / SNM19D201115C02	Policy/Cover Note No.:	DMPCSN30940918011
Vehicle Reg. No. (Insured):	SJC9161A	Policy No. (Claimant):	5091813816-01
		Excess:	S\$0.00
Repairer:	Tick Hai Motor & Welding Services - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 6747 4676, 68429089		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Eddie Sim]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/04/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 19 March 2019 4:14 PM
To: Aridas @ Associates
Cc: assignments
Subject: RE: AA.21535.19.159/SGL 8098U
Attachments: 19032019152914.pdf

Without prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Aridas @ Associates [mailto:aridasv@singnet.com.sg]
Sent: Tuesday, 19 March, 2019 3:51 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: AA.21535.19.159/SGL 8098U

Hi Boon Sen,

Our client has selected Adrian Ling.
Thanks.

Regards,
Marina

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 19 March 2019 3:39 PM
To: Aridas @ Associates <aridasv@singnet.com.sg>
Subject: RE: AA.21535.19.159/SGL 8098U

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Aridas @ Associates [<mailto:aridasv@singnet.com.sg>]

Sent: Tuesday, 19 March, 2019 3:33 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: AA.21535.19.159/SGL 8098U

Dear Sir,

Please see attach.

Regards,

Marina

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D

NOTARY PUBLIC

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #03-13, BOON SIEW BUILDING, SINGAPORE 229833
TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713
E-mail : aridasv @ singnet.com.sg

VYTINGAM ARIDAS

LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)

Service of Court Documents
By Fax
Is Not Acceptable

Our Ref : AA.21535.19.159
Your Ref : Please advise

18 MARCH 2019

CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLES SJL 8098U AND SJC 9161A AT
BLOCK 86 REDHILL CLOSE ON 11 MARCH 2019 AT 10:30.**

We are instructed by **BHAKTI ASHOK PATEL** to notify you of a road traffic accident on 11/3/2019 at 10:30 involving our client's vehicle registration number **SJL 8098U** and vehicle registration number **SJC 9161A** driven by your insured at the material time.

Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Our client's motor vehicle **SJL 8098U** can be inspected at

Please contact Ms Connie at office number: **68429089**

M/s Tick Hai Motor & Welding Services,
Block 1 Kaki Bukit Avenue 6,
#01-54 Auto @ Kaki Bukit, Singapore 417883.

Yours faithfully,
ARIDAS & ASSOCIATES

T. 5.21 p.m

P: Connie

V: Out

E-V



Volvo S60 T4 | \$47,500 | \$10,100 /yr | 28-Feb-2012 | 1,596 cc | 85,000 km | Luxury | Available

No Repair Needed, Perfect Engine Condition, Clean And Pristine Interior, Low Mileage Done At 85,000km, Price Negotiable, View The Car At Our Showroom.

Motor Universe Credit Pte Ltd

★ Posted: 28-Feb-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 T4 | \$57,800 | \$11,570 /yr | 31-Oct-2012 | 1,596 cc | 105,000 km | Luxury | Available

No Repair Needed, Perfect Engine Condition, Clean And Pristine Interior, Price Negotiable, View The Car At Our Showroom.

Motor Universe Credit Pte Ltd

★ Posted: 14-Mar-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 T4 | \$54,800 | \$10,410 /yr | 12-Dec-2012 | 1,596 cc | 102,000 km | Luxury | Available

3 Months Warranty From Our In House Workshop, High COE, Selling Close To Export Value. Owned By Careful Owner, Regular Servicing And Maintenance, Good Condition, Accident Free. New Engine Mounting And...

★ Posted: 16-Mar-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



Volvo S60 T4 | \$76,800 | \$11,860 /yr | 30-Apr-2014 | 1,596 cc | 95,000 km | Luxury | Available

Latest Stock! Exclusive 1 Year Warranty With 1 Year Free Servicing. Elegant Silver On Black, Comfortable, Supportive And Ergonomic Seats That Have Been A Hallmark Of Volvo Sedans In Recent Years. Full...

★ Posted: 21-Jan-2019 Tags: 2014 Volvo S60, 2014 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 Diesel D2 | \$61,000 | \$9,580 /yr | 27-Jun-2014 | 1,560 cc | 63,000 km | Luxury | Available

Fuel Type: Diesel (Euro 5 Engine and Above)

1 Owner. Interior Like New. 100% Accident Free. Sheltered Parking, Very Well Maintained. Immediate Delivery. Trade In And Loan Can Be Arranged. Selling With Bidder Car No Plate. Call Now To Test Drive...

DIRECT OWNER

★ Posted: 12-Mar-2019 Tags: 2014 Volvo S60, 2014 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 Diesel D2 | \$62,800 | \$9,220 /yr | 16-Jan-2015 | 1,560 cc | 78,000 km | Luxury | Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Asking Low! Nicely Kept By 1 Owner With Average Mileage Done, 100% Accident Free. High Paper Value At \$52K. Unit Which Not To Be Missed! Please Call For Appointment Viewing.

★ Posted: 21-Mar-2019 Tags: 2015 Volvo S60, 2015 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 Diesel D2 | \$69,800 | \$10,290 /yr | 11-Feb-2015 | 1,560 cc | 51,000 km | Luxury | Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Attractive Promotional Interest Rates Starts From 2.28%!(Low Interest And Monthly Installments! 100% Approval! Well Maintained And Agent Serviced! Pristine Condition! STA/VICOM Evaluation Are Most Welc...

PREMIUM AG

★ Posted: 17-Mar-2019 Tags: 2015 Volvo S60, 2015 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 Diesel D2 | \$68,000 | \$9,980 /yr | 13-Feb-2015 | 1,560 cc | 104,000 km | Luxury | Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Agent Car. Still Has 1 Paid Unused Service Package With Agent. Owner Selling Car To Move Overseas.

DIRECT OWNER

★ Posted: 28-Feb-2019 Tags: 2015 Volvo S60, 2015 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 T5 | \$79,800 | \$11,560 /yr | 16-Mar-2015 | 1,969 cc | 47,000 km | Luxury | Available

(Flexible Loan) 1 Owner Only! Fully Maintained By Volvo Agent, New Road Tax! Immaculate Condition, 100% Accident Free!

Oscars Auto

★ Posted: 16-Mar-2019 Tags: 2015 Volvo S60, 2015 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 Diesel D2 | \$85,000 | \$12,500 /yr | 16-Apr-2015 | 1,560 cc | 11,050 km | Luxury | Available

Fuel Type: Diesel (Euro 5 Engine and Above)

No Dealers/Consignment Agents. Genuine Mileage Shown. Well Maintained Interior/Exterior. Hurry, Call Me Now For More Info.

DIRECT OWNER

★ Posted: 02-Mar-2019 Tags: 2015 Volvo S60, 2015 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



Volvo S60 Diesel D2 | \$69,800 | \$9,680 /yr | 11-May-2015 | 1,560 cc | 55,000 km | Luxury | Available

Graded B by **STA**

Fuel Type: Diesel (Euro 5 Engine and Above)

Done 55000KM Only, 1 Owner, Keyless Entry Push Start, Well Maintained And Agent Serviced! Responsive Yet Economical 1.6L Diesel Engine With High Torque. Call Now For Viewing.

PREMIUM AG

★ Posted: 16-Mar-2019 Tags: 2015 Volvo S60, 2015 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo



SHORTLISTED HISTORY

Universe Motoring

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	1191H
Vehicle Details	
Vehicle No.:	SGL8098U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	VOLVO
Vehicle Model:	S60 T5 A/T ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	B4204T111046632
Chassis No.:	YV1FS40CDE2316092
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$27,844.00
Original Registration Date:	31 Jul 2014
First Registration Date:	31 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$20,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2024
PARF Rebate Amount:	\$15,736.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,700.00
COE Rebate Amount:	\$35,198.00
Total Rebate Amount:	\$50,934.00

The information contained herein is correct as at 21 Mar 2019

OK

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

Vehicle Number: SGL8098U
 Vehicle Model : Volvo S60
 Manufacturing Year : 2014
 Chassis : YV1FS40CDE2316092

*TP Chim
Veron*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	Item Description	Amount (\$)
1	Rear Bumper (Top) <i>Deland.</i>	\$ 1,528.71
2	Rear Bumper (Lower) <i>Deland.</i>	\$ 520.45
3	Rear Bumper Lower Centre Black Portion <i>new</i>	\$ 190.57
4	Rear Bumper Reinforcement <i>new</i>	\$ 1,366.60
5	Rear Bumper Clip x 8 pcs <i>new</i>	\$ 72.76
6	Reverse Sensor Wire	\$ 115.56
7	Exhaust Chrome Tip (LH) <i>new</i>	\$ 271.03
8	Exhaust Chrome Tip Retainer (LH) <i>new</i>	\$ 58.10
9	Taillamp Lower Bracket (LH)	\$ 414.52
Total :		\$ 4,538.30
Less 10% :		\$ 453.83
Amount :		\$ 4,084.47

*2049.16
1844.24*

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs <i>1 piece damaged</i>	\$ 416.00
Amount :		\$ 416.00

*208
208*

Labour	Amount (\$)
To check rear electrical wiring system include resetting of all electrical modules	\$ 450.00
To remove & reinstall reverse sensors	\$ 120.00
Labour to remove, cut, change & panel beating	\$ 1,200.00
To putty and respray affected areas	\$ 900.00
Labour Total :	\$ 2,670.00
Total (Parts & Labour)	\$ 7,170.47

560

*total: 2612.24
4/5: 2.1K.
030m.*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19004984/AVD3N2

Date: 25/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30940918011	
Claimant Vehicle No :	SGL8098U	Insured Vehicle No :	SJC9161A	
Date of Loss:	11/03/2019	Nature of Claim:	TP	Claim No: SNM19D201115C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL8098U	Engine No:	B4204T111046632
Make & Model:	VOLVO S60, 2.0 (A)	Chassis No:	YV1FS40CDE2316092
Reg. Date:	31/07/2014 (Man. Year: 2014)	Odometer:	100919 km
Colour:	Beige		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45R17	Rear Tyre Size:	235/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,500.47	2,097.24	2,403.23	53.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	560.00	2,110.00	79.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,170.47	2,657.24	4,513.23	62.94
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	7,170.47	2,100.00	5,070.47	70.71
+ GST 7.00/7.00% (S\$)	501.93	147.00	354.93	70.71
Nett Amount (S\$)	7,672.40	2,247.00	5,425.40	70.71

INSPECTION

Date of Assignment: 25/03/2019

Date Inspected: 20/03/2019 Inspected At:

Tick Hai Motor & Welding Services -
Kaki Bukit (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-54
AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2019)
Parts:	143	VOLVO S60 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL8098U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (TOP)	Deformed	1,528.71 FL	*1,528.71 FL
2	1		*REAR BUMPER (LOWER)	Deformed	520.45 FL	*520.45 FL
3	1		*REAR BUMPER LOWER CENTRE BLACK PORTION	Not Necessary	190.57 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,366.60 FL	*- FL
5	8		*REAR BUMPER CLIP	Necessary	72.76 FL	*50.00 FL
6	1		*REVERSE SENSOR WIRE	Not Necessary	115.56 FL	*- FL
7	1		*EXHAUST CHROME TIP (LH)	Not Necessary	271.03 FL	*- FL
8	1		*EXHAUST CHROME TIP RETAINER (LH)	Not Necessary	58.10 FL	*- FL
9	1		*TAILLAMP LOWER BRACKET (LH)	Not Necessary	414.52 FL	*- FL
10	1		*REVERSE SENSOR (2 Pcs)	Damaged (1 Pc only)	416.00 FS	*208.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,954.30	2,307.16
- List Item Discount on L Items 10.00/10.00% (\$\$)	453.83	209.92
Total Parts (\$\$)	4,500.47	2,097.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING SYSTEM INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	0.00
2	TO REMOVE & REINSTALL REVERSE SENSORS	New	120.00	60.00
3	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING	New	1,200.00	250.00
4	TO PUTTY AND RESPRAY AFFECTED AREAS	New	900.00	250.00
Gross Labour Cost (S\$)			2,670.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >