

ASS. PRG. BY

Surveys

RPT

CS3/LPC 19001775/121+d3-1

Ed Instruction

ASSIGNMENT (Office)

From (Person)

Ung Li Li

at

LPC

Date/Time

15/03/2019

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SKM 3800

Insured

SKM 8738C

at Workshop m/s

Eng Shing

Tel

6453 7380

of

160 Sin Ming Ave #06-21

98482189

Policy No

Claim No

18/19/19 / VP05/021370.

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

26/01/2019

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time

28/01/2019 11:41am

Person Contacted

H.O.D. Endorsement

Vehicle

IN/OUT

Date/Time

Action/Instruction ( X ) Estimate

SKM 3800 - X

SKM 8738C - (TE/ALH/4016761 / Ah2a3w2

DA: 31032014

Submit PRS Report

Rasul,

pls check parts prices & see my remarks.

days of repair 1  
lump sum \$7100-  
(Red: 4050; 36%)

parts price

check

OK

  
5/4/2019

814 - File pass to typist.

RECEIVED 0 8 APR 2019

*PR5*

*PR5*

28/6/2012  
2012

Insured / Policy No.  
Insured / TP / WS / TP RES / OD RES / EVA / INV / MV

Insured / Vehicle No. **SKM 3800**  
Insured / Make **GEN SHING**  
Insured / Model **160, SM MINOR OR Hob-21**  
Insured / Year **LPC**

Insured / Make of Vch

Insured / Make of Vch

Insured / Make of Vch

Insured / Make of Vch

Insured / Make of Vch

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Insured / Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Secn Consistent? : Yes or No

Est. Repairs: 7 days Res. Yes or No

Lum. Com. % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Insured / Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

Insured / Make **SKM 3800**  
Insured / Type **C** / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Insured / Truck / Trailer or

Insured / Make **B.N.W X3** Year **1997**

Insured / Colour **GOO** A/C Insured / Std / NI / NA

Insured / Sp Reading **70164** T/Radio Insured / Std / NI / NA

Insured / Eng/No

Insured / C/No **W3AWX520000 B25388**

Insured / Gen. Cond: Good / Fair / Poor / Burnt

Insured / Steering: J/under / Jammed / Leaked / Burnt or

Insured / Brake: J/under / Jammed / Leaked / Burnt or

Insured / Mod: Nil / S/Rim / STD A/Rim or

Insured / Tyre Size F: **245/45R18**  
R:

Insured / BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

Insured / TOYO / YOKO or

Insured / Front

Insured / R/Bal **6** mm R/Bal **6** mm

Insured / L/Bal **6** mm L/Bal **6** mm

Insured / D.O.A. **26/01/19** D.O.I. **28/01/19 2:06pm**

Insured / Survey held at **GEN SHING**

Insured / Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Insured / **Rear A/S**

Insured / The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 04 MAR 2013

Copy Date / File Pass No.

**1/3 Typst**

Copy Date / File Return to

☐ Preli. Report  
☒ Final Report

Days Of Repair: **7**

Resurvey No. of Trip: **7**

Report Format: **PR5-IP**

Lump Sum / TR Fee

Add Fee: ☐ Site Insp. (\$)  
☐ Interview (\$)  
☐ Tech. Insp. (\$)  
☐ Other (\$)

Survey Fee:  
Transportation

Y 2 x P 3

Price

Price

Price

Price

450

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Friday, 15 March 2019 11:05 AM  
**To:** Admin-D (LKKAuto); SUR  
**Cc:** MT\_Claim\_SG; assignments  
**Subject:** RE: Our Ref: SB/PO/Acc/2019-8908 Your Ref: 18/19/19/VP05/021370 Insurer of SKN 8728C [External General]  
**Attachments:** 21370 TP SURVEY REPORT.pdf

### Lonpac External - General

Dear Nivitha


Attached is the TP survey report.

Please let us have your surveyor's review/report.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

---

**From:** ONG LI LI  
**Sent:** Tuesday, 29 January, 2019 2:48 PM  
**To:** 'Admin-D (LKKAuto)'; SUR  
**Cc:** MT\_Claim\_SG; assignments  
**Subject:** RE: Our Ref: SB/PO/Acc/2019-8908 Your Ref: 18/19/19/VP05/021370 Insurer of SKN 8728C


Dear Catherine

Please see our claim ref. above and attached for our Insured's GIA report.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Monday, 28 January, 2019 1:05 PM  
**To:** ONG LI LI; SUR  
**Cc:** MT\_Claim\_SG; assignments  
**Subject:** RE: Our Ref: SB/PO/Acc/2019-8908 Your Ref: TBA Insurer of SKN 8728C

Dear Li Li,

Thank you for the assignment.

Kindly assist provide us the claim number.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI [<mailto:llong@lonpac.com>]

**Sent:** Monday, 28 January, 2019 11:41 AM

**To:** Oracle Law Corp <[mail@oraclelaw.sg](mailto:mail@oraclelaw.sg)>; [assignments@lkkauto.com](mailto:assignments@lkkauto.com); 'Admin-D (LKKAuto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** RE: Our Ref: SB/PO/Acc/2019-8908 Your Ref: TBA Insurer of SKN 8728C

Without Prejudice

Dear Catherine/Nivitha

fya


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



---

**From:** Oracle Law Corp [<mailto:mail@oraclelaw.sg>]

**Sent:** Monday, 28 January, 2019 11:39 AM

**To:** ONG LI LI

**Subject:** RE: Our Ref: SB/PO/Acc/2019-8908 Your Ref: TBA Insurer of SKN 8728C

Dear Li Li,

Workshop details already stated in our PRI Letter as:

Eng Shing Mechanical Works

160 Sin Ming Drive

#06-21 Sin Ming Autocity S(575722)

Tel No.: 6453-7380 ; Fax No. 6252-4129

Regards

Alvin Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11

The Alexcier, Singapore 159929

Telephone: 6538 6250 Facsimile: 6538 1860



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0418 Fax: 6266-7396  
Email: absolute.app.svcs@gmail.com

### Vehicle Inspection Report

To: Ho Jenny (He Qianying)  
191 Meyer Road #12-02  
Singapore 437980

Date of report: 20.02.2019  
Date of request: 28.01.2019  
Date of inspection: 28.01.2019  
Date of accident: 26.01.2019  
Claim type: Third Party Claim

Report No: AAS/2019/038

#### Particulars of affected vehicle:

Registration no: SKM380D  
Make/Model: BMW X3 (A)  
Year of registration: 2012  
Colour: Metallic Champagne

Odometer: 70164 km  
Engine Capacity: 1997 cc  
Engine no: B1640185N20B20A  
Chassis no: WBAWX320000B25388

#### Condition of tires:

Front Left: 6mm  
Make: Pirelli  
Rear Left: 6mm  
Make: Pirelli

Front Right: 6mm  
Make: Pirelli  
Rear Right: 6mm  
Make: Pirelli

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

#### Pre-accident condition (Static tests only)

|                              |            |
|------------------------------|------------|
| General Bodywork             | : Good     |
| Paintwork                    | : Good     |
| Handbrake                    | : In order |
| Footbrake                    | : In order |
| Steering                     | : In order |
| Apparent engine modification | : Nil      |

#### The Assignment

The inspection was conduct at M/s. Eng Shing Mechanical Works  
160 Sin Ming Drive #06-21  
Sin Ming Auto City (S) 575722

(Subsequent inspection was conducted)

#### Assessment

|                      |                         |
|----------------------|-------------------------|
| Repairer's estimate: | \$ 17,418.40            |
| Revised estimate:    | \$ 13,939.35            |
| Recommended reserve: | \$ 11,150.00 (Lump sum) |

Estimated normal duration of repairs : 5 Working days



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0413 Fax: 6266-7396  
Email: absolute.app.svcs@gmail.com

Vehicle No: SKM380D

Report No: AAS/2019/038

**W/O PREJUDICE**

**Point of impact**

At the rear portion.

**General description of damages**

The truck lid, LH tail lamp, rear bumper, tail end panel, exhaust muffler, etc.

Other parts were also found damaged. (See schedule for details)

**Recommendation**

The estimate cost of repair submitted by M/s Eng Shing Mechanical Works as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$13,939.35

**Conclusion**

The repairer has agreed to undertake the repair at a lumpsum of SGD \$11,150.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 8 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 83 photographs.

Your Faithfully  
Absolute Appraisal Services Pte Ltd



Nicky Seah  
Automobile Appraiser  
MSAAA / MSMCTA



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
 Mobile: 9688-0413 Fax: 6266-7396  
 Email: absolute.app.svcs@gmail.com

Vehicle No: SKM380D  
 Appraisal Schedule

Report No: AAS/2019/038

| S/N                 | Parts Description                 | Qty | Condition         |           | Repairer's Est | Revised Est                 |
|---------------------|-----------------------------------|-----|-------------------|-----------|----------------|-----------------------------|
| 1                   | Rear bumper                       | 1   | Dented            |           | \$ 1,518.15    | \$ 1,518.15 <sup>1409</sup> |
| 2                   | Rear bumper trim                  | 1   | Dented            |           | \$ 490.60      | \$ 490.60 <sup>102</sup>    |
| 3                   | Rear bumper tow hook cover        | 1   | Dented            |           | \$ 30.75       | \$ 30.75                    |
| 4                   | Rear bumper reflector LH          | 1   | Cracked           |           | \$ 49.95       | \$ 49.95                    |
| 5                   | Rear bumper side mount LH/RH      | 2   | LH Cracked        | \$ 126.55 | \$ 253.10      | \$ 126.55                   |
| 6                   | Rear bumper undercover            | 1   | Cracked           |           | \$ 69.50       | \$ 69.50                    |
| 7                   | Rear bumper centre mount LH/RH    | 2   | Cracked           | \$ 180.40 | \$ 360.80      | \$ 360.80 <sup>180.40</sup> |
| 8                   | Rear bumper PDC sensor            | 4   | 2pc Malfunctioned | \$ 220.70 | \$ 882.80      | \$ 441.40                   |
| 9                   | Rear bumper PDC sensor decoupling | 4   | Necessary         | \$ 5.10   | \$ 20.40       | \$ 20.40                    |
| 10                  | Rear bumper carrier               | 1   | Dented            |           | \$ 684.50      | \$ 684.50                   |
| 11                  | Tail lamp LH/RH                   | 2   | LH Cracked        | \$ 760.40 | \$ 1,520.80    | \$ 760.40 <sup>525</sup>    |
| 12                  | Truck lid                         | 1   | Dented            |           | \$ 2,578.10    | \$ 2,578.10 <sup>1763</sup> |
| 13                  | Truck lid emblem                  | 1   | Necessary         | 7391.65   | \$ 67.45       | \$ 67.45                    |
| 14                  | Truck lid nameplate 'X3'          | 1   | Necessary         |           | \$ 69.90       | \$ 69.90                    |
| 15                  | Truck lid top lock                | 1   | Serviceable       | 56        | \$ 284.40      | -                           |
| 16                  | Truck lid seal                    | 1   | Necessary         |           | \$ 185.70      | \$ 185.70                   |
| 17                  | Truck lid inner trim              | 1   | Serviceable       | 7022.06   | \$ 555.40      | -                           |
| 18                  | Tail end outer panel              | 1   | Dented            |           | \$ 750.15      | \$ 750.15 <sup>XRD</sup>    |
| 19                  | Exhaust muffler                   | 1   | Dented            |           | \$ 2,643.90    | \$ 2,643.90 <sup>1485</sup> |
| 20                  | Exhaust heat shield               | 1   | Dented            |           | \$ 155.70      | \$ 155.70                   |
| 21                  | Exhaust hanger                    | 3   | 1pc Torn          | \$ 25.45  | \$ 76.35       | \$ 25.45                    |
| List Total:         |                                   |     |                   |           | \$ 13,248.40   | \$ 11,029.35                |
| 1                   | Truck lid glass seal              | 1   | Necessary         |           | \$ 50.00       | \$ 20.00                    |
| 2                   | Truck lid glass sealant           | 1   | Necessary         |           | \$ 60.00       | \$ 40.00                    |
| 3                   | Joint sealant                     | 1   | Necessary         |           | \$ 60.00       | \$ 40.00                    |
| Special nett total: |                                   |     |                   |           | \$ 170.00      | \$ 100.00                   |
| Parts Total:        |                                   |     |                   |           | \$ 13,418.40   | \$ 11,129.35                |





**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0413 Fax: 6266-7396  
Email: absolute.app.svcs@gmail.com

Vehicle No: SKM380D

Report No: AAS/2019/038

S/N Labour Description

Repairer's Est

Revised Est

1 Check rear lightings & wirings for proper function.

\$ 50.00

\$ 30.00

2 Remove & transfer tailgate components.

\$ 150.00

\$ 120.00 <sup>60</sup>

3 Remove & transfer tailgate glass.

\$ 220.00

\$ 180.00 <sup>120</sup>

4 Renew & transfer reverse sensors.

\$ 60.00

\$ 40.00

5 Anti rust proofing on rear damaged panels.

\$ 100.00

\$ 60.00

6 Replace exhaust muffler.

\$ 100.00

\$ 80.00

7 Remove & reinstall rear upholstery to assist repairs.

\$ 120.00

\$ 100.00 <sup>60</sup>

8 To replace rear damaged parts. Repair, reform, realign all damaged area.

\$ 1,600.00

\$ 1,000.00 <sup>600</sup>

9 To conduct spray painting on rear replacement & affected area.

\$ 1,600.00

\$ 1,200.00 <sup>750</sup>

Labour Total:

\$ 4,000.00

\$ 2,810.00

Grand Total:

\$ 17,418.40

\$ 13,939.35

The final adjusted lump sum amount is \$11,150.00

Under normal circumstances, the repair should be completed within a reasonable period of 8 working days.

83 Photographs were taken at the time of inspection.

7,022.06

100.00

1,800.00

8,922.06

20%

7,137.64

4/3 7,100.00

7 days

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                            |                                 |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------|---------------------------------|-------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                   |                            | Ref : CS3/LPC19001775/R1td3n2-1 |                                                                                     |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                            | Date : 09-04-2019               |  |  |
|                                                                                                                                        |                            | Code : LPC2                     |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>                                                                |                            |                                 |                                                                                     |  |
| Insured Veh.                                                                                                                           | SKN 8728C                  | Veh. Inspected                  | SKM 380D                                                                            |  |
| Policy No.                                                                                                                             | Z18VP05018828              | Coverage (\$)                   | 0.00                                                                                |  |
| Claim No.                                                                                                                              | 18/19/19/VP05/021370       | Excess (\$)                     | 0.00                                                                                |  |
| Assign From                                                                                                                            | ONG LI LI                  | Assign Date                     | 15/03/2019                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                            |                                 |                                                                                     |  |
| Make & Model                                                                                                                           | BMW X3                     | c.c                             | 1997                                                                                |  |
| Engine No.                                                                                                                             | HIDDEN                     | Year of Reg.                    | 2012                                                                                |  |
| Chassis No.                                                                                                                            | WBAWX320000B25388          | Colour                          | GOLD                                                                                |  |
| Odometer                                                                                                                               | 70164                      | Steering                        | IN ORDER                                                                            |  |
| Brakes                                                                                                                                 | IN ORDER                   | Modification                    | SPORTS RIM                                                                          |  |
| General                                                                                                                                | FAIR                       |                                 |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                            |                                 |                                                                                     |  |
|                                                                                                                                        | Size                       | Make                            | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                         | 245/45 R18                 | PIRELLI                         | 6 mm                                                                                |  |
| L/H Front Tyre                                                                                                                         | 245/45 R18                 | PIRELLI                         | 6 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                          | 245/45 R18                 | PIRELLI                         | 6 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                          | 245/45 R18                 | PIRELLI                         | 6 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                       |                            |                                 |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS.                                                         |                            |                                 |                                                                                     |  |
| <b>5. General Information</b>                                                                                                          |                            |                                 |                                                                                     |  |
| Accident Date                                                                                                                          | 26/01/2019                 | Inspection Date                 | 28/01/2019                                                                          |  |
| Survey held at                                                                                                                         | 160 SIN MING DRIVE# 06-21  |                                 |                                                                                     |  |
| Repairer                                                                                                                               | ENG SHING MECHANICAL WORKS |                                 |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                     |                            |                                 |                                                                                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                            |                                 |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                            |                                 |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                            | 7 Working Days                  |                                                                                     |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 380D

| Qty                         | Description of Parts                      | Condition                  | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------------|----------------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                           |                            |                           |                   |
| 1                           | REAR BUMPER                               | DENTED                     | 1,518.15                  | 1,409.00          |
| 1                           | REAR BUMPER TRIM                          | DENTED                     | 490.60                    | 102.00            |
| 1                           | REAR BUMPER TOW HOOK COVER                | DENTED                     | 30.75                     | 30.75             |
| 1                           | REAR BUMPER REFLECTOR LH                  | CRACKED                    | 49.95                     | 49.95             |
| 2                           | REAR BUMPER SIDE MOUNT LH/RH @\$126.55    | N/S CRACKED                | 253.10                    | 126.55            |
| 1                           | REAR BUMPER UNDERCOVER                    | CRACKED                    | 69.50                     | 69.50             |
| 2                           | REAR BUMPER CENTRE MOUNT LH/RH @\$180.40  | N/S CRACKED                | 360.80                    | 180.40            |
| 4                           | REAR BUMPER PDC SENSOR @\$220.70          | MALFUNCTIONED (2 PCS ONLY) | 882.80                    | 441.40            |
| 4                           | REAR BUMPER PDC SENSOR DECOUPLING @\$5.10 | NECESSARY                  | 20.40                     | 20.40             |
| 1                           | REAR BUMPER CARRIER                       | DENTED                     | 684.50                    | 684.50            |
| 2                           | TAIL LAMP LH/RH @\$760.40                 | N/S CRACKED                | 1,520.80                  | 525.00            |
| 1                           | TRUCK LID                                 | DENTED                     | 2,578.10                  | 1,763.00          |
| 1                           | TRUCK LID EMBLEM                          | NECESSARY                  | 67.45                     | 67.45             |
| 1                           | TRUCK LID NAMEPLATE "X3"                  | NECESSARY                  | 69.90                     | 69.90             |
| 1                           | TRUCK LID TOP LOCK                        | SERVICEABLE                | 284.40                    | -                 |
| 1                           | TRUCK LID SEAL                            | NECESSARY                  | 185.70                    | 185.70            |
| 1                           | TRUCK LID INNER TRIM                      | SERVICEABLE                | 555.40                    | -                 |
| 1                           | TAIL END OUTER PANEL                      | TO REPAIR SEE LABOUR       | 750.15                    | -                 |
| 1                           | EXHAUST MUFFLER                           | DENTED                     | 2,643.90                  | 1,485.00          |
| 1                           | EXHAUST HEAT SHIELD                       | DENTED                     | 155.70                    | 155.70            |
| 3                           | EXHAUST HANGER @\$25.45                   | TORN (1 PC ONLY)           | 76.35                     | 25.45             |
|                             | LESS 5% DISCOUNT                          |                            | -                         | -369.58           |
|                             |                                           |                            | 13,248.40                 | 7,022.07          |
| <b>SPECIAL NETT ITEMS</b>   |                                           |                            |                           |                   |
| 1                           | TRUCK LID GLASS SEAL (SN)                 | NECESSARY                  | 50.00                     | 20.00             |
| 1                           | TRUCK LID GLASS SEALANT (SN)              | NECESSARY                  | 60.00                     | 40.00             |
| 1                           | JOINT SEALANT (SN)                        | NECESSARY                  | 60.00                     | 40.00             |
|                             |                                           |                            | 170.00                    | 100.00            |

Report Ref No. CS3/LPC19001775/R1td3n2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                                                                  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|     | <b>LABOUR</b>                                                                                                         |           |                           |                   |
|     | CHECK REAR LIGHTINGS & WIRINGS FOR PROPER FUNCTION.                                                                   |           | 50.00                     | 30.00             |
|     | REMOVE & TRANSFER TAILGATE COMPONENTS.                                                                                |           | 150.00                    | 60.00             |
|     | REMOVE & TRANSFER TAILGATE GLASS.                                                                                     |           | 220.00                    | 120.00            |
|     | RENEW & TRANSFER REVERSE SENSORS.                                                                                     |           | 60.00                     | 40.00             |
|     | ANTI RUST PROOFING ON REAR DAMAGED PANELS.                                                                            |           | 100.00                    | 60.00             |
|     | REPLACE EXHAUST MUFFLER.                                                                                              |           | 100.00                    | 80.00             |
|     | REMOVE & REINSTALL REAR UPHOLSTERY TO ASSIST REPAIRS.                                                                 |           | 120.00                    | 60.00             |
|     | TO REPLACE REAR DAMAGED PARTS,REPAIR,REFORM,REALIGN ALL DAMAGED AREA.INCLUSIVE OF THE REPAIR OF TAIL END OUTER PANEL. |           | 1,600.00                  | 600.00            |
|     | TO CONDUCT SPRAY PAINTING ON REAR REPLACEMENT & AFFECTED AREA.                                                        |           | 1,600.00                  | 750.00            |
|     |                                                                                                                       |           | 4,000.00                  | 1,800.00          |
|     | <b>GRAND TOTAL</b>                                                                                                    |           | <b>17,418.40</b>          | <b>8,922.07</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>                                           |           |                           | <b>7,100.00</b>   |

Report Ref No. CS3/LPC19001775/R1td3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.