



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

SIGNMECHANIC PTE LTD

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

06/07/2018

TP China.

Khnachan.

Accident date: 05/07/2018

Estimated repair cost for vehicle no: GBB9805B NISSAN CABSTAR '10

CHASSIS: JN1SC2F24Z0801641

S/n	Qty	Items / Nett	U/price	Amount
1	1	Rear Tailgate <i>Dented</i>		\$1,399.70 ✓
2	2	Rear Tailgate Top Side Handle <i>for u</i>	\$185.10	\$370.20 +
3	2	Rear Tailgate Lower Side Lock	\$48.20	\$96.40 +
4	3	Rear Tailgate Lower Hinges <i>Best 1 piece</i>	\$147.30	\$441.90 (1730)
5	2	Rear Tailgate Lower Side Bracket <i>LH Best</i>	\$125.50	\$251.00 125.50
6	2	Rear Tailgate Lower Side Bracket Stopper Rubber <i>LH Best</i>	\$22.10	\$44.20 22.10
7	1	Rear Tailgate Lower Member <i>Dented</i>		\$418.80 ✓
8	1	Rear Tailgate Lower Nissan Cabstar Sticker <i>ra</i>		\$55.00 ✓
9	2	Rear Tail Lamp <i>Cracked</i>	\$248.60	\$497.20 ✓
10	2	Rear Tail Lamp Bracket <i>Best</i>	\$111.20	\$222.40 ✓
11	1	Rear Number Plate Lamp <i>new</i>		\$67.50 +
12	1	Rear Number Plate Bracket <i>Best</i>		\$175.50 ✓
13	1	Rear Spare Tyre Lock <i>new</i>		\$238.30 *
14	2	Rear Exhaust Mounting <i>new</i>	\$33.50	\$67.00 +
15	1	Rear Floor Panel <i>Repair</i>		\$6,500.00 +

Subtotal :- \$10,845.10

3063.50

2757.15

S/n	Qty	Items / Special Nett	U/price	Amount
16	1	Rear Tailgate 70 Km/h Sticker <i>Free</i>		\$20.00 <i>10</i>
17	1	Rear Tailgate 6Pax Sticker		\$20.00 <i>10</i>
18	1	Rear Tailgate Company Sticker <i>New</i>		\$680.00 <i>350</i>
19	3	Rear Tailgate Reflective Sticker <i>New</i>	\$80.00	\$240.00 <i>80</i>
20	1	Rear Tailgate Aluminium Cover <i>New</i>		\$278.20 <i>+</i>
21	100	Rear Tailgate & Floor Panel Aluminium Rivet <i>New</i>	\$1.50	\$150.00 <i>+ 50.</i>
22	1	Rear Floor Panel Aluminium Cover <i>New</i>		\$850.00 <i>+</i>
23	1	Rear Reverse Sensor <i>New</i>		\$350.00 <i>+</i>
24	1	Rear Number Plate <i>Best</i>		\$50.00 <i>30</i>
25	1	Rear Spare Tyre <i>New</i>		\$380.00 <i>+</i>
26	1	Rear Center Chassis Member <i>Pyis</i>		\$680.00 <i>+</i>
27	1	Rear Exhaust <i>Free</i>		\$545.50 <i>+</i>
28	1	Rear Center Exhaust		\$423.40 <i>+</i>

530

Subtotal :- \$4,667.10

Labour charges

To remove & refit rear reverse sensor	\$100.00 <i>+</i>
To remove & refit rear & center exhaust	\$380.00 <i>+</i>
To remove & refit rear body & repair chassis member	\$1,200.00 <i>+ 700</i>
To remove & refit rear aluminium box	\$680.00 <i>+</i>
To check wiring	\$100.00 <i>30</i>
Tuff kote	\$150.00 <i>100</i>
Towing Fee	\$150.00 <i>+</i>
Panel beating	\$2,000.00 <i>800</i>
Spray painting	\$2,000.00 <i>700</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *Adrian Lj*
Date: *01/07/19*

Subtotal :- \$6,760.00

Total:- \$22,272.20

4.5K 07 Sep
total: 5617.15
4/5: 4.5K