

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 21 Mar 2019

Preliminary Advice

Insured Vehicle No : GBB3517Y

TP Vehicle No : FBJ1575A

Make : HONDA CBF150

Date of Inspection : 20/03/2019

Inspection At : Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Singapore 417883

Accident Date : 10/03/2019

Assignment Date : 20/03/2019

Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,085.50
Revised Amount	:S\$	1,684.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,684.70

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP