

VEHICLE NO:SLT 8996B

QTY	PARTICULAR	
PCS	REAR BUMPER	30* +
1 PCS	REAR BUMPER I	50* +
2 PCS	REAR BUMPER I	80* +
1 PCS	REAR BUMPER I	50* +
2 PCS	REAR BUMPER :	650* +
1 SET	REAR BUMPER	600* =
5 PCS	REAR BUMPER	1,460* *
2 PCS	TAILAMPS @\$12	
1 PCS	REAR END PAN	200* +
1 PCS	REAR END PAN	50* =
1 PCS	BOOTLID	250* *
1 PCS	BOOTLID REAR	
1 PCS	BOOTLID 'CERA	
1 PCS	BOOTLID 'K3' EI	3,326*49 +
1 PCS	BOOTLID 'C & C	1,460* +
1 PCS	BOOTLID WEAT	250* =
2 PCS	BOOTLID REFLE	5,036*49 *
	S.NETT	
1SET	REAR BUMPER I	5,036*49 x
1 PCS	REAR END PANE	80* %
		4,029*192 *

L/S → \$4,000

LABOUR CHARGES:

TO CHECK WIRING	\$80.
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.
TO TRANSFER BOOTLID MECHANISM	\$80.
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$120.
TO SPRAY RUST PROOFING	\$100.
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$880.
TO PUTTY & SPRAY PAINTING	\$1,500.
TO	\$12,998

not authorized
w/label
2/5 H020
Hdy
20/3/19

ms/se	\$1,280.30
de/tue	<u>\$845.20</u>
17	\$210.00
one	<u>\$599.20</u>
17	\$130.00
ten	\$50.00
17	\$165.00
one	<u>\$2,410.00</u>
ms	<u>\$833.20</u>
17	\$312.50
1	\$1,066.80
17	\$85.00
17	\$82.00
17	\$50.00
17	\$50.00
one	<u>\$299.20</u>
17	\$1,360.00
	\$9,828.40

(102)

club	\$280.00
see	\$50.00

L/S $\Rightarrow$ \$4,000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s)

3696.1
3326.49