

INS. CASE OWNER:

Kian Meng | CC 6, ALG 1900 5013, Ufa322

LKK:

IDAC:

Surveyor:

M. P. P. P.

DOI:

ASSIGNMENT

2013/19

Date / Time:

20/3/19

Registered in Merimen:

2013/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SLV 7842H

Name of Insured : SAM APITA

Insured Tel No. : HP: 013/19

Excess Sec II : SS D.O.A: 013/19

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

GPD 6450A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

25/3

Cpk

GPD 6450A - X; SLV 7842H - X

Rephaser: Back Auto (1/m)

6/5/2019

Spoke to OI, confirmed BOLA 28, 9 Car chain collision and OI is the last vehicle, No foreign involved. Agree to settle and aware HED will be attached send letter to OI.

file pass to type mandate report

24/10/19
Khinchine

File pass to Mei Kwan to close

After print photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 6/5/2019

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

4/5/2019

Sent By:

Cpk

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

SS 13,900

(15 days)

Reduction:

68 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

23/10/19

Confirm with:

Jason

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

(w/loss)

SS 14,873.00

Loss of Rental (LOR):

SS

-

(- days)

Loss of Use (LOU):

SS

1,020

(\$ 60 x 17 days)

Loss of Income (LOI):

SS

-

(\$ - x - days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

F320

Total:

SS

15,895.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

15,895.00

Name 1:

FASTECH AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

15

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBD6450A

Yr Regn:

9/3/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV200 c.c 1461

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

148159

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VSK43AM2080093712

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 mm

Rear

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

10/3/19

D.O.I.

20/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 7500

24/4/19 LTA 31062 howling, net 13938
4/5 13.900 confirmed with the

(Red \$ 29,151.90 / 68%.)

15 days + 2 Sunday = 17 days

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO:GBD 6450A

QTY	PARTICULAR (NETT ITEM)
1 PCS	REAR BACK DOOR LH
1 PCS	REAR BACK DOOR WIPER MOTOR LH
1 PCS	REAR BACK DOOR WIPER MOTOR ARM LH
1 PCS	REAR BACK DOOR WIPER BLADE LH
1 PCS	REAR BACK DOOR LICENCE PLATE LAMP
1 PCS	REAR BACK DOOR OUTER GARNISH LH
1 PCS	REAR BACK DOOR INNER HANDLE
1 PCS	REAR BACK DOOR INNER LOCK TOP LH
1 PCS	REAR BACK DOOR INNER LOCK BOTTOM LH
1 PCS	REAR BACK DOOR INNER LOCK MECHANISM LH
1 PCS	REAR BACK DOOR INNER TRIM BOARD LH
2 PCS	REAR BACK DOOR HINGES @\$98.50
1 PCS	REAR BACK DOOR RH
1 PCS	REAR BACK DOOR RUBBER CENTRE RH
1 PCS	REAR BACK DOOR INNER LOCK TOP RH
1 PCS	REAR BACK DOOR INNER LOCK BOTTOM RH
1 PCS	REAR BACK DOOR INNER TRIM RH
1 PCS	REAR BUMPER
2 PCS	REAR BUMPER RETAINERS @\$35.00
2 PCS	REAR BUMPER REFLECTORS @\$47.90
1 PCS	REAR BUMPER SPONGE
1 PCS	REAR SPARE TYRE BRACKET
1 PCS	REAR SPARE TYRE BRACKET LOCK
1 PCS	REAR END PANEL INNER
1 PCS	REAR END PANEL OUTER
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FENDER INNER BOARD N/S
1 PCS	REAR FENDER N/S
1 PCS	REAR MUDFLAP N/S
1 PCS	TROLLE BAG
1 PCS	BONNET
1 PCS	FRONT BUMPER
1 PCS	FRONT BUMPER REINFORCEMENT
2 PCS	FRONT BUMPER SIDE RETAINERS @\$25.10
2 PCS	HEADLAMP LOWER GARNISHS @\$348.60
1 PCS	FRONT SUPPORT PANEL CENTRE
2 PCS	FRONT SUPPORT SIDE PANELS @\$67.00
2 PCS	FRONT FENDERS @\$617.00
1 PCS	WIPER WASHER TANK
1 PCS	INTER COOLER
1 PCS	BONNET LOCK
2 PCS	BONNET HINGES @\$41.20
1 SET	BONNET INSULATOR CLIPS
2 PCS	HEADLAMPS @\$413.20
1 SET	HEADLAMP LOWER GARNISH CLIPS
1 PCS	FRONT GRILLE

Not Authorized
Mark
20/3/19
2/s = 13.900
15dy.

Body	\$1,462.30	✓
11	\$285.00	X
11	\$89.30	X
11	\$45.20	X
11	\$245.30	X
Del/ton	\$289.50	✓
11	\$66.50	X
11	\$90.50	X
tw/ton	\$165.80	✓
11	\$188.20	X
Del/ton	\$193.30	✓
11	\$197.00	X
Body	\$1,653.70	✓
ton	\$88.50	✓
11	\$90.50	X
tw/ton	\$165.80	✓
11	\$193.30	X
Del	\$512.00	✓
Missent	\$70.00	WC
Micro	\$95.80	IPC
ton	\$98.50	✓
Suc	\$242.80	X
11	\$60.50	X
Body	\$345.80	✓
Body	\$485.10	✓
11	\$2,162.30	X
11	\$166.00	✓
Body/ton	\$1,553.00	✓
ton	\$45.00	✓
N/S	\$1,150.00	X
Buc	\$858.50	✓
Del	\$563.50	✓
Del	\$591.90	✓
11	\$50.20	X
ton	\$697.20	✓
Body	\$395.70	✓
11	\$135.20	X
Self/Suc	\$1,234.00	✓
11	\$245.00	X
put	\$1,450.00	✓
tw	\$54.60	✓
Self	\$82.40	✓
11	\$45.00	✓
11	\$826.40	✓
11	\$25.00	X
Self/ton	\$344.10	✓

102

1 PCS	FRONT GRILLE LOGO
1 PCS	FRONT BUMPER SPONGE
1 PCS	AIR CON CONDENSER
1 PCS	RADIATOR
1 PCS	RADIATOR FAN ASSY
1 PCS	NV 200' EMBLEM
1 PCS	DCI' EMBLEM
1 PCS	NISSAN LOGO
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR END PANEL WEATHERSTRIP
2 PCS	TAILLAMPS @\$319.70
1 PCS	REAR FLOOR PANEL TOP BOARD
1 PCS	REAR EXHAUST
1 PCS	AIRCON HOSE
1 PCS	CENTRE EXHAUST
2 PCS	AIR CON SIDE GARNISHS @\$184.00
1 PCS	INTER COOLER HOSE
1 PCS	ENGINE MOUNTING BRACKET O/S
1 PCS	AIRCON DISCHARGE HOSE
1 PCS	AIRCON SUCTION HOSE
2 PCS	HEADLAMP TOP <i>parts</i> @\$211.00
1 PCS	AIR DUCT
1 PCS	AIR CLEANER BOX
1 PCS	REAR LEAFSPRING ASSY N/S
1 PCS	REAR AIR VENT N/S
1 PCS	ALTERNATOR ASSY
1 PCS	ENGINE OIL FILTER
1 PCS	STARTER MOTOR
1 PCS	70 KM/H STCIKER
1 PCS	4 PAX STICKER
1 SET	REAR BACK & FRONT CORPORATE STICKER
1 SET	REAR REVERSE SENSOR
1 PCS	REAR & FRONT LICENCE PLATE W/HOLDER
1 PCS	REAR END PANEL SEALANT
2 PCS	REAR BACK DOOR GLASS SEALANT
1 PCS	RADIATOR COOLANT
1 SET	REAR REVERSE CAMERA
1 PCS	REAR FLOOR PANEL TOP MAT

102

<i>per</i>	\$35.80	
<i>Torn</i>	\$293.60	
<i>Seal/2m</i>	\$688.20	
<i>Seal/2m</i>	\$596.30	
<i>CRA/1m</i>	\$452.70	
<i>per</i>	\$163.50	
<i>per</i>	\$155.20	
<i>per</i>	\$35.80	
<i>D's</i>	\$198.60	
<i>per</i>	\$82.80	
<i>M/S 3do</i>	\$639.40	<i>12C</i>
<i>one</i>	\$650.00	
<i>Seal</i>	\$620.00	
<i>11</i>	\$245.00	X
<i>Seal/Tm</i>	\$845.00	
<i>O/S TO 11</i>	\$368.00	<i>12C</i>
<i>11</i>	\$65.00	X
<i>one</i>	\$145.00	
<i>Seal</i>	\$288.00	
<i>Seal</i>	\$265.00	X
<i>Seal</i>	\$422.00	
<i>one</i>	\$268.30	
<i>11</i>	\$485.30	X
<i>SVC</i>	\$1,100.00	X
<i>per</i>	\$98.20	
<i>Seal</i>	\$1,485.00	X
<i>11</i>	\$25.00	X
<i>SVC</i>	\$1,250.00	X
<i>per</i>	\$15.00	<i>105.2</i>
<i>100</i>	\$15.00	<i>105.2</i>
<i>11</i>	\$600.00	X
<i>shorts</i>	\$280.00	<i>1005.2</i>
<i>for but</i>	\$80.00	<i>405.2</i>
<i>per</i>	\$50.00	
<i>per</i>	\$100.00	<i>805.2</i>
<i>11</i>	\$30.00	X
<i>Seal</i>	\$380.00	X
<i>Torn</i>	\$650.00	<i>4005.2</i>
\$34,261.90		

LABOUR CHARGES:

TO CHECK WIRING	\$100.00	<i>30</i>
TO DISMANTLE & REFIX REVERSE SENSOR	\$80.00	<i>50</i>
TO DISMANTLE & REFIX REAR BOTH BACK DOOR GLASS	\$200.00	
TO DISMANTLE & REFIX REAR EXHAUST ASSY	\$180.00	<i>100</i>
TO DISMANTLE & REFIX REAR BOTH BACK DOOR COMPONENTS	\$200.00	<i>120</i>
TO DISMANTLE & REFIX FUEL TANK	\$100.00	X
TO MOUNT VEHICLE ON CAR O-LINER	\$380.00	X
TO SPRAY RUST PROOFING	\$200.00	<i>150</i>
TO REFILL AIR CON GAS	\$150.00	<i>100</i>
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$4,200.00	<i>2400</i>
TO PUTTY & SPRAY PAINTING	\$3,000.00	<i>2000</i>

TOTAL \$43,051.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 4956M

Vehicle Details

Vehicle No.: GBD6450A

Vehicle to be Exported: No

Intended Deregistration Date: 20 Mar 2019

Vehicle Make: NISSAN

Vehicle Model: NV200 1.5L MT ABS AIRBAG 2WD 6DR
EURO 5

Primary Colour: Black

Manufacturing Year: 2014

Engine No.: K9KC400D054242

Chassis No.: VSKYBAM20Z0093712

Maximum Power Output: -

Open Market Value: \$20,544.00

Original Registration Date: 09 Mar 2015

First Registration Date: 09 Mar 2015

Transfer Count: 0

Actual ARF Paid: \$1,028.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 08 Mar 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$52,101.00

COE Rebate Amount: \$31,062.00

Total Rebate Amount: \$31,062.00

The information contained herein is correct as at 20 Mar 2019

OK

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBD6450A		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5		
Chassis No. :	VSKYBAM20Z0093712		
Propellant :	Diesel		
Engine No. :	K9KC400D054242		
Engine Capacity :	1461 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	2030 kg		
Unladen Weight :	1320 kg		
Year Of Manufacture :	2014		
Original Registration Date :	09 Mar 2015		
Lifespan Expiry Date :	08 Mar 2035		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$52,101.00		
COE Expiry Date :	08 Mar 2025		
Road Tax Expiry Date :	08 Sep 2019		
Inspection Due Date :	08 Mar 2020		
Intended Transfer Date :	20 Mar 2019		
CO2 Emission :	138.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	4956M

Vehicle Details

Vehicle No.:	GBD6450A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	K9KC400D054242
Chassis No.:	VSKYBAM20Z0093712
Maximum Power Output:	-
Open Market Value:	\$20,544.00
Original Registration Date:	09 Mar 2015
First Registration Date:	09 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$1,028.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	08 Mar 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,101.00
COE Rebate Amount:	\$31,093.00
Total Rebate Amount:	\$31,093.00

The information contained herein is correct as at 18 Mar 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Nissan NV200

Price Range

Depreciation

2015

Vehicle Type



Submit

[Advanced Search](#)
[Home](#) » [Used Cars](#) » [Direct Owners](#) » Nissan NV200 1.5M

Nissan NV200 1.5M

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[DIRECT OWNER](#)

Price	\$42,500	Fuel Type	Diesel
Depreciation	\$6,670 /yr View models with similar depre	Reg Date	31-Jul-2015 (6yrs 4mths 10days COE left)
Mileage	69,771 km (19.2k /yr)	Manufactured	2015
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$32,155 as of today (change)	OMV	\$20,122
COE	\$50,502	ARF	\$1,007
Engine Cap	1,461 cc	No. of Owners	1
Curb Weight	1,320 kg		
Type of Vehicle	Van		

Features

Still Under Warranty. View specs of the [Nissan NV200 \(2011\)](#)

Description

We Have 3 Van And This Is Rarely Use.

Category

Direct Owner Sale

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Posted on: 12-Mar-2019 | Last Updated on: 19-Mar-2019

Upfront Payment

[* more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$4,250 (change)	Maximum 90% Loan
1st Instalment	\$612	Based on 3.4% interest rate
Total Upfront Payment	\$4,887	
Compare		




100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER



Price Chart

Summary



[Click on the point to view the vehicle](#)

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Contact Person(s)	Darren Sim
Contact No.	92387970
Enquiry	☒ Contact Seller

ESSENTIAL TRANSACTION FORMS

- * Indemnity form
- * Receipt
- * Ownership Transfer
- * Sales agreement
- * Hand-over form

[f Connect with Facebook](#)

SELLING YOUR CAR?

Browse our exclusive list of direct car dealers for the best price for your car

HOME

NEW CARS

USED CARS

COMMERCIAL VEH

RENTAL CARS

SELL CARS

MOTOR D

Home > Used Commercial Veh > Nissan NV200 1.5M

DIRECT SELLER

NISSAN NV200 1.5M

OVERVIEW

GALLERY

Share



Price	\$46,000	
Registration Date	29-Sep-2015	
COE Remaining	6yrs 5mths 6days	
Manufactured	2015	
Mileage	70,000 km	
No. of Owners	1	
Transmission	Manual	
Engine Capacity	1,461 cc	
Fuel Type	Diesel	
COE	\$37,540	
Paper Value	N.A.	
Depreciation	\$7,140 / year	
Type	Van	



USED VEHICLE S

nissan nv200

Category

Transmission

Min Price

Min Depreciation

2015

VEHICLE TOOLS

COE Results

Post an Ad

Carpark Rates

Still Under Factory Warranty For 5 Year. Careful Owner. Already Signed Out For Maintenance Package (Left 2 Free Service).

Accessories: Pioneer AV Receiver/DVD Player, Hand Free Speaker, Bluetooth, Reverse Camera, Speaker Replaced.

More info on Nissan NV200 |

For full set of payment break-down, <https://www.sgcarMart...=801962&DL=1000>

Status: Available | Category: Direct Seller Vehicles, Diesel Vehicles

Date Posted: 05-Mar-2019 | Date Updated: 17-Apr-2019

SELLER INFORMATION

DIRECT SELLER

Ng Kwee Yong

98181145 EMAIL SELLER

“ SAY YOU SAW THIS AD ON STCARS.SG! ”



Instructions on how to complete a seller to end-consumer deal

Once buyer & seller confirms the deal, sgCarMart Connect will provide 100% FREE settlement on Loans, Insurance & Paperwork for both parties. Call 6744 3540.

These are the essential forms to facilitate direct buyer and seller exchanges.

Indemnity Form | Sales Agreement | LTA Vehicle Transfer Form | Handover Form | Invoice

SIMILAR VEHICLES





AVIVA

NISSAN NV 200

Price Range

Depreciation

2015

Vehicle Type

Home » Used Cars » Net Link Partners Pte Ltd » Nissan NV200 1.5M

Nissan NV200 1.5M

Overview

Financial

Accessories

Similar

Research

Photos

Map

NETLINK

Your Commercial Specialist

Specialized in New & Used Commercial Vehicles. Insurance. Hire Purchase. Scrap/Export

Price	\$41,800	Lifespan	08-Mar-2035
Depreciation ?	\$7,110 /yr View models with similar depre	Reg Date	09-Mar-2015 (5yrs 10mths 12days COE left)
Mileage	N.A.	Manufactured ?	2014
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$31,265 as of today (change)	OMV ?	\$20,544
COE ?	\$53,202	ARF ?	\$1,028
Engine Cap	1,461 cc	No. of Owners ?	1
Curb Weight ?	1,320 kg		
Type of Vehicle	Van		

Features

View specs of the Nissan NV200 (2011)

Description

New Paint! Well Maintained By Previous Owner! Low Maintenance And Fuel Efficient! The Only Diesel Medium-Sized Van From A Japanese Brand! Ideal For Work And Personal Usages! Loan And High Trade In Available! Look No Further! Call Now To Inquire! All Price Inquires Are Welcome! Hurry Before It's Gone.


Category

Premium Ad Car


Status

Available

Compare



Price Chart



Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 23 October 2019 1:38 PM
To: Jason
Cc: Admin A
Subject: RE: YOUR REF:SLV7842H MY REF:GBD6450A DOA:10/03/2019.

Tracking:	Recipient	Delivery
	Jason	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 23/10/2019 1:38 PM
	shupeil@lkkauto.com	Delivered: 23/10/2019 1:38 PM
	olivialau@lkkauto.com	Delivered: 23/10/2019 1:38 PM

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter and your e-mail below.

We confirm settlement as per your LOD dated 24/4/2019 for **\$15,895.00(all in)**.

We will proceed to do the necessary.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason <Jason@fastechauto.com.sg>
Sent: Friday, 18 October 2019 12:48 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: YOUR REF:SLV7842H MY REF:GBD6450A DOA:10/03/2019.

Without Prejudice

Dear Khanchna,

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	20 Mar 2019 11:53	Clim Dtl Modified	Claimant's Name: -> -.	[A] HOW MEI KWAN
2	20 Mar 2019 11:53	Clim Veh Model Changed	(206159) NISSAN NV200 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M).	[A] HOW MEI KWAN
3	20 Mar 2019 11:53	Clim Created	Reg No: GBD6450A. Acct Date: 2019/03/10. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Fastech Auto Pte Ltd (HQ)	[A] HOW MEI KWAN
4	20 Mar 2019 11:53	Clim Existing Check Notice		[A] HOW MEI KWAN
5	20 Mar 2019 11:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
6	20 Mar 2019 11:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/29	[A] HOW MEI KWAN
7	20 Mar 2019 11:53	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
8	20 Mar 2019 11:53	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
9	20 Mar 2019 11:54	Label Added	(19):Fastlane.	[A] HOW MEI KWAN
10	20 Mar 2019 11:54	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
11	21 Mar 2019 11:57	Clim Dtl Modified	Claimant's Name: - -> SUNMACT TECHNOLOGY. Claimant's ID: -> 53392402B.	[A] HOW MEI KWAN
12	21 Mar 2019 11:57	Clim Registration Modified	Acct Time:00:00:00->16:00:00.	[A] HOW MEI KWAN
13	13 Jun 2019 16:00	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
14	13 Jun 2019 16:00	Clim Dtl Modified	JPJ Reg. Date: -> 2015/03/09.	[A] NUR SHAQILAH BTE ABDOL WAHAB
15	13 Jun 2019 16:00	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
16	27 Aug 2019 16:05	Adj Mandate Request	Cur.Req:15895.00:BOLA 28: 9 VEHICLE CHAIN COLLISION, OUR INSURED VEHICLE LAST VEHICLE.[**15 days recommendation for repair + 2 Sundays = 17 days] C Claims Handler: Khanchna	[A] Khanchna Pothuraj

Date From



Date To



Audit Type None



Go

ACTIVITY

[06/05/2019 17:53] Chong Poh Kin:

spoke to OID (Mr Abhijit), confirmed accident details. BOLA 28, OID involved in 9 car chain collision, OID is the last vehicle. NO foreign vehicle involve. Informed TP claim and NCD issue.

OID agreed to settle, aware NCD issue. send letter to OI.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2177004	13/06/2019 16:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBD6450A	SLV7842H	11.77

Print Received Message

This mail is associated with :

***GBD6450A (0222756474SG)**

[SLV7842H]

TP

SUNMACT TECHNOLOGY

Mar 10 2019 4:00PM

[SAMARPITA]

Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 22/10/2019 19:32 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15895.00) - GBD6450A - Claim Handler: Chan, Kian-Meng

Approved:15895.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2019 Edit Reg		20 Mar 2019 00:00 Edit Adj Rpt	S\$13,900.00 Edit Estimates	S\$13,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SAMARPITA, Co. Reg. No.: 53316774D, Tel: +6598630771		
Main Claimant:	SUNMACT TECHNOLOGY, Co. Reg. No.: 53392402B		
Vehicle Reg. No.:	GBD6450A	Date of Loss:	10/03/2019 16:00 - :59 [48 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0222756474SG	Policy/Cover Note No.:	1800001571 (Comprehensive)
Vehicle Reg. No. (Insured):	SLV7842H	Policy No. (Claimant):	5079873989-03
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (22/10/2019): Alert - Adj Mandate Approved (S\$15895.00) - GBD6450A - Claim Handler: Chan, Kian...
- AIG_SG (21/03/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***GBD6450A (0222756474SG)**
[SLV7842H]

TP

SUNMACT TECHNOLOGY

Mar 10 2019 4:00PM

[SAMARPITA]

Fastech Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 08:45	Chassis Number	Load JPG	☒
2	07/05/19 08:45	Odometer Reading	Load JPG	☒
3	07/05/19 08:45	General View	Load JPG	☒
4	07/05/19 08:45	General View	Load JPG	☒
5	07/05/19 08:45	General View	Load JPG	☒
6	07/05/19 08:45	General View	Load JPG	☒
7	07/05/19 08:45	General View	Load JPG	☒
8	07/05/19 08:45	General View	Load JPG	☒
9	07/05/19 08:45	General View	Load JPG	☒
10	07/05/19 08:45	General View	Load JPG	☒
11	07/05/19 08:45	General View	Load JPG	☒
12	07/05/19 08:45	General View	Load JPG	☒
13	07/05/19 08:45	General View	Load JPG	☒
14	07/05/19 08:45	General View	Load JPG	☒
15	07/05/19 08:45	General View	Load JPG	☒
16	07/05/19 08:45	General View	Load JPG	☒
17	07/05/19 08:45	General View	Load JPG	☒
18	07/05/19 08:45	General View	Load JPG	☒
19	07/05/19 08:45	General View	Load JPG	☒
20	07/05/19 08:45	General View	Load JPG	☒
21	07/05/19 08:45	General View	Load JPG	☒
22	07/05/19 08:45	General View	Load JPG	☒
23	07/05/19 08:45	General View	Load JPG	☒
24	07/05/19 08:45	General View	Load JPG	☒
25	07/05/19 08:45	General View	Load JPG	☒
26	07/05/19 08:45	General View	Load JPG	☒
27	07/05/19 08:45	General View	Load JPG	☒
28	07/05/19 08:45	General View	Load JPG	☒
29	07/05/19 08:45	General View	Load JPG	☒
30	07/05/19 08:45	General View	Load JPG	☒
31	07/05/19 08:45	General View	Load JPG	☒
32	07/05/19 08:45	General View	Load JPG	☒
33	07/05/19 08:46	General View	Load JPG	☒
34	07/05/19 08:46	General View	Load JPG	☒
35	07/05/19 08:46	General View	Load JPG	☒
36	07/05/19 08:46	General View	Load JPG	☒
37	07/05/19 08:46	General View	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/05/19 08:46	General View	 Load JPG	☒
39	07/05/19 08:46	General View	 Load JPG	☒
40	07/05/19 08:46	General View	 Load JPG	☒
41	07/05/19 08:46	General View	 Load JPG	☒
42	07/05/19 08:46	General View	 Load JPG	☒
43	07/05/19 08:46	General View	 Load JPG	☒
44	07/05/19 08:46	General View	 Load JPG	☒
45	07/05/19 08:46	General View	 Load JPG	☒
46	07/05/19 08:46	General View	 Load JPG	☒
47	07/05/19 08:46	General View	 Load JPG	☒
48	07/05/19 08:46	General View	 Load JPG	☒
49	07/05/19 08:46	General View	 Load JPG	☒
50	07/05/19 08:46	General View	 Load JPG	☒
51	07/05/19 08:46	General View	 Load JPG	☒
52	07/05/19 08:46	General View	 Load JPG	☒
53	07/05/19 08:46	General View	 Load JPG	☒
54	07/05/19 08:46	General View	 Load JPG	☒
55	07/05/19 08:46	General View	 Load JPG	☒
56	07/05/19 08:46	General View	 Load JPG	☒
57	07/05/19 08:46	General View	 Load JPG	☒
58	07/05/19 08:46	General View	 Load JPG	☒
59	07/05/19 08:46	General View	 Load JPG	☒
60	07/05/19 08:46	General View	 Load JPG	☒
61	07/05/19 08:46	General View	 Load JPG	☒
62	07/05/19 08:46	General View	 Load JPG	☒
63	07/05/19 08:46	General View	 Load JPG	☒
64	07/05/19 08:46	General View	 Load JPG	☒
65	07/05/19 08:46	General View	 Load JPG	☒
66	07/05/19 08:46	General View	 Load JPG	☒
67	07/05/19 08:46	General View	 Load JPG	☒
68	07/05/19 08:46	General View	 Load JPG	☒
69	07/05/19 08:46	General View	 Load JPG	☒
70	07/05/19 08:46	General View	 Load JPG	☒
71	07/05/19 08:46	General View	 Load JPG	☒
72	07/05/19 08:46	General View	 Load JPG	☒
73	07/05/19 08:46	General View	 Load JPG	☒
74	07/05/19 08:46	General View	 Load JPG	☒
75	07/05/19 08:46	General View	 Load JPG	☒
76	07/05/19 08:46	General View	 Load JPG	☒
77	07/05/19 08:46	General View	 Load JPG	☒
78	07/05/19 08:46	General View	 Load JPG	☒
79	07/05/19 08:46	General View	 Load JPG	☒
80	07/05/19 08:46	General View	 Load JPG	☒
81	07/05/19 08:46	General View	 Load JPG	☒
82	07/05/19 08:46	General View	 Load JPG	☒
83	07/05/19 08:46	General View	 Load JPG	☒
84	07/05/19 08:46	General View	 Load JPG	☒
85	07/05/19 08:46	General View	Load JPG	☒
86	07/05/19 08:46	General View	Load JPG	☒
87	07/05/19 08:46	General View	Load JPG	☒
88	07/05/19 08:46	General View	Load JPG	☒
89	07/05/19 08:46	General View	Load JPG	☒
90	07/05/19 08:46	General View	Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	07/05/19 08:46	General View	 Load JPG	✓
92	07/05/19 08:46	General View	 Load JPG	✓
93	07/05/19 08:46	General View	 Load JPG	✓
94	07/05/19 08:46	General View	 Load JPG	✓
95	07/05/19 08:46	General View	 Load JPG	✓
96	07/05/19 08:46	General View	 Load JPG	✓
97	07/05/19 08:46	General View	 Load JPG	✓
98	07/05/19 08:46	General View	 Load JPG	✓
99	07/05/19 08:46	General View	 Load JPG	✓
100	07/05/19 08:46	General View	 Load JPG	✓
101	07/05/19 08:46	General View	 Load JPG	✓
102	07/05/19 08:46	General View	 Load JPG	✓
103	07/05/19 08:46	General View	 Load JPG	✓
104	07/05/19 08:46	General View	 Load JPG	✓
105	07/05/19 08:46	General View	 Load JPG	✓
106	07/05/19 08:46	General View	 Load JPG	✓
107	07/05/19 08:46	General View	 Load JPG	✓
108	07/05/19 08:46	General View	 Load JPG	✓
109	07/05/19 08:46	General View	 Load JPG	✓
110	07/05/19 08:46	General View	 Load JPG	✓
111	07/05/19 08:46	General View	 Load JPG	✓
112	07/05/19 08:46	General View	 Load JPG	✓
113	07/05/19 08:46	General View	 Load JPG	✓
114	07/05/19 08:46	General View	 Load JPG	✓
115	07/05/19 08:46	General View	 Load JPG	✓
116	07/05/19 08:46	General View	 Load JPG	✓
117	07/05/19 08:46	General View	 Load JPG	✓
118	07/05/19 08:46	General View	 Load JPG	✓
119	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
120	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
121	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
122	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
123	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
124	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
125	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
126	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
127	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
128	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
129	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
130	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
131	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
132	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
133	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
134	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
135	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
136	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
137	07/05/19 08:46	Reinspection Photo	 Load JPG	✓
138	07/05/19 08:47	Reinspection Photo	Load JPG	✓
139	07/05/19 08:47	Reinspection Photo	Load JPG	✓
140	07/05/19 08:47	Reinspection Photo	Load JPG	✓
141	07/05/19 08:47	Reinspection Photo	Load JPG	✓
142	07/05/19 08:47	Reinspection Photo	Load JPG	✓
143	07/05/19 08:47	Reinspection Photo	Load JPG	✓

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
144	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
145	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
146	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
147	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
148	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
149	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
150	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
151	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
152	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
153	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
154	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
155	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
156	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
157	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
158	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
159	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
160	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
161	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
162	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
163	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
164	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
165	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
166	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
167	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
168	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
169	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
170	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
171	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
172	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
173	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
174	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
175	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
176	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
177	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
178	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
179	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
180	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
181	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
182	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
183	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
184	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
185	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
186	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
187	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
188	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
189	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
190	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
191	07/05/19 08:47	Reinspection Photo	Load JPG	☒
192	07/05/19 08:47	Reinspection Photo	Load JPG	☒
193	07/05/19 08:47	Reinspection Photo	Load JPG	☒
194	07/05/19 08:47	Reinspection Photo	Load JPG	☒
195	07/05/19 08:47	Reinspection Photo	Load JPG	☒
196	07/05/19 08:47	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▾	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
197	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
198	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
199	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
200	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
201	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
202	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
203	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
204	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
205	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
206	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
207	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
208	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
209	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
210	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
211	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
212	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
213	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
214	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
215	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
216	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
217	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
218	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
219	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
220	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
221	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
222	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
223	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
224	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
225	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
226	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
227	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
228	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
229	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
230	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
231	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
232	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
233	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
234	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
235	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
236	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
237	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
238	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
239	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
240	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
241	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
242	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
243	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
244	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
245	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
246	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
247	07/05/19 08:47	Reinspection Photo	Load JPG	☒
248	07/05/19 08:47	Reinspection Photo	Load JPG	☒
249	07/05/19 08:47	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
250	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
251	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
252	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
253	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
254	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
255	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
256	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
257	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
258	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
259	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
260	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
261	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
262	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
263	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
264	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
265	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
266	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
267	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
268	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
269	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
270	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
271	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
272	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
273	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
274	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
275	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
276	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
277	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
278	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
279	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
280	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
281	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
282	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
283	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
284	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
285	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
286	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
287	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
288	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
289	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
290	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
291	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
292	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
293	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
294	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
295	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
296	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
297	07/05/19 08:47	Reinspection Photo	Load JPG	☒
298	07/05/19 08:47	Reinspection Photo	Load JPG	☒
299	07/05/19 08:47	Reinspection Photo	Load JPG	☒
300	07/05/19 08:47	Reinspection Photo	Load JPG	☒
301	07/05/19 08:47	Reinspection Photo	Load JPG	☒
302	07/05/19 08:47	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
303	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
304	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
305	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
306	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
307	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
308	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
309	07/05/19 08:47	Reinspection Photo	 Load JPG	☒
310	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
311	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
312	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
313	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
314	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
315	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
316	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
317	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
318	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
319	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
320	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
321	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
322	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
323	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
324	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
325	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
326	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
327	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
328	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
329	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
330	07/05/19 08:48	Reinspection Photo-after repair	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/03/19 16:20	TP GIA REPORT	 Load PDF	
2	04/05/19 15:11	TP Estimate-Marked	 Load PDF	
3	13/06/19 16:58	GIA SEARCH	 Load PDF	
4	13/06/19 16:58	LETTER TO OI	 Load PDF	
5	04/11/19 13:53	AUTHORISATION TO ACT	 Load PDF	
6	04/11/19 13:53	RELEASE VOUCHER	 Load PDF	
7	04/11/19 13:54	LOD	 Load PDF	
8	04/11/19 13:54	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/03/19 13:39	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV7842H (Insd veh)	Model:	NISSAN NV200 1.5 ABS
	GBD6450A (TP veh)		AIRBAG 2WD 6DR EURO 5 (M)
Date of Accident:	10/03/2019		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$			46,065.53
Final Repair Cost	:	\$			14,873.00
Loss of Use	:	\$			1,020.00
Rental (if any)	:	\$			17.00 days at \$60.00 per day
LTA / GIA Search Fee	:	\$			2.00
Others:	:	\$			
	:	\$			
Final Settlement Sum	:	\$			15,895.00

Is Third Party Workshop GIA Registered?	[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop : Agreed Liability _____ 100 _____ (%)					
B) For GIA Registered Workshop : BOLA Applicable: Yes/ No BOLA Scenario No: _____					
BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)					
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 15,895.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

04 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19005013/UKA3S2
Date: 04/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800001571
Claimant Vehicle No : GBD6450A **Insured Vehicle No :** SLV7842H
 Date of Loss: 10/03/2019 Nature of Claim: TP Claim No: 0222756474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD6450A**
 Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M) Engine No: K9KC400D054242
 Reg. Date: 09/03/2015 (Man. Year: 2014) Chassis No: VSKYBAM20Z0093712
 Colour: Black Odometer: 149159 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14 Rear Tyre Size: 175/70R14
 Front Left Side: Firemax 6 mm Rear Left Side: Firemax 6 mm
 Front Right Side: Firemax 6 mm Rear Right Side: Firemax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,261.90	19,678.88	14,583.02	42.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,790.00	5,150.00	3,640.00	41.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,051.90	24,828.88	18,223.02	42.33
Approved Total (Overridden) (S\$)		13,900.00		
(S\$)	43,051.90	13,900.00	29,151.90	67.71
+ GST 7.00/7.00% (S\$)	3,013.63	973.00	2,040.63	67.71
Nett Amount (S\$)	46,065.53	14,873.00	31,192.53	67.71
+ Loss of Use (17.0 x S\$60.00/day) (S\$)		1,020.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		15,895.00		

INSPECTION

Date of Assignment: 20/03/2019
 Date Inspected: 20/03/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 15.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

11/4/2019

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BACK DOOR LH	Badly Dented	1,462.30 F	*1,462.30 FN
2	1		*REAR BACK DOOR WIPER MOTOR LH	Not Necessary	285.00 F	*- FN
3	1		*REAR BACK DOOR WIPER MOTOR ARM LH	Not Necessary	89.30 F	*- FN
4	1		*REAR BACK DOOR WIPER BLADE LH	Not Necessary	45.20 F	*- FN
5	1		*REAR BACK DOOR LICENCE PLATE LAMP	Not Necessary	245.30 F	*- FN
6	1		*REAR BACK DOOR OUTER GARNISH LH	Deformed / Torn	289.50 F	*289.50 FN
7	1		*REAR BACK DOOR INNER HANDLE	Not Necessary	66.50 F	*- FN
8	1		*REAR BACK DOOR INNER LOCK TOP LH	Not Necessary	90.50 F	*- FN
9	1		*REAR BACK DOOR INNER LOCK BOTTOM LH	Twisted / Jammed	165.80 F	*165.80 FN
10	1		*REAR BACK DOOR INNER LOCK MECHANISM LH	Not Necessary	188.20 F	*- FN
11	1		*REAR BACK DOOR INNER TRIM BOARD LH	Deformed / Torn	193.30 F	*193.30 FN
12	2		*REAR BACK DOOR HINGES	Not Necessary	197.00 F	*- FN
13	1		*REAR BACK DOOR RH	Badly Dented	1,653.70 F	*1,653.70 FN
14	1		*REAR BACK DOOR RUBBER CENTRE RH	Torn	88.50 F	*88.50 FN
15	1		*REAR BACK DOOR INNER LOCK TOP RH	Not Necessary	90.50 F	*- FN
16	1		*REAR BACK DOOR INNER LOCK BOTTOM RH	Twisted / Jammed	165.80 F	*165.80 FN
17	1		*REAR BACK DOOR INNER TRIM RH	Not Necessary	193.30 F	*- FN
18	1		*REAR BUMPER	Distorted	512.00 F	*512.00 FN
19	1		*REAR BUMPER RETAINERS	N/s Bent	70.00 F	*35.00 FN
20	1		*REAR BUMPER REFLECTORS	N/s Cracked	95.80 F	*47.90 FN
21	1		*REAR BUMPER SPONGE	Torn	98.50 F	*98.50 FN
22	1		*REAR SPARE TYRE BRACKET	Serviceable	242.80 F	*- FN
23	1		*REAR SPARE TYRE BRACKET LOCK	Not Necessary	60.50 F	*- FN
24	1		*REAR END PANEL INNER	Badly Dented	345.80 F	*345.80 FN
25	1		*REAR END PANEL OUTER	Badly Dented	485.10 F	*485.10 FN
26	1		*REAR FLOOR PANEL	Repair	2,162.30 F	*- FN
27	1		*REAR FENDER INNER BOARD N/S	Deformed	166.00 F	*166.00 FN
28	1		*REAR FENDER N/S	Badly Dented / Buckled	1,553.00 F	*1,553.00 FN
29	1		*REAR MUDFLAP N/S	Torn	45.00 F	*45.00 FN
30	1		*TROLLE BAG	No such part	1,150.00 F	*- FN
31	1		*BONNET	Buckled	858.50 F	*858.50 FN
32	1		*FRONT BUMPER	Distorted	563.50 F	*563.50 FN
33	1		*FRONT BUMPER REINFORCEMENT	Distorted	591.90 F	*591.90 FN
34	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	50.20 F	*- FN
35	2		*HEADLAMP LOWER GARNISHS	Torn	697.20 F	*697.20 FN
36	1		*FRONT SUPPORT PANEL CENTRE	Bent	395.70 F	*395.70 FN
37	2		*FRONT SUPPORT SIDE PANELS	Repair	135.20 F	*- FN
38	2		*FRONT FENDERS	Bent / Buckled	1,234.00 F	*1,234.00 FN
39	1		*WIPER WASHER TANK	Not Necessary	245.00 F	*- FN
40	1		*INTER COOLER	Punctured	1,450.00 F	*1,450.00 FN
41	1		*BONNET LOCK	Twisted	54.60 F	*54.60 FN
42	2		*BONNET HINGES	Bent	82.40 F	*82.40 FN
43	1		*SET BONNET INSULATOR CLIPS	Necessary	45.00 F	*45.00 FN
44	2		*HEADLAMPS	Cracked	826.40 F	*826.40 FN
45	1		*SET HEADLAMP LOWER GARNISH CLIPS	Not Necessary	25.00 F	*- FN
46	1		*FRONT GRILLE	Bent / Cracked	344.10 F	*344.10 FN
47	1		*FRONT GRILLE LOGO	Necessary	35.80 F	*35.80 FN
48	1		*FRONT BUMPER SPONGE	Torn	293.60 F	*293.60 FN
49	1		*AIR CON CONDENSER	Bent / Punctured	688.20 F	*688.20 FN
50	1		*RADIATOR	Bent / Punctured	596.30 F	*596.30 FN
51	1		*RADIATOR FAN ASSY	Cracked / Jammed	452.70 F	*452.70 FN
52	1		*NV 200 EMBLEM	Necessary	163.50 F	*163.50 FN
53	1		*DCI EMBLEM	Necessary	155.20 F	*155.20 FN
54	1		*NISSAN LOGO	Necessary	35.80 F	*35.80 FN
55	1		*REAR END PANEL TOP GARNISH	Distorted	198.60 F	*198.60 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
56	1	*REAR END PANEL WEATHERSTRIP	Twisted	82.80 F	*82.80 FN
57	1	*TAILLAMPS	N/s Broken	639.40 F	*319.70 FN
58	1	*REAR FLOOR PANEL TOP BOARD	Cracked	650.00 F	*650.00 FN
59	1	*REAR EXHAUST	Bent	620.00 F	*620.00 FN
60	1	*AIRCON HOSE	Not Necessary	245.00 F	*- FN
61	1	*CENTRE EXHAUST	Bent / Twisted	845.00 F	*845.00 FN
62	1	*AIR CON SIDE GARNISHS	O/s Torn	368.00 F	*184.00 FN
63	1	*INTER COOLER HOSE	Not Necessary	65.00 F	*- FN
64	1	*ENGINE MOUNTING BRACKET O/S	Cracked	145.00 F	*145.00 FN
65	1	*AIRCON DISCHARGE HOSE	Bent	288.00 F	*288.00 FN
66	1	*AIRCON SUCTION HOSE	Serviceable	265.00 F	*- FN
67	2	*HEADLAMP TOP PANELS	Buckled	422.00 F	*422.00 FN
68	1	*AIR DUCT	Cracked	268.30 F	*268.30 FN
69	1	*AIR CLEANER BOX	Not Necessary	485.30 F	*- FN
70	1	*REAR LEAFSPRING ASSY N/S	Serviceable	1,100.00 F	*- FN
71	1	*REAR AIR VENT N/S	Twisted	98.20 F	*98.20 FN
72	1	*ALTERNATOR ASSY	Serviceable	1,485.00 F	*- FN
73	1	*ENGINE OIL FILTER	Not Necessary	25.00 F	*- FN
74	1	*STARTER MOTOR	Serviceable	1,250.00 F	*- FN
75	1	*SET REAR BACK & FRONT CORPORATE STICKER	Not Necessary	600.00 F	*- FN
76	1	*REAR END PANEL SEALANT	Necessary	50.00 F	*50.00 FN
77	1	*RADIATOR COOLANT	Not Necessary	30.00 F	*- FN
78	1	*SET REAR REVERSE CAMERA	Serviceable	380.00 F	*- FN
79	1	*70 KM/H STICKER	Necessary	15.00 FS	*10.00 FS
80	1	*4 PAX STICKER	Necessary	15.00 FS	*10.00 FS
81	1	*REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
82	1	*REAR & FRONT LICENCE PLATE W/HOLDER	Front Bent	80.00 FS	*40.00 FS
83	1	*REAR BACK DOOR GLASS SEALANT	Necessary	100.00 FS	*80.00 FS
84	1	*REAR FLOOR PANEL TOP MAT	Torn	650.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	34,261.90	21,783.20
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	2,104.32
Total Parts (\$\$)	34,261.90	19,678.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	100.00	30.00
2	TO DISMANTLE & REFIX REVERSE SENSOR.	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR BOTH BACK DOOR GLASS.	New	200.00	200.00
4	TO DISMANTLE & REFIX REAR EXHAUST ASSY.	New	180.00	100.00
5	TO DISMANTLE & REFIX REAR BOTH BACK DOOR COMPONENTS.	New	200.00	120.00
6	TO DISMANTLE & REFIX FUEL TANK.	New	100.00	0.00
7	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
8	TO SPRAY RUST PROOFING.	New	200.00	150.00
9	TO REFILL AIR CON GAS.	New	150.00	100.00
10	LABOUR FOR PANEL BEATING & REPLACING PARTS.	New	4,200.00	2,400.00
11	TO PUTTY & SPRAY PAINTING.	New	3,000.00	2,000.00
Gross Labour Cost (S\$)			8,790.00	5,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >