

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 20 Mar 2019

**Preliminary Advice**

Vehicle No	: SDY633U	Accident Date	: 17/03/2019
Make	: SUBARU FORESTER	Policy No.	: 2100480285-02
Assignment Date	: 20/03/2019	Excess	: S\$0.00
Date of Inspection	: 20/03/2019	Est. Duration of Repair	: 10 days
Inspection At	: Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH Singapore 319255		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 13,952.71
Revised Amount	:S\$ 7,354.90
Check Items (Estimated)	:S\$ 2,920.83
Total	:S\$ 10,275.73
Lump Sum Repair :S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 81,000.00
COE / PARF Rebate	:S\$ 57,066.00
Salvage Value	:S\$
Margin for Repair	:S\$ 23,934.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :