

22/04/2013

ASS. RES. INC.

REF:

CS/AIG/19005017/KSD322

Special Instruction:

SA/VEY/01

merimen

From (Person):

Kenneth
Chin Lee Ying

of

AIG

Date/Time:

20/3/19 @ 10.00am

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SPY 633U

Insured:

at Workshop in/

Motor Image

Tel:

86113195

of

11 lorong 8 fca payoh

Policy No:

Claim No:

Sum Insured:

Excess:

TBA

Make of Vch:

(Client's Record)

D.O.A

17/03/19

CA / (REV)

/ REP. / RESV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:37am @ 20/3/19

Person Contacted:

Dorel

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDY 633U - X
20/03/19	@ 13:44 p.m. received ZA to Loo Tong shing via merimen.
21/03/19	@ 10:26 a.m. mandate requested authorise repair to Tong shing via merimen.
23/03/19	@ 09:12 mandate approved by vicar koh.

ASS. REC. BY:

REF:

A/G/ CS/AIG/1900507/Ksd3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

20/19/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDY633U

Yr Regn:

08,16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Subaru Forester

c.c

1998

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

59610

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JF18JGK K85 4-6 075090

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fairken

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

17/3/19

D.O.I.

20/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1st oil

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

2/10/19

@ 12:12 p.m. revert authorisation report to Daniel (Superior) via email.

13/10/19

Confirmed r/p \$ 8,025.22 @ 10 days with Kenneth (\$ 6,455.25 Red - 45%)

RECEIVED 21 NOV 2019

RECEIVED 13 OCT 2019

Date/Time, File Pass to?

21/11/19



: Prel. Report

1) Type



: Final Report

Date/Time, File Return to?

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

\$ + RS \$

Flange

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.K (\$

8,025.22

200

11

211

*** SDY633U - OD RECOVERY CLAIM - AIG INSURED - ARRANGE SU...**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 20/3/2019 10:08:03 AM

Attachments:  SDY633U GIA REPORT - OD RECOVERY.PDF
 SDY633U ESTIMATE - OD RECOVERY.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Daniel Jude [<mailto:danieljude@motorimage.net>]
Sent: Wednesday, March 20, 2019 9:59 AM
To: AIG SGP, Claims-Survey
Cc: TPY Insurance Team; Mohamed Isman
Subject: SDY633U - OD RECOVERY CLAIM - AIG INSURED - ARRANGE SURVEY - 20/03/2019 - 1100HRS
Importance: High

Hi Claims Team,

Kindly assist to arrange survey for the above mentioned

20/03/2019 – 1100hrs

****non-drivable vehicle****

Thank You.

Best Regards
Daniel A Jude
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP: 8611 3195
Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5944B
Vehicle Details	
Vehicle No.:	SDY633U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	FA20A977486
Chassis No.:	JF1SJGK85GG075090
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$20,010.00
Original Registration Date:	31 Aug 2016
First Registration Date:	31 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$20,014.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2026
PARF Rebate Amount:	\$15,010.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$42,056.00
Total Rebate Amount:	\$57,066.00

The information contained herein is correct as at 20 Mar 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 23 October 2019 5:46 pm
To: Mohamed Isman; Daniel Jude
Cc: TPY Insurance Team; SUR; Ooi Siow Hooi
Subject: RE: SDY633U - OD RECOVERY CLAIM - AIG - FINALIZED

Dear All,

Confirmed final fig \$ 8,025.22 @ 10 days of repairs before excess \$ 0/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ooi Siow Hooi <hooi@motorimage.net>
Sent: Wednesday, 23 October 2019 2:51 pm
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: TPY Insurance Team <tpyinstead@tanchong.org>
Subject: SDY633U - OD RECOVERY CLAIM - AIG - FINALIZED

Hi Claim Teams,

Attached for your reference and follow up.

*****Kindly reply to all for easier follow up*****

Thank You

Best Regards,
Siowhooi
Admin Assistant
Motor Image Enterprises Pte Ltd
19 Toa Payoh Lorong 8, Singapore 319255
Tel: +65-6703 8333 DID: +65-6703 8115
Fax: +65-6253 5535

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 25 March 2019 12:12 PM
To: 'Daniel Jude'
Cc: 'SUR'
Subject: SDY 633 OD (AIG) DOA - 17/03/2019

Dear All,

As instructed by our client, please proceed to repair the insured vehicle **SDY 633U (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 23 October 2019 3:25 pm
To: Koh, Victor-CK
Cc: SUR
Subject: RE: Re: Alert - Adj Mandate Approved (S\$7354.90) - SDY633U - Claim Handler: Mohd Zawaye, Norsazani

Hi Victor,

According to our surveyor, supplementary of the labour has been take out.

Kindly let us have your mandate approval.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Monday, 21 October 2019 5:16 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Re: Alert - Adj Mandate Approved (S\$7354.90) - SDY633U - Claim Handler: Mohd Zawaye, Norsazani

Hi Shirley,

Then why is there supplementary labour for repair RH chassis again?

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

From: Do-Not-Reply [<mailto:do-not-reply@merimen.com>]
Sent: Monday, October 21, 2019 11:40 AM

Shirley Hiew (LKK Auto)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Monday, 21 October 2019 5:16 pm
To: Shirley Hiew (LKK Auto); SUR
Subject: RE: Re: Alert - Adj Mandate Approved (S\$7354.90) - SDY633U - Claim Handler: Mohd Zawaye, Norsazani

Hi Shirley,

Then why is there supplementary labour for repair RH chassis again?

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Monday, October 21, 2019 11:40 AM
To: Koh, Victor-CK
Cc: sur@lkkauto.com
Subject: [EXTERNAL] Re: Alert - Adj Mandate Approved (S\$7354.90) - SDY633U - Claim Handler: Mohd Zawaye, Norsazani

This message is from an external sender; be cautious with links and attachments.

This mail is associated with :
***SDY633U (4520178485SG)**
OD
Mar 17 2019 10:00AM
[TEO PING SIONG]
Motor Image Enterprises Pte Ltd

Dear Victor,

We refer to your below email above matter.

According to our surveyor, Labuor 7 has been taked out. Labour 11 photo no.32 show the engine has been removed.

The labour \$ 1,250.00 consist of replacing Bumper, Bonnet, RH fender and Front support panel. Align & pulling of RH chassis and repair of RH wheel housing. Kindly refer to photo no. 34 - 37 for damage to RH chassis.

View Received Message

This mail is associated with :

***SDY633U (45201784855G)**

OD

Mar 17 2019 10:00AM

[TEO PING SIONG]

Motor Image Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte, Ltd. (AIG_SG), sent on 23/10/2019 16:41 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8025.22) - SDY633U - Claim Handler: Loo, Tong Shing

Approved:8025.22:Labour 7 to take out not necessary. Labour 11 photos required. Why labour of 5 days \$1250 given? Kindly breakdown, Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

View Sent Message

This mail is associated with :

***SDY633U (4520178485SG)**

OD

Mar 17 2019 10:00AM

[TEO PING SIONG]

Motor Image Enterprises Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **21/10/2019 11:22 AM**.
To victor-ck.koh@aig.com
CC sur@lkkauto.com
Subject **Re: Alert - Adj Mandate Approved (S\$7354.90) - SDY633U - Claim Handler: Mohd Zawaye, Norsazani**

Dear Victor,

We refer to your below email above matter.

According to our surveyor, Labuor 7 has been taked out. Labour 11 photo no.32 show the engine has been removed.

The labour \$ 1,250.00 consist of replacing Bumper, Bonnet, RH fender and Front support panel. Align & pulling of RH chassis and repair of RH wheel housing. Kindly refer to photo no. 34 - 37 for damage to RH chassis.

Kindly let us have your mandate approval.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 25/03/2019 09:13 AM

Subject: Alert - Adj Mandate Approved (S\$7354.90) - SDY633U - Claim Handler: Mohd Zawaye, Norsazani

Approved:7354.90:Labour 7 to take out not necessary. Labour 11 photos required. Why labour of 5 days \$1250 given? Kindly breakdown. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Labour 11 photo 32 show engine has been removed.

The labour \$1250.00 consist of replacing Bumper, Bonnet, RH fender and front support panel. Align & pulling of RH chassis and repair of RH wheel housing. Refer to photo 34-37 for damage to RH chassis.

RE: SDY 633 OD (AIG) DOA - 17/03/2019

Ooi Siow Hooi <hooi@motorimage.net>

Fri 4/10/2019 2:22 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; TPV Insurance Team <tpvinsureteam@tanchong.org>

2 attachments (2 MB)

D5CN8885-min.jpg; D5CN8904-min.jpg

Hi Shirley,

5 given for the following:

1. Bumper
2. Bonnet
3. Rh fender
4. Front support panel
5. Right hand chassis repair

Kindly refer to the attached pictures if needed.

Thank You

Best Regards,

Siowhooi

Admin Assistant

Motor Image Enterprises Pte Ltd

19 Toa Payoh Lorong 8, Singapore 319255

Tel: +65-6703 8333 DID: +65-6703 8115

Fax: +65-6253 5535

Email: hooi@motorimage.net

Website: www.tanchong.com : www.motorimage.net

From: Daniel Jude <danieljude@motorimage.net>

Sent: Friday, October 4, 2019 12:04 PM

To: SUR <sur@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; TPV Insurance Team <tpvinsureteam@tanchong.org>; Mohamed Isman <isman@motorimage.net>

Subject: FW: SDY 633 OD (AIG) DOA - 17/03/2019

Importance: High

Hi Shirley,

5 given for the following:

1. Bumper
2. Bonnet
3. Rh fender
4. Front support panel
5. Right hand chassis repair

Kindly refer to the attached pictures if needed.

Thank You.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net

 https://s3-ap-southeast-1.amazonaws.com/mail.motorimage.net/footer-images/sawd_2018.jpg

 https://s3-ap-southeast-1.amazonaws.com/mail.motorimage.net/footer-images/facebook_2017.jpg

 https://s3-ap-southeast-1.amazonaws.com/mail.motorimage.net/footer-images/instagram_2017.jpg

 https://s3-ap-southeast-1.amazonaws.com/mail.motorimage.net/footer-images/youtube_2017.jpg

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

View Received Message

This mail is associated with :

***SDY633U (4520178485SG)**

OD

Mar 17 2019 10:00AM

[TEO PING SIONG]

Motor Image Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 25/03/2019 09:13 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$7354.90) - SDY633U - Claim Handler: Mohd Zawaye, Norsazani

Approved:7354,90:Labour 7 to take out not necessary. Labour 11 photos required. Why labour of 5 days \$1250 given? Kindly breakdown, Re-inspection to be done for damage check and supplementary items / labour,

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 20 Mar 2019

Preliminary Advice

Vehicle No	: SDY633U	Accident Date	: 17/03/2019
Make	: SUBARU FORESTER	Policy No.	: 2100480285-02
Assignment Date	: 20/03/2019	Excess	: S\$0.00
Date of Inspection	: 20/03/2019	Est. Duration of Repair	: 10 days
Inspection At	: Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH Singapore 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,952.71
Revised Amount	:S\$	7,354.90
Check Items (Estimated)	:S\$	2,920.83
Total	:S\$	10,275.73

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	81,000.00
COE / PARF Rebate	:S\$	57,066.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,934.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 20:07
Date Of Accident	17/03/2019 10:00
Exact Location Of Accident	JUNCTION OF ENG NEO AVE & VENDA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDY633U
Insured/Policyholder	
Name Of Registered Owner	TEO PING SIONG
NRIC No	S7045944B
Email Address	CASTLE77@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91739572
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT CVT AWD SR (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL / LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100480285-02
Cover Note Number	

Driver

Name of Driver	TEO PING SIONG
NRIC No	S7045944B
Date Of Birth	22/12/1970
Occupation	INDOOR
Date Of Driving Pass	27/11/1990
Driving Experience	28 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91739572
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	CASTLE77@HOTMAIL.COM

Address	993 BUKIT TIMAH ROAD #04-12
Postcode	589631
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED DOCUMENTS AND VIDEO FOOTAGE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	ELENA
Phone Number	96424126
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR3823Y
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM TOW TONG
NRIC/Passport Number	S0172463J
Contact Number	91707757
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TEO PING SIONG
Approximate Age	
Injuries Sustain	STRAIN AND ACHE IN NECK AND BACK
Injured person in which vehicle?	SDY633U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:


18/13/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: DANIEL JOSE
NIC/TIN No.: 99001518D

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on Eng Neo Ave towards Bukit Timah Road. At the junction with Vanda Road, the traffic light was green in my favour. I was near the junction when the other car (SKR 3823Y) suddenly turned right, and his left side was in my path. I could not stop in time and crashed into the left side of that car.

VEH A : SDY 633U

VEH B : SKR 3823Y

DECLARATION

We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 18/3/19

GAAMAC (Standardised form) V2

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature]

Reporting Officer/Personnel's Signature

Name: DANIEL JUDE

NRIC/ID No.: 97001518D

SILVERCROSS HEALTHCARE PTE LTD
3 CHEONG CHIN NAM ROAD SINGAPORE 599728
TEL: 6875 1191 FAX: 6875 1911

17 March 2019

A&E PHYSICIAN IN ATTENDANCE

SILVERCROSS HEALTHCARE PTE LTD
3 CHEONG CHIN NAM ROAD SINGAPORE 599728
TEL: 6875 1191 FAX: 6875 1911

TEO PING SIONG

368574

993 BUKIT TIMAH ROAD MAPLEWOODS CONDOMINIUM #04-12 S(589631)

Tel : 3885010 / 91739572

NRIC : S7045944B

DOB : 22/12/1970

Gender : M

COM :

Allergy : SULPHUR / AGBACTR

17/3/2019 15:04:33

today RTA about 10am
pt driver in car going straight. seatbelt on.
another vehicle came into his path
pt's front bumper knocked left side of that vehicle

no one died

pt's airbag did not deploy
no shattered glass
pt was jerked forward. no HI/LOC.

since then, ache from lower neck to lower back

no giddy nausea neckstiff bov
no UL/LL numb/weak ; gait ok, no incont
no cp , sob , diaphoresis

o/e: T afab alert nontoxic , tongue moist
cn/neuro/gait/pearl ok
neck AROM full; spine midline nil tender, paravert nil spasm

imp: RTA , neck/back strain
adv red flags, return/A&E if unwell
adv on possibility of late symp appearing

plan:
- MC
- own Anarex
- memo to go hospital if unwell
- to request formal medical report from clinic if need

Silver Cross Family Clinic
3 Cheong Chin Nam Road
Singapore 599728
Tel: 6875 1191 Fax: 6875 1911

Locum

Silvercross Healthcare Pte Ltd



OFFICIAL RECEIPT

Patient ID : 368574

Patient Name : TEO PING SIONG

Attending Dr : Locum

Invoice No. : IN388488

Payment Mode : Credit Card (Visa)

Date Seen : 17/3/2019 (SCBT013175620)

STANDARD CONSULT - SUNDAY	\$43.93
Total Charge :	\$43.93
GST @ 7% :	\$3.08
TOTAL AMOUNT :	\$47.01

**DENTAL SERVICES ALSO AVAILABLE.**

Please call 6732 2237 for appointment or inquiry.

Visit www.healthwaydentalgroup.com for more details.

This is a computer generated document that does not require a signature.

MEDICAL CERTIFICATE

Date : 17/3/2019

Ref No. 013175620

This is to certify that **TEO PING SIONG (NRIC S7045944B)** is UNFIT FOR DUTY for **1** day(s)
from **18/3/2019** to **18/3/2019** inclusive.**LOCUM**
DoctorSilver Cross Family Clinic
3 Cheong Chin Nam Road
Singapore 599728
Tel: 6875 1191 Fax: 6875 1911

Not Valid for Absence from Court Attendance



ISLAND TOWING SERVICES
Blk 3026, Ubi Road 1 #04-146 Singapore 408719
Telephone: 6747 7400 Email: islandrecovery@gmail.com
Facsimile: 6844 7233 Web: www.islandrecovery.com.sg
Co. Reg. 53269210A

Cash Sales/ Work Order
NO. 49780
Date: 17/03/19

M/S: CASH

Vehicle No: SDY 633 U Model: SUBARU FORESTER
From: 993 BUKIT TIMAH RD Time Start: 11:35AM
To: 19 LOR 8 TUA PAHOH Time End:

Remarks:

- | | | |
|--|--|--|
| ☐ Change Tyres / Jump Start | ☒ Accident | ☐ Use Car Carrier |
| ☒ Basement / Multi Carpark | ☐ Crane Up / Winch Out | ☐ Open Door |
| ☒ Using King Dolly | ☐ Dismantle Shaft / Brake | ☐ Loaded |

AMOUNT S\$ 130 k

Received By
Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdeemeanour to your vehicle whilst being transported.

Ym9301H HUAT
Island Recovery Services



CERTIFICATE OF INSURANCE

SUBARU AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Teo Ping Siong
Period of Insurance : 31 Aug 2018 To 30 Aug 2019
Engine No. : FA20A977486
Chassis No. : JF1SJGK85GG075090

Vehicle No. : SDY633U
Policy No. : 2100480285-02
Endorsement No. :
Issued Date : 31 Jul 2018

ABOUT THE COVER

Make/Model : SUBARU
Engine Capacity/Tonnage : 1.998.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 150000 - 160000

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable):

Teo Ping Siong - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Motor Image Enterprises Pte Ltd Add: 10 Lorong 6 Tse Payoh Singapore 219255 64170100

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG 800 Mobile App. Simply search and download "AIG 800" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500619206

TAN CHONG CREDIT SUBARU-TIP
 911 BUKIT TIMAH ROAD
 SINGAPORE 589622

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

J. Tan

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

OTORIMAGE ENTERPRISES PTE. LTD.
9 LORONG 8, TOA PAYOH
SINGAPORE 319255

STIMATE : ACCIDENT/BODY REPAIRS
ORKSHOP : TOA PAYOH
ONTACT NO : 64730333
EREFERENCE : INS/IC/CHI/0109/2019
ATE : 20-MAR-2019

IG ASIA PACIFIC INSURANCE PTE LTD
8 SHENTON WAY
07-16 AIG BUILDING
(079120)
EL : 91007211
AX :
OTOR CLAIM DEPT

WNER'S NAME : TEO PING SIONG
DORESS : 993 BUKIT TIMAH ROAD
#04-12
S(589631)
ELEPHONE NO : 9173 9572

YPE OF CLAIM : COMPREHENSIVE CLAIM
ALICY NO : 2100480285-02
HICLE NO : SDY633U
DEL CODE : SJGCKX8
DEL/YEAR : FORESTER 2.0XT AND CVT
GINE NO : FA20A977486
ASSIS NO : JF1SJKX85GG075090
LEAGE : 1 KM
TE IN : 20/03/2019
ABILITY : 0.00
CESS CLAUSE : 0.00
TIMATE BY : DANIEL A JUDE**
CIDENT DATE : 17/03/2019

int Date : 20/03/2019
int Time : 09:46:12

OTORIMAGE ENTERPRISES PTE. LTD.
9 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDY633U

/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODRECOVERY	TO CONDUCT BODYWORK REPAIR (OWN DAMAGE RECOVERY) AGAINST SKR3823Y		
2	ZZ/001	CONDUCT OD RECOVERY AIG LOCATION:JUNG ENG NEO AVE & VENDA RD DATE:17/03/2019 TIME:1000HRS		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER,FRT BONNET,FRT RH FENDER ,FRT RH DOOR AND PANEL	1750.00	1250/-
4	ZZ/003	RESPRAY FRT BUMPER,FRT BONNET,FRT RH FENDER,FRT RH DOOR AND PANEL	1400.00	1000/-
5	ZZ/004	TRANSFER / BALANCE TYRE / RIM FRT RH WHEEL	28.00	~ 28.00
6	ZZ/005	REMOVE & REFIX AIR CON CONDENSOR & RADIATOR TO FACILITATE REPAIRS	171.00	✓
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	85.00	✓
8	ZZ/007	4 WHEEL ALIGNMENT	171.00	✓
9	ZZ/008	MECHANICAL REPAIRS - ALTERNATOR,COMPRESSOR, STEERING PUMP	171.00	?
10	ZZ/009	REMOVE & REFIX WIRE HARNESS	228.00	?
11	ZZ/011	REMOVE & REINSTALL ENGINE TO FACILITATE REPAIRS	342.00	✓ photo
12	ZZ/012	TO CONDUCT FRONT LIGHTING TEST	28.00	✓
13	ZZ/013	TO CONDUCT PROTECTANT COATING	250.00	200/-
14	ZZ/014	TO CONDUCT ANTI RUST COATING	290.00	250/-
15	ZZ/015	SUNDRIES	100.00	50/-
16	ZZ/016	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	125.00	✓
17	ZZ/10	FAULT DIAGNOSTIC AND RESET SYSTEMS	235.00	?
TOTAL LABOUR CHARGES			5374.00	

STORIMAGE ENTERPRISES PTE. LTD.
1 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY633U

DAMAGED PARTS & PRICES						
NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	DISC WHEEL AL 18 C75	28111SG140			SL	1500.00 X
2	RADIATOR ASSY	45111SG010				810.00 ?
3	FAN	45121FJ000	54.00	?		
4	SHROUD	45122SG000			CM	86.40 ✓
5	MOTOR	45131PG003				272.00 ?
6	HOSE RAD IN	45161SG000				39.60 ?
7	HOSE RAD OUT	45161SG010				28.80 ?
8	PACKING RAD SD	45167SG000				8.70 ?
9	PACKING RAD PNL	45167SG010				72.00 ?
10	DUCT AIR INTAKE	46012YC000				50.40 ?
11	CASE-AIR CLNR UPR	46052SG010				32.40 ?
12	CASE-AIR CLNR LMR	46052SG020				32.40 ?
13	WHEEL AFR FF C RPRH	51610SG1209P			CM	172.80 ✓ ?
14	RAD PNL COMPL RPR	53029SG0019P			RH	360.00 ✓
15	FRT FENDER RH	57120SG0209P			RH	270.00 ✓
16	HOOD F CPL	57229SG0009P			RH	882.00 ✓
17	HINGE COMPL F HD RH	57260SG0009P				43.20 ?
18	LOCK ASSY F HOOD RHD	57310SG000			R	54.00 ?
19	BRKT CORNER F RH	57707SG000			CM	36.00 ✓
20	BRKT CORNER F LH	57707SG010				36.00 ?
21	BRKT SD F RH	57707SG020			CM	12.60 ✓
22	BRKT SD F LH	57707SG030				12.60 ?
23	BUMPER FACE F (FOR HL/W)	57709SG011			CM	594.00 ✓
24	BACK BEAM CPL F	57711SG0009P			RH	288.00 ✓
25	ENERGY ABSOR F	57722SG020			RH	126.00 ✓

STORIMAGE ENTERPRISES PTE. LTD.
1 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY633U

NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
26 COVER HOOK F	SP	57731SG070			Nil	5.40 ✓
27 COVER FOG F SP	RH	57731SG080			Nil	43.20 ✓
28 COVER SD F SP	RH	57731SG120			Nil	12.60 ✓
29 PACKING PAD		57780SG010				9.00 ?
30 MUD GUARD ASSY F RH		59110SG021			CM	86.40 ✓
31 PNL COMPL DR F	RH	60009SG0429P			R	720.00 X
32 HANDLE OUT DR	SMT	61160FJ010E4			Sn	633.60 X
33 WSTR OUT DR F	RH	61280SG020			Sn	100.80 X
34 WSTR DR F LH	USE SG000	63511SG001			Sn	144.00 X
35 GLASSRUN F DR RH		63527SG100			Sn	72.00 X
36 WSTR BODY SD FLG F		63571SG001			Sn	122.40 X
37 CONDENSER ASSY		73210SG011				579.40 ?
38 FAN		73311FJ000				43.20 ?
39 SHROUD		73313SG000				64.80 ?
40 LAMP ASSY HEAD BOF		84002SG222			mgcm	2380.00 ✓
41 FOG LAMP ASSY F		84501AJ060			,	272.00 ?
42 NOZZLE-WINDSHIELD WASHER		86636SG000				115.20 ?
43 NOZZLE COVER ASSTRH		86636SG340TQ			Nil	54.00 ✓
44 NOZZLE H L WASHERRH		86636SG361			Sn	79.20 X
45 TAPE DR SASH F F RH		90422SG000			nn	5.40 X
46 TAPE DR SASH F M RH		90422SG020			nn	18.00 X
47 TAPE DR SASH F R RH		90422SG040			nn	18.00 X
48 INSULATOR HOOD TBH		90815SG061			Sn	36.00 X
49 INSULATOR HOOD TELH		90815SG070			Sn	36.00 X

STORIMAGE ENTERPRISES PTE. LTD.
1 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY633U

			DAMAGED PARTS & PRICES			
NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50	GRILLE ASSY F UPRHG PDI STOCK	91121SG210A			CM 140.40	✓
51	GRILLE ASSY F CTRHG PDI STOCK	91121SG240A			180.00	7
52	GRILLE ASSY F LWRHG PDI STOCK	91121SG280A			316.80	7
53	BKT GRILLE LWR	91165SG010			21.60	7
54	FRONT NUMBER PLATE	WM001		mis	45.00	✓
SUB TOTAL			54.00	0.00	45.00	12129.30
LESS DISCOUNT (NETT-20 % S/LIST-30 %)			10.80	0.00	0.00	3638.79
GRAND TOTAL			43.20	0.00	45.00	8490.51
OVERALL TOTAL			8578.71			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

INGAPORE 319255

MMARY OF ESTIMATE FOR VEHICLE REGN NO SDY633U

TOTAL LABOUR CHARGES	5374.00
TOTAL SPARE PARTS CHARGES	8578.71

AND TOTAL	13952.71 *

All charges do not include GST.

REVEYOR'S PARTICULARS

ME	:	
REVISED DATE	:	
AUTHORIZED DATE	:	
LESS CLAUSE	:	0.00
ABILITY	:	0.00
MARKS	:	

NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not authentic

Resurvey B4 point

10 days

Ex: 62564315

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHL/0109/2019
DATE : 20-MAR-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 BRANTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : TED PINO SIONG
ADDRESS : 993 BUKIT TIMAH ROAD
#04-12
S(589631)
TELEPHONE NO : 9173 9572

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100480285-02
VEHICLE NO : S07633U
MODEL CODE : SJC2888
MODEL/YEAR : FORESTER 2.0XT AND CVT
ENGINE NO : Y620A977486
CHASSIS NO : JF18JCH85G0075090
MILEAGE : 1 KM
DATE IN : 20/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE
ACCIDENT DATE : 17/03/2019

Print Date : 20/03/2019
Print Time : 09:46:12

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SUT633U

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RECOVERY TO CONDUCT BODYWORK REPAIR (OWN DAMAGE RECOVERY) AGAINST 6833623Y		
2 ZZ/001	CONDUCT ON RECOVERY AID LOCATION: JUNG KING WED AVE & VERGA RD DATE: 17/03/2019 TIME: 1000HRS		
3 ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT BONNET, FRT RE FENDER, FRT RH DOOR AND PANEL	1750.00	1250/-
4 ZZ/003	RESPRAY FRT BUMPER, FRT BONNET, FRT RH FENDER, FRT RH DOOR AND PANEL	1400.00	1000/-
5 ZZ/004	TRANSFER / BALANCE TYRE / RIM FRT RH WHEEL	28.00	✓
6 ZZ/005	REMOVE & REFLX AIR CON CONDENSOR & RADIATOR TO FACILITATE REPAIRS	171.00	✓
7 ZZ/006	TO CONDUCT WATER SKEEPAE TEST	85.00	✓
8 ZZ/007	4 WHEEL ALIGNMENT	171.00	✓
9 ZZ/008	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	171.00	✓
10 ZZ/009	REMOVE & REFLX WIRE HARNESS	228.00	✓
11 ZZ/011	REMOVE & REINSTALL ENGINE TO FACILITATE REPAIRS	342.00	✓
12 ZZ/012	TO CONDUCT FRONT LIGHTING TEST	28.00	✓
13 ZZ/013	TO CONDUCT PROTECTANT COATING	250.00	200/-
14 ZZ/014	TO CONDUCT ANTI RUST COATING	290.00	250/-
15 ZZ/015	SUNDRIES	100.00	50/-
16 ZZ/016	REMOVE/REFIX FRT HEADLAMP WASHIER AND PIPING	125.00	✓
17 ZZ/10	FAULT DIAGNOSTIC AND RESET SYSTEMS	235.00	✓

TOTAL LABOUR CHARGES

5374.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TUA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGD NO SUT635U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 DISC WHEEL AL 18 C75	28111B0140			<i>Sn</i> 1500.00	X
2 RADIATOR ASSY	45111S0010			<i>Sn</i> 810.00	X
3 FAN	45121F0000	<i>Sn</i> 34.00	X		
4 SERVOID	45122S0000			<i>CM</i> 86.40	✓
5 MOTOR	45131F0003			272.00	✓
6 HOSE RAD IN	45161B0000			39.60	✓
7 HOSE RAD OUT	45161B0010			28.80	✓
8 PACKING RAD SD	45167B0000			8.70	✓
9 PACKING RAD FHL	45167B0010			72.00	✓ <i>Sn</i> X
10 DUCT AIR INTAKE	46012YC000			50.40	✓
11 CASE-AIR CLNR UPR	46052B0010			32.40	✓
12 CASE-AIR CLNR LMR	46052B0020			32.40	✓
13 WHEEL APR FF C RPHH	51610B01209P			<i>Sn</i> CM 172.80	<i>Sn</i> X
14 RAD FHL COMPL RPH	53028B00019P			<i>Sn</i> 360.00	✓
15 FRT FENDER RH	57120B00209P			<i>R</i> 270.00	✓
16 HOOD F CPL	57228B00009P			<i>Sn</i> 882.00	✓
17 HINGE COMPL F HD RH	57260B00009P			<i>R</i> 43.20	X
18 LOCK ASSY F HOOD RHD	57310B0000			<i>R</i> 34.00	X
19 BRKT CORNER F RH	57707B0000			<i>CM</i> 36.00	✓
20 BRKT CORNER F LH	57707B0010			<i>Sn</i> 36.00	X
21 BRKT SD F RH	57707B0020			<i>CM</i> 12.60	✓
22 BRKT SD F LH	57707B0030			<i>Sn</i> 12.60	X
23 BUMPER FACE F (FOR HL/W)	57709B0011			<i>CM</i> 594.00	✓
24 BACK BEAM CPL F	57711B00009P			<i>R</i> 288.00	✓
25 TENSILE ARMOR F	57722B0020			<i>R</i> 126.00	✓

MYSTIC IMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY633U

P/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
26	COVER HOOK F SP	5773180070			MSY 5.40	✓
27	COVER FOG F SP RH	5773180080			MSY 43.20	✓
28	COVER SD F SP RH	5773180120			MSY 12.50	✓
29	PACKING PAD	5778080010			SM 9.00	X
30	MID GUARD ASSY F RH	5911080021			CM 86.40	✓
31	PNL COMPL DR F RH	80009600429P			R 720.00	X
32	HANDLE OUT DR BMT	611607J01084			SM 633.60	X
33	WSTR OUT DR F RH	6128080020			SM 100.80	X
34	WSTR DR F LH	USE 80000 6351180001			SM 144.00	X
35	GLASSWIN F DR RH	6352780100			SM 72.00	X
36	WSTR BODY SD FLG F	6357180001			SM 122.40	X
37	CONDENSER ASSY	7321080011			SM 579.40	X
38	FAH	733118J000			SM 43.20	X
39	SHROUD	7331380000			CM 64.80	✓
40	LAMP ASSY HEAD LOF	8400280222			MYGENT 2380.00	✓
41	FOG LAMP ASSY F	84501A7060			SM 272.00	X
42	NOZZLE-WINDSHIELD WASHER	8663680000			SM 115.20	X
43	NOZZLE COVER ASSYRH	86636803407Q			MSY 34.00	✓
44	NOZZLE B L WASHERRH	8663680341			SM 79.20	X
45	TAPE DR SASH F F RH	9042280000			RM 5.40	X
46	TAPE DR SASH F M RH	9042280020			RM 18.00	X
47	TAPE DR SASH F R RH	9042280040			RM 18.00	X
48	INSULATOR HOOD TIRH	9081580041			SM 36.00	X
49	INSULATOR HOOD TIRH	9081580070			SM 36.00	X

HYDORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TDA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO HDY633U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
50 GRILLE ASSY F UPPER	FOI STOCK 911218Q210A			674	140.40 ✓
51 GRILLE ASSY F CTR	FOI STOCK 911218Q240A			52	180.00 ✗
52 GRILLE ASSY F LWR	FOI STOCK 911218Q280A			52	316.80 ✗
53 INT GRILLE LNR	911636G010			52	21.60 ✗
54 FRONT NUMBER PLATE	WM001			117	45.00 ✓
SUB TOTAL		54.00	0.00	45.00	12129.30
LESS DISCOUNT (NETT-20 % S/LIST-30 %)		10.80	0.00	0.00	3638.79
GRAND TOTAL		43.20	0.00	45.00	8490.51
OVERALL TOTAL		8578.71			

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDY633U

TOTAL LABOUR CHARGES	5374.00
TOTAL SPARE PARTS CHARGES	8578.71
GRAND TOTAL	13952.71 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

DATE	
SURVEYED DATE	
UTILIZED DATE	
EXCESS CHARGE	0.00
LIABILITY	0.00
REMARKS	

14488.47

Not Authorized
Resurvey B4 paint
10 days



Fax: 6256 4315

MV
811c

LS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

14533 62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Motor Image Enterprises Pte Ltd
19 Loring 8 Ton Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SDY 6330

Surveyor: _____

DESCRIPTION	PART NO	AMOUNT
1 <u>CUSHION RUBBER - TRANSMISSION B</u>	<u>41022YC000</u>	<u>CRA \$108.00</u>
2 _____	_____	_____
3 _____	_____	_____
4 <u>HOSE ASSEMBLY - CRUISER - UPPER</u>	<u>86655SG150</u>	<u>Cut \$14.80</u>
5 _____	_____	_____
6 _____	_____	_____
7 _____	_____	_____
8 _____	_____	_____
9 _____	_____	_____
10 _____	_____	_____
11 _____	_____	_____
12 _____	_____	_____
13 _____	_____	_____
14 _____	_____	_____
15 _____	_____	_____
16 _____	_____	_____
17 _____	_____	_____
18 _____	_____	_____
19 _____	_____	_____
20 _____	_____	_____
21 _____	_____	_____
22 _____	_____	_____
23 _____	_____	_____
24 _____	_____	_____
25 _____	_____	_____

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

MotorIn



Motor Image Enterprises Pte Ltd
19 Lorong 8 Teo Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SDY-633-U

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1 REPAIR FRONT. LHS. FRAME ☒ \$ 250 ^

2 REPAIR. FRONT. RHS FRAME ☒ \$ 200 ^

3 _____

4 _____

5 _____

6 _____

7 _____

8 _____

9 _____

10 _____

11 _____

12 _____

Motor Image Consultants hence notify
the Repairer of the following:

- To complete labour after survey relating
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0109/2019
DATE : 25-MAR-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : TEO PING SIONG
ADDRESS : 993 BUKIT TIMAH ROAD
#04-12
S(589631)
TELEPHONE NO : 9173 9572

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100480285-02
VEHICLE NO : SDY633U
MODEL CODE : SJGKXK8
MODEL/YEAR : FORESTER 2.0XT AND CVT
ENGINE NO : FA2CA977486
CHASSIS NO : JF1SJKR8500075090
MILEAGE : 59620 KM
DATE IN : 25/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 17/03/2019

Print Date : 23/10/2019
Print Time : 14:45:29

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO 50Y633U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	00000000	TO CONDUCT BODYWORK REPAIR (OWN DAMAGE RECOVERY) AGAINST SER3823Y		
2	ZZ/001	CONDUCT OD RECOVERY AT LOCATION: JUNG ENG NEO AVE & VENDA RD DATE: 17/03/2019 TIME: 1000HRS		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT BONNET, FRT RH FENDER, FRT RH DOOR AND PANEL	1750.00	1250.00
4	ZZ/003	RESPRAY FRT BUMPER, FRT BONNET, FRT RH FENDER, FRT RH DOOR AND PANEL	1400.00	1000.00
5	ZZ/004	TRANSFER / BALANCE TYRE / RIM FRT RH WHEEL	28.00	.00
6	ZZ/005	REMOVE & REFIX AIR CON CONDENSOR & RADIATOR TO FACILITATE REPAIRS	171.00	171.00
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	85.00	.00
8	ZZ/007	4 WHEEL ALIGNMENT	171.00	171.00
9	ZZ/008	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	171.00	.00
10	ZZ/009	REMOVE & REFIX WIRE HARNESS	228.00	228.00
11	ZZ/011	REMOVE & REINSTALL ENGINE TO FACILITATE REPAIRS	342.00	342.00
12	ZZ/012	TO CONDUCT FRONT LIGHTING TEST	28.00	28.00
13	ZZ/013	TO CONDUCT PROTECTANT COATING	250.00	200.00
14	ZZ/014	TO CONDUCT ANTI RUST COATING	290.00	250.00
15	ZZ/015	SUNDRIES	100.00	50.00
16	ZZ/016	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	125.00	125.00
17	ZZ/017	REPAIR FRONT RHS FRAME (SUPP)	250.00	.00
18	ZZ/018	RESPRAY FRONT RHS FRAME (SUPP)	200.00	.00
19	ZZ/10	FAULT DIAGNOSTIC AND RESET SYSTEMS	235.00	235.00
TOTAL LABOUR CHARGES			5824.00	4050.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO S07633U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	DISC WHEEL AL 18 C75	28111SG140			1500.00	X
2	CUSHION RUB R (SUPP)	41022YC000			108.00	OK
3	RADIATOR ASSY	45111SG010			810.00	X
4	PAM	45121FJ000	54.00			X
5	SERVOID	45122SG000			86.40	OK
6	MOTOR	45131FG003			272.00	X
7	HOSE RAD IN	45161SG000			39.60	X
8	HOSE RAD OUT	45161SG010			28.80	X
9	PACKING RAD SD	45167SG000			8.70	X
10	PACKING RAD PNL	45167SG010			72.00	X
11	DOCT AIR INTAKE	46012YC000			50.40	X
12	CASE-AIR CLNR UPR	46052SG010			32.40	X
13	CASE-AIR CLNR LMR	46052SG020			32.40	X
14	WHEEL AFR FF C RPRH	51610SG1209P			172.80	X
15	RAD PNL COMPL RPR	53029SG0019P			360.00	OK
16	FRT FENDER RH	57120SG0209P			270.00	OK
17	HOOD F CPL	57229SG0009P			882.00	OK
18	HINGE COMPL F HD RH	57260SG0009P			43.20	X
19	LOCK ASSY F HOOD RH	57310SG000			54.00	X
20	BRKT CORNER F RH	57707SG000			36.00	OK
21	BRKT CORNER F LH	57707SG010			36.00	X
22	BRKT SD F RH	57707SG0020			12.60	OK
23	BRKT SD F LH	57707SG0030			12.60	X
24	BUMPER FACE F (FOR HL/W)	57709SG011			594.00	OK
25	BACK BEAM CPL F	57711SG0009P			288.00	OK

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 ENERGY ABSOR F	57722SG020			126.00	OK
27 COVER BOOK F SP	57731SG070			5.40	OK
28 COVER FOG F SP RH	57731SG080			43.20	OK
29 COVER SD F SP RH	57731SG120			12.60	OK
30 PACKING RAD	57780SG010			9.00	X
31 MUD GUARD ASSY F RH	59110SG021			86.40	OK
32 FHL COMPL DR F RH	60009SG0429P			720.00	X
33 HANDLE OUT DR SHT	61160FJ010E4			633.60	X
34 WSTR OUT DR F RH	61280SG020			100.80	X
35 WSTR DR F LH	USE SC000 63511SG001			144.00	X
36 GLASSRUN F DR RH	63527SG100			72.00	X
37 WSTR BODY SD FLG F	63571SG001			122.40	X
38 CONDENSER ASSY	73210SG011			579.40	X
39 FAN	73311FJ000			43.20	X
40 SHROUD	73313SG000			64.80	OK
41 LAMP ASSY HEAD EOF	84002SG222			2380.00	OK
42 FOG LAMP ASSY F	84501AJ060			272.00	X
43 NOZZLE-WINDSHIELD WASHER	86636SG000			115.20	X
44 NOZZLE COVER ASSYRH	86636SG340TQ			54.00	OK
45 NOZZLE H L WASHERRH	86636SG361			79.20	X
46 HOSE ASSY H/L WAS (SUPP)	86655SG150			64.80	OK
47 TAPE DR SASH F F RH	90422SG000			5.40	X
48 TAPE DR SASH F M RH	90422SG020			18.00	X
49 TAPE DR SASH F R RH	90422SG040			18.00	X

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
50	INSULATOR HOOD TRH	90815G0061				36.00	X
51	INSULATOR HOOD TELH	90815G0070				36.00	X
52	GRILLE ASSY F UPENG	FDI STOCK 911219G210A				140.40	OK
53	GRILLE ASSY F CTENG	FDI STOCK 911219G240A				180.00	X
54	GRILLE ASSY F LWRG	FDI STOCK 911219G280A				316.80	X
55	EXT GRILLE LMR	91165G0010				21.60	X
56	FRONT NUMBER PLATE	WM001			45.00		OK
SUB TOTAL			0.00	0.00	45.00	5614.60	
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	1684.38	
GRAND TOTAL			0.00	0.00	45.00	3930.22	
OVERALL TOTAL			3975.22				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255


SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SDY633U

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	45.00
S/LIST ITEM	5614.60
LESS 30 %	-1684.38
S/LIST AMOUNT	3930.22
TOTAL LABOUR CHARGES	4050.00
TOTAL SPARE PARTS CHARGES	3975.22
TOTAL CHARGES	8025.22
ADD 7 % GST	561.77
GRAND TOTAL	8586.99

MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R001193
 Name 2: TEO PING SIONG
 Company: 993 BUKIT TIMAH ROAD
 License: SDY633U
 Year: 16
 Technician: KUGAN
 Odometer: 59611
 Date: 5.4.19 14:59

Subaru : Forester : 2016-18 (SJ)
4-Wheel Total Alignment



All diagnosis code

TEL:

FAX:

Employee. In charge:

E-mail:

Date and time: 4/10/2019 8:53:15 AM

Vehicle: Forester

VIN: JF1SJGK85GG075090

Model: 16MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			07249	450200	Current		
Past	P1604	Startability Malfunction	07218	7100	ommo		**

<Transmission : 0 piece>

<Brake Control : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			07249	450200	Current		
Past	C1721	Yaw Rate Sensor	07207	689500	ommo		**

<Body Control : 0 piece>

<Airbag : 0 piece>

<Brake Vacuum Pump : 0 piece>

<Power Steering : 0 piece>

All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 4/10/2019 8:59:28 AM

Vehicle: Forester

VIN: JF1SJGK85GG075090

Model: 16MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Brake Vacuum Pump : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			07250	20100	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535
25 Leng Kee Road Singapore 159097
Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L506999

**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**

DATE REC'D: 25-Mar-2019

SERVICE ADVISOR: H001

JOB No.: L498706

MILEAGE: 59620

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. 5(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0XT AWD CVT
ENGINE No.: FA20A977486
CHASSIS No.: JF15JGK85GG075090
REGISTRATION No.: SDY633U

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
1 ODRCO	TO CONDUCT BODYWORK REPAIR (OWN DAMAGE RECOVERY) AGAINST SKR3823Y	
2 REMARK	CONDUCT OD RECOVERY AIG LOCATION:JUNC ENG NEO AVE & VENDA RD DATE:17/03/2019 TIME:1000HRS	
3 INS01	FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
4 INS02	IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
5 INS03	STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
6 INS04	SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
7 INS05	INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
8 INS06	THE OWNER IS REQUIRED.	
9 INS07	CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
10 INS08	NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
11 INS09	CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
12 REMARK	REPAIR/REPLACE FRT BUMPER,FRT BONNET,FRT RH FENDER ,FRT RH DOOR & PANEL	1,250.00
13 REMARK	RESPRAY FRT BUMPER,FRT BONNET,FRT RH FENDER,FRT RH DOOR & PANEL	1,000.00
14 REMARK	REMOVE & REFIX AIRCOND CONDENSOR & RADIATOR TO FACILITATE REPAIRS	171.00
15 REMARK	TO CONDUCT 4 WHEEL ALIGNMENT	171.00
16 REMARK	REMOVE & REFIX WIRE HARNESS	228.00

Certified True Copy



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel (65) 64170100/101 Fax (65) 62535535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel (65) 64764776 Fax (65) 64791137
 Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L506999

**For cash sales, payment will be
 endorsed on this invoice and no
 separate receipt will be issued.**

DATE REC'D: 25-Mar-2019

SERVICE ADVISOR: HOOI

JOB No.: L498706

MILEAGE: 59620

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0XT AWD CVT
ENGINE No.: FA20A977486
CHASSIS No.: JF1SJGK85GG075090
REGISTRATION No.: SDY633U

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
17	REMARK REMOVE & REINSTALL ENGINE TO FACILITATE REPAIRS	342.00
18	REMARK TO CONDUCT FRONT LIGHTING TEST	28.00
19	REMARK TO CONDUCT PROTECTANT COATING	200.00
20	REMARK TO CONDUCT ANTI RUST COATING	250.00
21	REMARK SUNDRIES	50.00
22	REMARK REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	125.00
23	REMARK FAULT DIAGNOSTIC & RESET SYSTEMS	235.00
	TOTAL(LABOUR)	4,050.00
1	CUSHION RUB R	75.60
	41022YC000(Qty : 1 @ 108.00 each(Discount 30.00%))	
2	SHROUD	60.48
	45122SG000(Qty : 1 @ 86.40 each(Discount 30.00%))	
3	RAD PNL COMPL RPR	252.00
	53029SG0019P(Qty : 1 @ 360.00 each(Discount 30.00%))	
4	FRT FENDER RH	189.00
	57120SG0209P(Qty : 1 @ 270.00 each(Discount 30.00%))	
5	HOOD F CPL	617.40
	57229SG0009P(Qty : 1 @ 882.00 each(Discount 30.00%))	
6	BRKT CORNER F RH	25.20
	57707SG000(Qty : 1 @ 36.00 each(Discount 30.00%))	
7	BRKT SD F RH	8.82
	57707SG020(Qty : 1 @ 12.60 each(Discount 30.00%))	
8	BUMPER FACE F (FOR HL/W)	415.80
	57709SG011(Qty : 1 @ 594.00 each(Discount 30.00%))	
9	BACK BEAM CPL F	201.60
	57711SG0009P(Qty : 1 @ 288.00 each(Discount 30.00%))	
10	ENERGY ABSOR F	88.20
	57722SG020(Qty : 1 @ 126.00 each(Discount 30.00%))	

Certified True Copy

**Motor Image Enterprises Pte Ltd**

19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net

**TAX INVOICE**

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L506999

For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.

DATE REC'D: 25-Mar-2019

SERVICE ADVISOR: HOOI

JOB No.: L498706

MILEAGE: 59620

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING, S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0XT AWD CVT
ENGINE No.: FA20A977486
CHASSIS No.: JF1SJGK85GG075090
REGISTRATION No.: SDY633U

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
11	COVER HOOK F SP 57731SG070(Qty : 1 @ 5.40 each(Discount 30.00%))	3.78
12	COVER FOG F SP RH 57731SG080(Qty : 1 @ 43.20 each(Discount 30.00%))	30.24
13	COVER SD F SP RH 57731SG120(Qty : 1 @ 12.60 each(Discount 30.00%))	8.82
14	MUD GUARD ASSY F RH 59110SG021(Qty : 1 @ 86.40 each(Discount 30.00%))	60.48
15	SHROUD 73313SG000(Qty : 1 @ 64.80 each(Discount 30.00%))	45.36
16	LAMP ASSY HEAD E0F 84002SG222(Qty : 1 @ 2380.00 each(Discount 30.00%))	1,666.00
17	NOZZLE COVER ASSYRH 86636SG340TQ(Qty : 1 @ 54.00 each(Discount 30.00%))	37.80
18	HOSE ASSY H/L WAS 86655SG150(Qty : 1 @ 64.80 each(Discount 30.00%))	45.36
19	GRILLE ASSY F UPRHG 91121SG210A(Qty : 1 @ 140.40 each(Discount 30.00%))	98.28
20	FRONT NUMBER PLATE WM001(Qty : 1 @ 45.00 each)	45.00
TOTAL(SPARE PARTS)		3,975.22

Subtotal 8,025.22
GST(7%) 561.77
TOTAL \$8,586.99

DATE : 18-Nov-2019

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
T (05) 6417 0333 F (65) 6252 5655
W www.motorimage.net
Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured: TEO PING SIONG
Address of Insured: 993 BUKIT TIMAH ROAD #04-12 S(589631)
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP
Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225
Place of Accident: JUNCTION ENG NEO AVE & VENDA ROAD
Date of Accident: 17/03/2019 Vehicle No: SDY633U
Policy No: 2100480285-02 Claim No: _____

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of AIG ASIA PACIFIC INSURANCE PTE LTD settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.

I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:



Company's Chop & Signature

INSURED:



IC No. & Signature/Company's Chop **S7045944B**

DANIEL A JUDE

Name

11/04/2019

Date

TEO PING SIONG

Name

11/04/2019

Date

MotorImage

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Mar 2019		20 Mar 2019 12:40 Edit Adj Rpt	\$58,025.22 Edit Estimates	\$58,025.22 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TEO PING SIONG, ID: S7045944B, Tel: +6591739572, Email: CASTLE77@HOTMAIL.COM								
Vehicle Reg. No.:	SDY633U	Date of Loss:	17/03/2019 10:00 - :59 [30 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4520178485SG	Policy/Cover Note No.:	2100480285 (Comprehensive)						
		Excess:	\$0.00						
Repairer:	Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH, 319255 Toa Payoh - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/03/2019]								
Driver/Custodian:	TEO PING SIONG (48 / Male), NRIC: S7045944B, Tel: +6591739572 Email: CASTLE77@HOTMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (23/10/2019): Alert - Adj Mandate Approved (\$58025.22) - SDY633U - Claim Handler: Loo, Tong Sh... - AIG_SG (25/03/2019): Alert - Adj Mandate Approved (\$57354.90) - SDY633U - Claim Handler: Mohd Zawaye,... - AIG_SG (21/03/2019): SDY633U / OD / 17/03/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDY633U (4520178485SG)
 OD
 Mar 17 2019 10:00AM
 [TEO PING SIONG]
 Motor Image Enterprises Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
Video						1 per page v	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		Thumbnail	Print		
1	18/03/19 20:19	Video - Accident [Linked Accident Report Documents]		Load MP4			
2	18/03/19 20:19	Video - Accident [Linked Accident Report Documents]		Load MP4			
Assessment Reports						1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/03/19 13:44	Adjuster Immediate Advice		Load HTML			
Photos/Images						3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	21/03/19 10:45	General View		Load JPG	☒		
2	21/03/19 10:45	General View		Load JPG	☒		
3	21/03/19 10:45	General View		Load JPG	☒		
4	21/03/19 10:45	General View		Load JPG	☒		
5	21/03/19 10:45	General View		Load JPG	☒		
6	21/03/19 10:45	General View		Load JPG	☒		
7	21/03/19 10:45	General View		Load JPG	☒		
8	21/03/19 10:45	General View		Load JPG	☒		
9	21/03/19 10:45	General View		Load JPG	☒		
10	21/03/19 10:45	General View		Load JPG	☒		
11	21/03/19 10:45	General View		Load JPG	☒		
12	21/03/19 10:45	General View		Load JPG	☒		
13	21/03/19 10:45	General View		Load JPG	☒		
14	21/03/19 10:45	General View		Load JPG	☒		
15	21/03/19 10:45	General View		Load JPG	☒		
16	21/03/19 10:45	General View		Load JPG	☒		
17	21/03/19 10:45	General View		Load JPG	☒		
18	21/03/19 10:45	General View		Load JPG	☒		
19	21/03/19 10:45	General View		Load JPG	☒		
20	21/03/19 10:45	General View		Load JPG	☒		
21	21/03/19 10:45	General View		Load JPG	☒		
22	21/03/19 10:45	General View		Load JPG	☒		
23	21/03/19 10:45	General View		Load JPG	☒		
24	21/03/19 10:45	General View		Load JPG	☒		
25	21/03/19 10:45	General View		Load JPG	☒		
26	21/03/19 10:45	General View		Load JPG	☒		
27	21/03/19 10:45	General View		Load JPG	☒		
28	21/03/19 10:45	Odometer Reading		Load JPG	☒		
29	21/03/19 10:45	General View		Load JPG	☒		
30	21/03/19 10:45	Chassis Number		Load JPG	☒		
31	21/03/19 10:45	General View		Load JPG	☒		
32	05/09/19 09:15	Reinspection Photo		Load JPG	☒		
33	05/09/19 09:15	Reinspection Photo		Load JPG	☒		
34	05/09/19 09:15	Reinspection Photo		Load JPG	☒		
35	05/09/19 09:15	Reinspection Photo		Load JPG	☒		
36	05/09/19 09:15	Reinspection Photo		Load JPG	☒		

Video			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
37	05/09/19 09:15	Reinspection Photo		☒
38	05/09/19 09:15	Reinspection Photo		☒
39	05/09/19 09:15	Reinspection Photo		☒
40	05/09/19 09:17	Reinspection Photo		☒
41	05/09/19 09:17	Reinspection Photo		☒
42	05/09/19 09:17	Reinspection Photo		☒
43	18/10/19 09:28	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/19 13:47	ESTIMATE .pdf		☒
2	21/03/19 17:07	DRIVING & CI.pdf		☒
3	21/03/19 17:07	SDY 633U GIA.pdf		☒
4	18/10/19 09:28	ESTIMATE & SUPP MARKED.pdf		☒
5	23/10/19 15:23	ESTIMATE & SUPP MARKED 1.pdf		☒
6	22/11/19 08:16	Workshop Invoice		☒
7	22/11/19 08:16	Discharge Voucher		☒

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	18/03/19 20:19	Video - Accident		☒
2	18/03/19 20:19	Video - Accident		☒
Assessment Reports			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	18/03/19 20:22	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	18/03/19 20:18	Accident Photo		☒
2	18/03/19 20:18	Accident Photo		☒
3	18/03/19 20:18	Accident Photo		☒
4	18/03/19 20:18	Accident Photo		☒
5	18/03/19 20:18	Accident Photo		☒
6	18/03/19 20:18	Accident Photo		☒
7	18/03/19 20:18	Accident Photo		☒
8	18/03/19 20:18	Accident Photo		☒
9	18/03/19 20:18	Accident Photo		☒
10	18/03/19 20:18	Accident Photo		☒
11	18/03/19 20:18	Accident Photo		☒
12	18/03/19 20:18	Accident Photo		☒
13	18/03/19 20:18	Accident Photo		☒
14	18/03/19 20:18	Accident Photo		☒
15	18/03/19 20:18	Accident Photo		☒
16	18/03/19 20:18	Accident Photo		☒
17	18/03/19 20:18	Accident Photo		☒
18	18/03/19 20:18	Accident Photo		☒
19	18/03/19 20:18	Accident Photo		☒
20	18/03/19 20:18	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	18/03/19 20:21	Accident Sketch Plan		☒
2	18/03/19 20:21	Accident Sketch Plan		☒
3	18/03/19 20:21	OWNER LICENSE AND NRIC		☒
4	18/03/19 20:21	INSURANCE CERT		☒
5	18/03/19 20:21	MEDICAL		☒

Video			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
				☒
6	18/03/19 20:21	MEDICAL	 Load JPG	☒
7	18/03/19 20:21	TOWING SLIP	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19005017/KSD3E2

Date: 22/11/2019

REFERENCE

Insured/Claimant: TEO PING SIONG Policy No: 2100480285
Date of Loss: 17/03/2019 Nature of Claim: OD Claim No: 4520178485SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDY633U**
Make & Model: SUBARU FORESTER, 2.0 XT CVT AWD SR (A) Engine No: FA20A977486
Reg. Date: 31/08/2016 (Man. Year: 2016) Chassis No: JF1SJGK85GG075090
Colour: Metallic Silver Odometer: 59610 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$81,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm
Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,799.67	4,025.22	4,774.45	54.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,724.00	4,000.00	1,724.00	30.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,523.67	8,025.22	6,498.45	44.74
+ GST 7.00/7.00% (S\$)	1,016.66	561.77	454.89	44.74
Nett Amount (S\$)	15,540.33	8,586.99	6,953.34	44.74

INSPECTION

Date of Assignment: 20/03/2019
Date Inspected: 20/03/2019 Inspected At: Motor Image Enterprises Pte Ltd (HQ)
19 LORONG 8 TOA PAYOH
Singapore 319255
Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*DISC WHEEL AL 18 C75	Serviceable	1,500.00 FL	*- FL
3	1		*RADIATOR ASSY	Serviceable	810.00 FL	*- FL
4	1		*FAN	Serviceable	54.00 FN	*- FN
5	1		*SHROUD	Cracked	86.40 FL	*86.40 FL
6	1		*MOTOR	Serviceable	272.00 FL	*- FL
7	1		*HOSE RAD OUT	Serviceable	28.80 FL	*- FL
8	1		*PACKING RAD SD	Serviceable	8.70 FL	*- FL
9	1		*PACKING RAD PNL	Serviceable	72.00 FL	*- FL
10	1		*DUCT AIR INTAKE	Serviceable	50.40 FL	*- FL
11	1		*CASE-AIR CLNR UPR	Serviceable	32.40 FL	*- FL
12	1		*CASE-AIR CLNR LWR	Serviceable	32.40 FL	*- FL
13	1		*WHEEL APR FF C RPRH	Serviceable	172.80 FL	*- FL
14	1		*RAD PNL COMPL RPR	Buckled	360.00 FL	*360.00 FL
15	1		*FRT FENDER RH	Bent	270.00 FL	*270.00 FL
16	1		*HOOD F CPL	Buckled	882.00 FL	*882.00 FL
17	1		*HINGE COMPL F HD RH	Repair	43.20 FL	*- FL
18	1		*LOCK ASSY F HOOD RHD	Repair	54.00 FL	*- FL
19	1		*BRKT CORNER F RH	Cracked	36.00 FL	*36.00 FL
20	1		*BRKT CORNER F LH	Serviceable	36.00 FL	*- FL
21	1		*BRKT SD F RH	Cracked	12.60 FL	*12.60 FL
22	1		*BRKT SD F LH	Serviceable	12.60 FL	*- FL
23	1		*BUMPER FACE F (FOR HL/W)	Cracked	594.00 FL	*594.00 FL
24	1		*BACK BEAM CPL F	Bent	288.00 FL	*288.00 FL
25	1		*ENERGY ABSOR F	Bent	126.00 FL	*126.00 FL
26	1		*COVER HOOK F SP	Missing	5.40 FL	*5.40 FL
27	1		*COVER FOG F SP RH	Missing	43.20 FL	*43.20 FL
28	1		*COVER SD F SP RH	Missing	12.60 FL	*12.60 FL
29	1		*PACKING PAD	Serviceable	9.00 FL	*- FL
30	1		*MUD GUARD ASSY F RH	Cracked	86.40 FL	*86.40 FL
31	1		*PNL COMPL DR F RH	Repair	720.00 FL	*- FL
32	1		*HANDLE OUT DR SMT	Serviceable	633.60 FL	*- FL
33	1		*WSTR OUT DR F RH	Serviceable	100.80 FL	*- FL
34	1		*WSTR DR F LH	Serviceable	144.00 FL	*- FL
35	1		*GLASSRUN F DR RH	Serviceable	72.00 FL	*- FL
36	1		*WSTR BODY SD FLG F	Serviceable	122.40 FL	*- FL
37	1		*CONDENSER ASSY	Serviceable	579.40 FL	*- FL
38	1		*FAN	Serviceable	43.20 FL	*- FL
39	1		*SHROUD	Cracked	64.80 FL	*64.80 FL
40	1		*LAMP ASSY HEAD E0F	Mtg Cracked	2,380.00 FL	*2,380.00 FL
41	1		*FOG LAMP ASSY F	Serviceable	272.00 FL	*- FL
42	1		*NOZZLE-WINDSHIELD WASHER	Serviceable	115.20 FL	*- FL
43	1		*NOZZLE COVER ASSYRH	Missing	54.00 FL	*54.00 FL
44	1		*NOZZLE H L WASHERRH	Serviceable	79.20 FL	*- FL
45	1		*TAPE DR SASH F F RH	Not Necessary	5.40 FL	*- FL
46	1		*TAPE DR SASH F M RH	Not Necessary	18.00 FL	*- FL
47	1		*TAPE DR SASH F R RH	Not Necessary	18.00 FL	*- FL
48	1		*INSULATOR HOOD TBRH	Serviceable	36.00 FL	*- FL
49	1		*INSULATOR HOOD TBLH	Serviceable	36.00 FL	*- FL
50	1		*GRILLE ASSY F UPRHG	Cracked	140.40 FL	*140.40 FL
51	1		*GRILLE ASSY F CTRHG	Serviceable	180.00 FL	*- FL
52	1		*GRILLE ASSY F LWRHG	Serviceable	316.80 FL	*- FL
53	1		*BKT GRILLE LWR	Serviceable	21.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRONT NUMBER PLATE	Missing	45.00 FS	*45.00 FS
55	1		*CUSHION RUBBER-TRANSMISSION B	Cracked	108.00 FL	*108.00 FL
56	1		*HOSE ASSEMBLY - WASHER UPPER	Cut	64.80 FL	*64.80 FL
57	1		*HOSE RAD IN	Serviceable	39.60 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	12,501.10	5,709.60
- List Item Discount on L Items 30.00/30.00% (S\$)	3,690.63	1,684.38
- Nett Item Discount on N Items 20.00/20.00% (S\$)	10.80	0.00
Total Parts (S\$)	8,799.67	4,025.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE FRT BUMPER, FRT BONNET, FRT RH FENDER, FRT RH DOOR AND PANEL	New	1,750.00	1,250.00
2	RESPRAY FRT BUMPER, FRT BONNET, FRT RH FENDER, FRT RH DOOR AND PANEL	New	1,400.00	1,000.00
3	TRANSFER / BALANCE TYRE / RIM FRT RH WHEEL	New	28.00	0.00
4	REMOVE & REFIX AIR CON CONDENSOR & RADIATOR TO FACILITATE REPAIRS	New	171.00	171.00
5	TO CONDUCT WATER SEEPAGE TEST	New	85.00	0.00
6	4 WHEEL ALIGNMENT	New	171.00	171.00
7	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	New	171.00	0.00
8	REMOVE & REFIX WIRE HARNESS	New	228.00	228.00
9	REMOVE & REINSTALL ENGINE TO FACILITATE REPAIRS	New	342.00	342.00
10	TO CONDUCT FRONT LIGHTING TEST	New	28.00	28.00
11	TO CONDUCT PROTECTANT COATING	New	250.00	200.00
12	TO CONDUCT ANTI RUST COATING	New	290.00	250.00
13	REMOVE / REFIX FRT HEADLAMP WASHER AND PIPING	New	125.00	125.00
14	FAULT DIAGNOSTIC AND RESET SYSTEM	New	235.00	235.00
15	REPAIR FRONT RHS FRAME	New	250.00	0.00
16	RESPRAY FRONT RHS FRAME	New	200.00	0.00
Gross Labour Cost (S\$)			5,724.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >