

ASS. REC. BY:

REF: CS 3/AIG 19005022/Ded 302

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AIG

Date/Time:

20/3/19 @ 9:27am

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MVT CS

To Inspect Vehicle No:

SJB 1441A

Insured:

GBB 422G

at Workshop m/s

Lyc Designs

Tel:

6483 3353

of

10 Amk Ind. Park 2A #04-04

Policy No:

099999442

Claim No:

305688272556

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:04pm @ 20/3/19

Person Contacted:

Siew Hun

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

GBB 422G - CS / AIG 09024349 / va2h

D.O.A - 04/29/2009

SJB 144 / A - X

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

33

%

20

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJB1441A

Yr Regn:

2015 Apr 1

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz E250 G.C. 1991

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

47521

T/Radio: Insured / Std / NI / NA

Eng/No:

27492030358218

C/No:

WDD2120362B141060

Gen. Cond:

☒ Good / Fair / Poor / Burnt

Steering:

☒ In order / Jammed / Leaked / Burnt or

Brake:

☒ In order / Jammed / Leaked / Burnt or

Modi:

Nil / ☒ R / STD A/Rim or

Tyre Size:

F:

245/40 R18

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

08/02/2019

D.O.I.

20/03/2019

Survey held at

Lye Design AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear H/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ALG GBB 422 G No estimate.

Rear bumper, rear bumper bracket H/S, rear bumper retainers H/S.
Rear tail lamp H/S, rear boot lamp H/S

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format: DAR.

Lump Sum / I.B.I. (\$)

Survey Fee:

180

Transportation:

S + RS, SI

Photos

Others

10

TOTAL

190

- Pre-Repair Inspection - Vehicles GBB422G and SJB1441A

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 20/3/2019 9:27:15 AM
Attachments:  tmp8FAE.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Hor, Yinrul
Sent: Wednesday, March 20, 2019 8:30 AM
To: Chin, Lee-Ying
Cc: PRDSG.WORKLIST
Subject: #3056882725SG#027# FW: Pre-Repair Inspection - Vehicles GBB422G and SJB1441A

Hi Lee Ying,

As email below, kindly assist on this.
TP workshop contact details also provided for your necessary action.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Siew Hoon [<mailto:siewhoon@lyedesigns.com.sg>]
Sent: Tuesday, March 19, 2019 5:31 AM
To: 'Kelvin Tan'; Hor, Yinrul
Cc: 'Tan Chuan Wen Sean'
Subject: RE: Pre-Repair Inspection - Vehicles GBB422G and SJB1441A

Dear Kelvin

I have managed to stop spray painter. Stop work has been implemented.

We shall await further instruction from you to continue the job.

Kindly note that we have to defer the completion date from original plan. Appreciate your help to notify owner of this delay.

Thank you.

Warm Regards

Siew Hoon

Lye Designs

10 Ang Mo Kio Industrial Park 2A

#04-04 AMK Autopoint

Singapore 568047

T : 6483 3353

F : 6484 2457

E : siewhoon@lyedesigns.com.sg

W : www.lyedesigns.com.sg

From: Kelvin Tan [mailto:kelvin@vickiheng.com]

Sent: Tuesday, 19 March 2019 4:30 PM

To: YINRUL.HOR@AIG.COM

Cc: Tan Chuan Wen Sean; Siew Hoon

Subject: Pre-Repair Inspection - Vehicles GBB422G and SJB1441A

Dear Viviane

I refer to your earlier email today.

I understand that the workshop has commenced the repairs on the vehicle. I have asked that (to the extent possible) this be put on hold pending the review by your surveyor. Can you confirm that your surveyor will be going down by tomorrow? The address is 10 Ang Mo Kio Industrial Park 2A #04-04 AMK Autopoint Singapore 568047. I have copied the workshop representative Siew Hoon as well. I would be grateful if you can include her in all future communications as well.

Regards

Kelvin Tan

VICKI HENG LAW CORPORATION

Advocates & Solicitors | Commissioner for Oaths | Notary Public

140 Upper Bukit Timah Road

#03-08 Beauty World Plaza

Singapore 588176

Tel : (65) 6219 9027 | DID : (65) 67277 577 | Fax : (65) 6722 8323

This email is confidential. If you are not the intended recipient please notify us immediately then delete it.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Advocates & Solicitors • Commissioner for Oaths • Notary Public

Your Ref : To be advised
Our Ref : KT.PT.20193026 (Please quote our reference)

14 March 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 Shenton Way #07-16
Singapore 079120

By Fax (6835 7417)

Dear Sirs,

CLAIMANT: NG WEI WEI HENRY, NRIC No. S7710058Z
MOTOR ACCIDENT CLAIM ARISING FROM ACCIDENT INVOLVING COMMERCIAL
VEHICLE GBB422G AND MOTOR CAR SJB1441A AT THE JUNCTION OF OLD
AIRPORT ROAD AND CASSIA LINK ON 8 FEBRUARY 2019 AT 5.25PM

1. We refer to the matter above and our previous letter of 12 March 2019.
2. Please let us know by midnight on 15 March 2019 whether you will be appointing a surveyor to conduct a pre-repair survey (PRS) of our client's damaged vehicle SJB1441A.
3. Our client's independent surveyor will be conducting the PRS at 10am on 16 March 2019.
4. Thank you.

Yours faithfully,



VICKI HENG LAW CORPORATION
Cc Client

140 Upper Bukit Timah Road #03-08 Beauty World Plaza Singapore 588176
Tel. (65) 6219 9027 • Fax. (65) 6722 8323 (not for service of Court documents) • URL. <http://www.vickiheng.com>

Vicki Heng Law Corporation (UEN. 201323354K) is incorporated with limited liability.

MOTORCAR (Rear)

Rear Portion

Vehicle No: STB1441A

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993631	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper		✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket N/S		✓	
1148	993068	Rear Bumper Side Retainer N/S		✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp		✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH		✓	
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			

[illegible]

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2019 Edit Reg		20 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	KWANG CHUN PTE LTD, Co. Reg. No.: 201424747H, Tel: +6586691213								
Main Claimant:	-								
Vehicle Reg. No.:	SJB1441A	Date of Loss:	08/02/2019 17:00 - :59 [46 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3056882725SG	Policy/Cover Note No.:	0999994492 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	GBB422G	Policy No. (Claimant):							
		Excess:							
Repairer:	Lye Designs (HQ) 10 Amk Autopoint #04-04, Ang Mo Kio Industrial Park 2A, 568047 Ang Mo Kio - Tel: 64833353								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/03/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (21/03/2019): No Policy Found 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































Claim Documents






















***SJB1441A (3056882725SG)**
[GBB422G]

TP

-

Feb 8 2019 5:00PM
[KWANG CHUN PTE LTD]
Lye Designs

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print									
1	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
2	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
3	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
4	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
5	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
6	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
7	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
8	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
9	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
10	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
11	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
12	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
13	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
14	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
15	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
16	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
17	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
18	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
19	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
20	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
21	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
22	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
23	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
24	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
25	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
26	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
27	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
28	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
29	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
30	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
31	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
32	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
33	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
34	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
35	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
36	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									
37	07/05/19 11:08	General View		Load JPG	<input checked="" type="checkbox"/>									

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/05/19 11:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/05/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/03/19 09:55	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005022/GCD3E2

Date: 07/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994492

Claimant Vehicle
No :

SJB1441A

Insured Vehicle No :

GBB422G

Date of Loss: 08/02/2019

Nature of Claim:

TP

Claim No: 3056882725SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJB1441A

Make & Model:

MERCEDES-BENZ E250, 1.8 (A)

Engine No:

27492030358218

Reg. Date:

01/04/2015 (Man. Year: 2015)

Chassis No:

WDD2120362B141060

Colour:

Black

Odometer:

47521 km

Engine Capacity:

1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

245/40 R18

Rear Tyre Size:

245/40 R18

Front Left Side:

Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side:

Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

20/03/2019

Date Inspected:

20/03/2019 Inspected At:

Lye Designs (HQ)

10 Amk Autopoint #04-04, Ang Mo Kio

Industrial Park 2A

Singapore 568047

Estimated Period of Repair:

3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER BRACKET N/S	Cracked	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER N/S	Cracked	0.00 F	*- F
4	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
5	1		*BOOTLID LAMP LH	Mtg Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >