

ASS. REC. BY:

REP:

CS/ASM 19065023/Kap312

Special Instructions:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Kitty Teo

of

ASM(CAXA)

Date/Time:

20/3/2019

Estimated Cost:

Bill to:

OD

TP/WS/TP RES / OD RES / EVA / INV / MVTC3

To Inspect Vehicle No.:

SMH 6066A

Insured:

at Workshop n/z:

Ah Lim Motor

Tel:

64831244

of

10 Amk Ind. park 2A #01-09

Policy No:

Claim No:

S9M01H3X

Sum Insured:

Excess:

\$ 800.00

Make of Veh:

D.O.A.

14/3/19

(Client's Receipt)

CNY

REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:20am @ 20/3/19

Person Contacted:

Zila

Vehicle:

IN/OUT

Date/Time:

Action/Instruction (✓) Estimate

SMH 6066A - X

20/3/19 @ 3:39pm revised to Kitty Teo via Smart Claim

02/10/19 @ 1:20pm confirmed with Nui Hong final fig @ 9366.16, 5 days.

(Red @ 9168.42, 49%)

07/11/19 @ 1:41pm 2nd revised to Kitty Teo via Smart Claim (supplementary)...

049863632

ASS. REC. BY:

REF:

Axb/CS/ASM1905023/Kqd3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH8066A

Yr Regn:

07.13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E200

cc

1991

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

97989

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2120342A 788702

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: mic

245/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OMFSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

4

mm

Rear

R/Bal.

8

mm

L/Bal.

4

mm

L/Bal.

P

mm

D.O.A.

14/3/19

D.O.I.

20/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

Not more than 814k on part 4 part.

RECEIVED 07 NOV 2019

Date/Time, File Pass to?



: Prel. Report

11/07/11 transfer



: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

240

Transportation:

S + RS \$

Parking

Others

TOTAL

240

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Smart Claim

Lump Sum / I.B.I. (\$

9366.14



Service Request Details

Claim

S9M01H3X

Reference

None

Loss Date

March 14, 2019

Report Date

Mar 15, 2019 1:48:52 PM

Request Date

March 19, 2019

Due Date

March 26, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

14/6 DP
MS & 8000

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMH6066A

E200

E200

Service Address

10 Ang Mo Kio Ind. Park 2A, , 568047

Primary Contact/Insured

TAN WEE KIAT

BLK 12 WOODGROVE DRIVE, #03-62, 738212, Singapore

INSURANCE@UNIVERSEMOTORING.COM.SG

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

XS - \$800

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Nivitha (LKK Auto)

From: muihong@ahlimmotor.com.sg
Sent: Monday, 18 March 2019 2:26 PM
To: TEO Kitty; ANG Yvonne; TAN Jas
Subject: Unable to validate claim - SMH6066A DOA - 14/03/2019
Attachments: 6066 - AXA.PDF; ALM Audatex Estimate - SMH6066A.pdf

Dear Ladies,

Pls assist to create the claim as the portal is taking too long to validate the claim for me to create the claim.

Car is towed into workshop.

Pls do assist to arrange survey soonest

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 7 November 2019 1:20 PM
To: Mui Hong @ Ah Lim Motor; Kenneth Kong (LKKAUTO); SUR
Subject: RE: Draft Finalisation - SMH6066A S9M01H3X

Dear Mui Hong,

WITHOUT PREJUDICE

Confirm final fig \$9,366.16 before excess \$800.00 & GST and 5 repair days.

Kindly uploaded the discharge voucher and tax invoice in AXA Smart Claims system.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mui Hong @ Ah Lim Motor <muihong@ahlimmotor.com.sg>
Sent: Monday, 22 July 2019 2:28 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Draft Finalisation - SMH6066A S9M01H3X

Dear Kenneth,

Pls see attached the draft finalisation for SMH6066A S9M01H3X .

We have sent the Audatex Report over too.

Pls advise

Best Regards,

Kee Mui Hong

Ah Lim Motor @ AMK

10, Ang Mo Kio Industrial Park 2A

#01-09 AMK Autopoint S568047

Tel : 6483 1244 Fax : 6483 6170



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563581 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

7/11/2019

Survey Details:

Date of loss	14-Mar-19
Date of appointment	20-Mar-19
Date of survey	20-Mar-19
Location of survey	AH LIM MOTOR

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SMH 6066A
Make and Model	MERCEDES E200 SEDAN (R17)
Date of registration	1/7/2013
Excess	\$ 800.00
Market Value	\$ 80,000.00
Parf Rebate	\$ 65,090.00
Nett Loss	\$ 14,910.00

Repair details:

Initial Estimate	\$ 18,685.08	(ESTIMATE \$18,534.58 + SUPP \$150.50)
------------------	--------------	---

Proposed/Revised repair cost:

Parts	\$ 8,240.60
Check items (estimate)	\$ -
Labour	\$ 1,125.56
Total	\$ 9,366.16
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. We have received supplementary \$150.50 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Immediate Advice

To : AXA Insurance Pte Ltd

20/3/2019

Survey Details:

Date of loss	14-Mar-19
Date of appointment	20-Mar-19
Date of survey	20-Mar-19
Location of survey	AH LIM MOTOR

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SMH 6066A
Make and Model	MERCEDES E200 SEDAN (R17)
Date of registration	1/7/2013
Excess	\$ 800.00
Market Value	\$ 80,000.00
Parf Rebate	\$ 65,090.00
Nett Loss	\$ 14,910.00

Repair details:

Initial Estimate	\$ 18,534.58
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 7,825.90
Check items (estimate)	\$ 6,486.20
Labour	\$ 1,851.58
Total	\$ 16,163.68
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIRER AGREED REPAIR COST
NOT MORE THAN \$14,000.00 ON PART BY PART BASIS.
REPAIR COST ECONOMICAL. WE HAVE AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 20 March 2019 2:48 PM
To: muihong@ahlimmotor.com.sg; Kenneth Kong (LKKAuto)
Subject: RE: Repair to SMH6066A - AXA OD

Dear Mui Hong,

Re-send.

As spoken with you.

Please proceed to repair the insured vehicle SMH 6066A at repair cost not more than \$14,000.00 on part by part basis. (excess \$800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg <muihong@ahlimmotor.com.sg>
Sent: Wednesday, 20 March 2019 2:09 PM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Subject: Repair to SMH6066A - AXA OD

Dear Kenneth,

We refer to the above car surveyed by yourself and confirm that we are able to undertake the repair under \$14K.

Pls advise on authorisation soonest.

Thanks

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4062G
Vehicle Details	
Vehicle No.:	SMH6066A
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 SEDAN (R17)
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	27492030055944
Chassis No.:	WDD2120342A788702
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$42,967.00
Original Registration Date:	01 Jul 2013
First Registration Date:	01 Jul 2013
Transfer Count:	2
Actual ARF Paid:	\$47,154.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2023
PARF Rebate Amount:	\$33,007.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$75,000.00
COE Rebate Amount:	\$32,083.00
Total Rebate Amount:	\$65,090.00

The information contained herein is correct as at 20 Mar 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4062G

Vehicle Details

Vehicle No.: SMH6066A
Vehicle to be Exported: No
Intended Deregistration Date: 15 Mar 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: E200 SEDAN (R17)
Primary Colour: Silver
Manufacturing Year: 2013
Engine No.: 27492030055944
Chassis No.: WDD2120342A788702
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$42,967.00
Original Registration Date: 01 Jul 2013
First Registration Date: 01 Jul 2013
Transfer Count: 2
Actual ARF Paid: \$47,154.00 → \$23,577

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Jun 2023
PARF Rebate Amount: \$33,007.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$75,000.00
COE Rebate Amount: \$32,187.00
Total Rebate Amount: \$65,194.00

The information contained herein is correct as at 15 Mar 2019

OK

MV → \$80 ~ \$82k

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/03/2019 14:23
Date Of Accident	14/03/2019 10:30
Exact Location Of Accident	WOODLANDS LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH6066A
Insured/Policyholder	
Name Of Registered Owner	TAN WEE KIAT
NRIC No	S7204062G
Email Address	PAULTANWK@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-90036066
Alternative Phone No	OTHERS-90036066

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 (R17)-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA429102
Cover Note Number	19/12/2018 - 31/12/2019

Driver

Name of Driver	TAN WEE KIAT
NRIC No	S7204062G
Date Of Birth	25/01/1972
Occupation	INDOOR
Date Of Driving Pass	04/04/2011
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90036066
Fax Number	
Contact Number	OTHERS-90036066
EMail Address	PAULTANWK@YAHOO.COM.SG

Address	BLK 12 WOODGROVE DRIVE #03-62
Postcode	738212
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT AND SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ9283X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KUA KAR HUAT
NRIC/Passport Number	S1217272I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Axiom Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 14/03/19 Time: 10:30am Location: WOODLANDS LANE
 My Vehicle A: SMH 6066A Vehicle B: GZ9283 X Vehicle C: _____
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

we were travel from Woodlands lane turn left to Woodlands Drive 73. Vehicle suddenly jam brake before the turn left noted line.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address : paultanwke@yahoo.com.sg

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 001-00 AMH Auto Parts & Tyres 1000007
 Tel: 6403 1211 Fax: 6403 0170

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

AH LIM MOTOR COMPANY



redefining / insurance

AXA Insurance Pte Ltd
 1900 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

TAN WEE KIAT
 BLK 12
 WOODGROVE DRIVE
 #03-62
 SINGAPORE 738212

New business

date
 19/12/2018

your servicing distributor
 UNIVERSE MOTORING / 15318

your servicing distributor contact
 64632929

Policy Schedule

Your SmartDrive Comprehensive Essential

Your policy snapshot

Policyholder name	TAN WEE KIAT	Policy number	VA1 / GA429102
Cover	Comprehensive	FIN / NRIC	S7204062G
Period of Insurance	from 19/12/2018 to 31/12/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 0% NCD	SGD 2,044.39
Total Discounts	- SGD 217.23
7% GST	SGD 127.90
Final Premium	SGD 1,955.06

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Essential Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability

Vehicle details

Make & Model of Vehicle	MERCEDES E200	Year of manufacture	2013
Vehicle registration number	SWL8588 SMH6066A	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1991
Seating capacity (excl driver)	5	Engine number	27492030055944
Off-Peak car	No	Chassis number	WDD2120342A788702

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 800.00
Windscreen Excess	SGD 100.00

Drivers details

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 03/18/2019 10:39 AM

Full Report
 Registration: SMH6066A
 Printed: 18/03/2019 10:39 AM

LKR

can in
map

Summary Information

Claim

Location: Singapore (SG)
 Printed by: Kee Mui Hong
 Claim Reference: 001 claim
 Estimated Repair Time:
 Actual Repair Days:

Work Provider:
 Currency:
 Date of Incident:
 Hire Car Start:
 Hire Car End:

AXA Insurance Pte Ltd
 SGD
 2019-03-14

Vehicle Details

Vehicle

Manufacturer: MERCEDES-BENZ
 Model: E-CLASS (W212)
 Sub Model: E 200
 Model Sheet Number: 03 EE 46
 Registration: SMH6066A
 VIN number: WDD2120342A788702
 Odometer:

Model Specs

FR PRODUCTION START
 PARKTRONIC
 LAMINATED GLASS
 TRIM ELEGANCE
 S-WDW ROLLER BLIND
 PELVIS BAG
 7 SPEED AUTOMATIC
 SPARE WHEEL
 PREPARE OFF VEHICLE

MODEL 2014
 LOAD COMPARTMENT BOX
 HEATED WASHER UNIT
 MEMORY PACKAGE
 WOOD TRIM ASH TREE
 RR SCREEN SUN BLIND
 DIRECT CONTROL SUSP
 FUEL TANK 80 LTR
 CLEAR COAT HARD

FRT COLLISION ALARM
 AUDIO 20 CD CHANGER
 LEATHER TRIM
 PEDESTRIAN PROTECT
 REM RELEASE FUEL CAP
 ECO START/STOP
 TYRES 245/45 WR 17
 HD COOLING

EL DRIVE POS SELECT
 MULTIMEDIA INTERFACE
 SUNBLIND TWO-PIECE
 DIPPING MIRROR
 KEYLESS GO
 STRG COLUMN SHIFT
 WHEELS 8J X 17 ALLOY
 TWO COAT METALLIC

AH Lim Motor Company hereby notify

The Repairer of the following:

- To ensure information is being passed
- To deliver damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No single trade/contract is allowed
- Supplementary items must be reviewed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature

Date

Withheld

Recovery B4poin

Ex B800L



Sclay

Fax: 62564315

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Vehicle Condition

Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐Underbody ☐

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	13.50
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	9.00
61-1069 02	R + R COMPL LWR ENGINE COMPARTMENT COVER		3.0	13.50
88-1140 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL		7.0	31.50
88-1144 01	DIS + ASS FRONT BUMPER (BUMPER REMOVED)		9.0	40.50
88-1358 02	AFTER CHECK: RENEW PARTS IF NECESSARY ADDITION TO DIS + ASS FRONT BUMPER (BUMPER REMOVED)		2.0	9.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Code	Description	WU	Price SGD
88-1374 01	(VEHICLE WITH ULTRASONIC PARKING AID) ADDITION TO FRONT BUMPER DIS + ASS	1.0	4.50
88-1357 ZAX	(VEHICLE WITH PEDESTRIAN PROTECT) ADD TO DIS/ASS FRONT BUMPER CPL	2.0	9.00
82-4811 02)	(LUXURY VERSION VEHICLE) RENEW BOTH HEADLAMPS	9.0	40.50
88-2506 02	(BUMPER REMOVED) RENEW BONNET	10.0	45.00
	INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
88-2647 02	R + R L/BONNET HINGE	4.0	18.00
88-2652 02	R + R R/BONNET HINGE	4.0	18.00
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE	11.0	49.50
	INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION		
62-1256 01	R + R OR RENEW FRONT CROSSMEMBER AND COMPLETE TRUSSING BETWEEN WHEELHOUSES	15.0	67.50
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
09-8200 02	RENEW FRONT INTAKE AIR CHANNEL	2.0	9.00
20-3865 01	R + R RADIATOR	19.0	85.50
	INCLUDES: R + R CENTRE STIFFENING, FAN UNIT AND CHARGE AIR COOLER		
83-6543 ZAX	R + R AIR CONDITIONING CONDENSER	9.0	40.50
83-1762 02	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST	9.0	40.50
	(FOR ALL WORK ON THE SYSTEM)		
0741	L/F WING REPAIR	20.0*	90.00
0742	R/F WING REPAIR	20.0*	90.00
2085	LEFT DOOR FRAME REPAIR	10.0*	45.00
2086	RIGHT DOOR FRAME REPAIR	10.0*	45.00
Labour Cost			
Panel / Mechanical Labour		Hrs WU	
		18.10 181.0	814.50
Total of Labour			814.50

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	BONNET NEW PART PAINTING		30.0	
	LEFT BONNET HINGE NEW PART PAINTING		5.0	
	RIGHT BONNET HINGE NEW PART PAINTING		5.0	
	FRONT BUMPER COVER NEW PART PAINT K1G/P		29.0	
	L/F WING REPAIR PAINTING <50%		10.0	
	R/F WING REPAIR PAINTING <50%		10.0	
	LEFT DOOR FRAME REPAIR PAINTING <50%		9.0	
	RIGHT DOOR FRAME REPAIR PAINTING <50%		9.0	
	LEFT B-PILLAR REPAIR PAINTING <50%		10.0	
	RIGHT B-PILLAR REPAIR PAINTING <50%		10.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	102.68
0475	LEFT BONNET HINGE NEW PART PAINTING	0.52
0476	RIGHT BONNET HINGE NEW PART PAINTING	0.52
0283	FRONT BUMPER COVER NEW PART PAINT K1G/P	115.20
0741	L/F WING REPAIR PAINTING <50%	11.31
0742	R/F WING REPAIR PAINTING <50%	11.31
2085	LEFT DOOR FRAME REPAIR PAINTING <50%	8.40
2086	RIGHT DOOR FRAME REPAIR PAINTING <50%	8.40
2291	LEFT B-PILLAR REPAIR PAINTING <50%	8.72
2292	RIGHT B-PILLAR REPAIR PAINTING <50%	8.72

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			127.0	
Preparation Main Work Metal		2.50	25.0	112.50
Preparation Comp. Work Plastic		0.80	8.0	36.00
Total	10 WU/h	16.00	160.0	720.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Material Cost - Paint

New Part Painting

New Part Painting - Plastic K1G/PUR

Repair Painting

Material-constant Metal Preparation

Material-constant Plastic

Total

Price SGD

103.72

115.20

56.86

28.60

12.70

317.08

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0283	FRONT BUMPER COVER	212 880 2547 9999		900.00 7X
0319	L/F BUMPER GUIDE	218 880 0430		12.00 7X
0320	R/F BUMPER GUIDE	218 880 0430		12.00 7X
0340	FRT CTR BUMPER REINF	212 885 3965		65.00 X
0343	L/F BUMPER CARRIER	212 885 3765		45.00 ?
0344	R/F BUMPER CARRIER	212 885 3865		45.00 ?
0349	FRT/CTR IMPACT DAMP	212 880 0135		87.00 ?
0355	L/F OUT SPACER RING	000 542 1251		0.00 ?
0356	R/F OUT SPACER RING	000 542 1251		0.00 ?
0357	L/F CTR SPACER RING	000 542 1251		0.00 ?
0358	R/F CTR SPACER RING	000 542 1251		0.00 ?
0359	L/F INN SPACER RING	000 542 1251		0.00 ?
0360	R/F INN SPACER RING	000 542 1251		0.00 ?
0405	GRILLE	212 880 1483		650.00
0406	RAD GRILLE BRACKET	212 880 1403		180.00
0432	BONNET EMBLEM	221 880 0086		65.00
0471	BONNET	212 880 0357		1,500.00
0475	LEFT BONNET HINGE	204 880 0128		105.00 7X
0476	RIGHT BONNET HINGE	204 880 0228		105.00 7X
0481	CTR BONNET INSULAT	212 682 0126		175.00 X
0494	BONNET CATCH	212 880 0064		53.00 7X
0497	L/F BONNET STRUT	204 880 0029		80.00 X
0498	R/F BONNET STRUT	204 880 0029		80.00 X
0503	L/UPPER LATCH	212 880 0060		26.00 7X
0504	R/UPPER LATCH	212 880 0060		26.00 7X
0507	L/SPRING ELEMENT	204 880 0127		22.00
0508	R/SPRING ELEMENT	204 880 0127		22.00
0515	L/LOWER LATCH	212 880 0160		48.00 7X
0516	R/LOWER LATCH	212 880 0160		48.00 7X
0540	FRONT RADAR SENSOR	000 905 5103		780.00 ?
0561	LEFT HEADLAMP ASSY	212 820 1939		2,200.00
0562	RIGHT HEADLAMP ASSY	212 820 2039		2,200.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Code	Description	Part Number	Supplier	Price SGD
0930	CTR FRT REINF	212 620 1100		105.00 7✓
0988	BONNET LAND PNL SUPP	212 620 0900		26.00 X✓
0989	FRONT CTR RETAINER	212 898 0232		35.00 X✓
1001	FRT LWR CROSSMEMBER	212 620 1500		350.00 X✓
1187	L/F UPP REINF	212 620 4600		170.00 X✓
1188	R/F UPP REINF	212 620 4700		170.00 X✓
4465	AIR CON CONDENSER	204 500 0654		840.00 7X
7751	UPPER AIR GUIDE	212 500 0455		90.00 ✓
7753	AIR GUIDE	212 505 2930		48.00 X
7761	RADIATOR	099 500 6203		870.00 7X
7767	L/FASTENING CLIP	000 991 2595		8.50 7X
7768	R/FASTENING CLIP	000 991 2595		8.50 7X
7781	L/UPPER BEARING	169 504 0114		19.00 7X
7782	R/UPPER BEARING	169 504 0114		19.00 7X
7789	FAN UNIT	204 906 6802		770.00 7X
8385	AIR INTAKE HOSE	274 090 0400		270.00 X
9649	L/H-LAMP LVL C-UNIT	218 900 7206		650.00 X
9650	R/H-LAMP LVL C-UNIT	218 900 7206		650.00 7X
1000	INSULATOR CLIPS (10)	1		40.00 ✓
1001	FRT BUMP CLIPS (15)	1		60.00 7X
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				14,730.00
Addition(+10.00%)				1,473.00
Total				16,203.00

Extras

Code	Description	Price SGD
1002	RADIATOR COOLANT	30.00* ✓
1003	AIR CON GAS	50.00* ✓
1004	CHECK WIRING	40.00* 2cl
1005	TO RESET & DIAGNOSE	280.00* 7X
1006	REINSTAL BUMP SENSOR	80.00* 6cl
Total Extras		480.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	14,730.00	
Total Parts	1,473.00	
		16,203.00
Labour Time Base 10 WU/h		
Total 181.0 WU X 45.00 SGD/h	814.50	
Total of Labour		814.50
Total Of Extras		480.00
Paint Work Time Base 10 WU/h		
Labour Cost 160.0 WU X 45.00 SGD/h	720.00	
Material Cost	317.08	
Total Paint Including Material		1,037.08
Repair Cost Excludes GST		18,534.58
GST (+7.0%)		1,297.42
Repair Cost Included GST		19,832.00

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

18595.08

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
Assessment number: MC1900226
Version: 1810
Date calculated: 03/18/2019 10:39 AM

Full Report
Registration: SMH6066A
Printed: 18/03/2019 10:39 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:	001 claim	Date of Incident:	2019-03-14
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W212)
Sub Model:	E 200
Model Sheet Number:	03 EE 46
Registration:	SMH6066A
VIN number:	WDD2120342A788702
Odometer:	

Model Specs

FR PRODUCTION START	MODEL 2014	FRT COLLISION ALARM	EL DRIVE POS SELECT
PARKTRONIC	LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER	MULTIMEDIA INTERFACE
LAMINATED GLASS	HEATED WASHER UNIT	LEATHER TRIM	SUNBLIND TWO-PIECE
TRIM ELEGANCE	MEMORY PACKAGE	PEDESTRIAN PROTECT	DIPPING MIRROR
S-WDW ROLLER BLIND	WOOD TRIM ASH TREE	REM RELEASE FUEL CAP	KEYLESS GO
PELVIS BAG	RR SCREEN SUN BLIND	ECO START/STOP	STRG COLUMN SHIFT
7 SPEED AUTOMATIC	DIRECT CONTROL SUSP	TYRES 245/45 WR 17	WHEELS 8J X 17 ALLOY
SPARE WHEEL	FUEL TANK 80 LTR	HD COOLING	TWO COAT METALLIC
PREPARE OFF VEHICLE	CLEAR COAT HARD		

Not withain

Presumy B4 perik

Ex B800L

131
187
5 days

Fax: 62564315

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 03/18/2019 10:39 AM

Full Report
 Registration: SMH6066A
 Printed: 18/03/2019 10:39 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	13.50
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	9.00
61-1069 02	R + R COMPL LWR ENGINE COMPARTMENT COVER		3.0	13.50
88-1140 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL		7.0	31.50
88-1144 01	DIS + ASS FRONT BUMPER (BUMPER REMOVED) AFTER CHECK: RENEW PARTS IF NECESSARY		9.0	40.50
88-1358 02	ADDITION TO DIS + ASS FRONT BUMPER (BUMPER REMOVED)		2.0	9.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Code	Description	WU	Price SGD
88-1374 01	(VEHICLE WITH ULTRASONIC PARKING AID) ADDITION TO FRONT BUMPER DIS + ASS	1.0	4.50
88-1357 ZAX	(VEHICLE WITH PEDESTRIAN PROTECT) ADD TO DIS/ASS FRONT BUMPER CPL	2.0	9.00
82-4811 02)	(LUXURY VERSION VEHICLE) RENEW BOTH HEADLAMPS	9.0	40.50
88-2506 02	(BUMPER REMOVED) RENEW BONNET	10.0	45.00
	INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
88-2647 02	R + R L/BONNET HINGE	4.0	18.00
88-2652 02	R + R R/BONNET HINGE	4.0	18.00
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE	11.0	49.50
	INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION		
62-1266 01	R + R OR RENEW FRONT CROSSMEMBER AND COMPLETE TRUSSING BETWEEN WHEELHOUSES	15.0	67.50
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
09-8200 02	RENEW FRONT INTAKE AIR CHANNEL	2.0	9.00
20-3865 01	R + R RADIATOR	19.0	85.50
	INCLUDES: R + R CENTRE STIFFENING, FAN UNIT AND CHARGE AIR COOLER		
83-6543 ZAX	R + R AIR CONDITIONING CONDENSER	9.0	40.50
83-1762 02	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	40.50
0741	L/F WING REPAIR	na 20.0*	Y 90.00
0742	R/F WING REPAIR	na 20.0*	X 90.00
2085	LEFT DOOR FRAME REPAIR	5 na 10.0*	X 45.00
2086	RIGHT DOOR FRAME REPAIR	5 na 10.0*	X 45.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		18.10	181.0
Total of Labour			814.50

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 03/18/2019 10:39 AM

Full Report
 Registration: SMH6066A
 Printed: 18/03/2019 10:39 AM

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	30.0
	LEFT BONNET HINGE NEW PART PAINTING	5.0
	RIGHT BONNET HINGE NEW PART PAINTING	5.0
	FRONT BUMPER COVER NEW PART PAINT K1G/P	29.0
	L/F WING REPAIR PAINTING <50%	10.0
	R/F WING REPAIR PAINTING <50%	10.0
	LEFT DOOR FRAME REPAIR PAINTING <50%	9.0
	RIGHT DOOR FRAME REPAIR PAINTING <50%	9.0
	LEFT B-PILLAR REPAIR PAINTING <50%	10.0
	RIGHT B-PILLAR REPAIR PAINTING <50%	10.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	102.68
0475	LEFT BONNET HINGE NEW PART PAINTING	0.52
0476	RIGHT BONNET HINGE NEW PART PAINTING	0.52
0283	FRONT BUMPER COVER NEW PART PAINT K1G/P	115.20
0741	L/F WING REPAIR PAINTING <50%	11.31
0742	R/F WING REPAIR PAINTING <50%	11.31
2085	LEFT DOOR FRAME REPAIR PAINTING <50%	8.40
2086	RIGHT DOOR FRAME REPAIR PAINTING <50%	8.40
2291	LEFT B-PILLAR REPAIR PAINTING <50%	8.72
2292	RIGHT B-PILLAR REPAIR PAINTING <50%	8.72

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		127.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	160.0	720.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 03/18/2019 10:39 AM

Full Report
 Registration: SMH6066A
 Printed: 18/03/2019 10:39 AM

Material Cost - Paint	Price SGD
New Part Painting	103.72
New Part Painting - Plastic K1G/PUR	115.20
Repair Painting	56.86
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	317.08

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER COVER	212 880 2547 9999			900.00 ?
0319	L/F BUMPER GUIDE	218 880 0430			12.00 ?
0320	R/F BUMPER GUIDE	218 880 0430			12.00 ?
0340	FRT CTR BUMPER REINF	212 885 3965			65.00 X
0343	L/F BUMPER CARRIER	212 885 3765			45.00 ?
0344	R/F BUMPER CARRIER	212 885 3865			45.00 ?
0349	FRT/CTR IMPACT DAMP	212 880 0135			87.00 ?
0355	L/F OUT SPACER RING	000 542 1251			0.00 ?
0356	R/F OUT SPACER RING	000 542 1251			0.00 ?
0357	L/F CTR SPACER RING	000 542 1251			0.00 ?
0358	R/F CTR SPACER RING	000 542 1251			0.00 ?
0359	L/F INN SPACER RING	000 542 1251			0.00 ?
0360	R/F INN SPACER RING	000 542 1251			0.00 ?
0405	GRILLE	212 880 1483			650.00 ✓
0406	RAD GRILLE BRACKET	212 880 1403			180.00 ✓
0432	BONNET EMBLEM	221 880 0086			65.00 ✓
0471	BONNET	212 880 0357			1,500.00 ✓
0475	LEFT BONNET HINGE	204 880 0128			105.00 ?
0476	RIGHT BONNET HINGE	204 880 0228			105.00 ?
0481	CTR BONNET INSULAT	212 682 0126			175.00 X
0494	BONNET CATCH	212 880 0064			53.00 ?
0497	L/F BONNET STRUT	204 880 0029			80.00 X
0498	R/F BONNET STRUT	204 880 0029			80.00 X
0503	L/UPPER LATCH	212 880 0060			26.00 ?
0504	R/UPPER LATCH	212 880 0060			26.00 ?
0507	L/SPRING ELEMENT	204 880 0127			22.00 ✓
0508	R/SPRING ELEMENT	204 880 0127			22.00 ✓
0515	L/LOWER LATCH	212 880 0160			48.00 ?
0516	R/LOWER LATCH	212 880 0160			48.00 ?
0540	FRONT RADAR SENSOR	000 905 5103			780.00 ?
0561	LEFT HEADLAMP ASSY	212 820 1939			2,200.00 ✓
0562	RIGHT HEADLAMP ASSY	212 820 2039			2,200.00 ✓

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 03/18/2019 10:39 AM

Full Report

Registration: SMH6066A

Printed: 18/03/2019 10:39 AM

Code	Description	Part Number	Supplier	Price SGD
0930	CTR FRT REINF	212 620 1100		105.00 ?
0988	BONNET LAND PNL SUPP	212 620 0900		R 26.00 X
0989	FRONT CTR RETAINER	212 898 0232		R 35.00 X
1001	FRT LWR CROSSMEMBER	212 620 1500		R 350.00 X
1187	L/F UPP REINF	212 620 4600		R 170.00 X
1188	R/F UPP REINF	212 620 4700		R 170.00 X
4465	AIR CON CONDENSER	204 500 0654		840.00 ?
7751	UPPER AIR GUIDE	212 500 0455		CM 90.00 ✓
7753	AIR GUIDE	212 505 2930		SM 48.00 X
7761	RADIATOR	099 500 6203		870.00 ?
7767	L/FASTENING CLIP	000 991 2595		8.50 ?
7768	R/FASTENING CLIP	000 991 2595		8.50 ?
7781	L/UPPER BEARING	169 504 0114		19.00 ?
7782	R/UPPER BEARING	169 504 0114		19.00 ?
7789	FAN UNIT	204 906 6802		770.00 ?
8385	AIR INTAKE HOSE	274 090 0400		SM 270.00 X
9649	L/H-LAMP LVL C-UNIT	218 900 7206		SM 650.00 X
9650	R/H-LAMP LVL C-UNIT	218 900 7206		650.00 ?
1000	INSULATOR CLIPS (10)	1		MC 40.00 ✓
1001	FRT BUMP CLIPS (15)	1		60.00 ?
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 14,730.00
u: Used parts				Addition(+10.00%) 1,473.00
Total				16,203.00

Extras

Code	Description	Price SGD
1002	RADIATOR COOLANT	MC 30.00* ✓
1003	AIR CON GAS	MC 50.00* ✓
1004	CHECK WIRING	40.00* 2cl
1005	TO RESET & DIAGNOSE	280.00* ?
1006	REINSTAL BUMP SENSOR	80.00* 6cl
Total Extras		480.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
Assessment number: MC1900226
Version: 1810
Date calculated: 03/18/2019 10:39 AM

Full Report
Registration: SMH6066A
Printed: 18/03/2019 10:39 AM

Final Calculation

	SGD	SGD
Parts	14,730.00	
Addition(+10.00%)	1,473.00	
Total Parts		16,203.00
Labour Time Base 10 WU/h		
Total 181.0 WU X 45.00 SGD/h	814.50	
Total of Labour		814.50
Total Of Extras		480.00
Paint Work Time Base 10 WU/h		
Labour Cost 160.0 WU X 45.00 SGD/h	720.00	
Material Cost	317.08	
Total Paint Including Material		1,037.08
Repair Cost Excludes GST		18,534.58
GST (+7.0%)		1,297.42
Repair Cost Included GST		19,832.00

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 03/18/2019 10:39 AM

Full Report
 Registration: SMH6066A
 Printed: 18/03/2019 10:39 AM

Code	Description	WU	Price SGD
88-1374 01	(VEHICLE WITH ULTRASONIC PARKING AID) ADDITION TO FRONT BUMPER DIS + ASS	1.0	4.50
88-1357 ZAX	(VEHICLE WITH PEDESTRIAN PROTECT) ADD TO DIS/ASS FRONT BUMPER CPL	2.0	9.00
82-4811 02)	(LUXURY VERSION VEHICLE) RENEW BOTH HEADLAMPS	9.0	40.50
88-2506 02	(BUMPER REMOVED) RENEW BONNET	10.0	45.00
	INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
88-2647 02	R + R L/BONNET HINGE	4.0	18.00
88-2652 02	R + R R/BONNET HINGE	4.0	18.00
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE	11.0	49.50
	INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION		
62-1266 01	R + R OR RENEW FRONT CROSSMEMBER AND COMPLETE TRUSSING BETWEEN WHEELHOUSES	15.0	67.50
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
09-8200 02	RENEW FRONT INTAKE AIR CHANNEL	2.0	9.00
20-3865 01	R + R RADIATOR	19.0	85.50
	INCLUDES: R + R CENTRE STIFFENING, FAN UNIT AND CHARGE AIR COOLER		
83-6543 ZAX	R + R AIR CONDITIONING CONDENSER	9.0	40.50
83-1762 02	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	40.50
0741	L/F WING REPAIR	20.0*	90.00
0742	R/F WING REPAIR	20.0*	90.00
2085	LEFT DOOR FRAME REPAIR	10.0*	45.00
2086	RIGHT DOOR FRAME REPAIR	10.0*	45.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		18.10	181.0
Total of Labour			814.50

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 03/18/2019 10:39 AM

Full Report
 Registration: SMH6066A
 Printed: 18/03/2019 10:39 AM

Material Cost - Paint	Price SGD
New Part Painting	103.72
New Part Painting - Plastic K1G/PUR	115.20
Repair Painting	56.86
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	317.08

Spare Parts

				prices as at 2015-06-01	
Code	Description	Part Number	Supplier	Price SGD	
0283	FRONT BUMPER COVER	212-880-2547-9999		900.00	✓
0319	L/F BUMPER GUIDE	218-880-0430		12.00	✓
0320	R/F BUMPER GUIDE	218-880-0430		12.00	✓
0340	FRT CTR BUMPER REINF	212-885-3965		65.00	X
0343	L/F BUMPER CARRIER	212-885-3765		45.00	✓
0344	R/F BUMPER CARRIER	212-885-3865		45.00	✓
0349	FRT/CTR IMPACT DAMP	212-880-0135		87.00	✓
0355	L/F OUT SPACER RING	000-542-1251		0.00	✓
0356	R/F OUT SPACER RING	000-542-1251		0.00	✓
0357	L/F CTR SPACER RING	000-542-1251		0.00	✓
0358	R/F CTR SPACER RING	000-542-1251		0.00	✓
0359	L/F INN SPACER RING	000-542-1251		0.00	✓
0360	R/F INN SPACER RING	000-542-1251		0.00	✓
0405	GRILLE	212-880-1483		650.00	✓
0406	RAD GRILLE BRACKET	212-880-1403		180.00	✓
0432	BONNET EMBLEM	221-880-0086		65.00	✓
0471	BONNET	212-880-0357		1,500.00	✓
0475	LEFT BONNET-HINGE	204-880-0128		105.00	✓
0476	RIGHT BONNET-HINGE	204-880-0228		105.00	✓
0481	CTR BONNET-INSULAT	212-682-0126		175.00	X
0494	BONNET CATCH	212-880-0064		53.00	✓
0497	L/F BONNET-STRUT	204-880-0029		80.00	X
0498	R/F BONNET-STRUT	204-880-0029		80.00	X
0503	L/UPPER LATCH	212-880-0060		26.00	✓
0504	R/UPPER LATCH	212-880-0060		26.00	✓
0507	L/SPRING ELEMENT	204-880-0127		22.00	✓
0508	R/SPRING ELEMENT	204-880-0127		22.00	✓
0515	L/LOWER LATCH	212-880-0160		48.00	✓
0516	R/LOWER LATCH	212-880-0160		48.00	✓
0540	FRONT RADAR SENSOR	000-905-5103		780.00	✓
0561	LEFT HEADLAMP ASSY	212-820-1939		2,200.00	✓
0562	RIGHT HEADLAMP ASSY	212-820-2039		2,200.00	✓

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 03/18/2019 10:39 AM

Full Report
 Registration: SMH6066A
 Printed: 18/03/2019 10:39 AM

Code	Description	Part Number	Supplier	Price SGD	
0930	CTR FRT REINF	212 620 1100		105.00	7 Mch
0988	BONNET LAND PNL SUPP	212 620 0900		26.00	X Mch
0989	FRONT CTR RETAINER	212 898 0232		35.00	X Mch
1001	FRT LWR CROSSMEMBER	212 620 1500		350.00	X Mch
1187	L/F UPP REINF	212 620 4600		170.00	X Mch
1188	R/F UPP REINF	212 620 4700		170.00	X Mch
4465	AIR CON CONDENSER	204 500 0654		840.00	7
7751	UPPER AIR GUIDE	212 500 0455		90.00	✓
7753	AIR GUIDE	212 505 2930		48.00	X
7761	RADIATOR	099 500 6203		870.00	7
7767	L/FASTENING CLIP	000 991 2595		8.50	7
7768	R/FASTENING CLIP	000 991 2595		8.50	7
7781	L/UPPER BEARING	169 504 0114		19.00	7
7782	R/UPPER BEARING	169 504 0114		19.00	7
7789	FAN UNIT	204 906 6802		770.00	7
8385	AIR INTAKE HOSE	274 090 0400		270.00	X
9649	L/H LAMP LVL C-UNIT	218 900 7206		650.00	X
9650	R/H LAMP LVL C-UNIT	218 900 7206		650.00	7
1000	INSULATOR CLIPS (10)	1		40.00	✓
1001	FRT BUMP CLIPS (15)	1		60.00	7
f: OEM Parts				Savings	0.00
n: Non-OEM Parts				Subtotal	14,730.00
u: Used parts				Addition(+10.00%)	1,473.00
				Total	16,203.00

Extras

Code	Description	Price SGD	
1002	RADIATOR COOLANT	30.00*	✓
1003	AIR CON GAS	50.00*	✓
1004	CHECK WIRING	40.00*	2d
1005	TO RESET & DIAGNOSE	280.00*	7
1006	REINSTAL BUMP SENSOR	80.00*	6d
Total Extras		480.00	

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
Assessment number: MC1900226
Version: 1810
Date calculated: 10/06/2019 9:21 AM

Full Report
Registration: SMH6066A
Printed: 10/06/2019 9:21 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	14/03/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W212)
Sub Model:	E 200
Model Sheet Number:	03 EE 46
Registration:	SMH6066A
VIN number:	WDD2120342A788702
Odometer:	

Model Specs

FR PRODUCTION START	MODEL 2014	FRT COLLISION ALARM	EL DRIVE POS SELECT
PARKTRONIC	LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER	MULTIMEDIA INTERFACE
LAMINATED GLASS	HEATED WASHER UNIT	LEATHER TRIM	SUNBLIND TWO-PIECE
TRIM ELEGANCE	MEMORY PACKAGE	PEDESTRIAN PROTECT	DIPPING MIRROR
S-WDW ROLLER BLIND	WOOD TRIM ASH TREE	REM RELEASE FUEL CAP	KEYLESS GO
PELVIS BAG	RR SCREEN SUN BLIND	ECO START/STOP	STRG COLUMN SHIFT
7 SPEED AUTOMATIC	DIRECT CONTROL SUSP	TYRES 245/45 WR 17	WHEELS 8J X 17 ALLOY
SPARE WHEEL	FUEL TANK 80 LTR	HD COOLING	TWO COAT METALLIC
PREPARE OFF VEHICLE	CLEAR COAT HARD		

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
Assessment number: MC1900226
Version: 1810
Date calculated: 10/06/2019 9:21 AM

Full Report
Registration: SMH6066A
Printed: 10/06/2019 9:21 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	13.50
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	9.00
88-1140 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL		7.0	31.50
88-2155 01	RENEW RADIATOR COVER		3.0	13.50
82-4811 02)	RENEW BOTH HEADLAMPS (BUMPER REMOVED)		9.0	40.50
88-2506 02	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF		10.0	45.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 10/06/2019 9:21 AM

Full Report

Registration: SMH6066A

Printed: 10/06/2019 9:21 AM

Code	Description	WU	Price SGD
88-2620 02	NECESSARY R + R FRONT BONNET CABLE	3.0	13.50
60-1301 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT (FOR RENEWAL OF THE REINFORCEMENT) DOES NOT INCLUDE: R + R BUMPER AND LAMP UNITS	6.0	27.00
62-1301 01	R + R OR RENEW L/F TRUSSING BETWEEN WHEELHOUSES INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY	6.0	27.00
NO NUMBER	R + R FRONT AIR GUIDE	3.0	13.50
0283	FRONT BUMPER COVER REPAIR	20.0*	90.00
2085	LEFT DOOR FRAME REPAIR	5.0*	22.50
2086	RIGHT DOOR FRAME REPAIR	5.0*	22.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		8.20	82.0
Total of Labour			369.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	30.0
	FRONT BUMPER COVER REPAIR PAINT PLASTIC	16.0
	LEFT DOOR FRAME REPAIR PAINTING <50%	9.0
	RIGHT DOOR FRAME REPAIR PAINTING <50%	9.0
	LEFT B-PILLAR REPAIR PAINTING <50%	10.0
	RIGHT B-PILLAR REPAIR PAINTING <50%	10.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	102.68
0283	FRONT BUMPER COVER REPAIR PAINT PLASTIC	51.84
2085	LEFT DOOR FRAME REPAIR PAINTING <50%	8.40
2086	RIGHT DOOR FRAME REPAIR PAINTING <50%	8.40
2291	LEFT B-PILLAR REPAIR PAINTING <50%	8.72
2292	RIGHT B-PILLAR REPAIR PAINTING <50%	8.72

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900226

Version: 1810

Date calculated: 10/06/2019 9:21 AM

Full Report

Registration: SMH6066A

Printed: 10/06/2019 9:21 AM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		84.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	117.0	526.50

Material Cost - Paint	Price SGD
New Part Painting	102.68
Repair Painting	34.24
Repair Painting Plastic	51.84
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	230.06

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0405	GRILLE	212 880 1483		650.00
0406	RAD GRILLE BRACKET	212 880 1403		180.00
0432	BONNET EMBLEM	221 880 0086		65.00
0471	BONNET	212 880 0357		1,500.00
0500	BONNET CABLE	212 880 0559		55.00
0504	R/UPPER LATCH	212 880 0060		26.00
0507	L/SPRING ELEMENT	204 880 0127		22.00
0508	R/SPRING ELEMENT	204 880 0127		22.00
0561	LEFT HEADLAMP ASSY	212 820 1939		2,200.00
0562	RIGHT HEADLAMP ASSY	212 820 2039		2,200.00
0930	CTR FRT REINF	212 620 1100		105.00
0988	BONNET LAND PNL SUPP	212 620 0900		26.00
0989	FRONT CTR RETAINER	212 898 0232		35.00
1187	L/F UPP REINF	212 620 4600		170.00
7751	UPPER AIR GUIDE	212 500 0455		90.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	7,346.00
Addition(+10.00%)	734.60
Total	8,080.60

Extras

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900226
 Version: 1810
 Date calculated: 10/06/2019 9:21 AM

Full Report
 Registration: SMH6066A
 Printed: 10/06/2019 9:21 AM

Code	Description	Price SGD
1002	RADIATOR COOLANT	30.00*
1003	AIR CON GAS	50.00*
1004	CHECK WIRING	20.00*
1006	REINSTAL BUMP SENSOR	60.00*
	Total Extras	160.00

Final Calculation

	SGD	SGD
Parts	7,346.00	
Addition(+10.00%)	734.60	
Total Parts		8,080.60
Labour Time Base 10 WU/h		
Total 82.0 WU X 45.00 SGD/h	369.00	
Total of Labour		369.00
Total Of Extras		160.00
Paint Work Time Base 10 WU/h		
Labour Cost 117.0 WU X 45.00 SGD/h	526.50	
Material Cost	230.06	
Total Paint Including Material		756.56
Repair Cost Excludes GST		9,366.16
GST (+7.0%)		655.63
Repair Cost Included GST		10,021.79

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC1900226

Ref No: MF1900329

Date: 03 Jun 2019

Policy No: GA429102

Veh Reg No: SMH6066A

Make/Model: MERCEDES BENZ E200
A

Your Ref No: S9M01H3X

Claim Type: Own Damage

Accident Date: 14/03/2019

Repair Cost to Vehicle No (For Finalization):SMH6066A

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 BONNET CABLE		1 PC	55.00	
2 FRONT GRILLE		1 PC	650.00	
3 RAD GRILLE BRACKET		1 PC	180.00	
4 BONNET EMBLEM		1 PC	65.00	
5 BONNET		1 PC	1,500.00	
6 R/UPPER LATCH		1 PC	26.00	
7 L/SPRING ELEMENT		1 PC	22.00	
8 R/SPRING ELEMENT		1 PC	22.00	
9 LEFT HEADLAMP ASSY		1 PC	2,200.00	
10 RIGHT HEADLAMP ASSY		1 PC	2,200.00	
11 CTR FRT REINF		1 PC	105.00	
12 BONNET LAND PNL SUPP		1 PC	26.00	
13 FRONT CTR RETAINER		1 PC	35.00	
14 L/F UPP REINF		1 PC	170.00	
15 UPPER AIR GUIDE		1 PC	90.00	
			7,346.00	
	Add 10%		734.60	8,080.60
Special Nett				
16 RADIATOR COOLANT		1 PC	30.00	
				30.00
LABOUR				
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
18 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	50.00	
19 TO REMOVE AND REINSTALL/REPLACE FRONT BUMPER SENSORS.		1 PC	60.00	
20 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR FRONT BUMPER, FRONT DOOR PILLAR LH/RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	369.00	
21 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT DOOR PILLAR LH/RH		1 PC	756.56	
				1,255.56

~~AH LIM MOTOR COMPANY~~
No. 10 Ang Mo Kio Ind. Park 2A #01-09
AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
Email: ahlimco@singnet.com.sg

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S9M01H3X

Claim Type: Own Damage

Accident Date: 14/03/2019

Claim No: MC1900226

Ref No: MF1900329

Date: 03 Jun 2019

Policy No: GA429102

Veh Reg No: SMH6066A

Make/Model: MERCEDES BENZ E200
A

Repair Cost to Vehicle No (For Finalization):SMH6066A

Amount Before Excess	S\$ 9,366.16
Less Excess	S\$ 800.00
Amount Before GST	S\$ 8,566.16
Add GST @ 7%	599.63
Total Amount payable	S\$ 9,165.79

TOTAL: SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED SIXTY FIVE AND CENTS SEVENTY NINE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 20/03/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC1900226

Date: 22 Mar 2019

Policy No: GA429102

Veh Reg No: SMH6066A

Make/Model: MERCEDES BENZ E200
A

Your Ref No: S9M01H3X

Claim Type: Own Damage

Accident Date: 14/03/2019

Estimate Repair Cost to Vehicle No :SMH6066A

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
SPARE PARTS				
I BONNET CABLE		I PC	55.00	✓ 3m
			55.00	
	Add 10%		5.50	60.50

Handwritten: Please take up Survey on 20/3/19
Gmail Photo Back to

Amount Before Excess	S\$ 60.50
GST Amount	S\$ 4.24
Total Amount payable	S\$ 64.74

The above vehicle was surveyed by KENNETH KONG -LKK on 20/03/2019

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



SURPASS AUTO PARTS SUPPLIES PTE LTD

22/03/2019 14:18:29

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175
 Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com
 Co & Gst Reg No: 199904808E

AH LIM MOTOR COMPANY (A)
 10 ANG MO KIO IND PARK 2A
 #01-09 AMK AUTOPOINT
 SINGAPORE 568047

TAX INVOICE

Inv No. : 19030207
 Date : 21/03/2019
 Page : 1 of 2

S/N	Item No.	Description	Qty	U/ Price	Amount
1		SMH6066A			
2	A2128801463	GRILLE	1	650.00✓	650.00
3	A2128801403	GRILLE BEAM	1	180.00✓	180.00
4	A2218800066	2228101200 MERCEDES STAR	1	65.00✓	65.00
5	A2128800357	BONNET	1	1,500.00✓	1,500.00
6	A2048800127	SPRING BONNET 207/212	2	22.00✓	44.00
7	A2128201939	HEADLAMP	1	2,200.00✓	2,200.00
8	A2128202039	HEADLAMP	1	2,200.00✓	2,200.00
9	A2125000455	TOP FAN SHROUD NEW	1	90.00✓	90.00
10	A2126200900	BRACKET CTE	1✓	26.00✓	26.00
11	A2128800060	TOP CATCH	1✓	26.00✓	26.00
12	A2128980232	U-SHAPED STRIKER	1✓	35.00✓	35.00
13	A2126204600	HEADLAMP PANEL	1✓	170.00✓	170.00
14	A2128800559	BONNET CABLE I	1	55.00✓ ^{sup}	55.00

SURPASS AUTO PARTS SUPPLIES PTE LTD

22/03/2019 14:18:29

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175
 Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com
 Co & Gst Reg No: 199904808E

AH LIM MOTOR COMPANY (A)
 10 ANG MO KIO IND PARK 2A
 #01-09 AMK AUTOPOINT
 SINGAPORE 568047

TAX INVOICE

Inv No. : 19030207
 Date : 21/03/2019
 Page : 2 of 2

S/N	Item No.	Description	Qty	U/ Price	Amount
15	A2126201100	TOP STIFFENING	1✓	105.00✓	105.00

Page 1

Signature

Customer's Signature

Sub Total 7,346.00
 GST 7% 514.22
 Total 7,860.22