



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2013 MERCEDES E200 (SMH6066A)
Date of Loss	14 March 2019
Time of Loss	10.30
Loss Description	SMH6066A (INSD) HIT REAR OF GZ9283X (TP)
Comment	

Workshop Details

Total Rebate Amount	65090
Nett Loss Amount	\$14,910.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SMH6066A

Registration State SINGAPORE

Mileage 97969

Purchase Date dd/mm/yyyy

Registration Date * 01/07/2013

Age of Vehicle 5

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATION

Manufacturing
Year

2013

2013

Make

MERCEDES

MERCEDES BI

Driver Details

CATEGORY

FNOL
INFORMATION

POST SURVEY
INFORMATION

Driver Name

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Model	E200	E200 SEDAN I
Type		
Type of Paint		
Chassis No	WDD2120342A788702	WDD2120342
Engine No	27492030055944	27492030055
Engine Capacity		1991
Sum Insured	0	0
Market Value	0	80000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		dd/mm/yyyy
Age		
Occupation		
Education Qualification		
Driving Experience		
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		dd/mm/yyyy 
Address		
Address type		
Gender		
Marital status		
Identification #		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

20/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

800

Young/Inexperienced/
Unnamed Driver
Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Age of Tyres

Front Tyre Size

245/45R17

Front left side

MICHELIN4mm

Front right side

MICHELIN4mm

Spare wheel

Rear Tyre Size

245/45R17

Rear left side

MICHELIN8mm

Rear right side

MICHELIN8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT BUMPER COVER	Repair	0	0	No					0	Deny
		0	1		L/F BUMPER GUIDE	Serviceable	0	0	No					0	Deny
		0	1		R/F BUMPER GUIDE	Serviceable	0	0	No					0	Deny
		0	1		FRT CTR BUMPER REINF	Repair	0	0	No					0	Deny
		0	1		L/F BUMPER CARRIER	Serviceable	0	0	No					0	Deny
		0	1		R/F BUMPER CARRIER	Serviceable	0	0	No					0	Deny
		0	1		FRT/CTR IMPACT DAMP	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		L/F OUT SPACER RING (NPA)	Serviceable	0	0	No					0	Deny
		0	1		R/F OUT SPACER RING (NPA)	Serviceable	0	0	No					0	Deny
		0	1		L/F CTR SPACER RING (NPA)	Serviceable	0	0	No					0	Deny
		0	1		R/F CTR SPACER RING (NPA)	Serviceable	0	0	No					0	Deny
		0	1		L/F INN SPACER RING (NPA)	Serviceable	0	0	No					0	Deny
		0	1		R/F INN SPACER RING (NPA)	Serviceable	0	0	No					0	Deny
		0	1		GRILLE (WCP) (10%)	Cracked	0	715	No					715	Reviewing
		0	1		RAD GRILLE BRACKET (WCP) (10%)	Cracked	0	198	No					198	Reviewing
		0	1		BONNET EMBLEM (WCP) (10%)	Bent	0	71.5	No					71.5	Reviewing
		0	1		BONNET (WCP) (10%)	Bent	0	1650	No					1650	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		LEFT BONNET HINGE	Repair	0	0	No					0	Deny
		0	1		RIGHT BONNET HINGE	Repair	0	0	No					0	Deny
		0	1		CTR BONNET INSULAT	Serviceable	0	0	No					0	Deny
		0	1		BONNET CATCH	Serviceable	0	0	No					0	Deny
		0	1		L/F BONNET STRUT	Serviceable	0	0	No					0	Deny
		0	1		R/F BONNET STRUT	Serviceable	0	0	No					0	Deny
		0	1		L/UPPER LATCH	Repair	0	0	No					0	Deny
		0	1		R/UPPER LATCH (WCP) (10%)	Damaged	0	28.6	No					28.6	Reviewing
		0	1		L/SPRING ELEMENT (WCP) (10%)	Missing	0	24.2	No					24.2	Reviewing
		0	1		R/SPRING ELEMENT (WCP) (10%)	Missing	0	24.2	No					24.2	Reviewing
		0	1		L/LOWER LATCH	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		R/LOWER LATCH	Serviceable	0	0	No					0	Deny
		0	1		FRONT RADAR SENSOR	Serviceable	0	0	No					0	Deny
		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Cut	0	2420	No					2420	Reviewing
		0	1		RIGHT HEADLAMP ASSY (WCP) (10%)	Cracked	0	2420	No					2420	Reviewing
		0	1		CTR FRT REINF (WCP) (10%)	Bent	0	115.5	No					115.5	Reviewing
		0	1		BONNET LAND PNL SUPP (WCP) (10%)	Damaged	0	28.6	No					28.6	Reviewing
		0	1		FRONT CTR RETAINER (WCP) (10%)	Damaged	0	38.5	No					38.5	Reviewing
		0	1		FRT LWR CROSSMEMBER	Repair	0	0	No					0	Deny
		0	1		L/F UPP REINF (WCP) (10%)	Damaged	0	187	No					187	Reviewing
		0	1		R/F UPP REINF	Repair	0	0	No					0	Deny
		0	1		AIR CON CONDENSER	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		UPPER AIR GUIDE (WCP) (10%)	Cracked	0	99	No					99	Reviewing
		0	1		AIR GUIDE	Serviceable	0	0	No					0	Deny
		0	1		RADIATOR	Serviceable	0	0	No					0	Deny
		0	1		L/FASTENING CLIP	Serviceable	0	0	No					0	Deny
		0	1		R/FASTENING CLIP	Serviceable	0	0	No					0	Deny
		0	1		L/UPPER BEARING	Serviceable	0	0	No					0	Deny
		0	1		R/UPPER BEARING	Serviceable	0	0	No					0	Deny
		0	1		FAN UNIT	Serviceable	0	0	No					0	Deny
		0	1		AIR INTAKE HOSE	Serviceable	0	0	No					0	Deny
		0	1		L/H-LAMP LVL C-UNIT	Serviceable	0	0	No					0	Deny
		0	1		R/H-LAMP LVL C-UNIT	Serviceable	0	0	No					0	Deny
		0	10		INSULATOR CLIPS	Serviceable	0	0	No					0	Deny
		0	15		FRT BUMP CLIPS	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
			0		BONNET CABLE (WCP) (10%)	Damaged	0	60.5	No					60.5	Reviewing

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
			0		CHECK WIRING	0	20	0	0	Reviewing
			0		TO RESET & DIAGNOSE	0	0	0	0	Deny
			0		REINSTALL BUMP SENSOR	0	60	0	0	Reviewing
			0		181.0 WU X 45.00 SGD/H	0	369	0	0	Reviewing
			0		LABOUR COST 160.0 WU X 45.00 SGD/H	0	526.5	0	0	Reviewing
			0		MATERIAL COST	0	230.06	0	0	Reviewing



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
☐		0	DAYS OF REPAIR : 5 DAYS	Reviewing		0		
☐		0	RADIATOR COOLANT	Reviewing		30	NECESSARY	
☐		0	AIR CON GAS	Reviewing		50	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$8,566.16		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$8,080.60					
Labour	\$0.00	\$1,205.56					
Miscellaneous	\$0.00	\$80.00					
Excess		-\$800.00					

Submit for Review