

Attn: Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

EQ Insurance Co. Ltd

22 Gemmill Lane

Singapore 069257

Tel : 6223 - 9433

Fax : 6224 - 3903

TPEQ

Vic

Quotation

DATE : 20.03.2019

VEH NO : SLG2876Y

MODEL : Honda Shuttle

D O A : 19.03.2019

YR REF : SJR1225Z

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLG2876Y (HONDA SHUTTLE)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	1,150.60
2	Rear Bumper Clips <i>m</i>	1 set	30.00
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	136.00
4	Rear Bumper Lower Cover <i>Missing</i>	1	26.50
5	Rear Bumper Side Grille - LH & RH <i>RH cut</i>	2	140.00 55
6	Rear Bumper Side Reflector - LH & RH <i>new</i>	2	173.20
7	Rear End Panel <i>Dented</i>	1	601.90
8	Rear End Panel Top Garnish <i>Delnd</i>	1	261.00
9	Tail Lamp - LH & RH <i>new</i>	2	1,040.00
10	Tailgate <i>Distorted</i>	1	1,193.70
11	Tailgate Lock <i>Dented</i>	1	181.60
12	Tailgate Lock Sensor <i>Not new</i>	1	85.40
13	Tailgate Weatherstripe <i>cut</i>	1	168.50
14	Tailgate Inner Trim Board <i>Delnd</i>	1	320.40
15	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00
16	Tailgate Reflector - LH & RH <i>RH crushed</i>	2	609.00 344.50
17	Tailgate Outer Chrome Moulding <i>crushed</i>	1	435.00
18	Tailgate Glass Moulding <i>new</i>	1	138.90
19	Honda Logo <i>3 new</i>	1	30.10
20	Shuttle Wording <i>3 new</i>	1	65.00
21	Rear Fender Inner Trim Board - LH & RH <i>RH Deformed</i>	2	670.00 335
22	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	60.00 30.
23	Tools Tray <i>crushed</i>	1	428.00
24	Jack Cover <i>Deformed</i>	1	115.80
25	Spare Tyre Panel Top Cover <i>new</i>	1	299.00
26	Rear Exhaust Pipe <i>3 new</i>	1	745.90
27	Rear Exhaust Mounting <i>new</i>	1	26.50
			\$ 9,262.00

4902

6127.50

RE: ESTIMATE FOR ACCIDENT REPAIR SLG2876Y (HONDA SHUTTLE)

Less 25%

(2,315.50)

\$ 6,946.50

S/NET ITEMS

1	Reverse Sensor	David	1	280.00	20
2	Rear End Panel Sealant	Free	1	60.00	✓
3	Tailgate Glass Sealant		1	60.00	✓
4	Rear Camera	XRP MR	1	480.00	X
				880.00	

Total Parts

\$ 7,826.50

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts		\$ 1,200.00	800
2	To putty & spray up paint works		\$ 1,200.00	800
3	To check wiring		\$ 50.00	30
4	To under seal		\$ 150.00	60
5	To remove upholstery		\$ 150.00	80
6	To remove reverse sensor		\$ 100.00	50
7	To remove rear camera	2070	\$ 100.00	50
8	To remove exhaust pipe		\$ 150.00	X
9	To transfer tailgate fittings		\$ 150.00	80
10	To remove tailgate glass		\$ 180.00	120

Total Labour

\$ 3,430.00

Grand Total

\$ 11,256.50

GST Will be reflected in the final bills

NOTE: -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged parts for confirmation
- Parts price to be agreed for confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7292

4/5: 581c

06 Days