

ASS. REC. BY:

REF:

Tm1 / 003 / TM190005035 / Kqd3n2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

21/3/19 8:29 AM (Red 62374.99, 87%)

SHC 5322C - NA / CTE / S015157 / h4

SH 1019T - X

20/3/19 @ 4:05 PM Email GIA & Estimate to Tm1.

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

11/3/19 Tm1

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fixes

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

MER-TP

2900

250

10

260

Shiau Chan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 25 March 2019 3:40 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: TP VEHICLE SHC 5322C (DOA: 17/03/2019) -- AAD1903-118
Attachments: image001.wmz

WITHOUT PREJUDICE

Dear Shiau Chan

We confirmed COR amount \$ 2,900 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, 25 March, 2019 2:58 PM
To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHC 5322C (DOA: 17/03/2019)

Dear Wai Yin,

WITHOUT PREJUDICE

Based on our surveyor's estimate marking, the calculation repair cost will be at Lump Sum \$2,900.00 before GST and 2.5 repair days.

Kindly check.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 20 March 2019 4:05 PM
To: motorclaims@tokiomarine.com.sg
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 17/03/2019 , SHC 5322C (TP Vehicle), SLJ 9019T (OI Vehicle)
Attachments: SHC5322 EST.pdf; SHC5322 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5322C at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 19/03/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5322C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000950
Chassis No.:	VF1ABL15AUC276867
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	21 Mar 2014
First Registration Date:	21 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$22,068.00
Total Rebate Amount:	\$31,441.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 11:27
Date Of Accident	17/03/2019 10:20
Exact Location Of Accident	SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5322C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	TAN SENG KIEN
NRIC No	S0230842H
Date Of Birth	16/06/1954
Occupation	OUTDOOR
Date Of Driving Pass	24/12/1971
Driving Experience	47 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96536852
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 151 ANG MO KIO AVENUE 5 #11-3040
Postcode	560151
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : AH SOO - 90286811 GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 17.03.2019 at about 1020 hours, I was travelling straight on the extreme left lane along Serangoon Road when Vehicle B (SLJ9019T) which was travelling on my right suddenly swerved into my lane without checking for oncoming vehicle and hit onto my taxi right side portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ9019T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

ST George Rd

A: SHC 5322C

B: SLJ 9019T

Serangoon Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see the attach GLA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5322C**AAD1903-118***Not Notion.*
1/1/2014

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5322C

VF1ABL15AUC276867

RENAULT

LATITUDE

17.3.2019

TOKIO MARINE

21/3/2014

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER SUPPORT FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE LH
1	BUMPER BEAM FRT
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET LOWER LH
1	FENDER INSULATOR LH
1	DOOR PANEL FRT LH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	RADIATOR FAN COWLING
1	RADIATOR FAN MOTOR LH
1	RADIATOR FAN MOTOR RH
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	AIR CLEANER BOX
1	AIR CLEANER HOSE

LIST

\$	<i>Bu</i> 1,259.42 ✓
\$	<i>Sn</i> 181.75 X
\$	<i>Sn</i> 394.68 X
\$	<i>Sn</i> 151.41 X
\$	<i>Sn</i> 123.88 X
\$	<i>DI</i> 150.77 ✓
\$	<i>Sn</i> 123.88 X
\$	<i>Sn</i> 472.83 X
\$	<i>Sn</i> 266.80 X
\$	<i>Sn</i> 207.21 X
\$	<i>R</i> 914.08 X
\$	<i>Sn</i> 1,184.43 X
\$	<i>R</i> 152.15 X
\$	<i>R</i> 783.83 ✓
\$	<i>Sn</i> 278.84
\$	<i>Sn</i> 15.79
\$	<i>Sn</i> 130.84
\$	<i>R</i> 2,844.66
\$	<i>Sn</i> 1,707.78
\$	<i>Sn</i> 225.36
\$	<i>Sn</i> 1,353.75
\$	<i>Sn</i> 820.54
\$	<i>Sn</i> 967.36
\$	<i>Sn</i> 1,479.46
\$	<i>Sn</i> 1,353.75
\$	<i>R</i> 615.90
\$	<i>R</i> 89.79
\$	<i>Sn</i> 464.20
\$	<i>Bu</i> 175.85

X

Trans-cab Auto Services Pte Ltd

AAD1903-118

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5322C

TOTAL	\$	18,891.00
10%	\$	1,889.10
	\$	17,001.90

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00 } X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i> 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i> 30.00
1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 30.50
1	FRONT LEFT TYRE RIM	\$	<i>nn</i> 330.00 ✓
1	FRONT LEFT TYRE	\$	<i>nn</i> 300.00 X
		\$	938.00

TOTAL PARTS	\$	17,939.90
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00 <i>500/</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>600/</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30/</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 <i>60/</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>20/</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>15/</i>

Trans-cab Auto Services Pte Ltd

AAD1903-118

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5322C

To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00 X
To replace, refix and top up coolant for radiator	\$	nn 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00 X

TOTAL \$ 8,710.00

Over All Total \$ 26,649.90

LUMP SUM (REPAIR DAY)

10 DAYS

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19005035/KQD3N2

Date: 02/04/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MH001075
Claimant Vehicle No :	SHC5322C	Insured Vehicle No :	SLJ9019T
Date of Loss:	17/03/2019	Nature of Claim:	TP
		Claim No:	M1901712

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5322C	Engine No:	M9R8839C000950
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276867
Reg. Date:	21/03/2014 (Man. Year: 2013)	Odometer:	664040 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,939.89	2,370.62	15,569.27	86.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,710.00	1,285.00	7,425.00	85.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,649.89	3,655.62	22,994.27	86.28
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	26,649.89	2,900.00	23,749.89	89.12
+ GST 7.00/7.00% (S\$)	1,865.49	203.00	1,662.49	89.12
Nett Amount (S\$)	28,515.38	3,103.00	25,412.38	89.12

INSPECTION

Date of Assignment:	20/03/2019	
Date Inspected:	19/03/2019 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.5 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2019)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5322C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	* FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	* FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	* FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	* FL
6	1		*BUMPER RETAINER FRT RH	Distorted	150.77 FL	*150.77 FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	* FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	* FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	* FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	* FL
11	1		*BUMPER BEAM FRT	Repair	914.08 FL	* FL
12	1		*HEADLAMP LH	Serviceable	1,184.43 FL	* FL
13	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	* FL
14	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
15	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	* FL
16	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	* FL
17	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	* FL
18	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	* FL
19	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	* FL
20	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	* FL
21	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	* FL
22	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	* FL
23	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	* FL
24	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	* FL
25	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	* FL
26	1		*FRAME FULL SUPPORT PANEL	Repair	615.90 FL	* FL
27	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	* FL
28	1		*AIR CLEANER BOX	Serviceable	464.20 FL	* FL
29	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	* FL
30	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
31	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	* FS
32	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	* FS
33	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	* FS
34	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	* FS
35	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	* FS
36	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	* FS
37	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	* FS
38	1		*FRONT LEFT TYRE RIM	Dented	330.00 FS	*330.00 FS
39	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	* FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,828.99	2,590.02
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,889.10	219.40
Total Parts (\$\$)	17,939.89	2,370.62

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,500.00	500.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	20.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
10	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
11	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
Gross Labour Cost (\$\$)			8,710.00	1,285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >