

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 50523
Date Estimated : 18/03/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
DAI WEI
62 TANAH MERAH KECHIL AVENUE
#11-22
SINGAPORE
SINGAPORE 465530

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA2030R	5K81051	30/04/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To replace radiator assembly, fan housing with fan include pressure tests, bleed cooling system and conducting checks for leak *	702.00		702.00 ✓
--	--------	--	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

RADIATOR *	819.55	1.00		819.55 ✓
# FASTENING ELEMENTS *	11.00	2.00		22.00 ✓
# ANTI-FREEZE 1.5 LITRES *	20.10	2.00		40.20 ✓

Total Labour :	702.00
Total Parts :	881.75
Total Labour & Parts :	1,583.75