

BEST SOLUTION AUTOCARE PTE LTD

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Mar 003/2019
Date	19/03/19
Vehicle No	SIX7219X
Make / Model	Toyota Prius

TP A19
Vic

JTDKN364205100934

To:
Address:

Qty	DESCRIPTION	UNIT	Amount
	Items		
1pc	rear bumper <i>Debond</i>		\$ 685.00 ✓
2pcs	rear bumper side retainer <i>NEC</i>		\$ 97.00 ✓
1 set	rear bumper clip <i>NEC</i>		\$ 40.00 ✓
1set	rear bumper reverse sensor <i>damaged</i>		\$ 200.00 ✓
1pc	rear bumper reinforcement <i>sum</i>		\$ 275.00 +
1pc	rear bumper inner sponge		\$ 48.00 +
1pc	rear end panel <i>Reps</i>		\$ 735.00 +
1pc	rear end panel top garnish <i>NEC</i>		\$ 227.00 +
1set	rear end panel top garnish clip <i>NEC</i>		\$ 40.00 +
1pc	tailgate <i>Dented</i>		\$ 1,350.00 1008
1pc	tailgate glass sealant - upper		\$ 80.00 ✓
1pc	tailgate glass sealant - lower		\$ 80.00 ✓
1pc	tailgate Toyota emblem <i>NEC</i>		\$ 89.00 ✓
1pc	tailgate Prius emblem		\$ 89.00 ✓
1pc	tailgate Centre emblem		\$ 93.00 ✓
2pcs	tail lamp <i>Rit ut</i>		\$ 635.00 317.50
1pc	tailgate Hybrid Synergy Drive emblem <i>NEC</i>		\$ 97.00 ✓
1pc	rear no. plate <i>sum</i>		\$ 60.00 +
1pc	rear bumper under cover		\$ 327.00 +
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 800.00 500
2	to putty and spray painting on affected area		\$ 900.00 500
3	anti rust		\$ 80.00 +
4	wiring check		\$ 50.00 30
5	rear reverse sensor		\$ 80.00 50
6	rear windscreen - upper		\$ 150.00 120
7	rear windscreen - lower		\$ 120.00 60
	Subtotal:		\$ 4227.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Total: 3409.12
L/S: 2.71C
OS Reps

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MU: 422K
PV: 16.9K
MT: 45.1K