

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

Reference No: 22319**Date: 22.03.2019****Ho Wei Chyi (He Weiqi)****Blk 126D Edgedale Plains #10-316,****Singapore 824126.****Hyundai 05 Kona 1.0T GDI MT****Estimated Repair Cost for Vehicle Reg. No: SLZ 9083 Y****REPLACEMENT OF DAMAGED PANELS / PARTS (1)**

1 Pc. Front Bumper Cnt	481.00	✓	
1 Pc. Front Bumper Centre Grille Top NH	485.00	X	
1 Pc. Front Bumper Lower Spoiler Cnt	265.00	✓	
2 Pcs. Front Bumper H/Lamp Garnish RH/LH @ 239.20	478.40	✓	N/S Cnt o/s NH
2 Pcs. Front Bumper H/Lamp Cover NH @39.60	79.20	X	
2 Pcs. Front Bumper Fog Lamp Grille @51.40	102.80	✓	N/S Cnt o/s NH
2 Pcs. Front Bumper Side Retainer NH @ 20.50	41.00	X	
1 Pc. Front Bumper Beam Bt	645.40	✓	
1 Pc. Front Bumper Reflector LH NH	69.00	X	
1 Pc. Front Bumper Lower Lip Cnt / deformed	289.00	✓	
1 Pc. Front Bumper Lower Garnish NH	265.00	X	
20 Pcs. Front Bumper Clips NH @ 5.50	110.00	30.00 SH	
1 Pc. Front Bumper Sponge torn	96.20	✓	
4 sets Front Bumper Parking Sensor @ 179.80	719.20	✓	N/S 2pc Dam
1 Pc. Front Grille & Logo CRACK	486.85	✓	
2 Pcs. Front Headlamp RH/LH Assy. @ 1,844.00	3,688.00	✓	mainly crack / broken
2 Pcs. Front Signal Lamp RH/LH Assy. @ 773.50	1,547.00	✓	N/S Cnt o/s NH
1 Pc. Front Support Lower Garnish NH	355.00	X	
10 Pcs. Front Support Garnish Clips NH @5.50	55.00	X	
1 Pc. Front Support Panel Bt / CRACK	949.00	✓	
1 Pc. Front Air Bags Sensor (Bumper LH) Retainer	385.00	✓	
1 PC. Front Horn NH	98.00	X	

Sub Total (1) (Panels / Parts): 11,690.05 (SGD)

8709.15

30.00 SH

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

REPLACEMENT OF DAMAGED PANELS / PARTS (2)

1 Pc. RH Front Fender <i>Devent</i>	551.50 ✓
1 Pc. RH Front Fender Garnish <i>HN</i>	144.45 X
1 Pc. RH Front Fender Protector <i>Cut</i>	105.00 X
10 Pcs. RH Fender Protector Clips <i>HN</i> @ 5.50	55.00 20/- <i>SN</i>
12 Pcs. RH Front Fender Garnish Clips <i>HN</i> @ 5.50 <i>HN</i>	66.00 X
1 Pc. RH Front Fender Dust Garnish <i>HN</i>	175.48 X
10 Pc. RH Front Fender Dust Garnish Clips @ 5.50 <i>HN</i>	55.00 X
1 Pc. RH Door (Front) <i>BN</i>	1,594.30 ✓
1 Pc. RH Door Hinger Upper <i>BT</i>	63.20 ✓
1 Pc. RH Door Hinger Lower <i>BT</i>	63.20 ✓
1 Pc. RH Door Centre Stopper <i>BT</i>	65.30 ✓
1 Pc. RH Door Protector <i>dislodged</i>	173.20 ✓
10 Pcs. RH Front Door Protector Clips <i>HN</i> @ 5.50	55.00 20/- <i>SN</i>
1 Pc. RH Door Lock Assy. <i>Don</i>	245.30 ✓
1 Pc. RH Door Outer Handle <i>HN</i>	147.50 X
1 Pc. RH Door Side Mirror Assy. <i>HN</i>	692.00 X
1 Pc. RH Door Frame Sticker <i>HN</i>	77.10 ✓
1 Pc. RH Door Glass Moulding <i>BT</i>	72.60 ✓
1 Pc. RH Door Inner Rubber <i>damaged</i>	135.00 ✓
1 Pc. RH Door Power Window Regulator Assy. <i>BT</i>	195.00 ✓
1 Pc. RH Door Board <i>damaged</i>	512.00 ✓
1 Pc. RH Door Control Switch <i>HN</i>	573.00 X
10 Pcs. RH Door Board Clips <i>HN</i> @ 5.50	55.00 20/- <i>SN</i>

Sub Total (2) (Panels / Parts): 5,871.13 (SGD)**REPLACEMENT OF DAMAGED PANELS / PARTS (3)**

1 Pc. RH Door Inner Seal (Front) <i>HN</i>	146.60 ✓
1 Pc. RH Door Inner Sealant <i>HN</i>	80.00 20/- <i>SN</i>
1 Pc. RH Door Inner Moulding <i>HN</i>	72.60 X
1 Pc. RH Door Channel Rubber <i>HN</i>	95.30 X

3894.30

80.00 *SN*

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. RH Front Door Frame Rubber <i>deformed</i>	89.10	✓
1 Pc. RH Rear Door <i>bn</i>	1,832.95	✓
1 Pc. RH Rear Door Hinger Upper <i>bt</i>	63.20	✓
1 Pc. RH Rear Door Hinger Lower <i>bt</i>	63.20	✓
1 Pc. RH Rear Door Stopper <i>bt</i>	65.30	✓
1 PC. RH Rear Door Protector <i>bt</i>	142.00	✓
1 Pc. RH Rear Door Lock Assy. <i>Dom</i>	238.20	✓
1 Pc. RH Rear Door Outer Handle <i>Dom</i>	147.20	✓
1 Pc. RH Rear Door Frame Sticker <i>hlc</i>	63.00	✓
1 Pc. RH Rear Door Glass Moulding <i>bt</i>	89.00	✓
1 Pc. RH Rear Door Inner Rubber <i>deformed</i>	168.00	✓
1 Pc. RH Rear Door Power Window Regulator Assy. <i>bt</i>	190.00	✓
1 Pc. RH Rear Door Board <i>mondy crake</i>	533.00	✓
10 Pcs. RH Rear Door Board Clips <i>hlc</i> @ 5.50	55.00 30/- SH	
1 Pc. RH Rear Door Inner Seal <i>hlc</i>	147.00	X
1 Pc. RH Rear Door Inner Sealant <i>hlc</i>	80.00	X
1 Pc. RH Centre Door Pillar <i>hlc</i>	3,539.00	✓
1 Pc. RH Centre Pillar Housing <i>Deuter</i>	946.50	✓
1 Pc. RH Centre Local Panel <i>hlc</i>	1,480.00	✓
1 Pc. RH Centre Local Panel Garnish <i>deformed</i>	338.00	✓
10 Pc. RH Centre Local Panel Clips <i>hlc</i> @ 5.50	55.00 20/- SH	
1 Pc. RH Rear Door Pillar Rubber <i>hlc</i>	65.30	X
1 Pc. RH Rear Fender <i>Deuter</i>	1,768.00	✓
1 Pc. RH Rear Fender Protector <i>dislodged</i>	181.00	✓
10 Pcs. Rear Fender Protector Clips <i>hlc</i> @ 5.50	55.00 20/- SH	
1 Pc. Rear Bumper <i>Cnt</i>	475.00	✓
2 Pcs. Rear Bumper side Retainer <i>hlc</i> @ 37.00	74.00	X
1 set Rear Bumper Parking Sensor <i>Dom</i> @ 217.50	870.00	✓
1 Pc. Rear Bumper Beam <i>hlc</i>	218.00	X
2 Pcs. Rear Bumper Catch <i>hlc</i> @ 28.00	56.00	X
1 Pc. Rear Bumper Sponge <i>dislodged</i>	110.00	✓
1 Pc. Rear Fender Dust Garnish <i>dislodged</i>	159.50	✓
10 Pcs. Rear Fender Dust Garnish Clips @ 5.50 <i>hlc</i>	55.00 20/- SH	
1 Pc. Rear Fender Housing <i>hlc</i>	1,085.00	✓

Sub Total (3) (Panels / Parts): 15,890.95 (SGD)

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

REPLACEMENT OF DAMAGED PANELS / PARTS (4)

1 Pc. Rear Bumper Centre Pad <i>Cwt</i>	168.00	✓
2 Pcs. Rear Bumper Lamp Assy. <i>broken</i> @ 162.00	324.00	✓
1 Pc. Rear Bumper Dust Garnish RH <i>HW</i>	96.00	X
1 Pc. Rear Bumper Panel Garnish RH <i>HW</i>	109.00	X
1 Pc. Roof Airbags <i>actuated</i>	1,440.00	✓
1 Pc. Cushion Seat Airbags <i>actuated</i>	1,166.30	✓
1 Pc. Roof Airbags Sensor <i>Dom</i>	526.00	✓
1 Pc. Cushion Airbags Control Unit <i>actuated</i>	1,061.00	✓
1 Pc. Front RH Windscreen Pillar Garnish <i>HW</i>	158.00	X
1 Set Roof Lining Assy. <i>Wt</i>	1,535.30	✓
1 Pc. Front RH Safety Belt <i>actuated</i>	909.50	✓
1 Pc. Rear RH Safety Belt Control Unit <i>HW</i>	645.00	X
1 Pc. RH Cushion Assy. <i>Dom (driver)</i>	1,690.00	✓
1 Pc. FCA Control Unit (Agent Control Item) (Forward Collision Avoidance Asst.) <i>HW Dom</i>	1990.00	X ✓
1 Pc. Centre Pillar Upper Garnish <i>monty crack</i>	64.50	X ✓
1 Pc. Centre Pillar Lower Garnish <i>broken</i>	65.30	✓
1 Pc. Front Windscreen Top Moulding <i>HW</i>	55.00	X
1 Pc. Front Windscreen Inner Seal <i>HW</i>	52.00	X
1 Pc. Rear RH Quarter Glass Moulding & Sea Assy. <i>HW</i>	309.00	✓
1 Pc. Rear RH Cushion Top <i>defused</i>	699.00	✓
1 Pc. Rear RH Cushion Cover <i>defused</i>	95.00	✓
1 Pc. Dash Board <i>Wt / monty defused</i>	918.00	✓

Sub Total (4) (Panels / Parts): 12,085.90 (SGD)

12960.90

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

REPLACEMENT OF DAMAGED PANELS / PARTS (5)

1 Pc. RH Front Absorber <i>bt</i>		392.00	✓
1 Pc. RH Front Absorber Moulding <i>NH</i>		135.00	X
1 Pc. RH Front Knuckle Arm <i>distorted 1 bt</i>		382.00	✓
1 Pc. RH Front Knuckle Hup & Bearing <i>Dam</i>		573.00	✓
1 Pc. Steering Rack Assy. <i>Dam</i>		1,027.00	✓
1 Pc. RH Front Wheel Sensor <i>NH</i>		158.00	X
1 Pc. RH Lower Arm (Front) <i>distorted</i>		472.00	✓
2 Pcs. RH Rear Absorber RH/LH @ 278.00		556.00	✓ <i>o/s distorted N/S NH</i>
2 Pcs. RH Rear Absorber Mounting RH/LH @ 149.00 <i>NH</i>		298.00	X
1 Pc. RH Rear Axle <i>distorted</i>		1,235.00	✓
2 Pcs. RH Rear knuckle Hup Bearing & Sensor @ 487.00		974.00	✓ <i>o/s Dam N/S NH</i>
4 Pcs. Sport Rim (17") @ 330.00	SN	1,320.00	✓ <i>o/s front o/s Rear</i>
4 Pcs. Tyre (215 x 55 x R17) <i>568.00</i> @ 355.00 <i>80% SN</i>		1,420.00	✓ <i>o/s front o/s Rear</i>
1 Pc. Air Pressure Sensor <i>Dam o/s mar</i>		199.00	✓
1 Pc. Brake Oil <i>NH</i>		90.00	X
4 Pcs. Wheel Mudflap @ 59.00		236.00	3 pc <i>o/s front o/s Rear</i>
1 Set Front Number Plate & Box <i>bt</i>	SH <i>60.00</i>	451-SH	<i>N/S Rear front</i>

Sub Total (5) (Panels / Parts): **9,527.00 (SGD)***List price discount 20%.*Grand Total (1) (2) (3) (4) (5) (Panels / Parts): **55,065.03 (SGD)****Summary**

- (1) 11,690.05 (SGD)
 (2) 5,871.13 (SGD)
 (3) 15,890.95 (SGD)
 (4) 12,085.90 (SGD)
 (5) 9,527.00 (SGD)

5222.00

1273.00 SH

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

LABOR CHARGESTo check wiring, check SRS, Air-Bag & erase fault
Coding & coding & central lock wiring.~~800.00~~ 350/-

To remove and refit windscreen & quarter glass.

~~280.00~~ 180/-To remove & refit interior carpet garnish, roof
Lining, cushion & all accident affected area &
Cleaning.~~900.00~~ 300/-To remove & refit front & rear under carriage
Damage affected area.~~1,800.00~~ 800/-

To remove & renew sport rim, tyre & rebalancing.

~~200.00~~ 80/-To knocking, welding, straightening all accident
Damage affected area.~~3,000.00~~ 2600/-

To respray painting on all accident affected area.

~~2,400.00~~ 1900/-

To rust proof all accident affected area.

~~400.00~~ 150/-

To press wheel hup bearing.

200.00 44

To adjust computer wheel alignment & test drive.

~~280.00~~ 80/-To remove & refit air-con condenser & turbo cooler
& top-up gas & oil.~~280.00~~ 120/-

To remove & refit & renew dash board.

~~800.00~~ 180/-

Total (Labor Charges): 11,340.00 (SGD)

6740.00

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

TOTAL COST SUMMARY

PANELS / PARTS

LABOR CHARGES

Grand Total:

55,065.03

11,340.00

66,405.03 (SGD)

List

45422.50

20%

3633.80

SH

1473.00

Lebm

6740.00

44551.00

1/536000/-

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

GOH LEE HWA AUTOMOBILE PTE LTD

List

4343.28

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28/03/2019 @ 1100ms

NIA Antenna

2/Sum 25 days.

ryan

LKK Auto