

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0150/2019
DATE : 19-MAR-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : CHEONG WILLIAM CHOON FOONG
ADDRESS : 369 HOLLAND ROAD
#12-01
S(278640)
TELEPHONE NO : 97803989

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SDB7427Z
VEHICLE NO : SLM1435L
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2402503A
CHASSIS NO : SJNFEAJ11U1912756
MILEAGE : 1 KM
DATE IN : 19/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 18/02/2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

19-3-2019

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM1435L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	R/INSTALL ADJUST H/LAMP RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓
4	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	✓
5	ZZ/001	REPAIR FRONT H/LAMP PANEL RH & FRT UPPER PANEL RENEW FRT FENDER & FRT BUMPER COVER 150	750.00	500
6	ZZ/002	S/PAINT FRT BUMPER COVER, FRT FENDER RH & FRT PANEL 200	600.00	400
7	ZZ/003	CONDUCT WHEEL BALANCING & RENEW FRT S/RIM RH	15.00	✓
TOTAL LABOUR CHARGES			1726.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM1435L

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES / <i>MEC</i>	NPN		<i>20</i>	30.00
2 FENDER-ARC,FR / <i>CUT</i>	63810-4EA0A	483.00		
3 WHEEL-ROAD AL / <i>CUT</i>	D0300-4EA1A			1231.90
4 BRKT-BPR SIDE,R / <i>BR</i>	62222-4EA0A	20.90		
5 CLIP(1.2X10) / <i>MEC</i>	01553-05933	12.00		
6 FINISHER-FRONT <i>X</i>	62256-4EA0C	74.70		
7 BUMPER SET FR <i>X CUT B / CUT</i>	62022-4EA0H	614.60		
8 FENDER-FRONT RH / <i>DD</i>	F3100-4EAMB	622.70		
SUB TOTAL		1827.90	0.00	1261.90
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		365.58	0.00	0.00
GRAND TOTAL		1462.32	0.00	1261.90
OVERALL TOTAL		2724.22		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM1435L

TOTAL LABOUR CHARGES	1726.00
TOTAL SPARE PARTS CHARGES	2724.22
GRAND TOTAL	4450.22 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

83228813
Steve
22/5/19, 10.45 am
w/til
P/P
5 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: