

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0150/2019
DATE : 19-MAR-2019

DS => Steve (LKK)

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

ZHR

OWNER'S NAME : CHEONG WILLIAM CHOON FOONG
ADDRESS : 369 HOLLAND ROAD
#12-01
S(278640)
TELEPHONE NO : 97803989

Recommend Repair 7 Days.

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SDB7427Z
VEHICLE NO : SLM1435L
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2402503A
CHASSIS NO : SJNFEAJ11U1912756
MILEAGE : 1 KM
DATE IN : 19/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 18/02/2019

LOU => \$60 x 7 Days.
=> \$420.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM1435L

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 PHI	R/INSTALL ADJUST H/LAMP RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00 ✓
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00 X
3 RRMLB	TO RENEW REAR BEAM-SUPPLEMENTARY LABOUR	240.00	240.00 ✓ <i>Sup</i>
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00 ✓
5 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	93.00 ✓
6 ZZ/001	REPAIR FRONT H/LAMP PANEL RH & FRT UPPER PANEL RENEW FRT FENDER, FRT BUMPER & RR BUMPER(SUPPLE)	750.00	625.00 ✓
7 ZZ/002	S/PAINT FRT BUMPER COVER, FRT FENDER RH & FRT PANEL S/PAINT RR BUMPER-2 TONE(SUPPLE)	600.00	700.00 ✓
8 ZZ/003	CONDUCT WHEEL BALANCING & RENEW FRT S/RIM RH	15.00	15.00 ✓
TOTAL LABOUR CHARGES		1966.00	1821.00
ADDITIONAL DISCOUNT(5.00%)			91.05
FINAL LABOUR CHARGES			1729.95

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM1435L

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 BEAM-SUPPLEMENTARY ITEM (Axle Hdr) / BT	55501-4EA0A			1322.80	OK
2 RR ARC RH - SUPPLEMENTARY ITEM / CUT	93828-4EA0A	540.50			OK
3 FASCIA-RR BUMP-SUPPLEMENTARY ITEM / CUT	85022-4EA0H	796.70			OK
4 SUNDRIES	NPN			20.00	OK
5 FENDER-ARC,FR	63810-4EA0A	483.00			OK
6 WHEEL-ROAD AL	D0300-4EA1A			1231.90	OK
7 BRKT-BPR SIDE,R	62222-4EA0A	20.90			OK
8 CLIP(1.2X10) + 10PC SUPPLEMENTARY ITEM	01553-05933	24.00			OK
9 FINISHER-FRONT	62256-4EA0C	74.70			X
10 BUMPER SET FR	62022-4EA0H	614.60			OK
11 FENDER-FRONT RH	F3100-4EAMB	622.70			OK
SUB TOTAL		3102.40	0.00	2574.70	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		620.48	0.00	0.00	
GRAND TOTAL		2481.92 /	0.00	2574.70 /	
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-.00%)		124.10	0.00	0.00	
OVERALL TOTAL		4932.52 /			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLM1435L

NETT ITEM 3102.40
LESS 20.00%) -620.48
NETT AMOUNT 2481.92
ADDITIONAL DISCOUNT(5.00%) -124.10
FINAL AMOUNT 2357.82

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 2574.70
LESS .00%) 0.00
SPECIAL NETT AMOUNT 2574.70

TOTAL LABOUR CHARGES 1729.95 /
TOTAL SPARE PARTS CHARGES 4932.52 /

TOTAL CHARGES 6662.47 /
ADD 7 % GST 466.37

GRAND TOTAL 7128.84

Work Order: R000892
License: SLM1435L
Technician: A12

Before

J11

Front : Left

Actual	Before	Specified Range
-0°41'		-1°20' 0°20'
5°19'		4°37' 6°33'
0.8mm		-1.2mm 2.8mm
10°38'		10°37' 12°33'
9°57'		9°17' 12°53'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°54'		-1°20' 0°20'
4°58'		4°37' 6°33'
0.8mm		-1.2mm 2.8mm
12°59'		10°37' 12°33'
12°05'		9°17' 12°53'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°13'		-0°50' 0°50'
0°21'		-0°58' 0°58'
-2°21'		
1.6mm		-2.4mm 5.6mm

Rear : Left

Actual	Before	Specified Range
-1°30'		-1°20' 0°20'
-1.2mm		-2.0mm 4.0mm

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°17'		-1°20' 0°20'
17.6mm		-2.0mm 4.0mm

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-1°13'		
16.4mm		-4.1mm 7.9mm
-0°44'		

Work Order: R000896
License: SLM1435L
Technician: A12

After

J11

Front : Left

Actual	Before	Specified Range
-0°25'		-1°20' 0°20'
5°25'		4°37' 6°33'
0.8mm		-1.2mm 2.8mm
11°14'		10°37' 12°33'
10°49'		9°17' 12°53'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°07'		-1°20' 0°20'
5°09'		4°37' 6°33'
0.9mm		-1.2mm 2.8mm
11°41'		10°37' 12°33'
10°33'		9°17' 12°53'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°42'		-0°50' 0°50'
0°15'		-0°58' 0°58'
-0°27'		
1.7mm		-2.4mm 5.6mm

Rear : Left

Actual	Before	Specified Range
-1°03'		-1°20' 0°20'
-1.9mm		-2.0mm 4.0mm

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°35'		-1°20' 0°20'
4.5mm		-2.0mm 4.0mm

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°33'		
2.6mm		-4.1mm 7.9mm
-0°15'		

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0150/2019
DATE : 19-MAR-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : CHEONG WILLIAM CHOON FOONG
ADDRESS : 369 HOLLAND ROAD
#12-01
S(278640)
TELEPHONE NO : 97803989

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SDB74272
VEHICLE NO : SLM1435L
MODEL CODE : FRLARBEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2402503A
CHASSIS NO : SJNFEAJ11U1912756
MILEAGE : 1 KM
DATE IN : 19/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 18/02/2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

19-3-2019

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM1435L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	R/INSTALL ADJUST H/LAMP RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	/
4	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	/
5	ZZ/001	REPAIR FRONT H/LAMP PANEL RH & FRT UPPER PANEL RENEW FRT FENDER & FRT BUMPER COVER 150	750.00	500 625
6	ZZ/002	S/PAINT FRT BUMPER COVER, FRT FENDER RH & FRT PANEL 200	600.00	400 700
7	ZZ/003	CONDUCT WHEEL BALANCING & RENEW FRT S/RIM RH	15.00	/
TOTAL LABOUR CHARGES			1726.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM1435L

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES / <i>ALC</i>	NPN			<i>20</i> 30.00
2	FENDER-ARC,FR / <i>CUT</i>	63810-4EA0A	483.00		
3	WHEEL-ROAD AL / <i>CUT</i>	D0300-4EA1A			1231.90
4	BRKT-BPR SIDE,R / <i>BR</i>	62222-4EA0A	20.90		
5	CLIP(1.2X10) / <i>ALC</i>	01553-05933	12.00 <i>24</i>		
6	FINISHER-FRONT <i>X</i>	62256-4EA0C	74.70		
7	BUMPER SET FR <i>X CUT B / CUT</i>	62022-4EA0H	614.60		
8	FENDER-FRONT RH / <i>DD</i>	F3100-4EAMB	622.70		
SUB TOTAL			1827.90	0.00	1261.90
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			365.58	0.00	0.00
GRAND TOTAL			1462.32	0.00	1261.90
OVERALL TOTAL			2724.22		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM1435L

TOTAL LABOUR CHARGES	1726.00
TOTAL SPARE PARTS CHARGES	2724.22
GRAND TOTAL	4450.22 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Steve
SURVEYED DATE	:	22/5/19, 10.45 am
AUTHORIZED DATE	:	with signature
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	P/P 5 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

30-May-2019

INS/C/ZHR/0150/2019

AXA Insurance S'pore Pte Ltd
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Attn : Motor Claim Manager
Claim Dept

(Supp)

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SLM1435L
POLICY NO. : TP - SDB7427Z

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

Replacement of Damaged Items

1	REAR BUMPER	✓ CAT	\$717.00 NETT	✓
2	CLIP (\$1.2X10)	✓ APC	\$12.00 NETT	✓
3	RR FENDER ARC RH	✓ CAT	\$483.00 NETT	✓

Labour & S/PAINT

1	CONDUCT WHEEL BALANCING & RENEW S/RIM	\$15	✓
2	ADD LABOUR FOR RR BUMPER	\$125	✓
9	ADD S/PAINT FOR RR BUMPER(2 tone)	\$300	✓
10			

TOTAL \$ 1,212.00

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

TAN CHONG MOTOR SALES PTE LTD


M. Z. H. R. I.
Insurance Claim Dept

Cc: Surveryor