

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM1435L

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FHT	R/INSTALL ADJUST H/LAMP RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓
4 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	✓
5 ZZ/001	REPAIR FRONT H/LAMP PANEL RH & FRT UPPER PANEL RENEW FRT FENDER & FRT BUMPER COVER 150	750.00	500 625
6 ZZ/002	S/PAINT FRT BUMPER COVER, FRT FENDER RH & FRT PANEL 200	600.00	400 700
7 ZZ/003	CONDUCT WHEEL BALANCING & RENEW FRT S/RIM RH	15.00	✓
TOTAL LABOUR CHARGES		1726.00	

* Supplementary Labour

→ To renew Rear Beam

240 ✓

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM1435L

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES / <i>MLC</i>	NPH		<i>20</i> 30.00
2	FENDER-ARC,FR / <i>CUT</i>	63810-4EA0A	483.00	
3	WHEEL-ROAD AL / <i>CUT</i>	D0300-4EA1A		1231.90
4	BRKT-BPR SIDE,R / <i>BR</i>	62222-4EA0A	20.90	
5	CLIP(1.2X10) / <i>MLC</i>	01553-05933	12.00 <i>24</i>	
6	FINISHER-FRONT <i>X</i> NN	62256-4EA0C	74.70	
7	BUMPER SET FR <i>X</i> <i>CUT</i> <i>B</i> / <i>CUT</i>	62022-4EA0H	614.60	
8	FENDER-FRONT RH / <i>DD</i>	F3100-4EAMB	622.70	
SUB TOTAL			1827.90	0.00 1261.90
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			365.58	0.00 0.00
GRAND TOTAL			1462.32	0.00 1261.90
OVERALL TOTAL			2724.22	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

* supplementary parts

- 1) Beam (Ade Bar) / BT \$1322.80 (SN) ✓
- 2) RR Arc. RH / *Cut* \$540.50 (N) ✓
- 3) Fascia - RR Bumper - *cut* \$796.70 (N) ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM1435L

TOTAL LABOUR CHARGES	1726.00
TOTAL SPARE PARTS CHARGES	2724.22
GRAND TOTAL	4450.22 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

83228813
 Steve
 27/5/19, 10.45 am
 Wil Andrew
 P/P
 8 days
 7.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: