



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2007102
INV Date 20/10/2020
Reference CC3/CTI19005055/K1ea3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 3238X
Insured Veh. YM 6533A
Claim No. SNM19D205890C02
Policy No. DMCVSN1905591900
Accident Date 18/03/2019
Inspection Date 19/03/2019

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19005055/K1ea3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-10-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------------|----------------|------------|
| Insured Veh. | YM 6533A | Veh. Inspected | SHD 3238X |
| Policy No. | DMCVSN1905591900 | Coverage (\$) | 0.00 |
| Claim No. | SNM19D205890C02 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 19/03/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HYUNDAI I40 | c.c | 1685 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | KMHLB41UMGU091607 | Colour | BLUE |
| Odometer | 344887 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | | | |
|----------------|------------|---------|---------|
| | Size | Make | Balance |
| R/H Front Tyre | 205/60 R16 | CAMPEON | 6 mm |
| L/H Front Tyre | 205/60 R16 | CAMPEON | 6 mm |
| R/H Rear Tyre | 205/60 R16 | CAMPEON | 6 mm |
| L/H Rear Tyre | 205/60 R16 | CAMPEON | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 18/03/2019 | Inspection Date | 19/03/2019 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3238X

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | BOOT LID LAMP (RH) | CRACKED | 565.60 | 565.60 |
| 1 | TAIL LAMP (RH) | CRACKED | 697.80 | 697.80 |
| 1 | REAR BUMPER (NPA) | TO REPAIR SEE LABOUR | - | - |
| 1 | REAR FENDER (RH) (NPA) | TO REPAIR SEE LABOUR | - | - |
| | LESS 20% DISCOUNT | | -252.68 | -252.68 |
| | | | 1,010.72 | 1,010.72 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | REAR BUMPER RUBBER MAT (SN) | NOT NECESSARY | 50.00 | - |
| 2 | REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 | NECESSARY | 200.00 | 200.00 |
| | | | 250.00 | 200.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER (RH). | | 200.00 | 200.00 |
| | SPRAY PAINTING CHARGE -BOOTLID /BUMPER. | | 600.00 | 400.00 |
| | TUFF KOTE. | NOT NECESSARY | 50.00 | - |
| | | | 850.00 | 600.00 |
| | GRAND TOTAL | | 2,110.72 | 1,810.72 |
| | RECOMMENDED COST OF REPAIRS | | | 1,810.72 |

Report Ref No. CC3/CT19005055/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3238X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3238X

RE-INSPECTION

