

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3238X

DATE 18/3/2019 15:08

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Lamp (RH) <i>one</i>			\$ 565.60
	Tail Lamp (RH) <i>one</i>			\$ 697.80
	<i>Rear Bumper X repair</i>			
	<i>Rear Fender (RH) X repair</i>			
	SUB TOTAL			\$ 1,263.40
	LESS 20%			\$ 252.68
	DISCOUNTED TOTAL			\$ 1,010.72
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>one</i>		\$ 100.00	\$ 200.00
				\$ 250.00
	Labour Charge			
	Panel Beating			\$ 200.00
	Spray Painting Charge-Bootlid /Bumper <i>X</i>			\$ 600.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 850.00
	ESTIMATE TOTAL			\$ 2,110.72

Kali 10/10/19

19/3/19 11:56

2 P/L

P/L

After Repair p/h

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary items must be pre-approved
- is subject to final approval from his company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 20.03.2019

Time: 18:11:53

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305278656
REGN NO : SHD3238X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2016
DATE/TIME IN : 18.03.2019 11:10
ACCIDENT DATE : 18.03.2019

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0585-A 140VC LAMP ASSY-RR COMB O 1 697.80 20.00 558.24
0002 04-01-0103-0583-G 140V2 LAMP ASSY-RR COMB I 1 565.60 20.00 452.48

SUB-TOTAL : 1,010.72

JOB NATURE

0000 20-05 REAR FENDER ADVERTISEMENT 200.00
0001 PB PANEL BEATING 200.00
0002 SP SPRAYPAINT CHARGE 400.00

SUB-TOTAL : 800.00

TOTAL : 1,810.72

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Our Job Ref No : 305278656

Date : 21/03/19

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD3238X

18/03/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA YM6533A

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,010.72

(b) Labour Charges \$800.00

Total for Part-By-Part Repair Cost \$1,810.72

(c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Kaha

Date : 21/3/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: