

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3238X

DATE 18/3/2019 15:08

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Lamp (RH) ✓			\$ 565.60
	Tail Lamp (RH) ✓			\$ 697.80
	<i>Rear Bumper</i> ✕ <i>repair</i> <i>Rear Fender (RH)</i> ✕ <i>repair</i>			\$ 1,263.40
	SUB TOTAL			\$ 252.68
	LESS 20%			\$ 1,010.72
	DISCOUNTED TOTAL			
	Rear Bumper Rubber Mat ✕			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				\$ 250.00
	Labour Charge			
	Panel Beating			\$ 200.00
	Spray Painting Charge-Bootlid /Bumper ✕			\$ 600.00 400
	Tuff Kote			\$ 50.00 ✕
	TOTAL LABOUR			\$ 850.00
	ESTIMATE TOTAL			\$ 2,110.72

Kali 10/10/19

19/3/19 11:56

2 P2

P/P

After Repair p/h

LKK Auto Consultant's hereby notify the Repairer of the following:

- To resurvey the vehicle after painting
- To display damaged parts for survey
- Parts originality to be maintained
- Third party liability to be maintained
- No illegal modifications to be made
- Supplies to be used must be of good quality and is subject to the insurance company's approval

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.