

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9966Z**AAD1903-106***Not Authorized
C/Sing \$4300/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9966Z

VF1ABL15AUC273447

RENAULT

LATITUDE

15.3.2019

AXA

30/9/2013

PART**LIST**

- | | |
|----|-------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMPER BRACKET SIDE RH REAR |
| 5 | 1 BUMPER RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMPER BRACKET SIDE LH REAR |
| 8 | 1 BUMPER RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 BOOT REAR |
| 14 | 1 BOOT FINISHER |
| 15 | 1 BOOT WHEATERSTRIP |
| 16 | 1 BOOT REFLECTOR LAMP LH |
| 17 | 1 BOOT REFLECTOR LAMP RH |
| 18 | 1 BOOT BADGE 'RENAULT' |
| 19 | 1 BOOT BADGE |
| 20 | 1 BOOT STRUT LH |
| 21 | 1 BOOT STRUT RH |
| 22 | 1 BOOT HINGE LH |
| 23 | 1 BOOT HINGE RH |
| 24 | 1 BOOT INNER TRIM |
| 25 | 1 BOOT SWITCH |
| 26 | 1 BOOT LOCK |
| 27 | 1 BOOT LOCK CATCH |
| 28 | 2 LICENCE PLATE LAMP |
| 29 | 2 BOOT RUBBER PLUG |

\$	<i>R</i>	1,108.46	✓
\$	<i>Mr</i>	768.84	✓
\$	<i>Sn</i>	113.47	X
\$	<i>Sn</i>	135.97	X
\$	<i>Sn</i>	44.99	X
\$	<i>Sn</i>	43.61	X
\$	<i>Sn</i>	135.97	X
\$	<i>Dir</i>	44.99	✓
\$	<i>CM</i>	43.61	✓
\$	<i>R</i>	777.52	✓
\$	<i>R</i>	225.95	✓
\$	<i>R</i>	225.95	X
\$	<i>R</i>	2,872.68	} X
\$	<i>Sn</i>	470.06	
\$	<i>Sn</i>	323.05	
\$	<i>Sn</i>	493.35	
\$	<i>Sn</i>	493.35	
\$	<i>nn</i>	225.36	
\$	<i>nn</i>	225.36	
\$	<i>Sn</i>	276.08	
\$	<i>Sn</i>	276.08	
\$	<i>R</i>	367.84	
\$	<i>R</i>	367.84	
\$	<i>Sn</i>	586.45	
\$	<i>Sn</i>	168.13	
\$	<i>R</i>	202.67	
\$	<i>R</i>	74.40	
\$	<i>Sn</i>	50.52	
\$	<i>Sn</i>	221.81	

Trans-cab Auto Services Pte Ltd**AAD1903-106**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9966Z

30	1 FENDER PANEL REAR RH	\$	N	3,299.13	
31	1 WHEELARCH REAR RH	\$	SL	543.47	
32	1 FENDER PANEL REAR LH	\$	N	3,299.13	
33	1 WHEELARCH REAR LH	\$	SL	543.47	
34	1 TAILLAMP LH	\$	SL	552.55	
35	1 TAILLAMP PANEL LH	\$	N	986.70	
36	1 TAILLAMP RH	\$	SL	552.55	
37	1 TAILLAMP PANEL RH	\$	N	986.70	
38	1 OUTER PANEL REAR (End Panel)	\$	SL	1,471.77	
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56	X
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
42	1 EXHAUST REAR	\$	N	7,489.05	X
43	1 EXHAUST CAP REAR	\$	N	230.49	X

TOTAL	\$	34,526.04
10%	\$	3,452.60
	\$	31,073.44

Special Nett

1	1SET PARKING AID	\$	SL	700.00	X
2	1SET REAR BUMPER CLIP	\$	SL	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	SL	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	SL	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	SL	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	SL	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	SL	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	SL	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	SL	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	SL	17.82	X
11	1SET BOOT FINISHER CLIP	\$	SL	24.20	X
12	1 REAR BOOT ADVERTISEMENT STICKER	\$	SL	300.00	X
13	1 REAR BUMPER ADVERTISEMENT STICKER	\$	SL	300.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-106**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9966Z

14 1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i>	35.00	}	<i>X</i>
15 1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00		
16 1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00		
17 1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00		
18 1 TAILLAMP CLIP RH	\$	<i>nn</i>	5.00		
19 1 TAILLAMP CLIP LH	\$	<i>nn</i>	5.00		
20 2 REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00		
21 1 WINDSCREEN MOULDING	\$	<i>nn</i>	100.00		
22 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00		
23 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sh</i>	385.00		
24 1 SPARE TYRE	\$	<i>sh</i>	330.00		

TOTAL \$ 2,720.02**TOTAL PARTS \$ 33,793.46****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>4401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1903-106**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9966Z

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	na 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	4 380.00	X
TOTAL	\$	14,340.00	

Over All Total \$ 48,133.46**(LUMP SUM)****Repair Days****20 DAYS****4 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: