



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

21 MARCH 2019

REG NO.: GBG 7535 S
MAKE/MODEL: TOYOTA DYNA

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear tailgate	\$ 1,265.60
2	Rear tailgate lock hinges	\$ 290.00
1	Rear tailgate lower panel	\$ 878.50
2	Rear tailgate lower stopper rubbers	\$ 145.20
2	Rear tailgate lower stopper brackets	\$ 213.00
1	Rear tailgate "DYNA" sticker	\$ 38.10
2	Rear taillamps	\$ 659.30
2	Rear taillamp panels	\$ 399.00
1	Rear step bar	\$ 285.00
1	Rear number plate panel	\$ 98.50
1	Rear chassis member -L/H	\$ 1,285.00
1	Rear mudguard -L/H	\$ 280.90
1	Rear mudflap -L/H	\$ 126.50
		\$ 5,964.60
	Less 25%	\$ 1,491.15
		\$ 4,473.45

SPECIAL NETT ITEMS

1	Rear tailgate "13 PAX" sticker	\$ 25.00
1	Rear tailgate "70KM/H" sticker	\$ 25.00
1	Rear side box	\$ 650.00
1	Rear number plate	\$ 50.00
		\$ 750.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00
2	To apply undercoating.	\$ 200.00
3	Panel beating.	\$ 2,000.00
4	To re-spray painting on the affected areas.	\$ 1,800.00
5	To straighten rear chassis frame member and re-align chassis frame.	\$ 1,200.00
		\$ 5,280.00

Resurvey before/after spray painting
To display damaged part(s) during resurvey
Prices are subject to confirmation
Party survey is on a "Without Prejudice" basis
Illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
Subject to final approval from Insurance Company

GRAND TOTAL :

\$ 10,503.45

Acknowledged by Repairer

Signature:

Date: