

RECEIVED

REF CS/SPF 190050751 Jvd302

Special Instruction

Wei Yea

Anna Sie

ASSIGNMENT (Office)

From (Person) Wei Yea Jim

of SPF

Date/Time: 13/2/19 @ 4:24pm

Estimated Cost

Bill to:

① ID / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

Inspect Vehicle No:

QX538M

Insured:

at Workshop n/s:

SMRT

Tel:

of

Gu woodlands Ind. park E4

Policy No:

Claim No: HOMSPFE PQ16000399

Sum Insured

Excess:

Make of Veh:
(Client's Record)

D.O.A -

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

Person Contacted:

Mr. Kong

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Qx 538K - X
2/13/19	Revert to Wei Yea via email
3/4/19	@ 1134am Kim Pang said can submit our report
3/4/19	Parts - \$ 4115, Man-HR-(18 HR)
15/4/19	Email amended report to Kim Pang

Hwee Jie

REF: SPF

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: TBA
 (Client's Record)
 Make of Veh: _____

Veh No. QX538KM Yr Regn: _____ / -
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Avante c.c. _____
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 229453 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHOU418MAU019503
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 185/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

<u>Front</u>		<u>Rear</u>
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. _____		D.O.I. <u>20/3/19</u>

Survey held at Smvt
 Des. of Damages: Frt / Rear / O/S / N/S UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/4/19 @ 10:44am	Kim Pang said submit our report
	RECEIVED 13 APR 2019
	RECEIVED 16 APR 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?

Days Of Repair:
 Resurvey No. of Trip:

1) 3/4 - typist
 Report Format :
 Lump Sum / I.B.I.: (\$)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	<u>200</u>
Transportation:	
) S + PS. SI	
) Photos	
) Othas	
)	
TOTAL	<u>200</u>

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 15 April 2019 4:05 PM
To: Kim Pang CHAY (SPF)
Cc: SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538M)
Attachments: QX 538M.pdf (AMEND).pdf

Dear Kim Pang,

Enclosed amended report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 12 April 2019 5:27 PM
To: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538M)

Dear Kim Pang,

We will check and revert.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Sent: Friday, 12 April 2019 4:46 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538M)

Hi , Shirley

Your attached mail refers.

(1) Any reason why the scope of repairs have S/N 1.2 Replace rear anti-roll bar but material do not have the item?

(2) Are items 1.9 Exhaust Pipe (Front 1) and 1.10 Exhaust Pipe (Front 2) from Wei Yea's excel file attached necessary?

Registration No. QX 538M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT CROSS-MEMBER	1	DENTED	\$ 1,350.00	\$ 1,350.00	
1.2	REAR CROSS-MEMBER	1	BENT	\$ 480.00	\$ 480.00	
1.3	REAR LH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00	
1.4	REAR RH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00	
1.5	REAR LH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00	
1.6	REAR RH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00	
1.7	FUEL TANK	1	DENTED	\$ 650.00	\$ 650.00	
1.8	EXHAUST PIPE (CENTRE)	1	DENTED	\$ 680.00	\$ 680.00	
1.9	EXHAUST PIPE (REAR)	1	DENTED	\$ 450.00	\$ 450.00	
1.10	EXHAUST PIPE GASKET	4	NECESSARY	\$ 25.00	\$ 25.00	
	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 4,115.00	\$ 4,115.00	
1	SCOPE OF REPAIRS					
1.1	FRONT CROSS-MEMBER :					2
	REMOVE & REPLACE FRONT CROSS MEMBER					
1.2	REAR CROSS-MEMBER & ANTI-ROLL BAR :					4
	REMOVE & REPLACE REAR CROSS MEMBER					
	REMOVE & REPLACE REAR ANTI-ROLL BAR					
1.3	REAR LOWER ARM, STAB LINK :					1
	REMOVE & REPLACE REAR LH LOWER ARM					
	REMOVE & REPLACE REAR LH STAB LINK					
	REMOVE & REPLACE REAR RH LOWER ARM					
	REMOVE & REPLACE REAR RH STAB LINK					
1.4	FUEL TANK :					2
	REMOVE & RE-FILL FUEL IN FUEL TANK					
	REMOVE & REPLACE FUEL TANK					
1.5	EXHAUST PIPE :					1
	REMOVE & REPLACE EXHAUST PIPE					
1.6	4-WHEEL ALIGNMENT TEST					2
1.7	CLEANING & REMOVE OF RUST FOR THE ENTIRE UNDER CARRIAGE					4
1.8	TO APPLY 'TUFF COATING PAINT' FOR THE ENTIRE UNDER CARRIAGE					2
COSTING		TOTAL PARTS COST			\$4,115.00	
		TOTAL MAN-HOUR				18

Regards

Chay Kim Pang
Senior Contract Management Engineer (Vehicle Maintenance)
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4827



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 March 2019 2:35 PM
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538M)

Dear Wei Yea,

Please refer attached of the vehicle no QX 538M instead of QX 538K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]
Sent: Thursday, 21 March 2019 2:24 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538K)

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Wednesday, 13 February 2019 4:29 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538K)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX538K

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 March 2019 2:35 PM
To: 'Wei Yea LIM (SPF)'
Cc: 'Kim Pang CHAY (SPF)'; 'Kwee Huat TAN (SPF)'; 'Perry HE (SPF)'; 'Bernard SEAH (SPF)'; 'Peng Seng NG (SPF)'; 'Rashid ABU HASAN (SPF)'; assignments; Admin-D (LKKAuto); SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538M)
Attachments: QX 538M (SPF).pdf; LKK SURVEYOR PHOTO.pdf

Dear Wei Yea,

Please refer attached of the vehicle no QX 538M instead of QX 538K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 21 March 2019 2:24 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538K)

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Wednesday, 13 February 2019 4:29 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto'

Nivitha (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Wednesday, 13 February 2019 4:29 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX538K)
Attachments: QX538K.xlsx

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- **QX538K**

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Registration No. QX 538M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT CROSS-MEMBER	1	DENTED	\$ 1,350.00	\$ 1,350.00	
1.2	REAR CROSS-MEMBER	1	BENT	\$ 480.00	\$ 480.00	
1.3	REAR LH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00	
1.4	REAR RH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00	
1.5	REAR LH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00	
1.6	REAR RH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00	
1.7	FUEL TANK	1	DENTED	\$ 650.00	\$ 650.00	
1.8	EXHAUST PIPE (CENTRE)	1	DENTED	\$ 680.00	\$ 680.00	
1.9	EXHAUST PIPE (REAR)	1	DENTED	\$ 450.00	\$ 450.00	
1.10	EXHAUST PIPE GASKET	4	NECESSARY	\$ 25.00	\$ 25.00	
	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 4,115.00	\$ 4,115.00	
1	SCOPE OF REPAIRS					
1.1	FRONT CROSS-MEMBER :				2	
	REMOVE & REPLACE FRONT CROSS MEMBER					
1.2	REAR CROSS-MEMBER & ANTI-ROLL BAR ;				4	
	REMOVE & REPLACE REAR CROSS MEMBER					
	REMOVE & REPLACE REAR ANTI-ROLL BAR					
1.3	REAR LOWER ARM, STAB LINK :				1	
	REMOVE & REPLACE REAR LH LOWER ARM					
	REMOVE & REPLACE REAR LH STAB LINK					
	REMOVE & REPLACE REAR RH LOWER ARM					
	REMOVE & REPLACE REAR RH STAB LINK					
1.4	FUEL TANK :				2	
	REMOVE & RE-FILL FUEL IN FUEL TANK					
	REMOVE & REPLACE FUEL TANK					
1.5	EXHAUST PIPE :				1	

	REMOVE & REPLACE EXHAUST PIPE							
1.6	4-WHEEL ALIGNMENT TEST							2
1.7	CLEANING & REMOVE OF RUST FOR THE ENTIRE UNDER CARRIAGE							4
1.8	TO APPLY 'TUFF COATING PAINT' FOR THE ENTIRE UNDER CARRIAGE							2
							TOTAL PARTS COST	\$4,115.00
							TOTAL MAN-HOUR	18
COSTING								

Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR:	SMRT	VEH TYPE:	FRC	UNIT:	SENGKANG NPC
VEH NO:	QX538M		REPAIR TYPE:	ACCIDENT	
VEH MAKE/MODEL:	HYUNDAI AVANTE		ODOMETER:	229451	

Reference No.	0538/SPF/4W/19/01/29
iLMS No.	1100017937

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Front Cross-Member DD ✓	\$1,350.00	1			
1.2	Rear Cross-Member BT ✓	\$480.00	1			
1.3	Rear LH Lower Arm DD ✓	\$175.00	1			
1.4	Rear RH Lower Arm DD ✓	\$175.00	1			
1.5	Rear LH Stab Link CRA ✓	\$65.00	1			
1.6	Rear RH Stab Link CRA ✓	\$65.00	1			
1.7	Rear Anti-Roll Bar SVC X	\$175.00	1			
1.8	Fuel Tank DD ✓	\$650.00	1			
1.9	Exhaust Pipe (Front 1) n n X	\$195.00	1			
1.10	Exhaust Pipe (Front 2) n n X	\$260.00	1			
1.11	Exhaust Pipe (Centre) DD ✓	\$680.00	1			
1.12	Exhaust Pipe (Rear) DD ✓	\$450.00	1			
1.13	Exhaust Pipe Gasket ne ✓	\$25.00	4			
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:	Item 1.11 require Overseas Indentement. ETA:- 4 to 6 weeks				Parts Total:	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Cross-Member:		82	
	Remove & Replace Front Cross Member			
1.2	Rear Cross-Member & Anti-Roll Bar:		84	
	Remove & Replace Rear Cross Member			
	Remove & Replace Rear Anti-Roll Bar			
1.3	Rear Lower Arm, Stab Link:		81	
	Remove & Replace Rear LH Lower Arm			
	Remove & Replace Rear LH Stab Link			
	Remove & Replace Rear RH Lower Arm			
	Remove & Replace Rear RH Stab Link			
1.4	Fuel Tank:		82	
	Remove & Re-Fill Fuel in Fuel Tank			
	Remove & Replace Fuel Tank			
1.5	Exhaust Pipe:		81	
	Remove & Replace Exhaust Pipe			
1.6	4-Wheel Alignment Test		22	
1.7	Cleaning & Remove of Rust for the Entire Under Carriage		84	
1.8	To Apply 'Tuff Coating Paint' for the Entire Under Carriage		82	
	SUB-TOTAL		48	
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	
	SUB-TOTAL		2	
	Labour Total:			
	GRAND TOTAL :			
	Total sum billed under SOR only :			
	Total sum billed under CVR only :			
	Contractor shall complete the entire repair within <u>60</u> working days upon approval date . (Include parts awaiting time)			

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	07.2.2019	Date:		Date:	

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT CROSS-MEMBER	1	DENTED	\$ 1,350.00	\$ 1,350.00	
1.2	REAR CROSS-MEMBER	1	BENT	\$ 480.00	\$ 480.00	
1.3	REAR LH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00	
1.4	REAR RH LOWER ARM	1	DENTED	\$ 175.00	\$ 175.00	
1.5	REAR LH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00	
1.6	REAR RH STAB LINK	1	CRACKED	\$ 65.00	\$ 65.00	
1.7	FUEL TANK	1	DENTED	\$ 650.00	\$ 650.00	
1.8	EXHAUST PIPE (CENTRE)	1	DENTED	\$ 680.00	\$ 680.00	
1.9	EXHAUST PIPE (REAR)	1	DENTED	\$ 450.00	\$ 450.00	
1.10	EXHAUST PIPE GASKET	4	NECESSARY	\$ 25.00	\$ 25.00	
	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 4,115.00	\$ 4,115.00	
1	SCOPE OF REPAIRS					
1.1	FRONT CROSS-MEMBER :				2	
	REMOVE & REPLACE FRONT CROSS MEMBER					
1.2	REAR CROSS-MEMBER & ANTI-ROLL BAR ;				4	
	REMOVE & REPLACE REAR CROSS MEMBER					
	REMOVE & REPLACE REAR ANTI-ROLL BAR					
1.3	REAR LOWER ARM, STAB LINK :				1	
	REMOVE & REPLACE REAR LH LOWER ARM					
	REMOVE & REPLACE REAR LH STAB LINK					
	REMOVE & REPLACE REAR RH LOWER ARM					
	REMOVE & REPLACE REAR RH STAB LINK					
1.4	FUEL TANK :				2	
	REMOVE & RE-FILL FUEL IN FUEL TANK					
	REMOVE & REPLACE FUEL TANK					
1.5	EXHAUST PIPE :				1	

X

X

1.6	REMOVE & REPLACE EXHAUST PIPE 4-WHEEL ALIGNMENT TEST						2
1.7	CLEANING & REMOVE OF RUST FOR THE ENTIRE UNDER CARRIAGE						4
1.8	TO APPLY 'TUFF COATING PAINT' FOR THE ENTIRE UNDER CARRIAGE						2
TOTAL PARTS COST							\$4,115.00
TOTAL MAN-HOUR							18
COSTING							

Registration No. QX 538M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Cross-Member	1	Dented	\$1,350.00	\$1,350.00	
1.2	Rear Cross-Member	1	Bent	\$480.00	\$480.00	
1.3	Rear LH Lower Arm	1	Dented	\$175.00	\$175.00	
1.4	Rear RH Lower Arm	1	Dented	\$175.00	\$175.00	
1.5	Rear LH Stab Link	1	Cracked	\$65.00	\$65.00	
1.6	Rear RH Stab Link	1	Cracked	\$65.00	\$65.00	
1.7	Rear Anti-Roll Bar	1	Serviceable	\$175.00		
1.8	Fuel Tank	1	Dented	\$650.00	\$650.00	
1.9	Exhaust Pipe (Front 1)	1	Not Necessary	\$195.00		
1.10	Exhaust Pipe (Front 2)	1	Not Necessary	\$260.00		
1.11	Exhaust Pipe (Centre)	1	Dented	\$680.00	\$680.00	
1.12	Exhaust Pipe (Rear)	1	Dented	\$450.00	\$450.00	
1.13	Exhaust Pipe Gasket	4	Necessary	\$25.00	\$25.00	
1	Scope Of Repairs					
1.1	Front Cross-Member:				2	
	Remove & Replace Front Cross Member					
1.2	Rear Cross-Member & Anti-Roll Bar:				4	
	Remove & Replace Rear Cross Member					
	Remove & Replace Rear Anti-Roll Bar					
1.3	Rear Lower Arm, Stab Link:				1	
	Remove & Replace Rear LH Lower Arm					
	Remove & Replace Rear LH Stab Link					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19005075/Jvd3e2

ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 Date : 24-04-2019



ATTN : WEI YEA LIM Code : SPF

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	QX 538M
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ16000399	Excess (\$)	0.00
Assign From	WEI YEA LIM	Assign Date	13/02/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KMH DU41BMAU019503	Colour	WHITE
Odometer	229453	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	FALKEN	6 mm
L/H Front Tyre	185/65 R15	FALKEN	6 mm
R/H Rear Tyre	185/65 R15	FALKEN	6 mm
L/H Rear Tyre	185/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE UNDERCARRIAGE PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date		Inspection Date	20/03/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

--



Registration No. QX 538M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Cross-Member	1	Dented	\$1,350.00	\$1,350.00	
1.2	Rear Cross-Member	1	Bent	\$480.00	\$480.00	
1.3	Rear LH Lower Arm	1	Dented	\$175.00	\$175.00	
1.4	Rear RH Lower Arm	1	Dented	\$175.00	\$175.00	
1.5	Rear LH Stab Link	1	Cracked	\$65.00	\$65.00	
1.6	Rear RH Stab Link	1	Cracked	\$65.00	\$65.00	
1.7	Rear Anti-Roll Bar	1	Serviceable	\$175.00		
1.8	Fuel Tank	1	Dented	\$650.00	\$650.00	
1.9	Exhaust Pipe (Front 1)	1	Not Necessary	\$195.00		
1.10	Exhaust Pipe (Front 2)	1	Not Necessary	\$260.00		
1.11	Exhaust Pipe (Centre)	1	Dented	\$680.00	\$680.00	
1.12	Exhaust Pipe (Rear)	1	Dented	\$450.00	\$450.00	
1.13	Exhaust Pipe Gasket	4	Necessary	\$25.00	\$25.00	
1	Scope Of Repairs					
1.1	Front Cross-Member:					2
	Remove & Replace Front Cross Member					
1.2	Rear Cross-Member & Anti-Roll Bar:					4
	Remove & Replace Rear Cross Member					
	Remove & Replace Rear Anti-Roll Bar					
1.3	Rear Lower Arm, Stab Link:					1
	Remove & Replace Rear LH Lower Arm					
	Remove & Replace Rear LH Stab Link					
	Remove & Replace Rear RH Lower Arm					

	Remove & Replace Rear RH Stab Link					
1.4	Fuel Tank:					2
	Remove & Re-Fill Fuel in Fuel Tank					
	Remove & Replace Fuel Tank					
1.5	Exhaust Pipe:					1
	Remove & Replace Exhaust Pipe					
1.6	4-Wheel Alignment Test					2
1.7	Cleaning & Remove of Rust for the Entire Under Carriage					4
1.8	To Apply 'Tuff Coating Paint' for the Entire Under Carriage					2
COSTING		TOTAL PARTS COST			\$4,115.00	
		TOTAL MAN-HOUR				18

Registration No. QX 538M

Vehicle Inspected By

ONG HWEE JIE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.