



Mercedes-Benz

LKK Survey

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLE1598S

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
068811
63387288

Vehicle & Document Information

WIP No 31720
Reg No/Reg Date SLE1598S / 12/07/2016
Date In/Mileage / 0
Chassis No WDD2120342B315148
Engine No 27492030585610
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 021 197 Obsidian Bl/ 042 241 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator				
CSI00001	Cash	19/03/2019/ 18:21	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : GA133020/1 // 14/03/2019								
DRIVE IN/EXCESS : 14/03/209 // TP VEH NO FBC705K MSIG								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW								
BODY PANELS WITH REFINISH.								
A BPIRES								
RESPRAY BOOT LID, LEFT REAR FENDER AND REAR BUMPER								
A BPILAB								
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO								
STANDARD SETTINGS.								
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT								
A BPILAB								
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS								
AND SEATS FOR NEC. REPAIRS.								
M	BOOT LID MERCEDES STAR	neu			1.00	48.25	00.00	48.25
M	GROMMET	neu			3.00	2.29	00.00	6.87
M	BOOT LID CHROME MOULDING	?			1.00	117.11	00.00	117.11
M	BOOT LID E200 MODEL PLATE	neu			1.00	83.60	00.00	83.60
M	LEFT REAR LAMP COMBINATION	scd			1.00	712.05	00.00	712.05
M	REAR BUMPER	dg			1.00	1876.41	00.00	1876.41
M	REAR BUMPER BOTTOM	?			1.00	293.53	00.00	293.53
M	REAR BUMPER LOWER CHROME MOULDING	?			1.00	313.56	00.00	313.56
M	LEFT REAR BUMPER CHROME MOULDING	?			1.00	58.71	00.00	58.71
M	RIGHT REAR BUMPER CHROME MOULDING	?			1.00	58.71	00.00	58.71
M	LEFT REAR BASIC MOUNTING FOR BUMPER	?			1.00	37.51	00.00	37.51
M	REAR BASIC MOUNTING FOR BUMPER	?			1.00	179.92	00.00	179.92

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLE1598S

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
068811
63387288

Vehicle & Document Information

WIP No **31720**
Reg No/Reg Date **SLE1598S / 12/07/2016**
Date In/Mileage **/ 0**
Chassis No **WDD2120342B315148**
Engine No **27492030585610**
Make/Model **MB/MB E 200 2.0 SEDAN (W212) "EDITION E"**
Colour/Trim **021 197 Obsidian Bl/ 042 241 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	19/03/2019/ 18:21	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR CROSS MEMBER 7	1.00	817.08	00.00	817.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

6 days

T/P

09/04/19 P1030

EXCESS: NIL

Authorized

Resurvey before paint

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe-yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 11,703.31
7% GST on 11703.31 819.23

Authorized signatory and company stamp

Total Payable 12,522.54

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany