



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2015 MERCEDES E200 (SLE1598S)
Date of Loss	14 March 2019
Time of Loss	8.40
Loss Description	FBC705K (TP)BIKE HIT REAR OF SLE1598S (INSD)
Comment	

Workshop Details

Total Rebate Amount	91071
Nett Loss Amount	\$63,929.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SLE1598S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

12/07/2016



Mileage

60128

Age of Vehicle

2

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2015

2015

Make

MERCEDES

MERCEDES BENZ

Model

E200

E200 SEDAN EDI

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

TAY BENG CHOON

Date of Birth

21 December 1967

dd/mm/yy



Age

51

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	WDD2120342B315148	WDD2120342B3
Engine No	27492030585610	27492030585610
Engine Capacity		1991
Sum Insured	0	0
Market Value	0	155000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	24	
Driver License #		
License Type		
License Issue Date	1 January 1995	dd/mm/yy 
License Expiration Date		dd/mm/yy 
Address	BLK 900 DUNEARN RD #02-20, 589473, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S1826162F	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/04/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

265/35R18

Rear Tyre Size

265/35R18

Front left side

GOODYEAR6mm

Rear left side

GOODYEAR6mm

Front right side

GOODYEAR6mm

Rear right side

GOODYEAR6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMO
		0	1		BOOT LID MERCEDES STAR	Necessary	0	48.25	No					48.25	Reviewing	
		0	3		GROMMET	Necessary	0	2.29	No					6.87	Reviewing	
		0	1		BOOT LID CHROME MOULDING	Serviceable	0	0	No					0	Deny	
		0	1		BOOT LID E200 MODEL PLATE	Necessary	0	83.6	No					83.6	Reviewing	
		0	1		LEFT REAR LAMP COMBINATION	Damaged	0	712.05	No					712.05	Reviewing	
		0	1		REAR BUMPER	Deformed	0	1876.41	No					1876.41	Reviewing	
		0	1		REAR BUMPER BOTTOM	Serviceable	0	0	No					0	Deny	
		0	1		REAR BUMPER LOWER CHROME MOULDING	Serviceable	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMO
		0	1		LEFT REAR BUMPER CHROME MOULDING	Serviceable	0	0	No					0	Deny	
		0	1		RIGHT REAR BUMPER CHROME MOULDING	Serviceable	0	0	No					0	Deny	
		0	1		LEFT REAR BASIC MOUNTING FOR BUMPER	Serviceable	0	0	No					0	Deny	
		0	1		REAR BASIC MOUNTING FOR BUMPER	Serviceable	0	0	No					0	Deny	
		0	1		REAR CROSS MEMBER	Serviceable	0	0	No					0	Deny	
		0	3		NUT-AND-WASHER ASSEMBLY	Necessary	0	0.99	No					2.97	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMO
		0		PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	0	2400	0	0	Reviewing		
		0		RESPRAY BOOT LID, LEFT, REAR FENDER AND REAR BUMPER	0	1800	0	0	Reviewing		
		0		USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	0	380	0	0	Reviewing		

7/19/2019

Claim Portal

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMO
		0		CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	0	120	0	0	Reviewing		
		0		REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS AND SEATS FOR NEC. REPAIRS.	0	480	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 6 DAYS	Reviewing		0		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$7,910.15

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$2,730.15

Labour

\$0.00

\$5,180.00

[Submit for Review](#)