rimutes: 18321 CS 3/ AIG 1900 5088 /RICCO Special minutes ADS MALEY MINEGER Rasul ASSIGNMENT (Office) UnterTime 21.3.2019 From (Person); Chin la Ming A19 Estimated Cost OD (III) FWS / TP RES / OD RES / EVA / INV / MIV / CS SLM3718H FBM3798U To Inspect Vehicle No: Incorrect: 92720009 DSC motor LLP Teb at Workshop m/s 1 25 Kaki Butit Road 4, # 05-49 345523750786 Policy No. 2100,504951 Cham No: Norm Impared: Excess: D.O.A. 17-3-17 Make of Veh: (Client's Record) "WP" CA / REV / REP. / REV 24 HRS H.O.D. Endocuement: Date/Time: 20-3-19 5-30 km Person Contacted: Derrick Vehiclo IN DUT Action/Instruction (X) Estimate Date/Time DOA - 17/3/2019 SLM 3718H - (5/A16 1900 5068/EVAS FBM 3793 - X After repair: 5/4/2019 Dilson said they had sottled this claim. Just the invoice to them. Swee Peng said Sill \$700/ Sor PRI only.

VELLOC (Losau REF: AIG	
A	SSIGNMENT
Date: 21/3/2019	Veri No. FBM 31984 Vr Regn. Oct 17
	Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
mated Cost.	Truck / Trailer or
PIWS TP RES OD RES LEVA INV MY	Make: sc 184
nspect Vehicle No. FBM 3798 U	A A A M Insured / Std / NI / NA
vorleshop m/s DSC MOTOR	Colour DOTOC
25 kakl Bukit Pd 4#05-4	Sp. Keldung 3 270
ired:	Eng/No:
icy No.	CINO: LALPJL70443164822
ims No.	Gen, Cond. Good / Poor / Burnt
m Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
il sauco.	Brake: horder / Jammed / Leaked / Burnt or
Client's Record) Ike of Veh: Demick @ 92720009	Modi Nil /S/Rim / STD A/Rim or
ke of Veh. 1)eMcK (5) 92+20001	Tyre Size: F: 110 176-17
	A R: 140170-17
Policy Condition)	OIS BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
mark. The ven had commenced its	
repair at the time of inspection.	TOYO/YOKO OF TIMSW
al. or Market Value.	Front Rear
AC Accident Rport: Consistent? : Yes or No	R/Bal. Y mm (Vision)
IA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal mm
st Repairs: 3 days Res: Yes or No	D.O.A. D.O.I. >1 63 (5
2 Mal - Van or No	Survey held at \$S C M oTON.
um som.	Des. of Damages : Frt / Rear / O/9 / N/S / U/C / Rooftop or
A / REV / REP. / 24 HRS (U.P.)	
Date: Person Confacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
Date / Iline Action / Instruction	
- N	
DateTyne File Pass to? : Preli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
i) Final Report	Transportation:
Bann/Time, File Seturn 107	dd Fee: Site Insp (\$)_S=RS_S
	10 1 00.
2)	Interview 12
	Interview (\$) Photos
Report Format : PRC	Tech Invs (\$) Others Weekend (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING Ins Authord Adj Submitted Aut Rpt Adi Asslandi Est Submitted Pending for Survey Motified Calle 20 Mar 2019 Report 21 Mar 2019 00:00 Cancel Case Main Edit Reg Edit Adj Rpt Show All Documents Claim Details Reference Main [Created by adjuster] CLAIM SUBFOLDER DETAILS HO WEE LIN Inspred: MOHAMAD RIDHUWAN BIN RASHID Main Claimant: 17/03/2019 14:00 - :59 Date of Loss: Vehicle Reg. FBM3798U No : Policy/Cover 2100504951 (Comprehensive) TP / 3455237507SG Note No.: Claim Type: Policy No. Vehicle Reg. (Claimant): SLM3718H No. (Insured): Excess: Dac Motor Lip (HQ) 25 KAKI BUKIT ROAD 4, #05-49, 417800 Kaki Bukit - Tel: 92720009 AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com Repairer: Handling LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/03/2019] insurer: Adjuster: View All | Compose Case Mail ASSOCIATED MAIL RECEIVED AIG_SG (21/03/2019): TP GIA REPORT Create New Task Complete Search Tasks View All ALL ASSOCIATED TASKS Created On Done? Completed On Assigned By Handler Subject. Task Group Priority Type Dige Date: No results.

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE... From: Chin, Lee-Ying assignments@lkkauto.com, admin-a@lkkauto.com To: Cc: Fong, Andy-SY 20/3/2019 2:23:45 PM Sent 1 tmp393E.TIE Attachments: HILKK. Kindly assist to survey. Thanks: Best Regards Lee Ying, Chin AIG Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 Lee-Ying Chin@aig.com | www.aig.sg

From: mab_law06@yahoo.com.sg [mailto:mab_law06@yahoo.com.sg]

Sent: Wednesday, March 20, 2019 1:32 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azian, Syazairdina; Chan, Yoke

Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3718H AND

FBM3798U ON 17/03/2019

Dear Sir/Mdm

CLAIMANT: Mr Mohamad Ridhuwan Bin Rashid

ACCIDENT INVOLVING SLM 3718 H & FBM 3798 U along Pioneer Road North on 17/03/2019 at 2.00 pm

We refer to the above matter and to your email dated 20/03/2019.

Please note that we have our client's instructions to proceed to appoint Mr Dylan Lee from M/s Lee Appraisal Services as our motor surveyor to conduct the survey on our client's motorcycle no. FBM 3798 U.

You will have your own separate motor surveyor to conduct the survey.

Kindly contact Mr Derrick Cheo of motor-workshop M/s DSC Motor LLP at his mobile no. 9272 0009, address 25, Kaki Bukit Road 4, #05-49 Singapore 417800.

Please let us have a copy of the inspection report upon receiving it.

Mr Mahadi Abu Bakar

MAHADI ABU BAKAR & PARTNERS (UEN No. 53179837/B) Advocates & Solicitors #14-01 Tong Eng Building 101 Cecil Street Singapore 069533

Telephone: (65) 6225 2355 (3 lines)

Facsimile: (65) 6227 9913

CONFIDENTIALITY NOTICE This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

MAHADI ABU BAKAR & PARTNERS

ADVOCATES & SOLICITORS (UEN No. 53179837B)

#14-01, TONG ENG BUILDING, 101 CECIL STREET SINGAPORE 069533 TEL: 62252355 FAX: 62279913 email: mab_law06@yahoo.com.sg

YOUR REF:

SLM 3718 H

20 March 2019

OUR REF:

MAB/10763/19/zila

HO WEE LIN (HE WEILIN) 26 Bukit Batok East Avenue 2 #05-07 Singapore 659920

Dear Sir/Mdm

CLAIMANT: MR MOHAMAD RIDHUWAN BIN RASHID
ACCIDENT INVOLVING SLM 3718 H & FBM 3798 U ALONG PIONEER ROAD NORTH ON
17/03/2019 AT 2.00 PM

We are instructed by Mr Mohamad Ridhuwan Bin Rashid, the owner of motorcycle no. FBM 3798 U, to notify you of a road traffic accident on 17/03/2019 at about 2.00 pm along Pioneer Road North involving our client's vehicle registration number FBM 3798 U and your vehicle registration number SLM 3718 H driven by you/your driver at the material time. Copies of the Traffic Police Accident Report/Singapore Accident Statement lodged by the rider of motorcycle no. FBM 3798 U, is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

cc. 1) Client

Claims Department
 AIG Asia Pacific Insurance Pte. Ltd.
 AIG Building
 78 Shenton Way #07-16

lyl

Singapore 079120 YOUR REF: SLM 3718 H FAX & MAIL 6835 7416

URGENT





1 of 3

Report No. T/20190317/7007

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Tim 17/03/20	/Time Report Made: 3/2019 17:34			Vide Report No.: J/20190317/0102			Stat	ion Diary No.:	
nformar	t's Partic	culars					*********		
Vame of	Informant	te	IN	SINGA	PORE 640	RONG WEST	STREET	81 #05	5-442
ID Type / ID No.: NRIC NO / S9441152A				Contact No :			97384654		
Nationali	ty: ORE CITI	ZEN		Email: mohan	nadridhuwa	n@gmail.co	m		
Sex: Male	Age:		of Birth: 1/1994	Type o	of Informant	:			
Race: Malay				Langu			Institution	ion / School Name:	
Occupat	ion:			Driving Class:	Driving Licence Information:			of Expiry:	
			e Accident		Drink	Date/Tir		17	Type of Location
		Injury						13	Type of Location
Type of Accident	t;	Injury Attende	ed by Police		Drink Drive: No	Acciden)	Type of Location
Type of Acciden Location PIONES	nt; nt: ER ROAD	Injury Attende	ed by Police		Drive:	Acciden	t	Road	C-Junction Speed Limit
Type of Accident Location PIONES Weather Clear	nt: ER ROAD	Injury Attende	ed by Police	Road	Drive: No Surface:	Acciden	t	Road 60 Km	CJunction Speed Limit
Type of Accident Location PIONES Weather Clear	nt: ER ROAD	Injury Attende	ed by Police	Road Dry	Drive: No	Acciden 17/03/2	t	Road 60 Km Traffic Moder	Speed Limit: //h : Volume:
Type of Accident Location PIONES Weather Clear Traffic I Dual Co	er: Flow: arriage W	Injury Attende NORTH	ed by Police	Road Dry Traffi Traffi	Drive: No Surface:	Acciden 17/03/2	t	Road 60 Km Traffic Moder	Speed Limit: //h Volume:
Type of Accident Location PIONES Weather Clear Traffic I Dual Co Type of Between	er: Flow: arriage W	NORTH ay Vehicles	ed by Police	Road Dry Traffi Traffi	Drive: No Surface:	Acciden 17/03/2	t	Road 60 Km Traffic Moder Anyon ambut	Speed Limit: //h Volume: rate

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM3798U	A STATE OF THE OWNER,	HONDA	CBF190X	Black		0
SLM3718H	Car	-				0

Details of Ve	phicle Insurance	1	anne Ar	
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBM3798U	NTUC Income Insurance Co-Operative Limited	5104330739	17/10/2018	16/10/2019





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 Report No. T/20190317/7007

CONTINUATION OF REPORT

Any Pedestrian In	volved: No	T	of control in a	-	an MA
No. of Pedestrian	s Injured: NIL	Use of Pa	ecestrian	Cross	ing: NA
Rider			1 105 551		S9441152A
Name	MOHAMAD RIDHUWAN BIN F	RASHID	ID No.		5844115ZA
Related Vehicle	FBM3798U (Motorcycle)		Contact No. 97384654		97384654
Hospital/Clinic	NG TENG FONG GENERAL H	IOSPITAL	Class Drivin Licent Expiry	g e &	Class: 2B Date of Expiry: NIL
Date Treatment	NII	Date Dis	charge	NIL	
No of Concession	ted Medical Leave 14	The second secon	of Injury	Serio	us

At 2pm, I was going straight towards Pioneer Rd North junction from NTU. Upon reaching the trafficlight at Nanyang Flyover, the light was green in my favour so I proceeded straight. There was a SUV car, SLM3718H, from the opposite side fail to give way to me when I had the right of way and dashed to turn right entering PIE. The front part of the car hit on the middle of the right side of my motorcycle. I received serious injury and suffered fractured and bruises to my right leg. I was conveyed to Ng Teng Fong Hospital.





3 of 3

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20190317/7007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 17/03/2019 17:34
Officer In Charge Of Case: TP / TPIB / YAN MINGSHENG DANIEL	Classification Of Case:

Authentication Stamp

Contact No.: 65476252

NP165

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	FBM3798U
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model:	CBF190X
Chassis No.:	LALPJL704H3164822
Propellant:	Petrol
Engine No.:	SDH161FMKH3205554
Engine Capacity :	184 cc
Maximum Power Output:	
Maximum Laden Weight:	298 kg
Unladen Weight:	138 kg
Year Of Manufacture:	2017
Original Registration Date :	17 Oct 2017
Lifespan Expiry Date:	
COE Category:	D - Motorcycle
Quota Premium :	\$5,010.00
COE Expiry Date:	16 Oct 2027
Road Tax Expiry Date:	16 Oct 2019
Inspection Due Date:	16 Oct 2020
Intended Transfer Date:	16 May 2019
CO2 Emission:	•
CO Emission :	*
HC Emission:	
NOx Emission :	(S)
PM Emission:	
Late renewal fee(s) will be impo	sed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable. ent (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred

Amount Payable			
Daws was after	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00		25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars Singapore NRIC Owner ID Type: 1152A Owner ID: Vehicle Details FBM3798U Vehicle No.: Vehicle to be Exported: 16 May 2019 Intended Deregistration Date: HONDA Vehicle Make: CBF190X Vehicle Model: Black Primary Colour: 2017 Manufacturing Year: SDH161FMKH3205554 Engine No.: LALPJL704H3164822 Chassis No.: Maximum Power Output: \$3,084,00 Open Market Value: 17 Oct 2017 Original Registration Date: 17 Oct 2017 First Registration Date: 1 Transfer Count: \$463.00 Actual ARF Paid: Intended PARF Rebate Details No PARF Eligibility: PARF Eligibility Expiry Date: \$0.00 PARF Rebate Amount: Intended COE Rebate Details 16 Oct 2027 COE Expiry Date: D-Motorcycle COE Category: 10 COE Period(Years): \$5,010.00 QP Paid: \$4,216.00 COE Rebate Amount: \$4,216.00

The information contained herein is correct as at 16 May 2019

Total Rebate Amount:

101/Ben/ 12/Denied (2/Distanted 14)Cracked (5)Cut (6/Scratched 107/Defenned (00)Blothed (99/Bockled (19)Beoken (11)Necessary 112/Mining (13)Torn 114/Unconfirmed (15)Not Working

FOR MOTORCYCLE

ACTION (AC)

May 3805

L. Replace (1 2. Repair (X) 3. Check (?)

4. Net Consistent (NC)

-BM 3798 Motorcycle Vehicle No: \ NAC Item CON AC Qty NAC INC Item 991886 Front Number Plate 1001 10527 995074 Radiator 3001 995065 Front Tyre T053 992738 Radiator Cowling 3002 995095 Front Rim 3046 994146 Seat Assy 3003 994872 Front Tyre Rim Spoke 3047 990915 Engine Crash Bar DD 3004 991771 Front Fender Wheel Guard CWT 3048 990928 Engine Guard 3005 991283 Front Brake Disc 1067 990219 Battery 991281 Front Brake Caliper 3006 1068 990224 Battery Cover 3007 991785 Front Fork Assy 1069 990223 Battery Bracket 991787 Front Fork Inner Tube 3008 3049 991144 Foot Brake 991789 Front Fork Outer Tube 3009 3050 | 991154 | Front Foot Rest 3010 991167 Front Fork Bracket 3051 991779 Front Foot Rest Bracket 3011 991182 Front Fork Oil Seal 3052 994269 Side Stand 3012 991174 Front Fork Garnish 3053 992549 Main Stand 3013 | 992376 | Front Headlamp Rim 3054 990615 Clutch Engine Cover 3014 992328 Front Headlamp 3055 | 992478 | Kick Starter Rubber 3015 | 992337 Front Headlamp Bracket 3056 992477 Kick Starter Lever 3016 | 992345 Front Headlamp Fairing 3057 991145 Foot Gear Shifter 3017 992130 Front Windshield 3058 993500 Rear Foot Rest 3018 992134 Front Wing Mirror RA TND 3059 993501 Rear Foot Rest Bracket 3019 995245 Front LH Signal Lamp 992581 Exhaust Muffler Heat Shield DD 3060 3020 995246 Front RH Signal Lamp 3061 991058 Exhaust Muffler Assy 3021 992556 Meter Casing 1405: 993719 Rear LH Shock Absorber 3022 992553 Meter Assy 14456 993720 Rear RH Shock Absorber 1118 991019 ERP Bracket 3062 995065 Rear Tyre 1119 991020 ERP Unit 3063 991200 Rear Rim 3023 992446 Ignition Switch 3064 994872 Rear Tyre Rim Spoke 3024 992442 Ignition Key Assy 3065 993474 Rear Fender Wheel Guard 3025 990706 Cowling Stay 3066 993443 Rear Fender Mudflap 3026 994470 Steering Stem 3067 | 992940 | Rear Brake Disc 3027 994427 Steering Cone 3068 992936 Rear Brake Caliper 3028 992299 Handle Bar 995236 Rear Spocket 3069 3029 992312 Handle Bar Switch 3070 990585 Chain 992310 Handle Bar Grip 3030 990580 Chain Guard 3071 995184 Handle Bar Balancer LH 3031 3072 994530 Swing Arm 3032 992300 Handle Bar Balancer RH 14205 993819 Rear Sub frame 1252 992179 Fuel Tank 995245 Rear LH Signal Lamp 3073 3033 990438 Brake Reservoir 3074 995246 Rear RH Signal Lamp 3034 990621 Clutch Lever 3075 995251 Rear Taillamp 992293 | Hand Brake Lever 3035 BT RIST 993626 Rear Number Plate 1210 3036 991119 Side Fairing 3076 994192 Side Box 3037 994220 Side Fairing Top Garnish 3077 992927 Rear Box 3038 994219 Side Fairing Inner Garnish 3078 | 992928 | Rear Box Bracket 3039 991118 Fairing Shield 3079 991328 Emblem 3040 992047 Front Top Fairing Inner Garnish 四月36年 990247 Sticker 3041 991123 Fairing Top Garnish 3042 990538 Center Fairing 3043 993378 Rear Fairing 3044 991121 Fairing Stopper

ssessor:

991117 Fairing Lower

3045