

ASS. REC. BY:

REF: CS/FCI 19005089/ Usd3

Special Instruction:

Survivor:

CWS

ASSIGNMENT (Office)

From (Person):

Henry Kao

of

FCI

Date/Time:

10:17am 20/3/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

PBM 9545T

Insured:

SHC 0090D

at Workshop m/s

Sun Hock Hin

Tel:

6281 6526

of

No. 6 Defn Lane 4

Policy No:

Claim No:

D19001840MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/3/2019

CA / REV / REP. / REV 24 HRS

1up

20/3/19 @

H.O.D. Endorsement:

Date/Time: 11:30am 20/3/19

Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PBM 9545T - X
	SHC 0090D - X
21/03/19	@ 18:21 p.m. revised PA to Henry Kao via email.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE I, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001840MFSH

Date: 21 March 2019

Our Ref: CS/FCI19005089/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBM 9545T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/03/2019 at the premises of M/s Ban Hock Hin Co Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>765.00</u>
Revised Estimate Amount	: S\$ <u>519.00</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages
at the n/s front portion & o/s body.



Comments/ Present Status:

Damages Consistent.

Repair days: 2 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-03-2019	Our Ref No. D19001840MFSH
Accident Date	08-03-2019	Claim Type. Third Party
Insured Vehicle	SHC0090D	Third Party Vehicle. FBM9545T
Survey Location	NO. 6 DEFU LANE 4	
Contact Person.	RAYMOND	
Contact No.	62816520/ 0	Fax No. 62842969
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BAN HOCK HIN CO. PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 March 2019 6:21 PM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001840MFSH/1
Attachments: FBM 9545T - Preli Advise.pdf

Dear Henry,

Enclosed preliminary revised of vehicle FBM 9545T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 19 March 2019 3:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001840MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer arrange on 20/03/2019.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 19 March 2019 10:17 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001840MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0288K

Vehicle Details

Vehicle No.: FBM9545T

Vehicle to be Exported: No

Intended Deregistration Date: 20 Mar 2019

Vehicle Make: YAMAHA

Vehicle Model: YBR125

Primary Colour: Red

Manufacturing Year: 2017

Engine No.: E3F5E044668

Chassis No.: LBPRE101000059601

Maximum Power Output: -

Open Market Value: \$1,878.00

Original Registration Date: 30 May 2018

First Registration Date: 30 May 2018

Transfer Count: 0

Actual ARF Paid: \$282.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 May 2028

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$7,115.00

COE Rebate Amount: \$6,539.00

Total Rebate Amount: \$6,539.00

The information contained herein is correct as at 20 Mar 2019

OK

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBM9545T		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	YBR125		
Chassis No. :	LBPREF101000059601		
Propellant :	Petrol		
Engine No. :	E3F5E044668		
Engine Capacity :	124 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	285 kg		
Unladen Weight :	126 kg		
Year Of Manufacture :	2017		
Original Registration Date :	30 May 2018		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$7,115.00		
COE Expiry Date :	29 May 2028		
Road Tax Expiry Date :	29 Nov 2019		
Inspection Due Date :	29 May 2021		
Intended Transfer Date :	15 Mar 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

[OK](#)[Print](#)



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33822

FIRST CAPITAL INSURANCE LTD

06 RAFFLES QUAY #21-00
SINGAPORE 048580

MOTOR CLAIMS DEPT

VEHICLE NO. : FBM9545T
MAKE/MODEL : YAM / YBR125

DATE : 13/03/2019
CLAIM NO. : 11295
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

*Not Added
risk works
2 day
20/3/19
the price After repair*

P/P \$ 480.60

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	90.00
2	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
3	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	✓ Supply/Install	3.00	\$35.00	105.00
4	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	63.00
5	PEDAL BRAKE P/N: 44906	REPLACE	1.00	\$88.00	88.00
6	PROTECTOR EXHAUST P/N: 50024	REPLACE	1.00	\$119.00	119.00
7	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00	56.00
8	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
9	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.	✓	1.00	\$35.00	35.00

SUB TOTAL

\$765.00

GST @ 7 %

\$53.55

GRAND TOTAL

\$818.55

50% deposit required before ordering of parts.



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
Validity: 30 days					

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005089/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 90D	Veh. Inspected	FBM 9545T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001840MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	19/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA YBR125	c.c	124	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	LBPREF101000059601	Colour	RED / BLACK	
Odometer	33811	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	2.75-18	MICHELIN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	2.75-18	MICHELIN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2019	Inspection Date	20/03/2019	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 9545T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LAMP SIGNAL REAR LH (CUT)	NOT CONSISTENT WITH THE IMPACT	63.00	-
1	PEDAL BRAKE	SERVICEABLE	88.00	-
1	PROTECTOR EXHAUST	CUT	119.00	119.00
1	PROTECTOR EXHAUST CAP	CUT	56.00	56.00
1	RUBBER FOOTREST FRONT	TORN	14.00	14.00
1	COVER TAIL LH (RED)	NOT NECESSARY	90.00	-
1	CRASH BAR	DENTED / BENT	195.00	195.00
	LESS 10% DISCOUNT		-	-38.40
			625.00	345.60
LABOUR				
	LABOUR-FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.		105.00	100.00
	TRANSPORT CHARGES-FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.		35.00	35.00
			140.00	135.00
GRAND TOTAL			765.00	480.60
RECOMMENDED COST OF REPAIRS				480.60

Report Ref No. CS/FCI19005089/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.