

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date :18/03/2019

Reference: CHEVROLET

Make: ORLANDO

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLG1684R
CHASSIS NO.: KL1YA7589HK604958
ENGINE NO.: A14NET162000762

TP AIG.
Xico Tany

Name of insured :NG HONG CHIANG
Date of accident.: 17/03/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	REAR BUMPER STEP PLATE <i>Repld</i>	\$ 166.00
2	1	REAR BUMPER UPPER <i>Repld</i>	\$ 1,330.00
3	1	REAR BUMPER LOWER <i>Repld</i>	\$ 493.00
4	1	REAR BUMPER SILL PLATE(SILVER) <i>Repld</i>	\$ 223.00
5	1	REAR BUMPER TOWING COVER <i>Repld</i>	\$ 93.00
6	1	LHR BUMPER REFLECTOR <i>Repld</i>	\$ 140.00
7	1	RHR BUMPER REFLECTOR <i>Repld</i>	\$ 140.00
8	1	REAR REVERSE LIGHT AND BRAKE LIGHT <i>Repld</i>	\$ 307.00
9	1	REAR TAILGATE <i>Repld</i>	\$ 1,528.00
10	1	REAR TAILGATE STOPPED <i>Missing</i>	\$ 12.00
11	1	RHR TAILLAMP <i>Repld</i>	\$ 468.00
12	1	RHR TAILGATE LAMP <i>Repld</i>	\$ 328.00
13	1	RHR TAILLAMP PANEL <i>Repld</i>	\$ 125.00
14	1	REAR END PANEL <i>Repld</i>	\$ 776.00
15	1	REAR END PANEL TRIM <i>Repld</i>	\$ 186.00
16	1	REAR BUMPER CENTRE GUIDE <i>Repld</i>	\$ 148.00
17	1	RHR BUMPER GUIDE, OTR <i>Repld</i>	\$ 118.00
18	1	LHR BUMPER GUIDE, OTR <i>Repld</i>	\$ 118.00
19	1	REAR BUMPER LEFT CENTRE GUIDE, INR <i>Repld</i>	\$ 112.00
20	1	REAR BUMPER RIGHT CENTRE GUIDE, INR <i>Repld</i>	\$ 112.00
21	1	REAR BUMPER BEAM <i>Repld</i>	\$ 863.00
22	1	RR TAILGATE LOGO <i>Repld</i>	\$ 187.00
23	1	RR TAILGATE EMBLEM "CHEVROLET" <i>Repld</i>	\$ 133.00
24	1	RR TAILGATE EMBLEM "ORLANDO LS" <i>Repld</i>	\$ 148.00
25	1	RR TAILGATE EMBLEM TURBO <i>Repld</i>	\$ 151.00
26	1	RR TAILGATE LOCK - Latch <i>Repld</i>	\$ 331.00
27	1	RR TAILGATE LOCK CATCH - Striker <i>Repld</i>	\$ 121.00
28	1	RR TAILGATE INNER TRIM BOARD <i>Repld</i>	\$ 311.00
29	1	RR TAILGATE RUBBER BEADING <i>Repld</i>	\$ 272.00
30	2	RR BUMPER REVERSE SENSOR <i>Repld</i>	\$ 430.00

31	4	RR BUMPER REVERSE SENSOR SEAL	Not in	\$	40.00	+
32	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	Not in	\$	291.00	+
33	1	RR FENDER RH	Repair	\$	2,017.00	+
34	1	RR FENDER WHEELARCH GARNISH RH	Not in	\$	152.00	+

8050

7245

Parts Total: \$ 12,370.00

Less 10%: \$ 1,237.00

Total: \$ 11,133.00

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00
2	Carry out spray painting on affected area, RR BUMPER, RR TAILGATE, RR END PANEL, RR FENDER RH	\$ 1,000.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
4	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 200.00
5	To remove and refix reverse sensor and conduct test	\$ 120.00
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 200.00
7	To conduct water leakage test after repairs of vehicle	\$ 80.00
8	To conduct reset of engine light on	\$ 200.00
9	To remove and refix rear tail gate windscreen	\$ 180.00

1550

Labour Total: \$ 3,100.00

Others

No.	Other Description	Price (SGD)
1	10 FENDER INNERSHIELD CLIP	\$ 40.00
2	10 RR BUMPER CLIP	\$ 40.00
3	10 RR TAILGATE INNER TRIM BOARD CLIP	\$ 40.00
4	1 RR WINDSCREEN SEALANT	\$ 65.00
5	1 RR WINDSCREEN INNER SEAL	\$ 40.00
6	1 RR WINDSCREEN SOLAR FILM	\$ 200.00

110

Other Total: 425.00

TOTAL: 14,658.00

GRAND TOTAL: 14,658.00

LKK Auto Consultants hence notify

the Repairer of the following:

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

- To resurvey before/after spray painting
- To resurvey damaged parts during resurvey
- Parts prices are subject to confirmation
- Yours faithfully
- and parts supplied on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
4/5 05/09
P/P total: 8050
(P/P)