

INS. CASE OWNER:

CC 4 / AIG 1900

SUYS, Gp 34

LKK:

IDAC:

Surveyor:

KAB

DOI:

ASSIGNMENT

20/3/19

Date / Time:

19/3/19

Registered in Merimen:

20/3/19

Pre-assign / CCU / FTE

SKU 1364C



Insured Vehicle No.:

Claim No.:

Name of Insured:

CHEONG KAH YEE

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$5

D.O.A: 26/07/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

RBB 9564X



INSRS:

WSP: MCS Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

20/3

RBB 9564X - X ; SKU 1364C - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

CH 20/3/19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

TP:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: X 6Q

Repair Cost:

4x \$53,000

(4 days) Reduction:

50 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: STEP

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. 15

If NO or B 28, Ass. Lia:

Repair Cost:

\$53,000.00

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5,000.00

(\$30 x 4 days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5 -

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9320

Total:

\$54,000.00

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with: STEP

Email ☒ Call ☐

Payee 1:

\$54,000.00

Name 1:

MCS Auto

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

4 Days.
Lumpsum Repair.

After repair photos.

Quo Quap - 82880282 20/3/19

MCS Auto

1100 SERANGOON ROAD SINGAPORE 328195

TEL : 62969939 FAX : 62964038

Company Registration No: 53126812L

Email : mcs.auto@yahoo.com.sg

Customers hence notify

the following:

Before a car spray painting

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

Date of Accident :-	Days of Repair 7 days
Vehicle No : FBB 9564 X	Chassis No : -
Make & Model : Bandit 1250	Engine No : -
Year of Manufacture :-	Registration Date : 2000

S/No:	Spare parts Description	Qty	List Price	Remark
1	Headlamp assy / CAA	1	\$620.00	/
2	Headlamp bracket / NN	1	\$220.00	/
3	Front cowling / CAA	1	\$750.00	/
4	Meter cowling / CAA	1	\$220.00	/
5	View mirror / BT	2	\$240.00	/
6	Windshield / DIS	1	\$210.00	/
7	Front signal lamp RH / CAA	1	\$160.00	/
8	Front garnish / CAA	1	\$320.00	/
9	Brake lever / CAA	1	\$82.00	/
10	Handle bar / BT	1	\$350.00	/
11	Handle bar bracket X / NN	2	\$210.00	/
12	Handle grip X	2	\$40.00	/
13	Handle bar balancer / CAA	2	\$90.00	/
14	Front fender / DIS	1	\$210.00	/
15	Front brake disc RH / NN	1	\$445.00	/
16	Radiator assy / BT	1	\$480.00	/
17	Radiator bracket X / NN	2	\$160.00	/
18	Fuel tank / MC	1	\$950.00	/
19	Front engine cover RH X / NN	1	\$280.00	/
20	Brake pedal / BT	1	\$98.00	/
21	Front footrest RH / CAA	1	\$75.00	/
22	Front footrest bracket RH X / NN	1	\$135.00	/
23	Yoshimura exhaust muffler X / Repair	1	\$1,900.00	/
Total			\$8,245.00	
Less 10% :			\$824.50	
(A) Sub Total :			\$7,420.50	

S/No:	Spare parts Description	Qty	S/Nett
1	Steering cone /	1	\$105.00
2	Front number plate /	1	\$20.00
3	Fork oil / MC	2	\$40.00
4	Fork oil seal /	2	\$80.00
(B) Sub Total :			\$245.00
(A+B) Parts Total :			\$7,665.50

S/No:	Labour Charges	Amount
1	Transportation	\$60.00
2	Front body frame alignment	\$200.00
3	Front rim balancing	\$60.00
4	Front fork alignment	\$150.00
5	Spray painting	\$900.00
6	Replace, align and adjust damaged parts. Check wiring and lighting system.	\$350.00
(C) Labour Total :		\$1,720.00
Total Amount :		\$9,385.50

MCS Auto

1100 SERANGOON ROAD SINGAPORE 328195
TEL : 62969939 FAX : 62964038
Company Registration No. 53126812L
Email : mcs.auto@yahoo.com.sg

Fax on 18/03/2019

6735 7416

Date: 18 Mar 2019

Attn: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

3rd Party Direct Settlement

ACCIDENT INVOLVING FBB9564X / SKU1364C ON 26.07.2018

We act for **Mohammed Hafizhullah Ghouse Bin Haji Mohamed Omar**
who has appointed the undermentioned workshop to repair his motor vehicle no. FBB9564X

Please be informed that the said vehicle can be inspected at:

1100 Serangoon Road Singapore 328195
Business Hours: 9.30am-6.30pm
Contact: 62969939 Stephanie

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any

Please acknowledge our fax upon received or once your appointed surveyor is confirmed.

Yours faithfully,

Stephanie
Motor Claims Dept
Off: 62969939
Hp: 86178052
Fax: 62964038



For Surveyor Acknowledgement:

Gue Ong.
UK
20/3/19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	4565A
Vehicle Details	
Vehicle No.:	FBB9564X
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	SUZUKI
Vehicle Model:	GSF1250SAK7
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	W705110259
Chassis No.:	JS1CH113100103914
Maximum Power Output:	-
Open Market Value:	\$8,963.00
Original Registration Date:	27 Sep 2007
First Registration Date:	27 Sep 2007
Transfer Count:	4
Actual ARF Paid:	\$1,345.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$6,256.00
COE Rebate Amount:	\$5,321.00
Total Rebate Amount:	\$5,321.00

The information contained herein is correct as at 21 Mar 2019

OK

Pre-Repair Inspection Request – FBB9564X vs SKU1364C (OI) on D.O.A.: 26/07/2018

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 19/3/2019 1:37:15 PM
Attachments:  [img0013.tif](#)

Hi,

Please refer to the enclosed request from **MCS Auto**.

Claim no : 3739715786SG003
Case Owner : CHIT YAN FOO

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: mcs.auto@yahoo.com.sg [mailto:mcs.auto@yahoo.com.sg]
Sent: Tuesday, March 19, 2019 1:26 PM
To: Hor, Yinnul
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKU1364C AND FBB9564X ON 26/07/2018

Dear Sir/Madam,

Marcus Chua LKK Auto Consultants Pte Ltd

Thank you.

From: Hor, Yinnul
Sent: Tue, 19 Mar 2019 01:37:42 +0000
To: mcs.auto@yahoo.com.sg
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKU1364C AND FBB9564X ON 26/07/2018

Without Prejudice

Your Reference : FBB9564X
Our Reference : 3739715786SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd

10:56am @ 20/3/19
vehicle in
stephanie
sure@Steve

Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOI, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinru.Hor@aig.com / www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

MCS Auto

1100 SERANGOON ROAD SINGAPORE 328195

TEL : 62969939 FAX : 62964038

Company Registration No. 53126812L

Email : mcs.auto@yahoo.com.sg

Fax on 18/03/2019

6935 7416

Date: 18 Mar 2019

Attn: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

3rd Party Direct Settlement**ACCIDENT INVOLVING FBB9564X / SKU1364C ON 26.07.2018**

We act for Mohammed Hafizhullah Ghouse Bin Haji Mohamed Omar
who has appointed the undermentioned workshop to repair his motor vehicle no. FBB9564X

Please be informed that the said vehicle can be inspected at:

1100 Serangoon Road Singapore 328195
Business Hours: 9.30am-6.30pm
Contact: 62969939 Stephanie

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any

Please acknowledge our fax upon received or once your appointed surveyor is confirmed.

Yours faithfully,

Stephanie
Motor Claims Dept
Off: 62969939
Hp: 86178052
Fax: 62964038

**For Surveyor Acknowledgement:**

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jul 2018 Edit Reg		19 Mar 2019 00:00 Edit Adj Rpt	S\$3,900.00 Edit Estimates	S\$3,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS			[Created by adjuster]
Insured:	CHEONG KING YEE, ID: 57886605E		
Main Claimant:	MOHAMED HAFIZHULLAH GHOUSE BIN HAJI MOHAMED OMAR, ID: S9024565A		
Vehicle Reg. No.:	FBB9564X	Date of Loss:	26/07/2018 07:00 - :59 [129 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3739715786SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SKU1364C	Policy No. (Claimant):	5080190697-02TP
		Excess:	
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBB9564X (3739715786SG)
[SKU1364C]
TP
MOHAMED HAFIZHULLAH GHOUSE BIN HAJI MOHAMED OMAR
Jul 26 2018 7:00AM
[CHEONG KING YEE]
Mcs Auto

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/19 07:50	General View		Load JPG
2	28/03/19 07:50	General View		Load JPG
3	28/03/19 07:50	General View		Load JPG
4	28/03/19 07:50	General View		Load JPG
5	28/03/19 07:50	General View		Load JPG
6	28/03/19 07:50	General View		Load JPG
7	28/03/19 07:50	General View		Load JPG
8	28/03/19 07:50	General View		Load JPG
9	28/03/19 07:50	General View		Load JPG
10	28/03/19 07:50	General View		Load JPG
11	28/03/19 07:50	General View		Load JPG
12	28/03/19 07:50	General View		Load JPG
13	28/03/19 07:50	General View		Load JPG
14	28/03/19 07:50	General View		Load JPG
15	28/03/19 07:50	General View		Load JPG
16	28/03/19 07:50	General View		Load JPG
17	28/03/19 07:50	General View		Load JPG
18	28/03/19 07:50	General View		Load JPG
19	28/03/19 07:50	General View		Load JPG
20	28/03/19 07:50	General View		Load JPG
21	28/03/19 07:50	General View		Load JPG
22	28/03/19 07:50	General View		Load JPG

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/19 19:34	ACKNOWLEDGEMENT EMAIL TO AIG dd 20.3.2019		Load PDF
2	20/03/19 19:34	EMAIL FROM AIG DD 19.03.2019		Load PDF
3	20/03/19 19:34	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT		Load TIF
4	23/03/19 16:25	TP ESTIMATE - MARKED		Load PDF
5	23/03/19 16:25	TP GIA REPORT + PIR RESULT		Load PDF
6	16/03/20 08:48	WORKSHOP INVOICE		Load PDF
7	16/03/20 08:48	AUTHORISATION TO ACT FORM		Load PDF
8	16/03/20 08:48	Release Voucher		Load PDF
9	16/03/20 08:48	PIR		Load PDF
10	16/03/20 08:48	LETTER TO OI		Load PDF
11	16/03/20 08:48	LOD		Load PDF

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/03/19 08:44	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SKU1364C (Insd veh)	Model:	SUZUKI GSF1250SA 1.3
	FBB9564X (TP veh)		
Date of Accident:	26/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,385.50
Final Repair Cost	:	\$	3,900.00
Loss of Use	:	\$	120.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,020.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____100____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	MCS Auto	:	\$ 4,020.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

16 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19005095/GEA3Q2
Date: 16/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant FBB9564X Insured Vehicle No : SKU1364C
Vehicle No : FBB9564X Nature of Claim: TP Claim No: 3739715786SG
Date of Loss: 26/07/2018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBB9564X
Make & Model: SUZUKI GSF1250SA, 1.3 Engine No: W705110259
Reg. Date: 27/09/2007 (Man. Year: 2007) Chassis No: JS1CH113100103914
Colour: Black Odometer: 0 km
Engine Capacity: 1255 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 190/50Z R17
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,665.50	4,614.50	3,051.00	39.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	320.00	1,400.00	81.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,385.50	4,934.50	4,451.00	47.42
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	9,385.50	3,900.00	5,485.50	58.45
+ Loss of Use (4.0 x S\$30.00/day) (S\$)		120.00		
Nett Liability (S\$)		4,020.00		

INSPECTION

Date of Assignment: 19/03/2019
Date Inspected: 20/03/2019 Inspected At: Mcs Auto (HQ)
1100 Serangoon Rd
Singapore 328195
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY	Cracked	620.00 FL	*620.00 FL
2	1		*HEADLAMP BRACKET	Not Necessary	220.00 FL	*- FL
3	1		*FRONT COWLING	Cracked	750.00 FL	*750.00 FL
4	1		*METER COWLING	Cut	220.00 FL	*220.00 FL
5	2		*VIEW MIRROR	Broken	240.00 FL	*240.00 FL
6	1		*WINDSHIELD	Distorted	210.00 FL	*210.00 FL
7	1		*FRONT SIGNAL LAMP RH	Cracked	160.00 FL	*160.00 FL
8	1		*FRONT GARNISH	Cracked	320.00 FL	*320.00 FL
9	1		*BRAKE LEVER	Cut	82.00 FL	*82.00 FL
10	1		*HANDLE BAR	Bent	350.00 FL	*350.00 FL
11	2		*HANDLE BAR BRACKET	Not Necessary	210.00 FL	*- FL
12	2		*HANDLE GRIP	Not Necessary	40.00 FL	*- FL
13	2		*HANDLE BAR BALANCER	Cut	90.00 FL	*90.00 FL
14	1		*FRONT FENDER	Distorted	210.00 FL	*210.00 FL
15	1		*FRONT BRAKE DISC RH	Not Necessary	445.00 FL	*- FL
16	1		*RADIATOR ASSY	Bent	480.00 FL	*480.00 FL
17	2		*RADIATOR BRACKET	Not Necessary	160.00 FL	*- FL
18	1		*FUEL TANK	Buckled	950.00 FL	*950.00 FL
19	1		*FRONT ENGINE COVER RH	Not Necessary	280.00 FL	*- FL
20	1		*BRAKE PEDAL	Bent	98.00 FL	*98.00 FL
21	1		*FRONT FOOTREST RH	Cut	75.00 FL	*75.00 FL
22	1		*FRONT FOOTREST BRACKET RH	Not Necessary	135.00 FL	*- FL
23	1		*YOSHIMURA EXHAUST MUFFLER	Repair	1,900.00 FL	*- FL
24	1		*STEERING CONE	Necessary	105.00 FS	*105.00 FS
25	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*20.00 FS
26	2		*FORK OIL	Necessary	40.00 FS	*40.00 FS
27	2		*FORK OIL SEAL	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,490.00	5,100.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	824.50	485.50
Total Parts (\$\$)	7,665.50	4,614.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPOTATION	New	60.00	40.00
2	FRONT BODY FRAME ALIGNMENT	New	200.00	0.00
3	FRONT RIM BALANCING	New	60.00	30.00
4	FRONT FORK ALIGNMENT	New	150.00	50.00
5	SPRAY PAINTING	New	900.00	0.00
6	REPLACE ,ALIGN AND ADJUST DAMAGED PARTS .CHECK WIRING AND LIGHTING SYSTEM	New	350.00	200.00
Gross Labour Cost (\$\$)			1,720.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >