

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8820 S

1 pc	Front bumper	✓	\$ 531.00
1 pc	Front bumper emblem	✓	\$ 44.00
1 pc	Front bumper n/s side bracket	X sm	\$ 18.00
1 pc	Wheel cover	X repair	\$ 116.00
1 pc	Front n/s fender	✓ Def	\$ 384.00
1 pc	Front n/s fender inner shield	X sm	\$ 120.00
	Front n/s door X repair		\$ 1,213.00
	Less 10%		\$ 121.30
			\$ 1,091.70

S/NETT

1 set	Front bumper clips	✓	\$ 48.00
1 pc	Front n/s fender sticker	X m	\$ 30.00
1 set	Front n/s fender inner shield clips	X m	\$ 28.00
1 set	Front n/s door sticker	✓	\$ 100.00
	Sundry		\$ 50.00 20
	To check wheel alignment		\$ 80.00 X m
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 120.00 X m
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s door etc		\$ 750.00 400
	To putty and spray painting on front bumper, front n/s fender, front n/s door		\$ 600.00 540
	To apply rustproofing on the repaired and replaced panels.		\$ 120.00 50
			\$ 3,017.70

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)
LKK Auto Consultants hence notify the Repairer of the following
• To resurvey before/after spray painting
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES:
• To confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kohli 11/11/19
25/2/19 1400h
3 Days
L/S
After Repair p/b

21/2/19
old 4/3 \$1600/3 hrs
✓