

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 21 Mar 2019

Preliminary Advice

Vehicle No	: SLU6656R	Accident Date	: 15/03/2019
Make	: AUDI A4	Policy No.	: 1700087254
Assignment Date	: 21/03/2019	Excess	: S\$0.00
Date of Inspection	: 20/03/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,824.00
Revised Amount	:S\$	13,234.00
Check Items (Estimated)	:S\$	1,953.00
Total	:S\$	15,187.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	67,691.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,309.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 11 July 2019 3:22 PM
To: Boo seng yak; SUR; Carrine Leong; Chang Chee Sing;
jjayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLU6656R - OD AIG - SURVEYED 20 MAR 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$11,464.32 before excess \$300.00 & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 3 June 2019 9:20 AM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jjayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SLU6656R - OD AIG - SURVEYED 20 MAR 19

Hi Adrian and all,

Photographs of damaged items and revised estimate is attached.

Please confirm repair cost of \$11,464.32 @ 5 days of repairs.

Your early closure is appreciated.

Best regards - jb

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 25 March 2019 2:09 PM
To: Claims Dept; SUR
Subject: RE: OD CLAIMS FOR SLU 6656 R

Dear Kelvin,

As instructed by our client, please proceed to repair the **insured vehicle SLU 6656R (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 22 March 2019 10:26 AM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIMS FOR SLU 6656 R

Dear Kelvin,

Please be informed that we are pending for insurance's approval. Once approve, we will send you an email.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Friday, 22 March 2019 10:19 AM
To: SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR SLU 6656 R

Dear All,

Kindly advise who is the officer in-charge of this case to follow up repair approval.

Thank you.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Mar 2019 13:47	Cim Veh Model Changed		[] Merimen Administrator
2	16 Mar 2019 13:47	Cim Created	Reg No: SLU6656R, Acct Date: 2019/03/15, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119035205	[1] Merimen Administrator
3	18 Mar 2019 16:54	Cim Registration Modified	Acct Time:13:45:00->13:00:00, Pol No:->1700087254, Init.Est.:->5,000 - 6,000,	[1] Hor, Yinrul
4	18 Mar 2019 16:54	Cim Veh Model Changed	(206049) AUDI A4 1.4 (A).	[1] Hor, Yinrul
5	21 Mar 2019 10:32	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] LEE SU THING
6	21 Mar 2019 10:32	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
7	21 Mar 2019 10:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
8	21 Mar 2019 10:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/01	[A] LEE SU THING
9	21 Mar 2019 10:32	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] LEE SU THING
10	21 Mar 2019 10:32	Cim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
11	21 Mar 2019 10:32	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
12	21 Mar 2019 14:57	Adj Rpt Initiated		[A] SHIAU CHAN
13	21 Mar 2019 14:57	Cim Dtl Modified	JPJ Reg. Date: -> 2017/12/11.	[A] SHIAU CHAN
14	21 Mar 2019 14:57	Cim Details Notified		[A] SHIAU CHAN
15	21 Mar 2019 15:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/04/01	[A] SHIAU CHAN
16	21 Mar 2019 15:02	Adj Mandate Request	Cur.Req:15187.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	25 Mar 2019 09:34	Cim Registration Modified	Excess: -> 300.00, Excess Waived: -> 300.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[1] Loo, Tong Shing
18	25 Mar 2019 09:34	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	25 Mar 2019 10:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/01, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[1] Koh, Victor-CK
20	25 Mar 2019 10:22	Adj Mandate Set	Approved:13234.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[1] Koh, Victor-CK

Date From Date To Audit Type Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2092371	21/03/2019 14:57	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLU6656R		10.70

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9841H
Vehicle Details	
Vehicle No.:	SLU6656R
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CVN045372
Chassis No.:	WAUZZZF42JA023431
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,727.00
Original Registration Date:	11 Dec 2017
First Registration Date:	11 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$27,818.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2027
PARF Rebate Amount:	\$20,863.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$46,828.00
Total Rebate Amount:	\$67,691.00

The information contained herein is correct as at 21 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2019 13:12
Date Of Accident	15/03/2019 13:45
Exact Location Of Accident	KALLANG BAHU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU6656R
Insured/Policyholder	
Name Of Registered Owner	HUANG QINAN
NRIC No	S6879841H
Email Address	ANTAIBUILDING@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96884230
Alternative Phone No	OFFICE-96884230

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	HUANG QINAN
NRIC No	S6879841H
Date Of Birth	30/07/1968
Occupation	INDOOR
Date Of Driving Pass	27/09/1996
Driving Experience	22 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96884230
Fax Number	
Contact Number	OFFICE-96884230
EEmail Address	ANTAIBUILDING@HOTMAIL.COM

Address	APT BLK 203D COMPASSVALE ROAD # 14 -57
Postcode	544203
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS ACCIDENTALLY COLLIDED INTO THE TAXI (SHC 7985 B) WHEN I'M APPROACHING TO THE MAIN ROAD .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7985B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invokes, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


16/03/2019

FORM 1607 (REV 2017)



Driver's Signature
(if driver is not the policyholder)
Date & Time:

16/03/2019


Reporting Centre Person's Signature


Name: 

NRIC/FIN No: 



Sketch Plan #2

SKETCH PLAN



A - SUV 6856 R
 B - SHC 79853

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was accidentally collided into the taxi (SHC 79853) when I was approaching to the main road. ~~SHC 79853~~

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Center Personnel's Signature
 Name:
 NHC/IN No.:

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6879841H



Name

HUANG QINAN

黄 啟 南



Race

CHINESE

Date of birth

30-07-1988

Sex

M

S6879841H

Country/Place of birth

CHINA



S978415



NRIC No. S6879841H




Date of issue

25-05-2018

Address

AFT BLK 203D COMPASSVALE ROAD
#14-57
SINGAPORE S44203



YOU ARE EXEMPTED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Vehicle Class	Valid Until
Class 2B	Motor cycles not exceeding 250 cc	27 Sep 1988
Class 2	Motor Cycles and Motor Tractors (No weight or wheel restriction does not exceed 2000 kg weight)	27 Sep 1988

License No. S6879841H

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0351/2019/ DY
Date : 19-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Huang Qinan
Address : Blk 203 Compassvale Road
#14-57
Singapore 544203
Telephone : HP +65 96884230
Type of Claim : Own Damage Claims
Policy No. : 2100319416-06
Vehicle No : **SLU 6656R**
Model Code : A4 SEDAN 1.4 TFSI S
Model / Year : 11/12/2017
Engine No : CVN 045372
Chassis No : WAUZZZF42JA023431
Mileage : 35599 KM
Date In : NOT IN
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Mar-19
Place of Accident : Kallang Bahru

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 6656 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front cash management.	\$ 2,100.00	1250 ✓
3	To respray front bumper and rhs front fender.	\$ 1,500.00	1100 ✓
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	✗
5	To carry out diagnostic check.	S/N \$ 240.00 ¹⁹²	✓
TOTAL LABOUR CHARGES		: \$ <u>4,480.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. S1Q 571 K SL46656R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehnd</i>	\$ 1,946.00	✓ 1856.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 258.00	✓
3	FRONT BUMPER SECURING STRIP <i>new</i>	\$ 64.00	✓
4	FRONT BUMPER CLOSING ELEMENT <i>new combed.</i>	\$ 191.00	✓ 152.40 ✓
5	FRONT BUMPER AIR GUIDE - RH <i>combed.</i>	\$ 56.00	? 44.00 ✓
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	\$ 123.00	✓
7	BUMPER CARRIER <i>Not new</i>	\$ 733.00	? ✓
8	BUMPER CARRIER BRACKET - RH <i>new</i>	\$ 207.00	✓
9	FRONT BUMPER GUIDE SECTION - RH <i>Rehnd</i>	\$ 34.00	✓ 27.12
10	FOAM FILLER PIECE - RH <i>Not new</i>	\$ 16.00	? ✓
11	FOAM FILLER PIECE - MIDDLE <i>Not new.</i>	\$ 113.00	? ✓
12	RADIATOR GRILLE SUPPORT <i>new</i>	\$ 125.00	✓
13	RADIATOR GRILLE SUPPORT BRACKET - RH <i>new</i>	\$ 26.00	✓
14	FRONT FENDER - RH <i>Rehnd</i>	\$ 700.00	✓ 528.60
15	FRONT FENDER ATTACHMENT PART <i>Not new.</i>	\$ 183.00	? ✓
16	FENDER CLOSING ELEMENT RH <i>Rehnd.</i>	\$ 45.00	? 36 ✓
17	FENDER BRACKET - RH <i>Rehnd</i>	\$ 32.00	✓ 25.20
18	FENDER BRACKET DEFORMATION ELEMENT - RH <i>Rehnd</i>	\$ 45.00	✓ 35.60
19	FENDER BRACE - RH <i>Rehnd</i>	\$ 107.00	✓ 85.60
20	FRONT WHEEL HOUSING LINER - RH <i>Rehnd.</i>	\$ 220.00	✓ 175.60
SUB-TOTAL SPARE PARTS CHARGES		\$ 5,224.00	

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJO 571 K SLN 6656R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT WHEEL HOUSING LINER ATTACHMENT - RH <i>2nd new</i>	S 82.00	? X
22	FRONT WHEEL SPOILER - RH <i>cracked</i>	S 66.00	✓ 52.32
23	FRONT WHEEL SPOILER TRIM - RH <i>cracked</i>	S 33.00	? 29.84 ✓
24	FRONT FENDER STONE CHIP GUARD - RH <i>new</i>	S 46.00	✓ 36.64
25	FRONT FENDER TOP COVER - RH <i>new</i>	S 28.00	✓ 22.24
26	FRONT HEADLIGHT TOP COVER - RH <i>new</i>	S 21.00	✓ 16.16
27	HEADLIGHT - RH <i>cracked</i>	S 7,087.00	✓ 5669.60
28	HEADLIGHT POWER MODULE - RH <i>3rd new</i>	S 716.00	X
29	HEADLIGHT CONTROL UNIT - RH	S 685.00	X
30	HEADLIGHT LIFT CYLINDER - RH <i>2nd new</i>	S 192.00	? X
31	TYRE RIM - RHF <i>new new</i>	S 651.00	X
32	RUBBER VALVE <i>new new</i>	S 13.00	X
33	SUNDRIES <i>new</i>	S 500.00	? 41.20 ✓
TOTAL SPARE PARTS CHARGES		: \$ 15,344.00	
TOTAL LABOUR CHARGES		: \$ 4,480.00	
GRAND TOTAL		: \$ 19,824.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 20/03/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 25 Days

LJK Auto Consultants (Singapore) Pte Ltd
The Reparer of the Insured

- To receive advice/offer of assistance
- To assist in arranging a replacement vehicle
- Parts used are subject to approval
- Third party survey service "without prejudice" basis
- No Special Arrangements Allowed
- Supplemental charges not to be claimed and is subject to final approval from Insurer's Company

Authorised by Reparer

Signature

Date

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0351/2019/ DY
Date : 19-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
5 days - ok - /b - 3 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Huang Qinan
Address : Blk 203 Compassvale Road
#14-57
Singapore 544203
Telephone : HP +65 96884230
Type of Claim : Own Damage Claims
Policy No. : 2100319416-06
Vehicle No : **SLU 6656R**
Model Code : A4 SEDAN 1.4 TFSI S
Model / Year : 11/12/2017
Engine No : CVN 045372
Chassis No : WAUZZZF42JA023431
Mileage : 35599 KM
Date In : NOT IN
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Mar-19
Place of Accident : Kallang Bahru

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 6656 R

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front cash management.		\$ 2,100.00	\$ 360.00
3	To respray front bumper and rhs front fender.		\$ 1,500.00	\$ 1,250.00
4	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 1,100.00
5	To carry out diagnostic check.	S/N	\$ 240.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,480.00	\$ 2,902.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 571 K

SUN 6652R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,946.00	\$ 1,556.80
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	FRONT BUMPER SECURING STRIP	\$ 64.00	
4	FRONT BUMPER CLOSING ELEMENT	\$ 191.00	\$ 152.40
5	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	\$ 44.40
6	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 123.00	
7	BUMPER CARRIER	\$ 733.00	
8	BUMPER CARRIER BRACKET - RH	\$ 207.00	
9	FRONT BUMPER GUIDE SECTION - RH	\$ 34.00	\$ 27.12
10	FOAM FILLER PIECE -RH	\$ 16.00	
11	FOAM FILLER PIECE - MIDDLE	\$ 113.00	
12	RADIATOR GRILLE SUPPORT	\$ 125.00	
13	RADIATOR GRILLE SUPPORT BRACKET - RH	\$ 26.00	
14	FRONT FENDER - RH	\$ 700.00	\$ 559.60
15	FRONT FENDER ATTACHMENT PART	\$ 183.00	
16	FENDER CLOSING ELEMENT RH	\$ 45.00	\$ 36.00
17	FENDER BRACKET - RH	\$ 32.00	\$ 25.20
18	FENDER BRACKET DEFORMATION ELEMENT - RH	\$ 45.00	\$ 35.60
19	FENDER BRACE - RH	\$ 107.00	\$ 85.60
20	FRONT WHEEL HOUSING LINER - RH	\$ 220.00	\$ 175.60
	SUB-TOTAL SPARE PARTS CHARGES	\$ 5,224.00	\$ 2,698.32

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 571 K

SUBSIST

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 2,698.32
21	FRONT WHEEL HOUSING LINER ATTACHMENT - RH		\$ 82.00	
22	FRONT WHEEL SPOILER - RH		\$ 66.00	\$ 52.32
23	FRONT WHEEL SPOILER TRIM - RH		\$ 33.00	\$ 25.84
24	FRONT FENDER STONE CHIP GUARD - RH		\$ 48.00	\$ 36.64
25	FRONT FENDER TOP COVER - RH		\$ 28.00	\$ 22.24
26	FRONT HEADLIGHT TOP COVER - RH		\$ 21.00	\$ 16.16
27	HEADLIGHT - RH		\$ 7,087.00	\$ 5,669.60
28	HEADLIGHT POWER MODULE - RH		\$ 716.00	
29	HEADLIGHT CONTROL UNIT - RH		\$ 685.00	
30	HEADLIGHT LIFT CYLINDER - RH		\$ 192.00	
31	TYRE RIM - RHF		\$ 651.00	
32	RUBBER VALVE		\$ 13.00	
33	SUNDRIES		\$ 500.00	\$ 41.20
	TOTAL SPARE PARTS CHARGES	:	\$ 15,344.00	\$ 8,562.32
	TOTAL LABOUR CHARGES	:	\$ 4,480.00	\$ 2,902.00
	GRAND TOTAL	:	\$ 19,824.00	\$ 11,464.32

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLU 6656 R

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0351/2019/KK

22 Aug 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SLU 6656 R, Audi A4 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. **SLU 6656 R**, claimant, **Mr. Huang Qinan** please find the related document per attached.

1. A copy of the Original invoice no. 85014135 – S\$11,945.82.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLU 6656 R

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Teletax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Teletax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Teletax 6641 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 16:25

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014135	Account: A0006 (T 0)
	Date : 19/08/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLU6656R	
	Term : 30	

Regn No: SLU6656R (V 34973) **Regn Date:** 11/12/2017 **Mileage:** 61801 **WIP No.:** 46560
Model: A4 SEDAN 1.4 TFSI S tronic **Chassis:** WAUZZZF42JA023431 **Engine:** CVN 045372 **Dept:** U
You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ABW0941774A	HEADLIGHT	Less 020%	1.00	7087.00
X	ABW0821172A	WHEEL HOUS	Less 020%	1.00	219.50
X	ABW0853888E	SPOILER	Less 020%	1.00	65.40
X	ABW0821106A	FENDER	Less 020%	1.00	699.50
X	ABW0807611	PLATE(LAST)	Less 020%	1.00	190.50
X	ABW0807065C GRU	COVER	Less 020%	1.00	1946.00
X	ABW0821468	BRACKET	Less 020%	1.00	31.50
X	ABW0807284	GUIDE	Less 020%	1.00	33.90
X	ABW0821092	PLATE	Less 020%	1.00	45.00
X	ABW0821136C	SUPPORT	Less 020%	1.00	107.00
X	ABW0121764	AIR DUCT	Less 020%	1.00	55.50
X	ABW0823746	COVER	Less 020%	1.00	20.20
X	ABW0821470	BRACKET	Less 020%	1.00	44.50
X	ABW0853834	SPOILER	Less 020%	1.00	32.30
X	ABW0820582C	COVER	Less 020%	1.00	27.80
X	ABW0853824B 9B9	STONEGUARD	Less 020%	1.00	45.80
X	AWHT006099	SPEED NUT	Less 020%	2.00	5.00
X	AN 0161857	POP-RIVET	Less 020%	6.00	3.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 2 16:25

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: #5014135 Date : 19/08/2019 Order : SLU6656R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLU6656R (V 34973) Regn Date: 11/12/2017 Mileage: 61801 WIP No.: 46560

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF42JA023431 Engine: CVN 045372 Dept: 0

You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
X	AN 0161857	PGP-RIVET			
X	AN 0385053	RIVET	Less 020%	6.00	3.00
X	AN 105835019B9	RIVET	Less 020%	5.00	0.50
			Less 020%	2.00	1.50
					2.40

Parts 8,562.32
Labour 0.00
Sublet 2,902.00
Menus 0.00
Lubricant 0.00

Sub-Total 11,164.32

7% GST 781.50

Grand Total 11,945.82



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLU 6656 R

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0351/2019/KK
26 April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI S
Vehicle Chassis No. : WAUZZZF42JA023431
Vehicle Regn No. : **SLU 6656 R**
Vehicle Mileage : 54152 KM
Vehicle Owner : Mr. Huang Qinan
Certificate No : 210019416-06
Own Damage Excess : S\$321.00 (Inclusive 7% GST)
Accident Date : 15/3/2019
Place : Kallang Bahru
Repair Cost : \$ 11,915.82
WIP No. : 46560
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6386 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 27/5/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Mar 2019		21 Mar 2019 10:32 Edit Adj Rpt	S\$11,464.32 Edit Estimates	S\$11,464.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by Insurer]					
Insured:	HUANG QINAN, ID: S6879841H, Tel: +6596884230, Email: ANTAJBUILDING@HOTMAIL.COM								
Vehicle Reg. No.:	SLU6656R	Date of Loss:	15/03/2019 13:00 - :59 [15 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4758538166SG	Policy/Cover Note No.:	1700087254 (Comprehensive) Coverage: 11/12/2017 - 10/12/2019						
		Excess:	S\$300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/04/2019]								
Driver/Custodian:	HUANG QINAN (50 / Male) , NRIC: S6879841H, Tel: +6596884230 Email: ANTAJBUILDING@HOTMAIL.COM								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (25/03/2019): Alert - Adj Mandate Approved (S\$13234.00) - SLU6656R - Claim Handler: Loo, Tong ... AIG_SG (25/03/2019): SLU6656R / OD / 15/03/2019 / Coverage & Excess update 									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU6656R (4758538166SG)
OD
Mar 15 2019 1:00PM
[HUANG QINAN]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	Use Viewer
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)								Thumbnail	Print
1	16/03/19 13:42	Video - Accident <small>[Linked Accident Report Documents]</small>									Load MP4
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	21/03/19 15:01	Adjuster Immediate Advice									Load HTM
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
2	21/03/19 14:55	Chassis Number									Load JPG <input checked="" type="checkbox"/>
3	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
4	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
5	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
6	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
7	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
8	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
9	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
10	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
11	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
12	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
13	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
14	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
15	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
16	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
17	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
18	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
19	21/03/19 14:55	General View									Load JPG <input checked="" type="checkbox"/>
20	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
21	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
22	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
23	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
24	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
25	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
26	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
27	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
28	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
29	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
30	10/07/19 17:57	Reinspection Photo									Load JPG <input checked="" type="checkbox"/>
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	21/03/19 14:54	Singapore Accident Statement									Load PDF
2	21/03/19 14:54	Certificate of Insurance									Load PDF
3	21/03/19 14:54	Driver's Driving License									Load PDF
4	21/03/19 14:54	ESTIMATE									Load PDF
5	25/09/19 09:55	WORKSHOP INVOICE									Load PDF

25/09/19 09:55

DISCHARGE VOUCHER

Load PDF

Linked Accident Report Documents

			View	Use Viewer
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/03/19 13:42	Video - Accident	 Load MP4	<input checked="" type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/03/19 13:47	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/03/19 13:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/03/19 13:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/03/19 13:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/03/19 13:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	16/03/19 13:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	16/03/19 13:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	16/03/19 13:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/03/19 13:44	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	16/03/19 13:44	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19005106/AQD3N2

Date: 25/09/2019

REFERENCE

Insured/Claimant:	HUANG QINAN	Policy No:	1700087254	
Date of Loss:	15/03/2019	Nature of Claim:	OD	Claim No: 4758538166SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU6656R	Engine No:	CVN045372
Make & Model:	AUDI A4, 1.4 (A)	Chassis No:	WAUZZZF42JA023431
Reg. Date:	11/12/2017 (Man. Year: 2017)	Odometer:	50286 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,344.00	8,562.32	6,781.68	44.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	2,902.00	1,578.00	35.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,824.00	11,464.32	8,359.68	42.17
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	19,524.00	11,164.32	8,359.68	42.82
+ GST 7.00/7.00% (S\$)	1,366.68	781.50	585.18	42.82
Nett Amount (S\$)	20,890.68	11,945.82	8,944.86	42.82

INSPECTION

Date of Assignment:	21/03/2019		
Date Inspected:	20/03/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,946.00 FS	*1,556.80 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1	*FRONT BUMPER SECURING STRIP	Not Necessary	64.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
5	1	*FRONT BUMPER AIR GUIDE-RH	Cracked	56.00 FS	*44.40 FS
6	1	*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	123.00 FS	*- FS
7	1	*BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
8	1	*BUMPER CARRIER BRACKET-RH	Not Necessary	207.00 FS	*- FS
9	1	*FRONT BUMPER GUIDE SECTION-RH	Damaged	34.00 FS	*27.12 FS
10	1	*FOAM FILLER PIECE-RH	Not Necessary	16.00 FS	*- FS
11	1	*FOAM FILLER PIECE-MIDDLE	Not Necessary	113.00 FS	*- FS
12	1	*RADIATOR GRILLE SUPPORT	Not Necessary	125.00 FS	*- FS
13	1	*RADIATOR GRILLE SUPPORT BRACKET-RH	Not Necessary	26.00 FS	*- FS
14	1	*FRONT FENDER-RH	Buckled	700.00 FS	*559.60 FS
15	1	*FRONT FENDER ATTACHMENT PART	Not Necessary	183.00 FS	*- FS
16	1	*FENDER CLOSING ELEMENT RH	Damaged	45.00 FS	*36.00 FS
17	1	*FENDER BRACKET-RH	Bent	32.00 FS	*25.20 FS
18	1	*FENDER BRACKET DEFORMATION ELEMENT-RH	Necessary	45.00 FS	*35.60 FS
19	1	*FENDER BRACE-RH	Bent	107.00 FS	*85.60 FS
20	1	*FRONT WHEEL HOUSING LINER-RH	Deformed	220.00 FS	*175.60 FS
21	1	*FRONT WHEEL HOUSING LINER ATTACHMENT-RH	Not Necessary	82.00 FS	*- FS
22	1	*FRONT WHEEL SPOILER-RH	Cracked	66.00 FS	*52.32 FS
23	1	*FRONT WHEEL SPOILER TRIM-RH	Cracked	33.00 FS	*25.84 FS
24	1	*FRONT FENDER STONE CHIP GUARD-RH	Necessary	46.00 FS	*36.64 FS
25	1	*FRONT FENDER TOP COVER-RH	Necessary	28.00 FS	*22.24 FS
26	1	*FRONT HEADLIGHT TOP COVER-RH	Necessary	21.00 FS	*16.16 FS
27	1	*HEADLIGHT-RH	Cracked	7,087.00 FS	*5,669.60 FS
28	1	*HEADLIGHT POWER MODULE-RH	Not Necessary	716.00 FS	*- FS
29	1	*HEADLIGHT CONTROL UNIT-RH	Not Necessary	685.00 FS	*- FS
30	1	*HEADLIGHT LIFT CYLINDER-RH	Not Necessary	192.00 FS	*- FS
31	1	*TYRE RIM-RHF	Not Necessary	651.00 FS	*- FS
32	1	*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
33	1	*SUNDRIES	Necessary	500.00 FS	*41.20 FS
				Total Parts (\$\$)	15,344.00 8,562.32

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	240.00	192.00
Gross Labour Cost (S\$)			4,480.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >