

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0349/2019/DY
Date	:	19-Mar-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr.Martin Daniel Gerard
Address	:	Blk 221 Bukit Batok East Ave 3 #06-174 Singapore 650221
Telephone	:	HP +65 81184404
Type of Claim	:	Own Damage Claims
Policy No.	:	1800023129-01
Vehicle No	:	SLW 9079 B
Model Code	:	AUDI Q2 1.0 TFSI S-TRONIC
Model / Year	:	8/3/2018
Engine No	:	CHZ 676172
Chassis No	:	WAUZZZGA2JA067336
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Mar-19
Place of Accident	:	INFRONT OF 30 LEE KENG RD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 9079 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To carry out towing services	S/N FOC	
2	To carry out first measurement on car-o-liner.	S/N \$ 800.00 ?	✓
3	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 X	✓
4	To remove and transfer rhs front and rear doors' multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 720.00	✓
5	To remove and reinstall rhs front seat assy, ABCD pillar trims, sill rims, floor carpets, electronics components and fuse trays.	S/N \$ 1,400.00	✓
SUB LABOUR CHARGES		: \$ 3,280.00	

Excess - ?
20/13/19

Steve CLKK
8322 8813
00 - Revert
18 days PIP
Re bot of dismantle parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 9079 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damage and renew where necessary.	S/N \$ 1,400.00	? X
7	To remove and reinstall centre console, renew airbag control unit, roof liner, both curtain airbags, and both front seat belts.	S/N \$ 2,800.00	✓
8	To renew driver seat air bag and leather cover.	S/N \$ 800.00	✓
* 9	To remove and reinstall front suspension for car-o-liner repairs.	S/N \$ 2,400.00	? ✓ ✓
* 10	To remove and reinstall rear exhaust silencer assy, rear suspension assy and fuel tank, for car-o-liner repairs.	S/N \$ 2,800.00	? X
SUB LABOUR CHARGES		: \$ 10,200.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 9079 B

S/n	Nature of Jobs	S/N	Estimated Charges	Surveyor's Recommendation
* 11	To place vehicle on car-o-liner.		\$ 1,800.00	✓
	To dismantle front bumper, rhs front fender, rhs front and rear doors. Inspect rhs floor pan for damages. Cut out and weld rhs B-pillar, inner reinforcements and sill panel. Renew damaged panels. Reinstall all parts removed. <i>500</i>		\$ 9,100.00	✓ <i>5000</i>
12				
	To respray rhs front fender, rhs front and rear doors, door handles, rhs B-pillar, sill panel, door entrances and inner reinforcements. To carry out joint sealer works and stone chip treatment. <i>500</i>		\$ 5,600.00	✓ <i>3300</i>
13				
14	To carry out wheel alignment.		\$ 240.00	✓
15	To carry out diagnostic check.		\$ 384.00	✓
TOTAL LABOUR CHARGES		:	\$ 30,604.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 9079 B

S/N	Parts Description	Damaged Parts & Prices			Remark
		S/	Nett		
1	FRONT FENDER-RH / <i>DD</i>		\$	1,047.00	837.60.
2	FRONT FENDER ATTACHMENT PARTS X <i>AET NIN</i>		\$	36.00	X
3	FRONT FENDER UPPER BRACKET-LH <i>RH</i> / <i>NEC</i>		\$	14.00	11.04
4	FRONT FENDER BRACKET-LH <i>RH</i> / <i>NEC</i>		\$	43.00	34.08
5	FRONT FENDER LOWER BRACKET-LH <i>RH</i> / <i>NEC</i>		\$	14.00	11.04
6	FRONT FENDER CLOSING ELEMENT-LH <i>RH</i> ? / <i>NEC</i>		\$	30.00	23.76
7	FRONT FENDER COVER-RH X <i>NIN</i>		\$	37.00	
8	FRONT WHEEL HOUSING LINER-RH X <i>AET NIN</i> / <i>TN</i>		\$	183.00	146
9	WHEEL HOUSING LINER ATTACHMENT PARTS X <i>NIN</i> / <i>NEC</i>		\$	52.00	41.00
10	FRONT WHEEL COVER-LH/RH / <i>CUT</i> 1 2		\$	588.00	469.60
11	FRONT DOOR-RH / <i>DD</i>		\$	2,285.00	1828
12	DOOR ATTACHMENT PARTS X <i>AET NIN</i>		\$	85.00	X
13	FRONT DOOR HINGE HALF UPPER PART-RH UPPER ? / <i>BT</i>		\$	41.00	32.32
14	FRONT DOOR HINGE HALF LOWER PART-RH LOWER ? / <i>BT</i>		\$	41.00	32.32
15	FRONT DOOR HINGE HALF UPPER PART-RH LOWER ? / <i>BT</i>		\$	39.00	30.80
16	FRONT DOOR CATCH-RH ? / <i>BT</i>		\$	109.00	87.20
17	FRONT DOOR SEAL INNER-RH / <i>NEC</i>		\$	146.00	116.80
18	FRONT DOOR HANDLE EXTERIOR-RH / <i>BR</i>		\$	331.00	264.40
19	FRONT DOOR HANDLE HOUSING-RH / <i>BR</i>		\$	47.00	37.28
20	FRONT DOOR SLIDE VALE -RH X <i>NIN</i> / <i>NEC</i>		\$	12.00	8.96
SUB-TOTAL SPARE PARTS			:	\$ 5,180.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Material List for Accident Vehicle Regn No. SLW 9079 B

All charges are not inclusive of GST.
 Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Netf.

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 9079 B

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remark
41	APPLICATOR X	N/A	\$ 7.00	
42	REAR DOOR HINGE HALF UPPER PART-RH UPPER	/ RT	\$ 41.00	32.08
43	REAR DOOR HINGE HALF LOWER PART-RH UPPER	/ RT	\$ 44.00	35.04
44	REAR DOOR HINGE HALF UPPER PART-RH LOWER	/ RT	\$ 39.00	30.80
45	REAR DOOR HINGE HALF LOWER PART-RH LOWER	X RT N/A	\$ 41.00	X
46	REAR DOOR CATCH-RH	? / RT	\$ 109.00	87.20
47	REAR DOOR CATCH COVER-RH	? X N/A	\$ 14.00	X
48	REAR DOOR SEAL INNER-RH	/ N/A	\$ 256.00	204.80
49	REAR DOOR SEAL OUTER-RH	X N/A / N/A	\$ 53.00	41.92
50	DOOR ATTACHMENT PARTS	X N/A	\$ 85.00	
51	REAR WINDOW GUIDE-RH	X N/A	\$ 377.00	
52	REAR WINDOW APERTURE SEAL-RH OUTER	X N/A / N/A	\$ 124.00	99.20
53	REAR TRIM FOR PILLAR B-RH	? X N/A	\$ 105.00	X
54	REAR WINDOW REGULATOR WITHOUT MOTOR-RH	? X N/A	\$ 241.00	X
55	REAR WINDOW REGULATOR MOTOR-RH	? X N/A	\$ 270.00	X
56	REAR DOOR COVER-RH	/ N/A (not multiply)	\$ 206.00	164.80
57	REAR DOOR WIRING SET-RH	? X N/A	\$ 710.00	X
58	REAR FENDER-RH	/ 00	\$ 1,930.00	1544
59	REAR B-PILLAR INNER-RH	X N/A	\$ 899.00	X
60	REAR B-PILLAR PLATE-RH	X N/A	\$ 17.00	X
61	REAR SIDE MEMBER-RH	X N/A	\$ 409.00	X
SUB-TOTAL SPARE PARTS			\$ 5,977.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

TGA 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 9079 B

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remark
61	SIDE MEMBER-RH	X N/U	\$ 409.00	X
62	REAR A-PILLAR-OUTER RH	X N/U	\$ 746.00	X
63	FRONT DATA TAG-RH	/	\$ 423.00	338
64	FRONT DATE PRESSURE-RH	/ N/C	\$ 26.00	2056
65	SIDE MEMBER TRIM-RH	/ N/C	\$ 218.00	174.40
66	1 SET OF FOAM STRIPS	/ N/C	\$ 126.00	100.40
67	PLASTIC PRIMER 40ML	? X N/U	\$ 101.00	X
68	ACRYLIC SEALER	/ N/C	\$ 360.00	360
69	CAVITY WAX	/ N/C	\$ 280.00	280
70	STONE CHIP	/ N/C	\$ 180.00	180
71	ROOF LINER	/ CRU	\$ 1,809.00	1447.20
72	FRONT A-PILLAR TRIM-LH	? / BA CRU	\$ 294.00	234.40
73	HEAD AIR BAG UNIT-LH/RH	LH/ RH/ RR	\$ 2,644.00	2115.20
74	AIR BAG CONTROL UNIT	/ N/C	\$ 1,593.00	1274.40
75	PRESSURE SENSOR	/ N/C	\$ 245.00	196
76	CRASH SENSOR FOR AIR BAG	/ N/C	\$ 1,526.00	1220.80
77	FRONT GRAB HANDLE	? / Jumper	\$ 258.00	206.40
78	THREE POINT AUTOMATIC SEAT	(Seat belt) RH/ LH/ RR	\$ 1,904.00	1523.20
79	FELT STRIPS	X N/U	\$ 22.00	
80	SEAT BEALT HEIGHT ADJUSTER	?	\$ 322.00	257.60
81	BACKREST COVER-RH	/ TN	\$ 2,533.00	2026.40
SUB-TOTAL SPARE PARTS			\$ 16,019.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLW 9079 B**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	BACKREST COVER-RH <i>X RPT</i>	\$ 2,533.00	
82	PADDING FOR BACKREST-RH <i>? X MIV</i>	TBC	X
83	SIDE AIR BAG UNIT-RH <i>/ GR</i>	\$ 1,164.00	931.20
84	ADAPTER WIRING HARNESS FOR SIDE AIR BAG-FRONT <i>/ NEC</i>	\$ 88.00	70.24
85	SUNDRIES <i>? / hrs</i>	\$ 2,000.00	167.76
TOTAL SPARE PARTS		\$ 38,625.00	
TOTAL LABOUR CHARGES		\$ 30,604.00	
GRAND TOTAL		\$ 69,229.00	69,954

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant